



Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

TRAILER

Maintenance Request / Report Form

Information

310

Grand Prairie - Shop

Tuesday, June 9th 2026, 10:24 AM (MDT -06:00)

Unit Information

Date: June 9, 2026

Select Unit Number: 310

KMs: # 0

Hours: # 0

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

Wheels off Cvip Dave
Replace 4x pig tails
Replace 4x taillights
Replace 2x light grommets
Re-wire Trailer plug cord
Take measurements
Grease up bearings

Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Cvip

Location of repairs being completed:

Pick the location where the repairs were completed:



Grande Prairie Shop

FULL SERVICE COMPLETED? Check the box if Oil /Filters & inspection are performed.

Requested By:

Worker Requesting Repairs:



John Klatt

Request submitted to:

After signing Request Form be sure to: Request Signature or Approval Tab and select either from the Given Names below: Ron Jerome, Jason Brown, Jon Archibald.

Signatures

John Klatt, *Mechanic*



June 9th 2026, 10:24 AM (MDT -06:00)



55.3093316, -118.7968916

Northern Spring, Brake & Steering Ltd.

Box 6207 Fort St. John, BC V1J 4H7 Phone(250-787-0727) Fax(250-787-9127) G.S.T. # R103927190

Invoice

TRAILER

Bill To Brothers HDD
8107 - 93rd Street
Fort St. John, BC V1J 6X1
Canada

Kirk (250) 793-5936
Amanda (780) 806-6716
Email ap@brothershdd.ca

Invoice Date Jun 16 2026
Appointment May 28 2026 1:27 pm
Promised May 28 2026 3:27 pm

Plate 6CW601
Description White 2009 / 310
Make Dynamic Enclosed Tridem Trailer
Engine N/A
Odometer
VIN 2A915530991136403

PO # 16821
Work Order # 0000218661
Invoice # 0000177334
Svc Advisor Kelly, Curt
Technician Howe, David

Services Performed

RE & RE SINGLE AXLE ASSEMBLY

Re & Re Front Axle Assembly, Install Wiring For Electric Brakes, Replaced Both Front Springs, Replace Ubolts, Nuts & Washers And Replaced Both Front Spring Hangers.	5.00 hrs.	\$165.00 / hr.	\$825.00 GP*
--	-----------	----------------	--------------

note: should replace front tires

Sub \$825.00

Materials Received

Material Only

The following is a list of material items you purchased which are not associated with services or repairs.

DX00705GC - 7000lb Straight Axle Assembly	1.00 Units	\$816.67 / Unit	\$816.67 GP
H.f.=77-1/4", S.c.=62" S/o. C/w 1/2" STUD Electric Brakes			
6000LB-7000LB - Axle Freight (spring Type)	1.00 Units	\$135.00 / Unit	\$135.00 GP
AX71-103 - Ubolt Kit (7k) 9/16"	1.00 Units	\$58.13 / Unit	\$58.13 GP
DX28-001 - Front Hanger 4-1/4" 2" Spring	2.00 Units	\$25.52 / Unit	\$51.04 GP
140-3T3-RB1 - Trailer Spring (7 Leaf Slipper) 5/8" Bolt	2.00 Units	\$161.59 / Unit	\$323.18 GP
801-2 - Shackle Bolt	2.00 Units	\$5.30 / Unit	\$10.60 GP
04 5/8 - Nf Gr8 Hex Nut	2.00 Units	\$0.56 / Unit	\$1.12 GP
01 3/8 X 3 1/2 - Nc Gr5 Bolt	1.00 Units	\$0.39 / Unit	\$0.39 GP
08 3/8 - Gr5 Flatwasher	2.00 Units	\$0.03 / Unit	\$0.06 GP
07 3/8 - Nc Nylock	1.00 Units	\$0.08 / Unit	\$0.08 GP
76-9939 - Shrink Tube	2.00 Units	\$1.22 / Unit	\$2.44 GP
HD TIE-12 - Hd Tie Wrap	4.00 Units	\$0.80 / Unit	\$3.20 GP

Sub \$1,401.91

Invoice Totals

Total Labor	\$825.00
Total Parts	\$1,401.91
Total Before Taxes & Miscellaneous Charges	\$2,226.91
(*) Shop Supplies	\$41.25 GP
(G) Canadian Goods and Services Tax (GST)	5 % \$113.41
(P) British Columbia Provincial Sales Tax	7 % \$158.77
Totals	\$2,540.34

Invoice Comments

U-Bolts MUST Be Retightened Within 500km or 1 Week, Wheel Nuts must be Retightened Within 100-150km



Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

TRAILER

FORT MAC

Maintenance Request / Report Form

Information

310

Ledcor RZ 2601-014

Monday, January 26th 2026, 12:14 PM (MST -07:00)

Unit Information

Date: January 26, 2026

Select Unit Number: 310

KMs: # 1

Hours: # 3296

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Request - Request shop assistance in facilitating repairs.

CLEANED FUEL SUPPLY / ELECTRIC
PUMP
RUNNING GOOD.
ORDER SPARE PUMP

Repairs Required

Description of Repairs Required (attach photos):

 Can't get engine to fire

Serial/Part # if applicable: = ?

Urgency of Repairs:

Select priority level of repairs:

☒ Critical - Immediate attention needed

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Field Repaired

Requested by:

Worker Requesting Repairs:



Randy Zaiser

Request submitted to:

After signing Request Form be sure to: Request Signature or Approval Tab and select either from the Given Names below: Ron Jerome Dan Fontaine Jon Archibald

Signatures

Randy Zaiser, *Supervisor*



January 26th 2026, 12:14 PM [MST -07:00]



56.1093436, -111.8408649

A handwritten signature in black ink, appearing to be 'Randy Z'.



TRAILER

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

310

Cenovus RZ 2510-012

Wednesday, November 19th 2025, 11:14 AM (MST -07:00)

Unit Information

Date: November 19, 2025

Select Unit Number: 310

KMs: # 1

Hours: # 1

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Request - Request shop assistance in facilitating repairs.

Repairs Required

Description of Repairs Required (attach photos):

310 driver side rear axle dust cap missing needs replacement

COMPLETED

Serial/Part # if applicable: = ?

Urgency of Repairs:

Select priority level of repairs:

☒ Critical - Immediate attention needed

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Wainwright Shop

Requested by:

Worker Requesting Repairs:



Randy Zaiser

Signatures

Randy Zaiser, *Supervisor*



November 19th 2025, 11:14 AM (MST -07:00)



53.2619532, -110.0244708

A handwritten signature in black ink, appearing to be 'Randy Z'.



RANDY

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-771

Maintenance Request / Report Form

Information

 310

 2508-008 RZ Wally's Donalda to Bawlf

 Tuesday, September 9th 2025, 7:37 AM (MDT -06:00)

Unit Information

Date:  September 9, 2025

Select Unit Number:  310

KMs:  500

Hours:  500

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Request - Request shop assistance in facilitating repairs.

Repairs Required

Description of Repairs Required (attach photos):

 Mud pump needs new air filter

Serial/Part # if applicable:  No Response



Urgency of Repairs:

Select priority level of repairs:

☒ High Priority - Required within 1-2 days

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Field Repaired

Requested By:

Worker Requesting Repairs:

 Randy Zaiser

Signatures

Randy Zaiser, *Supervisor*

 September 9th 2025, 7:37 AM (MDT -06:00)

 52.7297645, -112.4471652





LAF 5024

7AL 7502



TRAILER

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

310

FSJ Shop

Wednesday, August 6th 2025, 8:02 AM (MDT -06:00)

Unit Information

Date: August 5, 2025

Select Unit Number: 310

KMs: # 001

Hours: # 001

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

Build new tank mounting plate, mount new diesel tank on 310, plumb in fuel lines



Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level or repairs:

 Completed

Location of repairs being completed:

Pick the location where the repairs were completed:

 Ft St. John Shop

Requested By:

Worker Requesting Repairs:

 Kirk Bauming

Signatures

Kirk Bauming, *Construction Coordinator - BC*



 August 6th 2025, 8:02 AM (MDT -06:00)

 56.228895, -120.8334237



Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7717

TRAILER

FTSJ

Maintenance Request / Report Form

Information

310

BHDD Shop

Friday, July 18th 2025, 6:16 PM (MDT -06:00)

Unit Information

Date: July 18, 2025

Select Unit Number: 310

KMs: # 0

Hours: # 0

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

 Cvip
-replaced left rear brake
-adjusted bearings
-repaired light
-topped up tires

Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level of repairs:

☒ High Priority - Required within 1-2 days

Location of repairs being completed:

Pick the location where the repairs were completed:

Requested By:

Worker Requesting Repairs:



Luke Jacobsen

Signatures

Luke Jacobsen, *Mechanic*



July 18th 2025, 6:16 PM [MDT -06:00]



56.2288263, -120.8346653

A handwritten signature in black ink, appearing to be 'LJ' or similar, located on the right side of the document.



TRAILER

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

 310

 FSJ Shop

 Wednesday, April 23rd 2025, 4:18 PM [MDT -06:00]

Unit Information

Date:  April 23, 2025

Select Unit Number:  310

KMs:  0

Hours:  0

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Request - Request shop assistance in facilitating repairs.

Repairs Required

Description of Repairs Required [attach photos]:

 Aluminum welding to repair steps into 310 mud trailer

Serial/Part # if applicable:  No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Low Priority - Repair at earliest convenience

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Ft. St. John Shop



Requested by:

Worker Requesting Repairs:



Kirk Bauming

Additional Photos



Signatures

Kirk Bauming, *Construction Coordinator - BC*



April 23rd 2025, 4:18 PM (MDT -06:00)



56.2294331, -120.8346263

A handwritten signature in black ink, consisting of stylized letters that appear to be "KB".



Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

TRAILER

FIST

Maintenance Request / Report Form

Information

310

Excel RZ 2507-004

Friday, July 18th 2025, 9:11 AM [MDT -06:00]

Unit Information

Date: July 18, 2025

Select Unit Number: 310

KMs: # 001

Hours: # 001

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Request - Request shop assistance in facilitating repairs.

Repairs Required

Description of Repairs Required (attach photos):

Fuel leak on generator fuel line/sight gauge line.
Needs new fuel cap

Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Standard Priority - Required within 3-5 days

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Ft St. John Shop

Requested by:

Worker Requesting Repairs:



Randy Zaiser

Signatures

Kirk Bauming, *Construction Coordinator - BC*

A handwritten signature in black ink, appearing to be 'KS' or similar, written over a light gray background.

July 18th 2025, 9:11 AM (MDT -06:00)



56.2291128, -120.8326727



TRAILER

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

 310

 FSJ Shop

 Thursday, May 15th 2025, 4:41 PM [MDT -06:00]

Unit Information

Date:  May 15, 2025

Select Unit Number:  310

KMs:  1776

Hours:  1776.1

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

 Full service on gen

Serial/Part # if applicable:  Unit 310

Urgency of Repairs:

Select priority level of repairs:

☒ General maintenance

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Ft. St. John Shop



Requested By:

Worker Requesting Repairs:



Brandon Cunningham

Additional Photos



Full service complete. Air filter still in good shape just blew it out and cleaned housing.

Signatures

Colin Budda-Binder, Supervisor



May 15th 2025, 4:41 PM [MDT -06:00]



56.2292201, -120.834977



Brandon Cunningham, Driller



May 15th 2025, 4:42 PM [MDT -06:00]



56.2292632, -120.8349272





MAINTENANCE WORK ORDER

Nº 2772

UNIT #: 310 Mud Mix trailer - Randy
ENGINE HOURS: N/A
MILEAGE:
WORK LOCATION: F57 - Grande Prairie Field
WORK REQUESTED: Randy

ORDER DATE: Dec. 3/24
COMPLETED DATE: Dec. 5/24
JOB #:

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: Remove electrical motor/mud pump, change tank plumbing and hoses, valving, install gas mix pump, install exhaust,

TECH COMMENTS: Install complete

LABOUR DESCRIPTION:

HOURS

Kirk

LABOUR TOTAL

PARTS & MATERIALS

Hoses/camlocks/pipe nipples

P.O. #

10865

QUANTITY

PRICE

AMOUNT

497.37Baron Oil Field

PARTS & MATERIALS TOTAL

WORK AUTHORIZED BY: KirkWORK COMPLETED BY: KirkUNIT RETURNED TO SERVICE: Dec. 5/24OVERALL CONDITION OF UNIT: GoodADDITIONAL COMMENTS:

ADDITIONAL COMMENTS:



MAINTENANCE REQUEST FORM

UNIT# 310

HRS/KM

DESCRIPTION OF REPAIRS REQUIRED

Rear step Needs repairs.

mud pump seal Needs replacement.

OUTSIDE WORK LAMPS X 3

#107

A/C RECHARGE

REQUESTED BY:

Randy Zaiser

DATE:

June 23/2024



MAINTENANCE REQUEST FORM

UNIT# 310

HRS/KM

DESCRIPTION OF REPAIRS REQUIRED

Mud Pump. Mechanical Seal Leaks Bad

REPAIRED BY OBT R JUNE 6/24

REQUESTED BY:

~~02/02/24~~ 

DATE:

June 02/2024



UNIT #: 310 (Engine)
ENGINE HOURS: 9312.8 hr
MILEAGE: N/A
WORK LOCATION: Wainwright Shop
WORK REQUESTED: _____

ORDER DATE: May 27 2024
COMPLETED DATE: May 27 2024
JOB #: 1894

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: oil change, change fuel filter, change air filter, fuel oil leak

TECH COMMENTS: _____

LABOUR DESCRIPTION:	HOURS
<u>oil change</u>	<u>0.5hr</u>
<u>Air Filter Change</u>	<u>0.5hr</u>
<u>fuel filter change</u>	<u>0.5hr</u>

LABOUR TOTAL 1.5hr

PARTS & MATERIALS	P.O. #	QUANTITY	PRICE	AMOUNT
<u>oil filter</u>		<u>1</u>		
<u>Fuel filter</u>		<u>1</u>		
<u>Air filter</u>		<u>1</u>		
<u>OW-40 oil</u>		<u>5.8L</u>		

PARTS & MATERIALS TOTAL _____

WORK AUTHORIZED BY: Ron WORK COMPLETED BY: Lucas

UNIT RETURNED TO SERVICE: Yes OVERALL CONDITION OF UNIT: Average

ADDITIONAL COMMENTS: _____



MAINTENANCE WORK ORDER

Nº 2713

UNIT #: 36

ENGINE HOURS:

MILEAGE:

WORK LOCATION: wainwright shop

WORK REQUESTED: cvip

REPAIRS REQUIRED: cvip

ORDER DATE: may/1/24

COMPLETED DATE: may/13/24

JOB #:

W.O. TYPE (Circle): PM CVIP Reactive

TECH COMMENTS:

LABOUR DESCRIPTION:

took tires, drums off fixed, replace trailer plug
repacked bearings

HOURS

LABOUR TOTAL

PARTS & MATERIALS

suspension parts
trailer plug shop had
wheel seals

P.O. # QUANTITY PRICE AMOUNT

1
6

PARTS & MATERIALS TOTAL

WORK AUTHORIZED BY: cory

UNIT RETURNED TO SERVICE: yes

ADDITIONAL COMMENTS:

WORK COMPLETED BY: chase

OVERALL CONDITION OF UNIT: dirty



MAINTENANCE WORK ORDER

Nº 2016

UNIT #: 310

ENGINE HOURS:

MILEAGE:

WORK LOCATION: EST Field

WORK REQUESTED:

ORDER DATE: Feb 19 24

COMPLETED DATE: Feb 19 24

JOB #:

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: Mechanical seal in mixer pump

α will need a new Impeller.

TECH COMMENTS:

LABOUR DESCRIPTION: HOURS

Impeller Banged up due to Rocks will need to be replaced.
Left Front hub cap missing Install new one and
Clean Bearings

LABOUR TOTAL 8

PARTS & MATERIALS

	P.O. #	QUANTITY	PRICE	AMOUNT
Mechanical seal				
1712400 / 99 / 004				
K14460				
1250-070-CWP				
A21-1250-070-CWP				

PARTS & MATERIALS TOTAL

WORK AUTHORIZED BY: Can R

WORK COMPLETED BY: Can R

UNIT RETURNED TO SERVICE:

OVERALL CONDITION OF UNIT:

ADDITIONAL COMMENTS:

Mod was a mess nothing was locked for travel. Everything
all over the place.

MAINTENANCE WORK ORDER

Nº 1680



UNIT #: 310

ENGINE HOURS: _____

MILEAGE: _____

WORK LOCATION: one o one

WORK REQUESTED: _____

ORDER DATE: Oct 10 2023

COMPLETED DATE: Oct 15 2023

JOB #: _____

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: No Brakes or lack off

TECH COMMENTS: Replaced all 6 Backing plates

LABOUR DESCRIPTION:	HOURS
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____

LABOUR TOTAL _____

PARTS & MATERIALS	P.O. #	QUANTITY	PRICE	AMOUNT
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

PARTS & MATERIALS TOTAL _____

WORK AUTHORIZED BY: Cam? WORK COMPLETED BY: chase/cam?

UNIT RETURNED TO SERVICE: Oct 15 2023 OVERALL CONDITION OF UNIT: _____

ADDITIONAL COMMENTS: needs left front tire

Bumper to Bumper®

CANADA'S PARTS PEOPLE

WAINWRIGHT

1801 - 14 Avenue, Wainwright, AB T9W 1T9
Ph: 780-842-4307 Fax: 780-842-5944

VIKING

5107 - 50 Street, Viking, AB T0B 4N0
Ph: 780-336-4730 Fax: 780-336-3450

Page 1/1

G.S.T. REG. NO. 105570139 RT

MERCHANDISE RETURNED IS SUBJECT TO A RE-STOCKING CHARGE OF 15% - ALL MERCHANDISE REMAINS THE PROPERTY OF VENDOR UNTIL FULLY PAID FOR.

2 % PER MTH 24 % PER ANNUM ON OVERDUE ACCOUNT

ADMINISTRATION CHARGES

SOLD TO

BROTHERS HDD INC.

2002 23 Avenue

SHIP TO

WAINWRIGHT ALBERTA
T9W 1L2

SAME

DELIVERY		ORDER 4072 UNIT 310		CUSTOMER 2665	TELEPHONE (780) 875-8845	PAYMENT CHARGE		INVOICE 1 -4590293				
		SLMS 1	CLERK CHARLIE	EXEMPT		GST		CONDITIONS NET/30	DATE 12/10/2023			
QTY ORD.	QTY SHIP	*	LINE	PART NUMBER		DESCRIPTION		LIST	NET	%	EXTENSION	TAX F
3	3		FTP	FP12-1220B		R.H. 7K. 12 " X 2 " ELEC. B		137.89	86.69		260.07	F
3	3		FTP	FP12-1219B		L.H. 7K. 12 " X 2 " ELEC.		137.89	86.69		260.07	F
PICKED BY		Delivered CB				SUB TOTAL		GST			TOTAL	
						520.14		26.01	0.00		546.15	

TERMS: NET 30 DAYS.
2% PER MONTH (24% PER ANNUM) CHARGED ON
OVERDUE ACCOUNTS.

ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE.
1:08:54 PM

CUSTOMER



MAINTENANCE WORK ORDER

N^o 1623

UNIT #: 310.

ENGINE HOURS: _____

MILEAGE: _____

WORK LOCATION: Shop.

WORK REQUESTED: _____

ORDER DATE: June 19, 2023

COMPLETED DATE: Sept 18 2023

JOB #: _____

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: _____

Mud Pump Seal. &

lights.

TECH COMMENTS: unit left before electricians could
fix the lights. will have to be done another time

LABOUR DESCRIPTION:

Changed seal

HOURS

2.

LABOUR TOTAL _____

PARTS & MATERIALS

	P.O. #	QUANTITY	PRICE	AMOUNT
Mechanical seal				
A21-1250-070 - COP				
A-185VXX				
18260190-99.002				

PARTS & MATERIALS TOTAL _____

WORK AUTHORIZED BY: _____ WORK COMPLETED BY: _____

UNIT RETURNED TO SERVICE: _____ OVERALL CONDITION OF UNIT: _____

ADDITIONAL COMMENTS: _____

UNIT #: 310

ENGINE HOURS: _____

MILEAGE: _____

WORK LOCATION: Brothars HDD

WORK REQUESTED: _____

REPAIRS REQUIRED: CVIPORDER DATE: April 13/23COMPLETED DATE: April 10/23

JOB #: _____

W.O. TYPE (Circle): PM CVIP Reactive

TECH COMMENTS: _____

LABOUR DESCRIPTION: _____ HOURS

took wheels off took ~~out~~ out old seals put new ones in
cleaned hubs and bearings fixed cracked frame fixed leak
on fuel tank

12

LABOUR TOTAL _____

PARTS & MATERIALS

	P.O. #	QUANTITY	PRICE	AMOUNT
<u>Wheel seals</u>		<u>6</u>		
<u>plug wire</u>		<u>6 ft</u>		
<u>Wheel indicators</u>		<u>48</u>		

PARTS & MATERIALS TOTAL _____

WORK AUTHORIZED BY: Cory WORK COMPLETED BY: ChaseUNIT RETURNED TO SERVICE: YES OVERALL CONDITION OF UNIT: good

ADDITIONAL COMMENTS: _____