



H02-120
SEP

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

RECLAIMER

Maintenance Request / Report Form

Information

513

BHDD Shop

Monday, June 29th 2026, 7:16 AM [MDT -06:00]

Unit Information

Date: June 23, 2026

Select Unit Number: 513

KMs: # 990

Hours: # 2620

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

Cvip, break wiring damaged, trailer plug, gen service

- full generator service
- repaired brake wiring
- replaced trailer plug
- replaced wheel bearings on one wheel

Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Completed

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Wainwright Shop

☒ FULL SERVICE COMPLETED? Check the box if Oil /Filters & inspection are performed.

Requested By:

Worker Requesting Repairs:

 Luke Jacobsen

Request submitted to:

After signing Request Form be sure to: Request Signature or Approval Tab and select either from the Given Names below: Ron Jerome, Jason Brown, Jon Archibald.

Signatures

Luke Jacobsen, *Mechanic*

 June 29th 2026, 7:16 AM (MDT -06:00)

 52.851425, -110.842149





RECLAIMER

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

 513

 Michels SK 2601-001

 Wednesday, February 18th 2026, 1:00 PM [MST -07:00]

Unit Information

Date:  February 15, 2026

Select Unit Number:  513

KMs:  0

Hours:  2164

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

 Service genset engine

Serial/Part # if applicable:  No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Repairs completed

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Field Repaired



FULL SERVICE COMPLETED? Check the box if Oil /Filters & inspection are performed.

Requested By:

Worker Requesting Repairs:



Colton Wookey

Request submitted to:

After signing Request Form be sure to: Request Signature or Approval Tab and select either from the Given Names below: Ron Jerome Dan Fontaine Jon Archibald

Signatures

Colton Wookey, *Mechanic*



February 18th 2026, 1:00 PM (MST -07:00)



55.3093923, -118.7970329

Ron Jerome, *Supervisor*



Approved



February 18th 2026, 3:36 PM (MST -07:00)



52.851269, -110.8420346



Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

RECLAIMER GP

Maintenance Request / Report Form

Information

513

Michels DL 2601-006

Monday, February 9th 2026, 9:19 AM (MST -07:00)

Unit Information

Date: February 9, 2026

Select Unit Number: 513

KMs: # 0

Hours: # 2062

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

Generator keeps shutting down out of no where.
It fires right back up after you reset it.

Serial/Part # if applicable:

No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Standard Priority - Required within 3-5 days

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Field Repaired

BAD FUEL.

ON GOING ISSUE

FOR MANY MONTHS NOW
MULTIPLE ELECTRITIONS

REPAIRED...TANK DRAINED



FULL SERVICE COMPLETED? Check the box if Oil /Filters & inspection are performed.

Requested By:

Worker Requesting Repairs:



Luke Watchel

Request submitted to:

After signing Request Form be sure to: Request Signature or Approval Tab and select either from the Given Names below: Ron Jerome Dan Fontaine Jon Archibald

Signatures

Luke Watchel, *No title*



February 9th 2026, 9:19 AM [MST -07:00]



54.3353111, -118.3616102



RECLAIMER

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

 513

 FSJ Shop

 Thursday, September 18th 2025, 5:22 PM (MDT -06:00)

Unit Information

Date:  September 18, 2025

Select Unit Number:  513

KMs:  2001

Hours:  001


Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

 Trash pump control switch not working, rewire remote



Rewire trash pump/charge pump controller

Serial/Part # if applicable:

No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Completed

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Ft St. John Shop

Requested By:

Worker Requesting Repairs:

 Kirk Bauming

Signatures

Kirk Bauming, Construction Coordinator - BC

 September 18th 2025, 5:22 PM [MDT -06:00]

 56.2290104, -120.8323692





TRAILER

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

 513

 FSJ Shop

 Monday, August 25th 2025, 11:21 AM [MDT -06:00]

Unit Information

Date:  August 20, 2025

Select Unit Number:  513

KMs:  001

Hours:  920



Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

 Replace hydraulic motor, pump, re-route hydraulics, control cables, power.
Install in new box



Serial/Part # if applicable:

— No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Completed

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Ft. St. John Shop

Requested By:

Worker Requesting Repairs:

 Kirk Bauming

Signatures

Kirk Bauming, *Construction Coordinator - BC*



August 25th 2025, 11:21 AM (MDT -06:00)



56.2288464, -120.8321955

A handwritten signature in black ink, appearing to be 'KB'.



RECLAIMER

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

 513

 BHDD Shop

 Friday, July 25th 2025, 12:02 PM [MDT -06:00]

Unit Information

Date:  July 25, 2025

Select Unit Number:  513

KMs:  181.8

Hours:  00000

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

 Replace 2 brakes one one drum

Serial/Part # if applicable:  No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Completed

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Ft St. John Shop

Requested by:

Worker Requesting Repairs:



Chase Atkinson

Signatures

Chase Atkinson, *Laborer*



July 25th 2025, 12:02 PM [MDT -06:00]



56.2290851, -120.8348307

A handwritten signature in black ink, appearing to be 'Chase Atkinson'.



RECLAIMER

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

513

BHDD Shop

Friday, July 4th 2025, 11:18 AM (MDT -06:00)

w/o # 000168

Unit Information

Date: June 24, 2025

Select Unit Number: 513

KMs: # 0

Hours: # 912

ENTERED
July 28, 2025
J. J. [Signature]

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

- Cvip, checkover, install hub meter
- replaced rear brakes
- replaced outer bearings on rear brakes
- installed new breakaway battery
- replaced front jack hydraulic lines
- Installed rear mudflap
- repaired light wiring

Dog did full service on generator



Serial/Part # if applicable:

No Response

Urgency of Repairs:

Select priority level of repairs:

Standard Priority - Required within 3-5 days

Location of repairs being completed:

Pick the location where the repairs were completed:

Wainwright Shop

Requested By:

Worker Requesting Repairs:

Luke Jacobsen

Signatures

Luke Jacobsen, *Mechanic*

July 4th 2025, 11:18 AM [MDT -06:00]

52.8511549, -110.8420979



RECLINER

MILES

MAINTENANCE REQUEST FORM

UNIT# 513

HRS/KM

DESCRIPTION OF REPAIRS REQUIRED

- 4 BROKEN LEAF SPRINGS

ORDERED 6 LEAF SPRING &

ALL HARDWARE @ PAULS

FEB 18

INTO UNIT # 624 (SERVICE TRUCK)

REQUESTED BY:

DATE:



RECOVERIES

WALS

213

- + BLOOD TEST RESULTS


ORDERED 6 MORE STAIN

ALL THE ABOVE 9 PARTS

FEB 18

INTO UNIT # 2 (SERVICE TRUCK)

#513



#213

Item	Description
NTP-UNA-268	5 Leaf Slipper Spring 3" Wide 30 1/2" Long
NTP-7-169	Spring Bolt - 10k, 12k, 15k Dexter
NTP-6-112	LOCKNUT 1" EQUALIZER BOLT
NTP-7-95	Spring Keeper Bolt 1/2" X 4 1/2"
NTP-6-46	1/2" Locknut
NTP-11-77LN	5" Round U Bolt

Qty	Price	Total
6	\$187.60	\$1,125.60
6	\$15.08	\$90.48
6	\$5.32	\$31.92
6	\$4.82	\$28.92
6	\$1.89	\$11.34
12	\$15.41	\$184.92



RECLAIMER

MAINTENANCE REQUEST FORM

UNIT# 513

HRS/KM

* REPLACED FUEL FILTERS ON SITE *

DESCRIPTION OF REPAIRS REQUIRED

- REPLACE LAST THREE LEAF SPRINGS / - TIRES

- COMPLETE SERVICE

- REPAIR RR HYD JACK / - STRAIGHTEN RP

REINFORCE

(SERVICE / FILL HYD ASSEMBLY)

BOWTELL (LAST 2/3 DAYS OF RUNNING ISSUES)

"LOW VOLTAGE"

"LOW VOLTAGE FREQUENCY"

COULD ONLY FUNCTION 1 PUMP AT A TIME

- WASH OUT RAD / INNER COOLER

* WILL REQUIRE SCREENS NEXT OUTING

AS PER MILES *

- CLEAN OUT DESILTER CONES

- ~~TIGHTEN~~ BELT (ALT ?)
REPLACED PULLEY

REQUESTED BY:

- EXHAUST PIPE WELD

DATE:


WORLD CLASS SILENT GENERATOR

MODEL :	US90E	SERIAL NO. :	US90E17100427
FREQUENCY :	60Hz	SPEED :	1800RPM
STANDBY OUTPUT :	100KW		125KVA
PHASE :	3	POWER FACTOR :	0.8LAG
VOLTAGE :	277/480V	CURRENT :	150A
FUEL TANK :	380L	WEIGHT :	1900KG

DIMENSION (L*W*H) :

2500*1050*1700 MM

GENERATOR SET IS DESIGNED TO OPERATE IN AMBIENT TEMPERATURES UP TO 50°C AND AT ALTITUDES OF 1200M. WE RESERVE THE RIGHT TO EXPLAIN THE TERMS OF THIS SPECIFICATION





Perkins

POLAR 700) 411-1190

MADE IN CHINA

4387764

Φ554.55

WATER IN FUEL SENSOR
FUEL FILTER HEAD WITH PRIMER

ENGINE TYPE

NR83169*R016222C*

LIST NO.

SERIAL NO.

4254-22
4254-22

PORT 100-11-11-11

PORT 100-11-11-11
PORT 100-11-11-11



TRAILER (ICELANDER)

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

 513



Rocky Gas DL 2503-009



Monday, May 26th 2025, 11:27 AM [MDT -06:00]

Unit Information

Date:



May 26, 2025

Select Unit Number:



513

KMs:

#

1

Hours:

#

1

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.





Maintenance Request - Request shop assistance in facilitating repairs.

Repairs Required


Description of Repairs Required (attach photos):




Front passenger side jack leaking, breakaway not working, hopper pump leaking, mud flap off, belt on engine squealing, hopper lid broken, gate handle broken



Hole in pump housing





Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Low Priority - Repair at earliest convenience

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Wainwright Shop

Requested By:

Worker Requesting Repairs:  Derik Lynch


Signatures

Derik Lynch, *Locator*

 May 26th 2025, 11:27 AM [MDT -06:00]

 52.8520118, -110.8417751





...

E/C



MAINTENANCE WORK ORDER

Nº 3384

UNIT #: 513

ENGINE HOURS: 531

MILEAGE:

WORK LOCATION: Wainwright

WORK REQUESTED:

ORDER DATE: Feb 25 2025

COMPLETED DATE: Mar 6 2025

JOB #:

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: Replace leaf springs
Fuel leak, checkover
Missing fitting on rear jack
Straighten front jack
Service generator

TECH COMMENTS:

LABOUR DESCRIPTION:	HOURS
Replaced leaf springs	25
Serviced generator, Installed fitting on jack, straightened jack	
Replaced worn tires	
Repaired exhaust pipe	

LABOUR TOTAL 25

PARTS & MATERIALS	P.O. #	QUANTITY	PRICE	AMOUNT

PARTS & MATERIALS TOTAL

WORK AUTHORIZED BY: Ron

WORK COMPLETED BY: Mike Jacobsen

UNIT RETURNED TO SERVICE: Mar 6 2025

OVERALL CONDITION OF UNIT: Good

ADDITIONAL COMMENTS:



MAINTENANCE WORK ORDER

Nº 3383

UNIT #: 513

ENGINE HOURS: _____

MILEAGE: _____

WORK LOCATION: Conklin

WORK REQUESTED: _____

ORDER DATE: Feb 22 2025

COMPLETED DATE: Feb 22 2025

JOB #: _____

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: Replace broken leaf springs

TECH COMMENTS: _____

LABOUR DESCRIPTION: _____ HOURS

Replaced rear axle and middle right leaf
springs; installed wheels & torqued 5

Travelled to Conklin 4

Travelled to Wainwright 4

LABOUR TOTAL 13

PARTS & MATERIALS P.O. # QUANTITY PRICE AMOUNT

PARTS & MATERIALS TOTAL _____

WORK AUTHORIZED BY: Ron

WORK COMPLETED BY: Mike Jacobson

UNIT RETURNED TO SERVICE: Feb 22 2025

OVERALL CONDITION OF UNIT: Good

ADDITIONAL COMMENTS: _____

Front, left middle axle need leaf springs



JAN 6
MILES

MAINTENANCE REQUEST FORM

UNIT# 513

HRS/KM

DESCRIPTION OF REPAIRS REQUIRED

- JACKS NOT WORKING ?? SOMETIMES
MILES FIXED @
REMOTE

- TOP (MIDDLE) TARP

- INSTALL EXTRA PLUG INS

} BOWTEL

- WORK LAMPS

- PULLEY (SQUEAL) SERVICE
ENGINE

- HOUR METER (FRIDAY)

- SERVICE

X COMPLETE WASH X

HEAT TRACER (INSTALL) THEY ALL WORK IN
SHOP

MIDDLE TARP

HEATER / LIGHT PLANT (BREAKERS ??)

REQUESTED BY:

BLOWS THEM OUT

DATE:

DEAN

2 CONES

COUPLERS & INSERTS

3 CLAMPS



MAINTENANCE WORK ORDER

Nº 3158

ENTERED
FEB 11 2025

UNIT #: 513

ENGINE HOURS: 000

MILEAGE: N/A

WORK LOCATION: Washwright Shop

WORK REQUESTED:

REPAIRS REQUIRED: Full Service

ORDER DATE: Jan 2 2025

COMPLETED DATE: Jan 2 2025

JOB #:

W.O. TYPE (Circle): PM CVIP Reactive

TECH COMMENTS:

LABOUR DESCRIPTION: service HOURS 1

LABOUR TOTAL

PARTS & MATERIALS

	P.O. #	QUANTITY	PRICE	AMOUNT
oil filter		1		
fuel filters		2		
Air filter		1		
OW-40 oil		8L		

PARTS & MATERIALS TOTAL

WORK AUTHORIZED BY: Ron WORK COMPLETED BY: Dog

UNIT RETURNED TO SERVICE: yes OVERALL CONDITION OF UNIT: Good

ADDITIONAL COMMENTS:



MAINTENANCE WORK ORDER

N^o 2957

UNIT #: 513

ENGINE HOURS: _____

MILEAGE: _____

WORK LOCATION: Shop

WORK REQUESTED: _____

REPAIRS REQUIRED: CVIP

ORDER DATE: JULY 25/21

COMPLETED DATE: AUG 7/21

JOB #: _____

W.O. TYPE (Circle): PM CVIP Reactive

TECH COMMENTS: _____

LABOUR DESCRIPTION: _____ HOURS

leaf springs replaced replaced 1 tire fix brakes

LABOUR TOTAL _____

PARTS & MATERIALS

leaf springs and ~~bolts~~ bolts

brakes

PARTS & MATERIALS TOTAL _____

WORK AUTHORIZED BY: Cory/ron

WORK COMPLETED BY: Chase

UNIT RETURNED TO SERVICE: YES

OVERALL CONDITION OF UNIT: good

ADDITIONAL COMMENTS: _____



MAINTENANCE REQUEST FORM

UNIT# 513

HRS/KM 2739 HRS.

DESCRIPTION OF REPAIRS REQUIRED

- REBUILD DESICTER PUMP
- UNPLUG AND CLEAN OUT FRONT JET
- INSTALL HEAT TRACE AND FOIL WRAP
- INSTALL TURN BUCKLE SYSTEM
- WINTER SET UP (FRAME AND TARP)

REQUESTED BY:

DATE:



MAINTENANCE REQUEST FORM

UNIT# 513

HRS/KM

DESCRIPTION OF REPAIRS REQUIRED
ARM LOAD (SETS CODES) TEST AT FULL LOAD
JACKS OPERATION (70) (140) REQUESTED
SCREENS 3x80 3x120
4" VICTOLIC VALVE @ SHAKER PIPE
SELUITE TABLE
HUB CAP (SCREW ON) PAUL'S TRAILER
FLIGHT PUMP(S)?

REQUESTED BY:

DATE:



MAINTENANCE REQUEST FORM

UNIT# 513

HRS/KM

DESCRIPTION OF REPAIRS REQUIRED

CHIP

CORY/CHASE/LUKE

SEE ATTACHED SHEET FOR

RECLAIM REPAIRS

REQUESTED BY:

DATE:

Fixing List

UNIT #513

- electrical issues (Gen under Voltage)
(Gen under Frequency) codes

- Can't Run all Functions at once.

- Gen Shuts down frequently

- Transfer Pump needs Rebuild, want Pump to Rpg.

- Valve Before Transfer Pump washed.

- Valves at Bottom Tank (Drain valves) need Replaced.

- Need Spare 5" Hose clamps for Despiter Cones.

- New Bullet Hinges for Hoppe Lpd.

- ~~new~~ ~~new~~ ~~new~~

Rpg 110 (220x300 vermeer)

- get Air Conditioning working

- RPP Pump apart (washed seats)

- RPP front end apart (Sloppy Jaw Blocks)

- Put upgrade kit on the Crows Nest

- Hydraulic Leak from Valve Bank at Back of Rpg

- Replace Hydraulic Hose to TOP arm. (we have the hose)

- Pump Stroking on PFS own (mud Pump)

- Wind shield wiper motor not working.

- Low Hydraulic Fluid Sensor to be Replaced. (mechanic has it)

- Build guard for the Low mud Pressure Sensor (need new Sensor)

- Encoder needs to work.

- Tighten Track Bolts

- Pump up Tracks

JD 350 G & JD 300 G Excavators

- Pins that hold Buckets on are slowly coming out. we have to Hammer them back in every couple days

- Clean out engine Bays

- Clean out Cabs

- Check Hrs for Service

- Pump up Tracks, Grease Apple Brake off JD 350.

- Sealed Rollers on Tracks (a few)

- Pin for Tooth on JD 300 Digging Bucket

- Parts Trailer & OFFPC Trailer

- Go through Trailers and do an Inventory on, Fluids & Products



MAINTENANCE WORK ORDER

Nº 1581

UNIT #: 5/3
ENGINE HOURS: 2442
MILEAGE: _____
WORK LOCATION: Shop
WORK REQUESTED: _____

ORDER DATE: Feb/19/24
COMPLETED DATE: Feb/19/24
JOB #: _____

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: full service

TECH COMMENTS: _____

LABOUR DESCRIPTION:	HOURS
<u>Changed oil and filter fuel filters changed</u>	<u>2</u>
<u>Air filters changed</u>	
<u>Checked fluids</u>	
<u>RON</u>	<u>1</u>
<u>CHECKED FIVE EXT</u>	

LABOUR TOTAL 3

PARTS & MATERIALS	P.O. #	QUANTITY	PRICE	AMOUNT
<u>oil filter</u>		<u>1</u>		
<u>fuel filter</u>	<u>5266</u>	<u>2</u>		<u>\$115.88</u>
<u>Air filter</u>		<u>2</u>		
<u>oil</u>		<u>5L</u>		

PARTS & MATERIALS TOTAL _____

WORK AUTHORIZED BY: Ron WORK COMPLETED BY: Chase

UNIT RETURNED TO SERVICE: YES OVERALL CONDITION OF UNIT: GOOD

ADDITIONAL COMMENTS: _____



MAINTENANCE WORK ORDER

N^o 1764

UNIT #: 513

ENGINE HOURS: 3509 HRS

MILEAGE:

WORK LOCATION: WAINWRIGHT SHOP

WORK REQUESTED:

ORDER DATE: MARCH 21/2023

COMPLETED DATE: MARCH 21/2023

JOB #:

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED:

TECH COMMENTS:

LABOUR DESCRIPTION: HOURS

REPAIR ELECTRIC BRAKE WIRING (RON 2) 2

LABOUR TOTAL 2

PARTS & MATERIALS P.O. # QUANTITY PRICE AMOUNT

WIRE / MISC MATERIAL SHOP

PARTS & MATERIALS TOTAL

WORK AUTHORIZED BY: CORY R WORK COMPLETED BY: RON JEROME

UNIT RETURNED TO SERVICE: MARCH 21/2023 OVERALL CONDITION OF UNIT:

ADDITIONAL COMMENTS:

 Perkins

ENGINE TYPE

SERIAL NO.

LIST NO.

NP8316*P01622K*

MADE IN CHINA