



H02-136  
SEP

Brothers HDD Inc  
2002 23 Avenue  
Wainwright, Alberta  
T9W 0B8  
780-214-7711

GEN SET / PUMP COMBO

## Maintenance Request / Report Form

### Information

537

Hamm CB 2604-008

Wednesday, May 6th 2026, 1:50 PM (MDT -06:00)

### Unit Information

Date: May 6, 2026

Select Unit Number: 537

KMs: # 10373

Hours: # 10373

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

### Repairs Required

Description of Repairs Required (attach photos):

Full service on GEN set



Did not do air or water separator. [ did not have the proper filters].

Serial/Part # if applicable:

☐ No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Field repair

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Field Repaired

 FULL SERVICE COMPLETED? Check the box if Oil /Filters & inspection are performed.



**Requested By:**

Worker Requesting Repairs:



Colin Budda-Binder

**Request submitted to:**

After signing Request Form be sure to: Request Signature or Approval Tab and select either from the Given Names below: Ron Jerome, Jason Brown, Jon Archibald.

**Signatures**

Colin Budda-Binder, *Supervisor*



May 6th 2026, 1:50 PM (MDT -06:00)



52.1863682, -106.6154282



PUMP SHACK

Brothers HDD Inc  
2002 23 Avenue  
Wainwright, Alberta  
T9W 0B8  
780-214-7711

## Maintenance Request / Report Form

### Information

 537

 BHDD Shop

 Thursday, August 14th 2025, 7:17 PM [MDT -06:00]

### Unit Information

Date:  August 14, 2025

Select Unit Number:  537

KMs:  0000

Hours:  0000

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

### Repairs Required

Description of Repairs Required (attach photos):

 Transmission was put back in after having new seals put in it. No leaks while running in neutral at high idle

Serial/Part # if applicable:  ....n/a

### Urgency of Repairs:

Select priority level of repairs:

☒ Low Priority - Repair at earliest convenience

FLUID LEVEL CHECKED AFTER RUNNING AGAIN !!

### Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Ft St. John Shop

Requested by:

---

Worker Requesting Repairs:



Jon Archibald

## Signatures

Jon Archibald, *Supervisor*



August 14th 2025, 7:17 PM (MDT -06:00)



56.2287964, -120.8333464

A handwritten signature in black ink, appearing to be 'JA' followed by a flourish.



PUMP SHACK

Brothers HDD Inc.  
2002 23 Avenue,  
Wainwright, Alberta  
T9W 0B8  
780-214-7711

## Maintenance Request / Report Form

|                                                                                                                                    |                     |
|------------------------------------------------------------------------------------------------------------------------------------|---------------------|
| <b>Information</b>                                                                                                                 |                     |
| 537                                                                                                                                |                     |
| BHDD Shop                                                                                                                          |                     |
| Saturday, July 26th 2025, 5:37 PM (MDT -06:00)                                                                                     |                     |
| <b>Unit Information</b>                                                                                                            |                     |
| Date:                                                                                                                              | July 26, 2025       |
| Select Unit Number:                                                                                                                | 537                 |
| KMs:                                                                                                                               | 0000                |
| Hours:                                                                                                                             | 0000                |
| <b>Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.</b> |                     |
| <input checked="" type="checkbox"/> Maintenance Report - Field completion of maintenance.                                          |                     |
| <b>Repairs Required</b>                                                                                                            |                     |
| Description of Repairs Required (attach photos):                                                                                   |                     |
| All heads and liners changed out to 7inch/ replace all clipper seals with new ones                                                 |                     |
| Serial/Part # if applicable:                                                                                                       | N/a                 |
| <b>Urgency of Repairs:</b>                                                                                                         |                     |
| <b>Select priority level of repairs:</b>                                                                                           |                     |
| <input checked="" type="checkbox"/> Low Priority - Repair at earliest convenience                                                  |                     |
| <b>Location of repairs being completed:</b>                                                                                        |                     |
| <b>Pick the location where the repairs were completed:</b>                                                                         |                     |
| <input checked="" type="checkbox"/> Ft St. John Shop                                                                               |                     |
| <b>Requested By:</b>                                                                                                               |                     |
| Worker Requesting Repairs:                                                                                                         | Kristopher Harrower |

## Signatures

**Jon Archibald**, *Supervisor*



 July 26th 2025, 5:37 PM (MDT -06:00)

 56.228798, -120.8333788

**Kristopher Harrower**, *Laborer*



 July 26th 2025, 5:38 PM (MDT -06:00)

 56.228798, -120.8333788



PUMP FM500

Brothers HDD Inc  
2002 23 Avenue  
Wainwright, Alberta  
T9W 0B8  
780-214-7711

## Maintenance Request / Report Form

### Information

 537

 BHDD Shop

 Saturday, July 26th 2025, 5:37 PM [MDT -06:00]

### Unit Information

Date:  July 26, 2025

Select Unit Number:  537

KMs:  0000

Hours:  0000

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

### Repairs Required

Description of Repairs Required (attach photos):

 All heads and liners changed out to 7inch/ replace all clipper seals with new ones

Serial/Part # if applicable:  N/a

### Urgency of Repairs:

Select priority level of repairs:

☒ Low Priority - Repair at earliest convenience

### Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Ft St. John Shop

Requested by:

---

Worker Requesting Repairs:



Kristopher Harrower

## Signatures

Jon Archibald, *Supervisor*



July 26th 2025, 5:37 PM (MDT -06:00)



56.228798, -120.8333788

A handwritten signature in black ink, appearing to be 'JA', located to the right of the supervisor's name.



COMBO UNIT

Brothers HDD Inc  
2002 23 Avenue  
Wainwright, Alberta  
T9W 0B8  
780-214-7711

## Maintenance Request / Report Form

### Information



537



HWN JJ Days - 2503-004



Friday, March 28th 2025, 4:56 PM [MDT -06:00]

### Unit Information

Date:



March 28, 2025

Select Unit Number:



537

KMs:



0

Hours:



10373

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.



Maintenance Report - Field completion of maintenance.

### Repairs Required

Description of Repairs Required (attach photos):



Hour meter

Serial/Part # if applicable:



No Response



Generator

### Urgency of Repairs:

Select priority level of repairs:

☒ Low Priority - Repair at earliest convenience

### Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Field Repaired

### Requested By:

Worker Requesting Repairs:

 JJ Piche

### Signatures

JJ Piche, *Supervisor*

 March 28th 2025, 4:56 PM [MDT -06:00]

 54.4459073, -117.4793221





ENGINEER STACKS

Brothers HDD Inc  
2002 23 Avenue  
Wainwright, Alberta  
T9W 0B8  
780-214-7711

## Maintenance Request / Report Form

### Information

 537

w/o #000142

 HWN JJ Days - 2503-004

 Wednesday, March 19th 2025, 5:17 PM (MDT -06:00)

### Unit Information

Date:  March 19, 2025

Select Unit Number:  537

KMs: # 0

Hours: # 10373

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

### Repairs Required

Description of Repairs Required (attach photos):

 None

ENTERED  
MAR 20 2025

Serial/Part # if applicable:  None

### Urgency of Repairs:

Select priority level of repairs:

☒ Low Priority - Repair at earliest convenience

### Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Field Repaired

Requested By:

Worker Requesting Repairs:



JJ Piche

Signatures

JJ Piche, *Supervisor*




March 19th 2025, 5:17 PM (MDT -06:00)



54.4457769, -117.4795876

A stylized, handwritten signature in black ink, likely belonging to JJ Piche.

MUD PUMP



## MAINTENANCE REQUEST FORM

UNIT# 537

HRS/KM

CRITICAL

WONOWON

### DESCRIPTION OF REPAIRS REQUIRED

WELDING BEAR TRAP INLET

TRAVIS \$160/HR

BUCKSHOT

WITH IN THE HOUR

WELDING

JAN 29 @ 4:00PM

REQUESTED BY:

DATE: