



H02-211
SEP

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

SEMI (CUBE VAN)

Maintenance Request / Report Form

Information

 404

 BHDD Shop

 Wednesday, July 15th 2026, 3:50 PM [MDT -06:00]

Unit Information

Date:  July 13, 2026

Select Unit Number:  404

KMs:  91289

Hours:  19918

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

 Cvip

- replace rear wheel seal
- repaired light

Serial/Part # if applicable:  No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Completed

Location of repairs being completed:

Pick the location where the repairs were completed:



FULL SERVICE COMPLETED? Check the box if Oil /Filters & inspection are performed.

Requested By:

Worker Requesting Repairs:



Luke Jacobsen

Request submitted to:

After signing Request Form be sure to: Request Signature or Approval Tab and select either from the Given Names below: Ron Jerome, Jason Brown, Jon Archibald.

Signatures

Luke Jacobsen, *Mechanic*



July 15th 2026, 3:50 PM (MDT -06:00)



52.8514571, -110.8421063



Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

SEMI (CUBE VAN)

Maintenance Request / Report Form

Information

404

Hamm CB 2604-008

Thursday, May 7th 2026, 4:10 PM [MDT -06:00]

Unit Information

Date: May 7, 2026

Select Unit Number: 404

KMs: # 91090

Hours: # 19825

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

Full service
-oil change
-oil filter
-fuel filter
-fuel water separator
-coolant filter

Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Standard Priority - Required within 3-5 days

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Field Repaired

☒ FULL SERVICE COMPLETED? Check the box if Oil /Filters & inspection are performed.

Requested By:


Worker Requesting Repairs:


 Luke Watchel

Request submitted to:

After signing Request Form be sure to: Request Signature or Approval Tab and select either from the Given Names below: Ron Jerome, Jason Brown, Jon Archibald.

Additional Photos





Original

Luke Watchel, *No title*

 May 7th 2026, 4:10 PM (MDT -06:00)

 52.1862571, -106.6155094



Revised on May 7th 2026, 4:16 PM (MDT -06:00)

Current View

Luke Watchel, *No title*

 May 7th 2026, 4:16 PM (MDT -06:00)

 52.1856196, -106.6152355





220 CUBE VAN

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

404

BHDD Shop

Tuesday, November 4th 2025, 9:38 AM [MST -07:00]

Unit Information

Date: November 4, 2025

Select Unit Number: 404

KMs: # 0

Hours: # 0

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Request - Request shop assistance in facilitating repairs.

Repairs Required

Description of Repairs Required (attach photos):

RELAY WED NOV. 12

Tuneup Hotsy in cube van

Serial/Part # if applicable: Na

Urgency of Repairs:

Select priority level of repairs:

☒ Standard Priority - Required within 3-5 days

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Wainwright Shop

Requested By:

Worker Requesting Repairs:



Myles MacMillan

Signatures

Myles MacMillan, *Supervisor*



November 4th 2025, 9:38 AM (MST -07:00)



53.2752482, -112.3879799

A handwritten signature in black ink, appearing to be 'M. MacMillan', written over a light blue grid background.

STOR



80515

ETL LISTED

CONFORMS TO
UL STD 1778

CERTIFIED TO

CAN/CSA C22.10.98-92

Contains components from one or more of the following countries: China, Italy, Japan and Thailand

CUST PART NO:

965B



MFG PART NO:

1.110-565.0

SERIAL NO:

11105650-100092

PSI: 3000

GPM: 3.0

Nozzle Size: 03.5

Model: 965B

Firing Rate: 2.07GPH

Max Temp: 225°F

248,500 BTU in

1.75-90-A

Fuel psi: 140

#1-#2 Fuel Oil



COPY



SEMI (CUBE VAN)

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information



404



BHDD Shop



Wednesday, September 24th 2025, 9:35 AM (MDT -06:00)

Unit Information

Date:



September 24, 2025

Select Unit Number:



404

KMs:



90041

Hours:



18409.6

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.



Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):



Replaced right rear shocks

Serial/Part # if applicable:



No Response

Urgency of Repairs:

Select priority level of repairs:



Completed

Location of repairs being completed:

Pick the location where the repairs were completed:



Wainwright Shop

Requested by:

Worker Requesting Repairs:



Chase Atkinson

Signatures

Chase Atkinson, *Laborer*

A handwritten signature in black ink, appearing to read 'Chase', written over a horizontal line.

September 24th 2025, 9:35 AM (MDT -06:00)



52.8511906, -110.8421193



SEMI (CUBE VAN)

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

404

w/o # 000151

BHDD Shop

Wednesday, April 16th 2025, 9:23 AM [MDT -06:00]

ENTERED
Apr 16/25

Unit Information

Date: April 3, 2025

Select Unit Number: 404

KMs: # 89058

Hours: # 18173

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

- Checkover and service
- serviced
- replaced door latch
- replaced batteries
- replaced middle diff lock switch
- replaced diff lock switch wire harness

CULP MEASUREMENTS

Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Standard Priority - Required within 3-5 days

Location of repairs being completed:

Requested By:

Worker Requesting Repairs:



Luke Jacobsen

Signatures

Luke Jacobsen, *Mechanic*



April 16th 2025, 9:23 AM (MDT -06:00)



52.8513216, -110.8421347

A handwritten signature in black ink, appearing to be 'LJ' or similar, located to the right of the timestamp and coordinates.



SEMI (CUBE VAN)

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

 404

 BHDD Shop

 Thursday, April 17th 2025, 8:44 AM (MDT -06:00)

Unit Information

Date:  February 20, 2025

Select Unit Number:  404

KMs:  88230

Hours:  17501

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

 Replaced alternator

Serial/Part # if applicable:  No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Standard Priority - Required within 3-5 days

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Field Repaired

Requested by:

Worker Requesting Repairs:



Myles MacMillan

Signatures

Ron Jerome, *Supervisor*



April 17th 2025, 8:44 AM [MDT -06:00]



52.8516373, -110.8418375

A handwritten signature in black ink, consisting of a stylized, cursive letter 'A' with a horizontal line through it.



Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request Form

Information

404
 Midwest Ipl 2501 004
 Sunday, January 26th 2025, 10:07 AM (MST -07:00)

Unit Information

Date: January 26, 2025
Select Unit Number: 404
KMs: 88766
Hours: 17587

Repairs Required

Description of Repairs Required (attach photos):

Service required and completed oil and fuel filters

Serial/Part # if applicable: Na

Urgency of Repairs:

Select priority level of repairs:

☒ Low Priority - Repair at earliest convenience

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Field Repaired

Requested By:

Worker Requesting Repairs: Myles MacMillan

Signatures

Myles MacMillan, Supervisor

January 26th 2025, 10:07 AM (MST -07:00)

55.4949226, -110.8573512



SEMI-CUB VAN

MAINTENANCE REQUEST FORM

UNIT# 404

HRS/KM

2007 KENWORTH TR994991

CNIP

DESCRIPTION OF REPAIRS REQUIRED

- DRIVERS INNER DOOR HANDLE

WONT OPEN DOOR

- WINDOW RUBBER (VAN BODY)

- 4x BATTERIES

- 4x CABLES 2 RED / 2 BLACK

JASON

- 8x STUD NUTS

1.84

DAN

EK LLOYD \$ 74.19

\$ 321.05

- CLUTCH SPRING

\$ 19.67

- CNIP

- SERVICE

REQUESTED BY:

DATE:

KENT

\$132.39
1 INDICATOR
2 JUMPERS
\$47.47

#404
12200

TH/31

1931
1932
1933
1934

1935
1936

PAACAR

DOOR
LATCH

R56-1028
50339AA
REV A


\$ 273.20

404

Good
HSTAL

Good

Good



SEMI
MILES

MAINTENANCE REQUEST FORM

UNIT# 404

HRS/KM

DESCRIPTION OF REPAIRS REQUIRED

ALTERNATOR

PRESTOLITE 8LHP 2170VF 160 AMP

BtB - \$595.00

\$621.22 OEM ✓
EDM KENWORTH - \$304.19 TIER * DAN EDMONTON BRANCH
LLOYD

INTO SERVICE TRUCK #624

NEED WD

REQUESTED BY: MILES

DATE: FEB 19/25

Prestolite



Leece-Neville



MODEL 8LHP2170VF

AMPS160

VOLTS12

DATE201244

SALES NO. 110-555PH0

B

MANUFACTURED IN USA BY PRESTOLITE ELECTRIC, INC.



MAINTENANCE WORK ORDER

N^o 1936UNIT #: 404ENGINE HOURS: NIA

MILEAGE: _____

WORK LOCATION: _____

WORK REQUESTED: RON JORDER DATE: APRIL 17/2024COMPLETED DATE: APRIL 17/2024

JOB #: _____

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: _____

TECH COMMENTS: _____

LABOUR DESCRIPTION: _____ HOURS

CHANGE PRESSURE WASHER PUMPFROM RIGHT HAND DRIVE TO LEFT HAND DRIVE 2

LABOUR TOTAL _____

PARTS & MATERIALS

PRESSURE WASHER ONLINE INV#PWC16256 P.O. # 00574 QUANTITY PRICE AMOUNT\$877.97

PARTS & MATERIALS TOTAL _____

WORK AUTHORIZED BY: RON J WORK COMPLETED BY: RON JUNIT RETURNED TO SERVICE: APRIL 17/2024 OVERALL CONDITION OF UNIT: GOOD

ADDITIONAL COMMENTS: _____



MAINTENANCE WORK ORDER

N^o 1592

UNIT #: 404
ENGINE HOURS: 16464.6
MILEAGE: 86735
WORK LOCATION:
WORK REQUESTED:

ORDER DATE: mar/25/24
COMPLETED DATE: apr/11/24
JOB #:

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: oil change air dryer fixed
put in new input shaft seal / joints

TECH COMMENTS:

LABOUR DESCRIPTION: ~~1~~ ~~seal~~ ~~seal~~ fixed air dryer
input shaft seal / joint full service greased

HOURS

7.5

LABOUR TOTAL

PARTS & MATERIALS

	P.O. #	QUANTITY	PRICE	AMOUNT
input shaft seal k&h worth				7813.44
winter valve bto b				39.72
coolant filter napa	-	1		13.90
fuel filters shephard	-	2		
oil filter shephard	-	1		

PARTS & MATERIALS TOTAL

WORK AUTHORIZED BY: cory

WORK COMPLETED BY: chase / cory

UNIT RETURNED TO SERVICE: yes

OVERALL CONDITION OF UNIT: good

ADDITIONAL COMMENTS: