



DZIL

H02-237
SEP

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

121

Red Deer - Shop

Monday, May 4th 2026, 12:09 PM (MDT -06:00)

Unit Information

Date: May 4, 2026

Select Unit Number: 121

KMs: # 0

Hours: # 4030

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

Completed full service on Vermeer 40x55 Unit # 121 @ 4030hrs

- New engine oil filter installed
- New engine oil installed
- New fuel filter installed
- New fuel/water separator filter installed
- New Crankcase filter installed
- 2x new small hydraulic filters installed
- 2x new large hydraulic filters installed
- Entire rig washed and greased

Serial/Part # if applicable:

- LF16243 Oil Filter
- DZ128543 Deisel/Water
- DZ115390 Deisel
- HF6704 Hydraulic x2
- HF6550 Hydraulic x2
- DZ105796 Crankcase

Urgency of Repairs:

Select priority level or repairs:



Completed

Location of repairs being completed:

Pick the location where the repairs were completed:



Red Deer Shop



FULL SERVICE COMPLETED? Check the box if Oil /Filters & inspection are performed.

Requested By:

Worker Requesting Repairs:



Chad Short

Request submitted to:

After signing Request Form be sure to: Request Signature or Approval Tab and select either from the Given Names below: Ron Jerome, Jason Brown, Jon Archibald.

Signatures

Chad Short, *Supervisor*



May 4th 2026, 12:09 PM (MDT -06:00)



52.2901238, -113.8654876