



P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit #: A312 Date: July 11/25 Machine Hours: 14055 Technician Signature:

Description

Parts & Description

Center Axle LH Side Front side
Brake Caliper swapped out for Rebuilt one.
Bled Brakes + Run + Test Functions
Properly.

X35-1
Aug



P.O. Box 650 Grimshaw, AB. T0H 1W0

Daily Report

Note: Date, Signature, Unit Numbers and Equipment Hours are all MANDATORY

Date:

May 22/25

Location:

Shop

Signature:

[Handwritten Signature]

A312.

Air Compressor install. Trans Water pump
Tube + Seal Replace. Install Exhaust.
manifold + Turbo Bell housing Plug.



P.O. Box 650 Grimshaw, AB. T0H 1W0

Daily Report

Note: Date, Signature, Unit Numbers and Equipment Hours are all MANDATORY

Date: ~~May 16/20~~ May 16/20 Location: Shop

Signature:

Ken Forsythe

A312 14052 Change master switch For lockout.
Install Rear Suspension
Service Rear Diff + Hubs.



P.O. Box 650 Grimshaw, AB. T0H 1W0

Daily Report

Note: Date, Signature, Unit Numbers and Equipment Hours are all MANDATORY

Date: May 15/25 Location: Shop.

Signature: Tim Forsyth

A312 14052. Trans oil + Filters Drop Box oil + Filters
Front Diff oil Hydraulic Filters Breather Filters.
Cabin air Filters Clean out HVAC.
Center Diff oil



P.O. Box 650 Grimshaw, AB. T0H 1W0

Daily Report

Note: Date, Signature, Unit Numbers and Equipment Hours are all MANDATORY

Date: May 14/25 Location: Shop Signature: [Signature]

A362 14058 Remove Air Compressor.
Service.



P.O. Box 650 Grimshaw, AB. T0H 1W0

Daily Report

Note: Date, Signature, Unit Numbers and Equipment Hours are all MANDATORY

Date: May 6 / 25 Location: Sharp Signature: Tim Frey the.

A312.

Tear down to Remove Walking Beams
Remove LH Beam change Bushings
Install LH Beam.



P.O. Box 650, Grimshaw, Alberta T0H 1W0 | P: 780.332.2054

Removed Both Rear Tires to put on A309 Put 2 work tires off A309 on the Rear.

Rock Truck 730E/A30F

Complete Service Done.

Unit #A312 Date: April 23/25 Hours: 14052 Signature: Tim Forsythe	
Service Remaining	13923
Engine Oil Level	good
Coolant Level	Tube at pump looking low
Hyd Oil Level	good
Trans Oil Level	good
Drop Box Oil Level	good
Washer Fluid	works half
Wiper	works good
Mirrors	LH convex Broken good
Check For Leaks	
Tail Gate Pins	NA
Exhaust Condition	Cracked manifold
Grease all Nipples	✓
Cab Clean	
Exterior Washed	
Tire Pressures	good.
Tire Condition	like new
2-Way Radio Functions	yes
Antenna	yes
Lights Working	yes
Stock:	
Wiper	✓
Mirrors	✓
Check For Leaks	✓
Tail Gate Pins	✓
Exhaust Condition	✓
Grease all Nipples	✓
Cab Clean	✓

Comments:

All glass good Doors + Opening windows Function properly.
Seat Functions as it should

Seat Belt good
A/C Blows cold. / heater works.
* Operators manual damaged
Back up alarm works.

A312. 14052 hrs.

✓ Front Axle LH Rotor 15.5 mm pads good
✓ Reservoirs Full RH Rotor 15.5 mm. pads good

No leaks.

→ Shocks leaking

→ Suspension Springs & thru bolts loose.
Tires excellent condition almost new

✓ Center Axle LH Rotor 14.6 mm pads good
✓ Reservoir Full RH Rotor 14.5 mm pads good

LH wheel seal leaking.

Tires Almost new

✓ Rear Axle LH Rotor 14.5 mm pads good
✓ Reservoir Full RH Rotor 14.6 mm pads good

No leaks.

✓ Walking beams need bushings. all 4 springs need replaced.
Tires Almost new. - all changed.

✓ Main Bm Springs need Replaced. changed

✓ Receiver dryer needs service oil coming out Compressor? Replaced.

✓ Trans water pump top tube into pump leaking Repaired.

✓ LH hood latch leaking Replaced

Front door shock needs replacing.

✓ Exhaust manifold cracked — Replaced.

✓ Dash vents Broken. Round Nozzles broken. Replaced.

✓ Instrument Cluster light bulbs changed

✓ Main Light switch changed

✓ Instrument cluster dimmer switch. changed.

✓ NO Beacon light or harness From Cab to light. Missing

✓ LH convex mirror broken Replaced.



P.O. Box 650 Grimshaw, AB-T0H 1W0

Unit #: A312

Date:

Machine Hours: 14052

Technician Signature: Travis Foy

Description		Parts & Description
Oil Filters	B76 x2.	
Oil Filter	B7685 x1	
Fastener cluster bulbs	x10	VOE9166327.
Fuel Filter	BF46233 x1	
"	BF1359-SP x1	
TRANS Breather	PAS700 x1	
Trans Filters	BT8851-MPG x2	
Air dryer cartridge	x1	VOE20546795
Air Filter	Duker x1	RS3870
Drop box Filter	PAS700 x1	
Fuel tank breather	Filter PA5311 x2 +	Hydraulic tank breather.
Hydraulic oil Filter	VOE	17438620

COMMENTS: Cabin Filters PA 4991 + PA536

Trans oil ATF 50L

Turbo gasket set 20781146

Axle oil 75w-90 28L

Turbo nuts 1543499

Drop box oil 85L 75w-90

Turbo oil supply gskt 22206133

Keyed master switch 7N-0718 (CAT)

Turbo oil RTN gskt 420643

4 new rear susp blocks

Exhaust brake mount screws

Rear DAF + Manof oil 75-90 34L

984739 x2
spacers 846339 x2

Hood latch VOE 1117688

washers 60113882 x2

Compressor Seal 471708

Clamp 11056190

Water pump tube 11121586

Bolts 904739 x3

Water pump seal 11030312

nuts 940950 x3

Exhaust manifold 11129421

Clamp 303033054

Manifold bolts 984760 x12

Air Shutter 3176435 x2

spacers 1546517 x12

Convex Mirror 17500365

gaskets 21482601 x6

Bm Rubber Damper 16262026 x2

plug bell housing 15134976

Bacon light harness 11116243

Turbo spacers 478344

Bacon light - grotte 78033



Notes

P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit #: Servicing Date: Mar 7/25 Machine Hours: Technician Signature: [Signature]

Description	Parts & Description
A-307 Both front shocks blown out	lock out temp out Put in
need Refilled / Replaced / Reseal	to A-307 A-304 A-312
A-304 RH side shock Blown out	
needs Refilled or Replace / Reseal	
A-302 RH tailgate bar fell off Jarden	on site to fix
All tires look good, not seeing any leaks	of any kind
A-312 Due for service ^{hrs 13949} ^{Due at 13924}	seeing any leaks of any kind
tires all look good, windows are good	

NUMBER: 220

WORK ORDER

COMPANY New Gen.

DARCY KURIGA 780-835-8090 dkuriga@yahoo.com

DATE	UNIT	SERIAL	HOURS/KILOMETERS
Sept 4/24			

UNIT/SERIAL	JOB DESCRIPTION	HOURS
	Loan.	

A 302	- checked out Broken Exhaust. - Fixed leaks on tail gate Rem. - checked out leaking Injector cylinder	2
C-106.	- checked out A/C system *note needs new suction hose. Fitting is Rusted and weint seal.	3
A-312	Removed Broken Exhaust for Bowl Heater.	2
G102	checked out transmission leaks Steel cooler line cracked ordered parts.	4
	Travel to Red Earth and Home	4
JOB TOTAL		15

DATE COMPLETED:

COMPLETED BY:

Darcy Kuriga



Aug 22/24

[illegible]



P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit#

A-312

Machine Hours

13 229 hrs.

Apr. 27/24

Description	Tech	Parts & Description	Price
- Eng service.			\$
- Eng Air filters replaced			\$
- Cab Filters replaced			\$
- Trans, hyd, coolant good			\$
- Replaced cab light bulb.			\$
- Wipers work, lights work			\$
- A/C good			\$
			\$
* Needs right rear signal light.			\$
			\$
			\$
			\$



P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit#

A-310


Machine Hours

6361

Dec 6/93

Erben

[illegible]



A-312

12 504 hrs

Sept. 29/23

[illegible]

2G PARTS AND EQUIPMENT LTD

BOX 290 5714 - 51 ST
GRIMSHAW, AB T0H 1W0
(780) 332-2240
GST 721743292 RT0001

INVOICE: 1-16065

Date: September 27, 2023

Ship To

NEW GEN PROJECTS
BOX 650
GRIMSHAW, AB, CANADA T0H 1W0

Bill to:

NEW GEN PROJECTS
BOX 650
GRIMSHAW, AB, CANADA T0H 1W0

(780) 332-2054
admin@newgenprojects.ca

(780) 332-2054
admin@newgenprojects.ca

CUST ID	PO:			SALES PERSON	SHIP VIA	
1213	A312			ADMIN	cwc	
VENDOR PLU	DESCRIPTION		QTY	UNIT PRICE	Unit Discount	AMOUNT
	VOLVO A30D BOX HEATER COUPLING		1	2,000.00		2,000.00
Posted						
Thank you for choosing 2G Parts and Equipment Ltd.						


Regular Price: \$2000.00
Paid by On Account \$2,100.00

SUBTOTAL	2,000.00
GST	100.00
TOTAL	\$2,100.00

TERMS: NET 15th OF MONTH FOLLOWING INVOICE DATE.
INTEREST WILL BE CHARGED ON ALL OVERDUE ACCOUNTS.
SIGNATURE ON INVOICE INDEMNIFIES PARTY BILLED-TO.

RECEIVED BY
PRINT NAME _____

SIGNATURE X _____



Unit#

A-312

Machine Hours

12 433

Sept. 13/23

[illegible]

P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit#

A30D A3/2

Machine Hours

12032 hrs next service 12247

VIN: A30DV15018

June 20/23

Description

Tech

Parts & Description

Price

Service Fuel system; contamination		(1) Seat air control switch	\$(Value)
found in suction lines and filters;		(2) A3/2 decals	\$
RtR fuel filters and back flush		(2) NewGen Projects decals	\$
all lines and clean fuel drain back		(1) 20lb extinguisher	\$
passage and float ball. Exhaust system			\$
and box heater; OK. Tail gate and			\$
cables; OK; tail gate; swing arms			\$
and cables Home made and no longer			\$
factory * Air systems; OK minor			\$
look down. Brake systems; Front			\$
Diff; Pads 50% disc; visual inspection; OK		Calipers; visual inspection; OK	\$
Hard lines; OK. Flex lines; cracked and rotten, new lines ordered. Operation; OK			\$

Diff lock system; Bad lines, adapter plates and diaphragms ripped; parts robbed from A311 to repair unit, system function
Test; OK Diff Drive #1 Brake system; Pads 50% Disc; visual inspection; OK Calipers; visual inspection; OK Hand

Hydraulic brake systems, lines degraded. New lines ordered. Operation; no pressure present at Calipers; Master cylinder inspected and tested for pressure and brake pot tested for operation; OK Lines pulled and found blockage in lines due to improper flex lines causing degraded rubber into hard lines. System flush and re-test; OK Flex lines ordered system flush required when flex lines are LTR. Diff drive #2 Brake system; Pads SD 26, disc; ~~visual~~ visual inspection; OK Calipers; visual inspection; OK Hard lines; visual inspection; OK. Flex lines; dry rott + cracked; New lines ordered. System operation; OK. Master cylinders + reservoirs + pots; visual inspection; OK operation; OK Codant system; visual inspection; OK no leaks found system full. Cab, steps, railing; visual inspection; OK lights; head lamps Hi and Low beam; OK Markers; Front not operational; wiring repaired, socket plugs repaired re-test; OK Rear not operational; damaged rear harness, test lights not operational; re-build rear harness from chassis to light box, repair wiring in frame, take lights from A3M for A312, repair wiring for pot sensors; re-test light systems; OK all driver warnings and shut down messages no longer present. repair light box and cover plates. HVAC; not operational; remove system; repair heater box, replace cables, replace HVAC control panel, repair mounts for fan motor, clean entire HVAC system, re-test and re-test; OK repair seat functions; OK * no seat sensor; by passed by previous owner. Side windows not sliding; cleaned tracks and removed debris; re-test; OK Backup Alarm + light; OK Horn and wiper function; OK LH RR split rim and RH R split rim wheel locks installed; missing. All cab + operator controls working, stocked + fire extinguisher installed. Box safety Arm present and passed visual inspection. Unit operation tested in yard; no faults found.

P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit#

A300 A312
VIN: A30DY15018

Machine Hours

12032 hrs next service 12247

June 20/23
Parts & Description

Price

Description	Tech	Parts & Description	Price
Check over of systems and operation and repair deficiencies as necessary. Check all fluids; Engine oil; OK Hydraulic; OK Trans: Serviced; change oil + Filters, trans fluid extremely dirty no cuttings found in Filters. Drop box serviced: fluid extremely dirty, no cuttings found on magnets. Front diff; OK: new oils in diff + hubs. Drive #1; OK: new oils in diff + hubs. Drive #2; OK: new		(1) 79220 Ram X 20" wiper blades (2) BT 8851 MPG Trans Filters (1) BF1559 SP fuel filter (1) BF46233 fuel filter (1) PA5310 Outer cabin Air (1) 11121365 LH convex mirror - (1) 11196683 HVAC control panel (1) 9920-11 50Amp ANSI/AMI stop (1) 11113563 HVAC control cable (1) 11113564 HVAC control cable (1) 11113561 HVAC control cable (2) VDE 4789993 Split rim lock	\$ \$ \$ \$ \$ \$(Value) \$(Value) \$ Sure \$(Value) \$ 11 \$ 11 \$ 11

oils in diff + hubs. drive line; All U-joints greased and pass visual inspection. Inter axle shaft damaged at weld due to Roll over, wish bone also damaged due to Roll over + shaft contact. Tires OK; new pressures set to 60 PSI. Frame rails straight and OK.



Unit #: A312 Date: 2016 Machine Hours: 1501 Technician Signature: [Signature]

Technician Signature: _____

[illegible]