

Maintenance Record

114-2
SEP

Company Name: _____ Date: 1026 Mar 23

Company Address: _____

Repair Made By: Onur

Scheduled Maintenance: Yes ☐ No ☒ (Please Circle)

as this form is not valid without a vehicle inspection, on 1/1/21, unless done by a licensed mechanic or repair shop.
This is according to your maintenance schedule with your vehicle inspection. Please do not use this form for a vehicle inspection.

Alt # or Vin # or Plate #: TH8

Domestic Reading: _____ Mile OR Mile Reading: _____ Mile

Description of work performed:

- Brakes fixed on trailer. Release stuck shoes.
Assist Sam Run out winch line to end of
Trailer

Complete Mar 23 Onur = 1.0

Signature: Onur

Signature of Repair Person

(If more than one repair person please print name, sign, and date on bottom of maintenance record)

DRIVER'S DAILY VEHICLE INSPECTION REPORT

Carrier North of 55 Oilfield Hauling
 Address 500 Birch Road NE
 City Slave Lake, AB T0G 2A0

Omer Mac Donald
 Driver (please print)

2025 Oct 28
 Inspection Date

10975
 Odometer Reading (miles/kms)

TH8
 Trailer - License Plate or Unit #

Slave Lake yard 2
 Location of Inspection

10:15
 Inspection Time

014
 Power Unit # or License Plate #

TH8
 Trailer - License Plate or Unit #

TRUCK/TRACTOR

Check any **DEFECTIVE ITEMS** and give details under remarks (as per Schedule 1)

- | | | | | |
|---|---|---|---|---|
| ☐ Engine | ☐ Air Compressor | ☐ Drive Line | ☐ Exhaust System | ☐ Tail - Dash Lights |
| ☐ Oil Pressure | ☐ Warning Signal, Low Pressure | ☐ Radiator | ☐ Front Axle | ☐ Turn Indicators |
| ☐ Battery | ☐ or Low Vacuum Signal | ☐ Steering | ☐ Suspension, Springs, Air Bag & Controlling Attachments | ☐ Clearance Lights |
| ☐ Clutch | ☐ Air Brake Adjustments & Connections | ☐ Steering Wheel | ☐ Rear End | ☐ Reflectors |
| ☐ Generator/Alternator | ☐ Brake Accessories | ☐ Mirrors (Adjustment & Condition) | ☐ Tires | ☐ Reflective Triangles |
| ☐ Fuel System | ☐ Air Lines | ☐ Tachograph | ☐ Wheels, Rims, Fasteners | ☐ Fire Extinguisher |
| ☐ Air Horn | ☐ Brakes | ☐ Windshield & Windows | ☐ Fifth Wheel | ☐ Spare Seat Beam |
| ☐ Electric Horn | ☐ Brake Booster | ☐ Windshield Wiper, Washer | ☐ Towing & Coupling Devices | ☐ Emergency Equipment |
| ☐ Defroster & Heaters | ☐ Hydraulic Brake Fluid | ☐ Transmission | ☐ Tire Chains | ☐ Load Covering |
| ☐ Brake Air Pressure | ☒ Brake Failure Warning Light | ☐ Driver's Seat Belt & Seat Security | ☐ Head - Stop Lights | ☐ Load Security |
| | ☐ Parking Brake | | | |

TRAILERS

- ☐ Coupling (King) Pins
☐ Parking Brake
☐ Air Brake Adjustments & Connections
☐ Tires
☐ Wheels, Rims, Fasteners
☐ Suspension, Springs, Air Bags
☐ Towing & Coupling Devices
☐ Hitch/Landing Gear
☐ All Lights & Reflectors
☐ Doors/Roof
☐ Reefer/Fuel System
☐ Load Security
☐ Load Covering
☒ Other: 7 pin door cover

☒ Pre-Trip Inspection ☐ Post-Trip Inspection of Vehicle is Satisfactory

Remarks Tractor ABS lamp on, TH8 light cord socket door brake

Driver's Signature Omer

Date 2025 Oct 28

☐ NO DEFECTS FOUND

☐ ABOVE DEFECTS CORRECTED

☒ ABOVE DEFECTS NEED NOT BE CORRECTED FOR SAFE OPERATION OF EQUIPMENT

Supervisor/Mechanics Signature _____

Date _____

Maintenance Record

Company Name: N155 Date: 2025 June 02

Company Address: _____

Repairs Made By: Oleh
Print Name

Scheduled Maintenance: Yes or No (Please Circle)

If no, use this form for all work performed on vehicles, equipment, etc. If yes, ensure the scheduled maintenance on your commercial vehicle is according to your maintenance schedule within your Alberta Transportation Manual and/or manufacturer's specifications.

Unit # or Vin # or Plate #: OF1 TH8

Odometer Reading: _____ kms OR Hub Reading: 7643 hours
(If Applicable) (If Applicable)

Description of work performed:

- ✓ - Gbd hands.
- ✓ - 1 2.5 Amber Lamp, 1 oval amber changed.
- ✓ - TEE on service line C Rear Axle Frame Rail
→ #3 Relay & → Rear Gbd hands.

Complete June 2

Oleh = 3.0

Omer = 1.0

Signature: _____

Signature Of Repair Person

(If more than one repair person please print name, sign, and date on bottom of maintenance record)

Maintenance Record

Company Name: N55 Date: 2026 Jan 21

Company Address: _____

Repair Made By: Owner/Oleh

Scheduled Maintenance: Yes or No (Please Circle)

Use this form first with guidance on vehicle, equipment, etc. If you cannot do the maintenance on your own, please take it to a qualified mechanic. This form is not a substitute for a professional inspection.

Unit # or Vin # or Plate #: T48

Odometer Reading: _____ Mile OR Mile Reading: 10690 Mile

Description of work performed:

- ✓ - #2R Set tires skidded off.
- Twine Connector door missing
- ✓ - Rt midship marker out - tied into tail lamps.
- Flags Ratty.
- ✓ - Swing outs L.R. Rust through, L.F.
- Tool box door latch front.
- ✓ - upper shock Bolt axle #1 $3\frac{1}{2} \times 3\frac{1}{2} \times .188 \times 4\frac{1}{2}$ #250 Used.
- ✓ - Auto slack #3L ✓ #2L ✓
- ✓ - X member / Shock Bolt. Rusted through #1, #2, #3. Replace.
- Sg. Tubing, upper bag mounts.
- 2 Air Bags #1 All 6 Air Bags: top bolts.
- ✓ - Shocks Axle #2
- Brakes adjusted to 25 mm.

Owner = 3.0 hrs

Oleh = 74.5 hrs

Completed 2026 Jan 30

Signature: _____
Signature Of Repair Person

(If more than one repair person please print name, sign, and date on bottom of maintenance record)

SCHAFER MECHANICAL SERVICES LTD.

BOX 827 #600 CARIBOU TRAIL SW

SLAVE LAKE, AB T0G2A0

Phone: 780-849-2449 Fax:

**INVOICE
62047**

30-Jan-2026 9:35 am

Page 1 of 1

P.O. # TH08

Ship Via:

Salesman:

Sold to:

NORTH OF 55

BOX 618

SLAVE LAKE, AB T0G 2A0

Ship to:

Part Number	Description	Ordered	Shipped	B/O	List \$	Unit \$	Extended
FTG-1201	RH SWING OUT ARM	1	1		120.04	85.36	85.36
	Goods and Services Tax				4.27	4.27	4.27

Stocked Items	Non- Stocked	Cores	Enviro Charges	Misc Charges	Other Charges	GST	PST	Payments	Document Total
35.36	0.00	0.00	0.00	0.00	0.00	4.27	0.00	0.00	89.63

TERMS 2% NET 30
GST# 89205 0956 RT0001

APPROVED BY:

We are now accepting E-Transfers,
send to
schafer-parts@schafermech.com

OMER

HEAVY EQUIPMENT REPAIR LTD.

OPEN ORDER
001-915932

Box 2343, 404 Balsam Road N.E.
Slave Lake, Alberta T0G 2A0
Phone (780) 849-3768 FAX (780) 849-4453
www.heavyequipmentrepair.ca

BILL TO				SHIP TO				PG 1 OF 2 OPEN ORDER	
AAA				AAA					
NORTH OF 55 OILFIELD HAULING LTD. BOX 618 SLAVE LAKE, AB T0G 2A0 CANADA				NORTH OF 55 OILFIELD HAULING LTD. BOX 618 SLAVE LAKE, AB T0G 2A0 CANADA					
HEAVY EQUIPMENT REPAIR LTD.				GST Number 12155-3671 RT				REFERENCE NUMBER 001-915932	
MTH. DAY YR.	WRITER	ORDER NO.	CUSTOMER P.O. NUMBER	TERMS	SHIP VIA				
1/21/26	JER	1/21/26 915932	UNIT# TH08	NET 30	CUSTOMER PICKUP KND 1				
QUANTITY ORDERED	QUANTITY SHIPPED	BACK ORDERED	PART NUMBER AND DESCRIPTION		CODE	PRICE (LIST & SELL)		NET AMOUNT	
123	123		STL ST3 1/2 X3 1/2 X1/4 SQUARE TUBING		TG	3.090	2.570 IN	316.11	
3.00	3.00		LAB STEEL CUTTING CHARGE		TG	7.500	5.000 EA	15.00	
			ORDERED BY OMER						
24	24		STL ALFL 1/4 X 2 ALUMINUM FLAT BAR		TG	0.450	0.320 IN	7.68	
1.00	1.00		LAB STEEL CUTTING CHARGE		TG	7.500	5.000 EA	5.00	
2	2		SSS 1020 2-1/2" DOUBLE LIGHT BOX		TG FB R9		33.140 EA	66.28	
1	1		SSS 1202 LH SWING OUT LIGHT ARM		TG FB R9		83.380 EA	83.38	
2	2		MID 400-20216 SLACK ADJUSTER 1.5 10SPL		TG F4D2		185.000 EA	370.00	
			- DROP AXLE						
2	2		ARM VX8050 AIR BAG		TG WARM		196.090 EA	392.18	
2	2		BEN 236056 3/8" NPT ANCHOR TEE		TG F6A2		36.740 EA	73.48	
3	3		P-T MHT1000 LH AIRBAG PLATE		TG		222.270 EA	666.81	
3	3		P-T MHT1002 RH AIRBAG PLATE		TG		222.700 EA	668.10	
1	1		FRT FREIGHT CHARGES		TG		50.000 EA	50.00	
			TAKEN BY OMER						
2	2		BEN 236056 3/8" NPT ANCHOR TEE		TG F6A2		36.740 EA	73.48	
4	4		ARM VX8050 AIR BAG		TG WARM		196.090 EA	784.36	
10	10		FAS CS8SC-075-250 3/4 X 2-1/2 GR8 PL NC BOLT		TG GBSC		2.942 EA	29.42	
10	10		FAS NN8SC-075 3/4 GR8 NC NYLON LK NUT		TG GBSC		0.944 EA	9.44	
10	10		WAL 11-T052 5X3/64X7/8 ZIPCUT		TG SW8		7.290 EA	72.90	
			- STEEL/SS						
1	1		RUS V2164838 150Z SPRAY BRIGHT RED		TG F18B4		19.080 EA	19.08	
1	1		*** EHF-AB-405 AEROSOL PAINT ECO FEE		G		0.400 EA	0.40	
1	1		POL 11-721 7 WAY FEMALE SOCKET		TG NSL2		18.600 EA	18.60	
1	1		RRR DW-1/8-BK-48 48 IN PC 1/8 IN DUAL WALL		TG 2WOOD		14.930 EA	14.93	
1	1		RRR DW-3/16-BK-48 48 IN PC 3/16 IN DUAL WALL		TG 2WOOD		15.000 EA	15.00	
1	1		ULT UF-4941 16.10Z MAPP SUB CYLINDER		TG FF R2		15.180 EA	15.18	
1	1		*** EHC-AB-306-L 18.92 LITRE OIL E.H.C.		TG		1.140 EA	1.14	
1	1		*** EHC-AB-306-C 18.92 L CONTAINER E.H.C.		TG		2.270 EA	2.27	
1	1		EUC E-886 DUST SHIELD		TG F1 C2		58.690 EA	58.69	
			- SUB# RA607						
2	2		GBR 85014 FLEETLINE COMMERCIAL SHOCK		TG FBKS		103.990 EA	207.98	
4	4		ANC 4989314 FLAG, ORANGE LOAD		TG	9.200	6.517 EA	26.07	
			- 18" X 18"						
1	1		TWD SKD1316-U SKID INDICATOR UNI-MOUNT		TG WW1		41.430 EA	41.43	
					GOODS & SERVICES TAX (CODE G)	\$205.22			
Warranties - all returns and exchanges for warranty are subject to manufacturer inspection and decision.				X		GOODS RECEIVED BY		SUB-TOTAL TAX	
Terms are net 30 days upon receipt of invoice. Past due interest charged at 2% per month (24% per annum) on all over-due accounts. Positively no goods accepted for credit without prior authorization and invoice number. A minimum of 10% handling charge on goods returned when supplied as ordered. Cores or Merchandise are not returnable after 90 days.						TIME PREPARED		TOTAL	
								Continued	

ERRORS AND OMISSIONS EXPECTED

OPEN ORDER
001-915932

[illegible]

ERRORS AND OMISSIONS EXCEPTED

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

TH08 Pass w/o Copy.

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Trailer										kg									
Vehicle Information																			
VIN	2	L	9	H	S	C	D	3	1	V	1	0	7	8	2	6	6		
Unit Number TH08			Year 1997			Make Arrow			Model Tri Hi			Odometer 10,690							
Registered Owner's Name North of 55															Plate Number 6KB397				
Address 500 Birch Road, PO Box 618										Postal Code T0G 2A0					Phone Number (780) 849-4333				

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		LEFT	FRONT	RIGHT		
100 psi	100 psi	420.16 mm	Drums/Rotors	419.74 mm	100 psi	100 psi
13 mm	13 mm	19 mm	Linings/Pads	19 mm	12 mm	11 mm
		32 mm	Push Rod Travel	30 mm		
100 psi	100 psi	420.62 mm	Drums/Rotors	419.75 mm	0 psi	0 psi
11 mm	11 mm	19 mm	Linings/Pads	17 mm	0 mm	0 mm
		30 mm	Push Rod Travel	36 mm		
100 psi	100 psi	420.16 mm	Drums/Rotors	420.75 mm	100 psi	100 psi
10 mm	8 mm	420.16 mm	Linings/Pads	420.75 mm	10 mm	10 mm
		50 mm	Push Rod Travel	35 mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		

Park Brake Lining Left NA mm Right NA mm Trans NA mm
Wheel Torque Checked ☐ Inner NA ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train								
Component	P	F	NA	Component	P	F	NA	
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓	

NOTES:

APPENDIX "A"								
Component	P	F	NA	Component	P	F	NA	
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓	
A.2. Compressed Natural Gas (CNG) Fuel System			✓					

NOTES:

Section 2 - Suspension								
Component	P	F	NA	Component	P	F	NA	
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓			
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓	
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓			
2.4. Spring & Spring Attachment			✓					

NOTES:

2.7 upper shock bracket broken axle #2. (All 3 axles rebuilt, air bags and shocks replaced.)

Defects corrected WO TH8 2026 Jan 21

Section 3H - Hydraulic Brakes								
Component	P	F	NA	Component	P	F	NA	
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			✓	
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			✓	
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓	
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓	
3H.9. Air-Boosted Trailer Brake System			✓					

NOTES:

Section 3A - Air Brakes								
Component	P	F	NA	Component	P	F	NA	
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓			
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓	
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓	
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓			
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓	
3A.14. Brake Chamber	✓			3A.23. Brake Performance			✓	
3A.15. Drum Brake System Components	✓							

NOTES:

3A.16 auto slack #3L defective

Defects corrected

Section 4 - Steering								
Component	P	F	NA	Component	P	F	NA	
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓	
4.4. Kingpin			✓					

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

DEFECTS:

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door	✓			8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)	✓		

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

9.1/9.2 tires #2R flat spotted and deflated

Defects Corrected

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler	✓		

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8609347) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/01/29	A7768	18667	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/01/29

Customer Signature

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Trailer										kg									
Vehicle Information																			
VIN	2	L	9	H	S	C	D	3	1	V	1	0	7	8	2	6	6		
Unit Number TH08			Year 1997			Make Arrow			Model Tri Hi			Odometer 10,690							
Registered Owner's Name North of 55															Plate Number 6KB397				
Address 500 Birch Road, PO Box 618										Postal Code T0G 2A0					Phone Number (780) 849-4333				

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		<u>LEFT</u>	<u>FRONT</u>	<u>RIGHT</u>		
100 psi	100 psi	420.16 mm	Drums/Rotors	419.74 mm	100 psi	100 psi
13 mm	13 mm	19 mm	Linings/Pads	19 mm	12 mm	11 mm
		32 mm	Push Rod Travel	30 mm		
100 psi	100 psi	420.62 mm	Drums/Rotors	419.75 mm	0 psi	0 psi
11 mm	11 mm	19 mm	Linings/Pads	17 mm	0 mm	0 mm
		30 mm	Push Rod Travel	36 mm		
100 psi	100 psi	420.16 mm	Drums/Rotors	420.75 mm	100 psi	100 psi
10 mm	8 mm	420.16 mm	Linings/Pads	420.75 mm	10 mm	10 mm
		50 mm	Push Rod Travel	35 mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
Park Brake Lining Left <u>NA</u> mm Right <u>NA</u> mm Trans <u>NA</u> mm Wheel Torque Checked ☐ Inner <u>NA</u> ft lbs Outer <u>500</u> ft lbs						

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly		✓	
2.4. Spring & Spring Attachment			✓				

NOTES:

2.7 upper shock bracket broken axle #2

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System		✓	
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓		
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance			✓
3A.15. Drum Brake System Components	✓						

NOTES:

3A.16 auto slack #3L defective

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin			✓				

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.1. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.2. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door	✓			8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)	✓		

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth		✓		9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition		✓		9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

9.1/9.2 tires #2R flat spotted and deflated

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler	✓		
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **FAILED** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/01/21	A7768	18667	<i>McDermid Macdonald</i>

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/01/21

Customer Signature