


R1419
LEAD
SEP



DATE Apr 23/26

KM 54721 HRS _____

UNIT NUMBER SB160A

COMPLAINT: Broken fender bracket

CAUSE: _____


CORRECTION: weld center axle fender bracket

Stocked Parts:

Repairs done by [Signature]

Date: April 23/2026

Authorized by: [Signature]



DATE April 11th

KM 47632 HRS _____

UNIT NUMBER SB160A


COMPLAINT: fire has a bulge

CAUSE: _____

CORRECTION: replaced 1LHS after fire

Stocked Parts:

1x tire



Retorque Notice Tag # 2513

Date: April 12 WO# _____

Unit #: SB160A Odometer: 47632

Issued By: Conce


Initial Completed	(X) Install	Axle	Axle	(X) Install	Initial Completed
	X	1	1		
		2	2		
		3	3		
		4	4		
		5	5		

Comments: Retorque to footings

Retorque Completed

Date: _____ Odometer: _____
Name: _____ Signature: _____

Note: Retorque must be completed within 150 km or at the first available outside facility.
Initial each wheel for which retorque was done.

DATE April 3rdKM 46 133

HRS _____

UNIT NUMBER SB160COMPLAINT: Service - Light issues

CAUSE: _____

CORRECTION: - 4 sets of Brake shoes and Drums 2nd
axle both sides, 4th axle both sides - 4 new tires
22.5 2nd axle - Greased - fixed wiring back of "Lead"
- 2 new lights back of lead up top

Stocked Parts:

Brake shoes x4 (4707)
Drums x4 PF3600
LED2500-12RP x2
PT6020 x2

Repairs done by MorganAuthorized by: [Signature]

Retorque Notice

Tag # **2575**Date: April 6th

WO# _____

Unit #: SB160Odometer: 46 133Issued By: Morgan

Initial Completed	(X) Install	Axle	Axle	(X) Install	Initial Completed
☒	☒	1	1	☒	☒
		2	2		
		3	3		
☒	☒	4	4	☒	☒
		5	5		

Comments: _____

Valley Printers # 26620

Retorque Completed

Date: _____	Odometer: _____
Name: _____	Signature: _____

Note: Retorque must be completed within 150 km or at the first available outside facility. Initial each wheel for which retorque was done.



Maintenance Details

[illegible]

**DRIVER'S ASSET INSPECTION REPORT**March 31, 2026
07:30 am MDT

Driver	Kyle Simonson ID: 65	Carrier	Drive Logistics Inc
Location	R360 Laglace AB		
Inspection Duration	03m 46s		
Asset	SB160A	License Plate Number	6KZ702
Defects	Type	Status	Resolved by
18 - Lamps/Reflectors			
Driver rear outside red marker not working			
Required lamp does not function as intended	Minor	Open	
Other	Minor	Open	
Top rear red markers out			

Driver Signature

I declare that this asset has been inspected in accordance with the applicable requirements of Schedule 1 and/or jurisdiction legislation.

03/31/2026 MDT

X Forge Supply LTD.

INVOICE

Airport Industrial Park, 16 Cessna Rd - Po Box 6353 Peace River, Alberta, T8S1S3
Phone: 780-219-7730
Email: jake@xforgesupplyltd.ca
Web: xforgesupplyltd.ca
GST/HST #: 783261431RT001

INV-20260505-001

Date: 2026-05-05 08:11:00

Bill To

Customer: Drive Logistics
Invoice Date: 2026-05-05 08:11:00
Due Date: 2026-06-04
Status: Pending

Invoice Details

Payment Terms: Net 30
PO Number: SB 160
Pickup Person: Peter

Description	Qty	Unit Price	Total
Angle 2 - 1/4: 1 piece x 10.0 ft (includes 1 cuts)	10.00	\$5.65	\$56.50

Subtotal:	\$56.50
Tax (5.0%):	\$2.83
Total:	\$59.33

Thank you for your business!
Payment is due within 30 days. Please contact us at 780-219-7730 if you have any questions.

This invoice was generated on 2026-05-05 08:11:00 | All sales are subject to our standard terms and conditions

X Forge Supply LTD.

INVOICE

Airport Industrial Park, 16 Cessna Rd - Po Box 6353 Peace River, Alberta, T8S1S3
Phone: 780-219-7730
Email: jake@xforgesupplyltd.ca
Web: xforgesupplyltd.ca
GST/HST #: 783261431RT001

INV-20260504-004

Date: 2026-05-04 12:40:00

Bill To

Customer: Drive Logistics
Invoice Date: 2026-05-04 12:40:00
Due Date: 2026-06-03
Status: Pending

Invoice Details

Payment Terms: Net 30
PO Number: Shop
Pickup Person: Kathy

Description	Qty	Unit Price	Total
Angle 2 - 1/4: 1 piece x 10.0 ft (includes 1 cuts)	10.00	\$5.65	\$56.50

Subtotal:	\$56.50
Tax (5.0%):	\$2.83
Total:	\$59.33

SR100.



Retorque Notice

Date: MAY 5, 2026 Tag # 2565
Unit #: SR100A Odometer: 55,607km
Issued By: JOHN, CONER, MORGAN

Initial Completed	(X) Install	Axle	Axle	(X) Install	Initial Completed
☒	☒	1	1	☒	
☒	☒	2	2	☒	
	☒	3	3	☒	
		4	4		
		5	5		

Comments:

Retorque Completed

Date:	Odometer:
Name:	Signature:

Note: Retorque must be completed within 150 km or at the first available outside facility. Initial each wheel for which retorque was done.

Thank you for your business!
in 30 days. Please contact us at 780-219-7730 if you have any questions.

ed on 2026-05-04 12:40:00 | All sales are subject to our standard terms and conditions



Retorque Notice

Date: MAY 5, 2026 Tag # 2566
Unit #: SR100B Odometer: 55,607km
Issued By: JOHN, CONER, MORGAN

Initial Completed	(X) Install	Axle	Axle	(X) Install	Initial Completed
☒	☒	1	1	☒	
☒	☒	2	2	☒	
		3	3		
		4	4		
		5	5		

Comments:

Valley Printers # 26620

Retorque Completed	Odometer:	Signature:
Date:		
Name:		

Note: Retorque must be completed within 150 km or at the first available outside facility. Initial each wheel for which retorque was done.