



250 HRS Service Inspection Form

Hrs: 10,743

Date: June 15, 2016 Unit # 519

Odometer: 603,239

Multipoint Inspection									
Front Left			Front Right			Under Hood			
Pass	Fail		Pass	Fail		Pass	Fail		
☒		Headlight	☒		Headlight				Horn
☒		Signal Light	☒		Signal Light	☒			Antifreeze Level
☒		Hazard Light	☒		Hazard Light	☒			Drive Belt
☒		Windshield			Windshield	☒			Radiator Condition
		Cracked			Cracked	PSI	Duration		Coolant Pressure test
		Chipped	☒		Chipped				
		Washer System			Washer System	Under Vehicle			
		Wiper			Wiper	☒			Suspension Comp
<u>9mm</u>		Tire Tread	<u>9mm</u>		Tire Tread	☒			Exhaust System
<u>100PSI</u>		Tire Pressure			Tire Pressure	☒			Shocks
		PSI			PSI	☒			Fuel Leaks
Rear Left			Rear Right			☒			Oil Leaks
☒		Brake Light		☒	Brake Light	☒			Engine Oil Replaced
☒		Signal Light		☒	Signal Light	☒			Oil Filter Replaced
☒		Hazard Light		☒	Hazard Light	☒			Replace Air Filter
		Back-Up Light		☒	Back-Up Light	☒			Torque all Wheels
<u>19mm</u>		Tire Tread	<u>20mm</u>		Tire Tread				
<u>100PSI</u>		Tire Pressure			Tire Pressure				
100PSI	100PSI	PSI			<u>100</u> PSI				
Fluids			Steering Components						
Checked Added			Pass Fail			<i>Rept</i> <i>Torqued all wheels</i>			
Front Differential	☒ Y/N Y/N	☒	Left Ball Joints/King Pins						
Rear Differential	☒ Y/N Y/N	☒	Right Ball Joints/King Pins						
Transfer Case	☒ Y/N Y/N	☒	Left Tie Rods Ends						
Transmissions	☒ Y/N Y/N	☒	Right Tie Rods Ends						
Power Steering	☒ Y/N Y/N	☒	Center Link						
Brake Fluid	☒ Y/N Y/N	☒	Pitman Arm						
Brakes	Pass Fail	☒	Steering Arm						
Left Front	☒	☒	Stabilizer Shock						
Left Rear	☒	☒	Sway Bars						
Right Front	☒	☒	Wheel Alignment						
Right Rear	☒								
Emergency Brake									
Brake Cables									
Mechanic's Signature						Comments: <i>Replaced Air filter</i> <i>Greased</i> <i>fixed lights</i> <i>Replaced L front spring</i>			
Next Service Due:									

Reviewed By



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1429	Customer: JAYMAR	Start Date: June 15 /2026
Unit #: 579	Location: Slave Lake	End Date: June 16 /2026
Grouch List Checked:		Grouch List Checked with Dave:

Driver's side leaf spring **B81-6013-004** ✓
change wiper blades **BOS-EV022 x2** ✓

- raised and supported front end on 2 Jack stands
removed left side steer wheel. ~~removed~~ removed shock
~~removed~~ Cut U-bolts. removed shackles and spring.
installed new spring and oil Shims. installed. old shackles.
fastened and torqued U-bolts to 500 ft/lbs. fastened shackle
bolts and front mount bolts. Greased front end of truck
and checked fluids. Changed out wipers fixed issue w/
~~1 of the stop~~ 1 of the ~~stop~~ exit lights ~~by~~ trimming back and
hard wiring connection. Replaced one of the Exit lights terminal
was corroded off

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours **3.25**

Assigned Mechanic:

Entered By:

**YOSHI
SHAY**

Signature: _____

Qty	Parts Requested/Parts Nos. /Parts Details
1	Spring
2	wipers
1	Amber Exit light.

I certify that the above unit was repaired under my supervision

Name: _____

Sign: _____



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # <u>1419</u>	Customer: JAYMAR	Start Date: <u>June 23/2026</u>
Unit #: <u>519</u>	Location: Slave Lake	End Date: <u>June 29 2026</u>
Grouch List Checked:		Grouch List Checked with Dave:
<u>Reseal the turbo.</u>		
<u>removed All air intake piping. tested CAC for leaks and found none. replaced started disassembling turbo to find any signs of leaking anywhere within components till the turbo had to eventually come off. Turbo checked internals but found no obvious signs of leakage. removed off EGR to replace turbo to manifold bolts. cleared all turbo + Exhaust mating surfaces. mounted turbo w/ new gasket gasket and torqued new bolts to manufacture spec. installed all EGR and all other components w/ the required O-rings and gaskets. and torqued each to manufacture spec. in cleared and installed all intake piping. filled engine w/ Coolant. ran truck and took for test drive.</u>		
<u>When installing USED parts, please specify.</u>		
<u>back. All after treatment harnesses had to be removed including for inspection by date Dave. Helped Dave w/ modifications. installed Harness back in. truck working properly.</u>		
EXCESSIVE TIME DESCRIPTION		

CVIP Hours _____ Repair Hours 12

Assigned Mechanic: Yoshi SHAY
Entered By:

Signature: [Signature]

Qty	Parts Requested/Parts Nos. /Parts Details
1	197645APE Clamp / 197645IDE Clamp
1	496641 Gasket / 2106210PE Gasket

I certify that the above unit was repaired under my supervision

Name:	Sign: <u>[Signature]</u>
-------	--------------------------



NO WC .372
In system as 1371
can be added

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # <u>1372/1371</u>	Customer: JAYMAR	Start Date: <u>June 1</u> /2026
Unit #: <u>519</u>	Location: Slave Lake	End Date: <u>June 5</u> /26
Grouch List Checked:		Grouch List Checked with Dave:

CVIP

- Removed all wheels w/ coltin.
- Removed and replaced ~~suspension~~ all Air bags. had to cut out all original Air lines / fittings because ~~they~~ all were siezed installed new air bags and use a series of 1/2" fittings to connect the whole system along w/ 10 ft of 1/2" Air hose.
- Removed rear leveling valve and replaced w/ new one and used a 45° fitting (1/2") to replace one of the broken quick connects. replaced a rod end on leveling valve w/ old one to keep ride height the same.
- Diagnosed Lighting issues by tracing wiring and found corroded terminals in rear weather pack connectors. ~~fixed~~ fixed w/ new wire and terminals. ~~big fix~~ fixed other broken or corroded wires w/ the same harness w/ soldering. ~~equipment~~
- installed power When installing USED parts, please specify.
- Steer reservoir Cap.
- fixed Air leak on top of transmission w/ quick connect. was a red spaghetti line with a pin hole

EXCESSIVE TIME DESCRIPTION

- Shock nut was siezed ~~A2~~ heated up w/ torch 'out threads still got torn out. replaced shock w/ new one and fastened all bolts.

CVIP Hours _____ Repair Hours 26

Flip →

Assigned Mechanic:
Entered By:

YOSHI SHAY

Signature: _____

Qty	Parts Requested/Parts Nos. /Parts Details
8 ✓	Airbags
3 ✓	weather pack pins + 3 seals
1 ✓	1/2" 45° brass
6 ✓	1/2" T fittings brass
1 ✓	Shock
2 ✓	90° brass fitting 1/2"
1	straight 1/4" fitting
	a series of bolts or washers nuts.
	Stack adjuster.
	quick connect coupler.

I certify that the above unit was repaired under my supervision

Name: _____

Sign: _____

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # <u>1159</u>	Customer: JAYMAR	Start Date: <u>April 10/2026</u>
Unit #: <u>519</u>	Location: Slave Lake	End Date: <u>Apr 11/26</u>
Grouch List Checked:		Grouch List Checked with Dave:

✓ 500 Hour Service

Dropped oil, changed Fuel & oil filters
checked fluids, greased, adjusted brakes
checked tire pressures, torqued lines

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 3

Assigned Mechanic: COLT
Entered By: SHAY

Signature: CG

Qty	Parts Requested/Parts Nos. /Parts Details
✓ <u>6</u>	<u>Dust Shield 156.1004</u>

I certify that the above unit was repaired under my supervision

Name: _____	Sign: <u>[Signature]</u>
-------------	--------------------------

☐ Check if you put on the retorque tags after working on tires



500 Hrs Service Inspection Form

Hrs: 10,422 472
Date: April 10, 2016 Unit # 519 Odometer: 589,251

Multipoint Inspection									
Front Left			Front Right			Under Hood			
Pass	Fail		Pass	Fail		Pass	Fail		
/		Headlight	/		Headlight	/		Horn	
/		Signal Light	/		Signal Light	/		Antifreeze Level	
/		Hazard Light	/		Hazard Light	/		Drive Belt	
/		Windshield	/		Windshield	/		Radiator Condition	
/		Cracked	/		Cracked	PSI	Duration	Coolant Pressure test	
/		Chipped	/		Chipped				
/		Washer System	/		Washer System	Under Vehicle			
/		Wiper	/		Wiper	/		Suspension Comp	
/		Tire Tread	/		Tire Tread	/		Exhaust System	
/		Tire Pressure	/		Tire Pressure	/		Shocks	
/		PSI	/		PSI	/		Fuel Leaks	
Rear Left			Rear Right			/		Oil Leaks	
/		Brake Light	/		Brake Light	X/N		Engine Oil Replaced	
/		Signal Light	/		Signal Light	X/N		Oil Filter Replaced	
/		Hazard Light	/		Hazard Light	X/N		Replace Air Filter	
/		Back-Up Light	/		Back-Up Light	Y/N		Torque all Wheels	
/		Tire Tread	/		Tire Tread	Fire Extinguisher (Check & Initial)			
/		Tire Pressure	/		Tire Pressure	Expiry Date:			
/		PSI	/		PSI	CVIP Exp Date:			
Fluids			Steering Components						
Checked Added			Pass Fail						
Front Differential	Y/X	X/N	Left Ball Joints/King Pins						
Rear Differential	Y/X	X/N	Right Ball Joints/King Pins						
Transfer Case	Y/X	X/N	Left Tie Rods Ends						
Transmissions	Y/X	X/N	Right Tie Rods Ends						
Power Steering	Y/X	X/N	Center Link						
Brake Fluid	Y/X	X/N	Pitman Arm						
Brakes			Steering Arm						
Left Front	/		Stabilizer Shock						
Left Rear	/		Sway Bars						
Right Front	/		Wheel Alignment						
Right Rear	/		Comments: 						
Emergency Brake	/								
Brake Cables									
Mechanic's Signature									
Next Service Due:									
Reviewed By:									



250 HRS Service Inspection Form

JAY-012

Hrs: _____
Date: April 2nd 1976 Unit # 519 Odometer: 589 323

Multipoint Inspection

Front Left			Front Right			Under Hood		
Pass	Fail		Pass	Fail		Pass	Fail	
✓		Headlight	✓		Headlight	✓		Horn
✓		Signal Light	✓		Signal Light	✓		Hood Light
✓		Hazard Light	✓		Hazard Light	✓		Drive Belt
✓		Windshield	✓		Windshield	✓		Radiator Condition
✓		Cracked	✓		Cracked	✓		Hose Clamps
✓		Chipped	✓		Chipped	✓		Heater Hose
✓		Washer System	✓		Washer System	Under Vehicle		
✓		Wiper	✓		Wiper		✗	Suspension Comp
✓		Tire Tread	✓		Tire Tread	✓		Exhaust System
✓		Tire Pressure	✓		Tire Pressure	✓		Shocks
✓		PSI	✓		PSI	✓		Fuel Leaks
Rear Left			Rear Right					Oil Leaks
✓		Brake Light	✓		Brake Light	Y/N		Engine Oil Replaced
✓		Signal Light		✗	Signal Light	Y/N		Oil Filter Replaced
✓		Hazard Light	✓		Hazard Light	Y/N		Replace Air Filter
✓		Back-Up Light	✓		Back-Up Light	Y/N		Torque all Wheels
✓		Tire Tread	✓		Tire Tread			
✓		Tire Pressure	✓		Tire Pressure			
✓		PSI	✓		PSI			
Fluids				Steering Components				
Checked Added				Pass Fail				
Front Differential	Y/N	Y/N	Left Ball Joints/King Pins					
Rear Differential	Y/N	Y/N	Right Ball Joints/King Pins					
Transfer Case	Y/N	Y/N	Left Tie Rods Ends					
Transmissions	Y/N	Y/N	Right Tie Rods Ends					
Power Steering	Y/N	Y/N	Center Link					
Brake Fluid	Y/N	Y/N	Pitman Arm					
Brakes			Pass Fail			Steering Arm		
Left Front		✗				Stabilizer Shock		
Left Rear	✓					Sway Bars		
Right Front	✓					Wheel Alignment		
Right Rear		✗						
Emergency Brake	✓							
Brake Cables								

Mechanic's Signature

Next Service Due:

Reviewed By

- Comments:
- All Air bags have lots of dry rot
 - Trailer output right signal stays on
 - Axle 2L and Axle 3R brake pots out
 - Fifth wheel ~~mount~~ slides back and forth
 - Headlight fault

- power steer reservoir needs cap
- Exhaust Leak behind turbo
- Coolant leaking from banjo hose below EGR pipe.
- 12 lower motor busted

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # <u>1091</u>	Customer: JAYMAR	Start Date: <u>Mar 18 /2026</u>
Unit #: <u>519</u>	Location: Slave Lake	End Date: <u>Mar 18 2026</u>
Grouch List Checked:		Grouch List Checked with Dave:

Helping Eddie with light issue

- replaced light and connector because terminals were corroded
- cleaned up connections to other lights. Lights working
- traced back wiring for one of the marker lights not receiving power. found broken wire. repaired wire and installed heat shrink tube to secure connections. secured harnesses w/ electrical tape where required.

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 1.25

Assigned Mechanic: Yoshi

Signature: 

Entered By: Annette

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name:	Sign:
-------	-------



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1003	Customer: JAYMAR	Start Date: 6/30/2026
Unit #: 519	Location: Slave Lake	End Date: March 2 2026
		Requested by: Dave
Grouch List Checked:		Grouch List Checked with Dave:
- removed headlight cover		
- removed bulb and inspected		
- bulb was broken		
- installed new bulb and tested light.		
- light working		
- installed headlight cover.		
When installing USED parts, please specify.		

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 0.25

Assigned Mechanic: yoshi
Entered By: Katie

Signature: 

Qty	Parts Requested/Parts Nos. /Parts Details
1	bulb
3	Bolts
3	washers

I certify that the above unit was repaired under my supervision

Name:	Sign:
-------	-------



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 3484	Customer: JAYMAR	Start Date: Feb 17/2026
Unit #: 519	Location: Slave Lake	End Date: Feb 17/26
Equip Desc: Semi	Year: 2017	Make: Kenworth
VIN: 1XKZDP0X8HJ986776	Plate #: 0BJ980	Model: T880
KM: 570,075	Hours: 9,996	Requested by: Dave
Grouch List Checked: yes.		Grouch List Checked with Dave:
Reattach light cord Replace Both male ends from truck to trailer, Test trailer cord and it was good		
- Fab up bracket above head ache Rack and added a spring (New) to help hold the trailer cord		
When installing USED parts, please specify.		
Replace Deck with MDNC, Fab up Tie down to hold deck in place		

EXCESSIVE TIME DESCRIPTION


CVIP Hours _____ Repair Hours 910

Assigned Mechanic: Eddie
Entered By: Shay

Signature: 

Qty	Parts Requested/Parts Nos. /Parts Details
1	tender kit page 3992 (spring)
	did not find truck to trailer ends

I certify that the above unit was repaired under my supervision

Name: _____	Sign: 
-------------	--



Work Order Pending

Helping Eddie with full service	
- Greased truck and inspected	✓
- Torqued wheels	✓
checked and topped up tire pressures as required	✓

Signature: _____

I certify that the above unit was repaired under my supervision





1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 3261	Customer: JAYMAR	Start Date: Dec 12/2025
Unit #:519	Location: Slave Lake	End Date: Dec 12/25
Equip Desc: Semi	Year: 2017	Make: Kenworth
VIN:1XKZDP0X8HJ986776	Plate #: 0BJ980	Model: Tandem
KM: 566,601	Hours: 9866	Requested by: Dave
Grouch List Checked:		Grouch List Checked with Dave:
Full service		
- Replace Oil and Fuel Filters		
- P/S Back up light missing Replace with New		
- splice open wire Rear bumper of truck		
When installing USED parts, please specify.		
Installed new blower screw for fuel system		

EXCESSIVE TIME DESCRIPTION


CVIP Hours _____ Repair Hours 4

Assigned Mechanic: Eddie
Entered By: Shay

Signature: 

Qty	Parts Requested/Parts Nos. /Parts Details
✓ 1	filterkit 1714364
✓ 42L	5W40 bulk
✓ 1	Filter K371012
✓ 1	UNILW4232C

I certify that the above unit was repaired under my supervision

Name: _____	Sign: 
-------------	--



500 Hrs Service Inspection Form

JAY-013

Hrs: 9866

Date: Dec 22/25 Unit # 519

Odometer: 566601

Multipoint Inspection

Front Left			Front Right			Under Hood		
Pass	Fail		Pass	Fail		Pass	Fail	
/		Headlight	/		Headlight			Horn
/		Signal Light	/		Signal Light			Antifreeze Level
/		Hazard Light	/		Hazard Light			Drive Belt
/		Windshield	/		Windshield			Radiator Condition
		Cracked			Cracked	PSI	Duration	Coolant Pressure test
		Chipped			Chipped			
/		Washer System	/		Washer System	Under Vehicle		
/		Wiper	/		Wiper			Suspension Comp
/		Tire Tread	/		Tire Tread			Exhaust System
/		Tire Pressure	/		Tire Pressure			Shocks
/		PSI	/		PSI			Fuel Leaks
Rear Left			Rear Right					Oil Leaks
/		Brake Light	/		Brake Light	Y/N		Engine Oil Replaced
/		Signal Light	/		Signal Light	Y/N		Oil Filter Replaced
/		Hazard Light	/		Hazard Light	Y/N		Replace Air Filter
/		Back-Up Light	/		Back-Up Light	Y/N		Torque all Wheels
/		Tire Tread	/		Tire Tread	Fire Extinguisher (Check & Initial)		
/		Tire Pressure	/		Tire Pressure	Expiry Date:		
/		PSI	/		PSI	CVIP Exp Date:		
Fluids			Steering Components					
Checked Added			Pass Fail					
Front Differential	Y/N	Y/N	Left Ball Joints/King Pins					
Rear Differential	Y/N	Y/N	Right Ball Joints/King Pins					
Transfer Case	Y/N	Y/N	Left Tie Rods Ends					
Transmissions	Y/N	Y/N	Right Tie Rods Ends					
Power Steering	Y/N	Y/N	Center Link					
Brake Fluid	Y/N	Y/N	Pitman Arm					
Brakes			Steering Arm					
Pass Fail			Stabilizer Shock					
Left Front			Sway Bars					
Left Rear			Wheel Alignment					
Right Front								
Right Rear								
Emergency Brake								
Brake Cables								
Mechanic's Signature			Comments:					
Next Service Due:								
Reviewed By:								

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466


Work Order Pending

WO # 3168	Customer: JAYMAR	Start Date: Oct/30/2025
Unit #: 519	Location: Slave Lake	End Date: Oct 30/25
Equip Desc: Tandem KW	Year: 2017	Make: Kenworth
VIN: 1XKZDPOX8HJ986776	Plate #: 0BJ980	Model: Tandem
KM: 349392	Hours: 9781	Requested by: Eddie
Grouch List Checked: Yes		Grouch List Checked with Dave:
Fabrication code from truck to trailer for trailer's gate locks and suspension dump		
Used Quad Axle switch in dash		
When installing USED parts, please specify.		

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 2

Assigned Mechanic: Eddie
Entered By: Basil

Signature: 

Qty	Parts Requested/Parts Nos. /Parts Details
15'	4 wire blue 3603
2	male plug ISO 7way 15830

I certify that the above unit was repaired under my supervision

Name: _____	Sign: 
-------------	--

☐ Check if you put on the retorque tags after working on tires



75

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2811	Customer: JAYMAR	Start Date: July 21/2025
Unit #: 519	Location: Slave Lake	End Date: July 21/2025
Equip Desc: Tandem	Year: 2017	Make: Kenworth
VIN: 1XKZDP0X8HJ986776	Plate #: 0BJ980	Model: T 880
KM: 555,928	Hours: 9,695	Requested by: Dave

Grouch List Checked:

Grouch List Checked with Dave:

Change 7 wire electrical cord

Replaced entire cord and both ~~flange~~ ends

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 1

Assigned Mechanic: John
Entered By: Emmanuel

Signature:

☐

Check if you put on the retorque tags after working on tires



EP

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2710	Customer: JAYMAR	Start Date: June 19/2025
Unit #: 519	Location: Slave Lake	End Date:
Equip Desc: Tandem	Year: 2017	Make: Kenworth
VIN: 1XKZDP0X8HJ986776	Plate #: 0BJ980	Model: T 880
KM: 541,591	Hours: 9,493	Requested by: Dave
Grouch List Checked:		Grouch List Checked with Dave:
Fixing fender bracket		
<u>When installing USED parts, please specify.</u>		

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 40 hrs

Assigned Mechanic: John Rosaasen
Entered By: Emmanuel

Signature: _____

☐ Check if you put on the retorque tags after working on tires



702 OSP #:

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2621	Customer: JAYMAR	Start Date: May 20/2025
Unit #: 519	Location: Slave Lake	End Date: May 22/25
Equip Desc: Tandem	Year: 2017	Make: Kenworth
VIN: 1XKZDP0X8HJ986776	Plate #: 0BJ980	Model: T 880
KM: 540,046	Hours: 9,464	Requested by: Dave
Grouch List Checked: Yes		Grouch List Checked with Dave:
CVIP wheel off		
Manifold has crack & hydraulic pump not working good		
④ ✓ Changed Shocks on rear Axles		
⑦ + ③ ✓ Change d B Shoes and Joints on both Steer Axle		
✓ Replaced PTO		
When installing USED parts, please specify.		
Zac helped		

EXCESSIVE TIME DESCRIPTION

CVIP Hours 19 Repair Hours

Assigned Mechanic: John Rosaasen
Entered By: Emmanuel


Signature:



OSP #:

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2667	Customer: JAYMAR	Start Date: June 4 /2025
Unit #: 519	Location: Slave Lake	End Date: June 4/25
Equip Desc: Semi truck	Year: 2017	Make: KW
VIN: 1XKZDP0X8HJ986776	Plate #: OBJ980	Model:
KM: 540408	Hours: 9474	Requested by: Dave
Grouch List Checked: Yes		Grouch List Checked with Dave:
Fix antifreeze leak above transmission		
- Had to go threw the floor were the shifter is, the line from the Head to the Trans. cooler, Replace fitting on back of Head		
- Plug the Second line that goes to the DEF Tank		
- Pressure test anti Freeze and check for leaks and found another leak and it was the line coming out of the Second line for the transmission cooler. Just tighten clamp and fix leaks		
		

EXCESSIVE TIME DESCRIPTION

It's a Hard place to get at

CVIP Hours _____ Repair Hours 8

Assigned Mechanic: Eddie
Entered By: AnnetteSignature: 



OSP #:

Work Order Pending

- Drain Transmission Fluid
- Remove PTO shifter cover
- cleaned old gasket off of PTO and shift cover

When installing USED parts, please specify.

- ✓ - Put New Gasket
- Top up Transmission and put 20L

~~4~~ 4

[Handwritten signature]



33

OSP #:
3486, 3488
3487,

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2410	Customer: JAYMAR	Start Date: Feb 26/2025
Unit #: 519	Location: Slave Lake	End Date: feb 26/25
Equip Desc: Tandem	Year: 2017	Make:
VIN: 1XKZDP0X8HJ986776	Plate #: 0BJ980	Model: Kenworth
KM: 535,216	Hours: 9,369	Requested by: Dave
Grouch List Checked: Yes		Grouch List Checked with Dave:
✓ 500Hr Full service		
- Grease truck		
- Set brakes		
✓ Change oil / oil filter 42 (Ltrs) 3486		
When installing USED parts, please specify.		
✓ Change fuel filters 3488 1 bottle of ATF		
- Fill up coolant 3486		
✓ Change driver door seal R421165 PG 3423512		
✓		

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 7 hrs

Assigned Mechanic: TY

Signature: 

Entered By: Martine



OSP #:

3459

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2353	Customer: JAYMAR	Start Date: Feb 12/2025
Unit #: 519	Location: Slave Lake	End Date: Feb 12/25
Equip Desc: Tandem	Year: 2007	Make: Kenworth
VIN: 1XKZDP0X8HJ986776	Plate #: CGK-6689	Model:
KM: 532,602	Hours: 9,304	Requested by: Dave

Grouch List Checked: Yes

Grouch List Checked with Dave:

Check out starter

exiter wire was Broken ✓

When installing USED parts, please specify.**EXCESSIVE TIME DESCRIPTION**CVIP Hours _____ Repair Hours 1

Assigned Mechanic: Zack Signature: 
Entered By: Martine



JB

OSP #:

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2253	Customer: JAYMAR	Start Date: Jan 13 2025
Unit #: 519	Location: Slave Lake	End Date: Jan 13/25
Equip Desc: Tandem Kenworth	Year: 2017	Make: Tandem
VIN: 1XKZDP0X8HJ986776	Plate #: OBJ980	Model: Kenworth
KM: 527779	Hours: 9144	Requested by: Dave
Grouch List Checked: YES		Grouch List Checked with Dave:
Install new air charge cooler 2310286 G.W.K.W.		
Evac & Recharge AC system		
Set Brakes, Grease, Check Fluids.		
Top up Transmission.		
<u>When installing USED parts, please specify.</u>		
		
EXCESSIVE TIME DESCRIPTION		

CVIP Hours _____ Repair Hours _____

Assigned Mechanic: Dave
Entered By: Martine

Signature: 



March 6 JB

OSP #:

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2351	Customer: JAYMAR	Start Date: Feb 12/2025
Unit #: 519	Location: Slave Lake	End Date: Feb 12
Equip Desc: Tandem	Year: 2017	Make: Kenworth
VIN: 1XKZDP0X8HJ986776	Plate #: CGK-6689	Model:
KM: 532,601	Hours: 9,301	Requested by: Dave
Grouch List Checked: Yes		Grouch List Checked with Dave:
Changing Valve on air tank		
<u>When installing USED parts, please specify.</u>		

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 20 min

Assigned Mechanic: Trae Signature: Trae
Entered By: Martine