C40-24
NOV

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1510	Customer: JAYMAR	Start Date: June 30/2026
Unit #: 519	Location: Slave Lake	End Date: June 30/2026
Grouch List Checked:	Grouch List Checked with Dave:	

Swap fuel filters

- Swapped ~~both~~ fuel filters + ~~both~~ oil filters.

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 1

Assigned Mechanic: YOSHI
Entered By: SHAY

Signature: _____

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1438	Customer: JAYMAR	Start Date: June 15/2026
Unit #: 519	Location: Slave Lake	End Date: June 16/26
Grouch List Checked:	Grouch List Checked with Dave:	

250 hr service

Replaced Air filter - on YL WO 1429
Greased
fixed lights

9-11.3

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 4

Assigned Mechanic: MIKE
Entered By: SHAY

Signature:

Qty	Parts Requested/Parts Nos. /Parts Details
1	Air filter - 3 on Yoshi WO 1429 DNP1637453
1	~~Spring~~ front spring - 3 B81-6013-004

I certify that the above unit was repaired under my supervision

Name:	Sign:

☑ Check if you put on the retorque tags after working on tires

JAYMAR HAULING LTD.

250 HRS Service Inspection Form

Hrs: 10,743

Date: June 15 26 Unit # 519 Odometer: 603,239

Multipoint Inspection

Front Left			Front Right			Under Hood		
Pass	Fail		Pass	Fail		Pass	Fail	
✓		Headlight	✓		Headlight			Horn
✓		Signal Light	✓		Signal Light	✓		Antifreeze Level
✓		Hazard Light	✓		Hazard Light	✓		Drive Belt
✓		Windshield			Windshield	✓		Radiator Condition
		Cracked			Cracked	PSI	Duration	Coolant Pressure test
		Chipped	✓		Chipped			
		Washer System			Washer System	Under Vehicle		
		Wiper			Wiper	✓		Suspension Comp
9mm		Tire Tread	9mm		Tire Tread	✓		Exhaust System
100psi		Tire Pressure	"		Tire Pressure	✓		Shocks
		PSI			PSI	✓		Fuel Leaks
Rear Left			Rear Right			✓		Oil Leaks
✓		Brake Light		✓	Brake Light	Y/N		Engine Oil Replaced
✓		Signal Light		✓	Signal Light	Y/N		Oil Filter Replaced
✓		Hazard Light		✓	Hazard Light	Y/N		Replace Air Filter
•		Back-Up Light		✓	Back-Up Light	Y/N		Torque all Wheels
19mm		Tire Tread	20mm		Tire Tread			
100psi		Tire Pressure			Tire Pressure			
[redacted]	[redacted]	PSI			100 PSI			

Fluids

Checked	Added	
Front Differential	Y/N	Y/N
Rear Differential	Y/N	Y/N
Transfer Case	Y/N	Y/N
Transmissions	Y/N	Y/N
Power Steering	Y/N	Y/N
Brake Fluid	Y/N	Y/N

Brakes

	Pass	Fail
Left Front	✓	
Left Rear	✓	
Right Front	✓	
Right Rear	✓	
Emergency Brake	•	
Brake Cables		

Steering Components

Pass	Fail	
✓		Left Ball Joints/King Pins
✓		Right Ball Joints/King Pins
✓		Left Tie Rods Ends
✓		Right Tie Rods Ends
✓		Center Link
✓		Pitman Arm
✓		Steering Arm
✓		Stabilizer Shock
✓		Sway Bars
✓		Wheel Alignment

[redacted]
Torqued all Wheels

Mechanic's Signature

[redacted]

Next Service Due:

Comments:

Replaced Air filter
Greased
fixed lights
Replaced L front spring

Reviewed By

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1429	Customer: JAYMAR	Start Date: June 15 /2026
Unit #: 579	Location: Slave Lake	End Date: June 16 /2026
Grouch List Checked:	Grouch List Checked with Dave:	

Driver's side leaf spring B81-6013-004 ✓
change wiper blades BOS-EV022 x2 ✓

- raised and supported front end on 2 jack stands removed Left side Steer Wheel. ~~unbolted~~ removed Shock ~~bolts~~ Cut U-bolts. removed shackles and spring. installed new spring and old Shim. installed old shackles. fastened and torqued U-bolts to 500 ftlbs. fastened shackle bolts and front mount bolts. Greased front end of truck and checked fluids. Changed out wipers fixed issue w/ ~~the~~ 1 of the ~~stupid~~ Exit lights ~~busy~~ trimming back and hard wiring connections. replaced one of the Exit lights terminal was corroded off

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 3.25

Assigned Mechanic: YOSHI
Entered By: SHAY

Signature: _____

Qty	Parts Requested/Parts Nos. /Parts Details
1	Spring
2	wipers
1	Amber Exit light.

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1419	Customer: JAYMAR	Start Date: June 23/2026
Unit #: 519	Location: Slave Lake	End Date: June 29 2026
Grouch List Checked:	Grouch List Checked with Dave:	

Reseal the turbo.

- removed All air intake piping. tested CAC for leaks and found none. ~~replaced~~ started dissassembling turbo to find any signs of leaking anywhere within components till the turbo had to eventually come off. ~~Turbo~~ checked internals but found no obvious signs of leakage. ~~so~~ removed ~~egr~~ EGR to replace turbo to manifold bolts. cleaned all turbo + exhaust mating surfaces. mounted turbo w/ new ~~gasket~~ gasket and torqued new bolts to manufactue spec. installed ~~all~~ EGR and all other components w/ the required O-rings and gaskets. and torqued Each to manufacture spec. cleaned and installed all intake piping. filled engine w/ Coolant. ran truck and took for test drive. ~~when~~ when it was back. All after treatment harnesses had to be removed ~~including~~ for inspection by ~~Dave~~ Dave. Helped Dave w/ modifications. installed Harness back in. truck working property.

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 12

Assigned Mechanic: Yoshi
Entered By: Shay

Signature: _____

Qty	Parts Requested/Parts Nos. /Parts Details
1	1976452PE Clamp / 1976451PE Clamp
1	496641 Gasket / 2106210PE Gasket

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

4/3

NO WC .372
In system as 1371
Can be added

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # ~~1372~~ 1371	Customer: JAYMAR	Start Date: June 1 /2026
Unit #: 579	Location: Slave Lake	End Date: June 5 /26

Grouch List Checked:	Grouch List Checked with Dave:

CVIP
- Removed all wheels w/ coltin.
- Removed and replaced all Air bags. had to cut out all original Air lines / fittings because all were siezed installed new air bags and use a series of 1/2" fittings to connect the whole system along w/ 10 ft of 1/2" Air hose.
- Removed rear leveling valve and replaced w/ new one and used a 45° fitting (1/2") to replace one of the broken quick connects. replaced rod end on leveling valve w/ old one to keep ride height the same.
- Diagnosed Lighting issues by tracing wiring and found corroded terminals in rear weather pack connectors. fixed w/ new wire and terminals. fixed other broken or corroded wires up the same harness w/ soldering.
- installed power steer reservoir cap.
- fixed Air leak on top of transmission w/ quick connect. was a red spaghetti line with a pin hole

(DNC)

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

- Shock nut was siezed heated up w/ torch cut threads still got torn out. replaced Shock w/ new one and fastened all bolts.

Flip

CVIP Hours_____ **Repair Hours** 26

Assigned Mechanic: YCSHH
Entered By: SHAY

Signature:

Qty	Parts Requested/Parts Nos. /Parts Details	Qty	
8 ✓	Air bags	2 ✓	90° brass fitting 1/2"
3 ✓	weather pack pins + 3 seals	1	straight 1/2" fitting
1 ✓	1/2" 45° brass		a series of bolts washers nuts.
6 ✓	1/2" T fittings brass	1	Stack adjuster.
1 ✓	Shock	1	quick connect coupler.

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1371	Customer: JAYMAR	Start Date: June 1 /2026
Unit #: 519	Location: Slave Lake	End Date: June 2 /26
Grouch List Checked:	Grouch List Checked with Dave:	

CVIP
Pulled all tires to inspect & get measurements
I replaced x4 air bags passenger side

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 8

Assigned Mechanic: COLT
Entered By: SHAY

Signature: CG

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1357	Customer: JAYMAR	Start Date: May 27 /2026
Unit #: 519	Location: Slave Lake	End Date: May 27/26
Grouch List Checked:		Grouch List Checked with Dave:

Change A/C ~~pump~~ Compresson ✓

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

~~Took out~~ took off ac pump, fixed air lines, put new ac pump on, changed tensioner pully ✓

CVIP Hours_____ **Repair Hours** 4

Assigned Mechanic: TRAE
Entered By: SHAY

Signature: ~~O~~

Qty	Parts Requested/Parts Nos. /Parts Details
	A/C compressor - LF4313

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

B

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1293	Customer: JAYMAR	Start Date: May 12 /2026
Unit #: 519	Location: Slave Lake	End Date: May 12/26
Grouch List Checked:	Grouch List Checked with Dave:	

Installing brake pot

changed out brake pot & greased up track

adjusted brakes

① LCP 30 30 L ✓

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 1

Assigned Mechanic: Coltin **Signature:** CG
Entered By: Katie

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1274	Customer: JAYMAR	Start Date: May 6 /2026
Unit #: 519	Location: Slave Lake	End Date: may 6/26
Grouch List Checked:		Grouch List Checked with Dave: ✓

- Recharge A/C
- Replace Cab Filter. part not installed yet. may 22/26
needs 830.61032 CH, CF19501, BALP#30287
830.61032 CH CFR19501,

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours**_____

Assigned Mechanic: Dave **Signature:** _____
Entered By: Katie

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

April 28

WO # 1234	Customer: JAYMAR	Start Date: /2026
Unit #: 519	Location: Slave Lake	End Date: April 28
		Requested by: Dave

Grouch List Checked:	Grouch List Checked with Dave:

Fix Gladhand

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

Changed air fitting on glad hand

CVIP Hours_____ **Repair Hours** 1

Assigned Mechanic: TRAE
Entered By: SHAY

Signature: _____

Qty	Parts Requested/Parts Nos. /Parts Details
1	3/8 hose Sleeve 884.1490-6

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1175	Customer: JAYMAR	Start Date: April 14/2026
Unit #: 519	Location: Slave Lake	End Date: April 14/26
Grouch List Checked:	Grouch List Checked with Dave:	

✓ Change heater fan - tested - now Quiet & Blows Good.

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 1

Assigned Mechanic: Dave
Entered By: Shay

Signature: _____

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1159	Customer: JAYMAR	Start Date: April 10/2026
Unit #: 519	Location: Slave Lake	End Date: Apr 11/26
Grouch List Checked:	Grouch List Checked with Dave:	

✓ 500 Hour Service

Dropped oil, changed fuel & oil filters
checked fluids, greased, adjusted brakes
Checked tire pressures, torqued lines

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 3

Assigned Mechanic: COLT
Entered By: SHAY

Signature: CG

Qty	Parts Requested/Parts Nos. /Parts Details
✓ 6	Dust Shield 156.1006

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

500 Hrs Service Inspection Form

Hrs: 10,422 AR

Date: April 10,26 Unit # 519 Odometer: 589,251

Multipoint Inspection								
Front Left			Front Right			Under Hood		
Pass	Fail		Pass	Fail		Pass	Fail	
✓		Headlight	✓		Headlight	✓		Horn
✓		Signal Light	✓		Signal Light	✓		Antifreeze Level
✓		Hazard Light	✓		Hazard Light	✓		Drive Belt
✓		Windshield	✓		Windshield	✓		Radiator Condition
✓		Cracked	✓		Cracked	PSI	Duration	Coolant Pressure test
✓		Chipped	✓		Chipped			
✓		Washer System	✓		Washer System	Under Vehicle		
✓		Wiper	✓		Wiper	✓		Suspension Comp
✓		Tire Tread	✓		Tire Tread	✓		Exhaust System
✓		Tire Pressure	✓		Tire Pressure	✓		Shocks
✓		PSI	✓		PSI	✓		Fuel Leaks
Rear Left			Rear Right			✓		Oil Leaks
✓		Brake Light	✓		Brake Light	~~Y~~/N		Engine Oil Replaced
✓		Signal Light	✓		Signal Light	~~Y~~/N		Oil Filter Replaced
✓		Hazard Light	✓		Hazard Light	~~Y~~/N		Replace Air Filter
✓		Back-Up Light	✓		Back-Up Light	Y/N		Torque all Wheels
✓		Tire Tread	✓		Tire Tread	Fire Extinguisher (Check & Initial)		
✓		Tire Pressure	✓		Tire Pressure	Expiry Date:		
✓		PSI	✓		PSI	CVIP Exp Date:		

Fluids			**Steering Components**	
Checked	Added		Pass	Fail
Front Differential	Y/~~N~~	~~Y~~/N	Left Ball Joints/King Pins	
Rear Differential	Y/~~N~~	~~Y~~/N	Right Ball Joints/King Pins	
Transfer Case	Y/~~N~~	~~Y~~/N	Left Tie Rods Ends	
Transmissions	Y/~~N~~	~~Y~~/N	Right Tie Rods Ends	
Power Steering	Y/~~N~~	~~Y~~/N	Center Link	
Brake Fluid	Y/~~N~~	~~Y~~/N	Pitman Arm	
Brakes	Pass	Fail	Steering Arm	
Left Front	✓		✓ Stabilizer Shock	
Left Rear	✓		✓ Sway Bars	
Right Front	✓		✓ Wheel Alignment	
Right Rear	✓			
Emergency Brake	✓			
Brake Cables				

Mechanic's Signature

CG

Next Service Due:

Reviewed By:

Comments:

DJ

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1136	Customer: JAYMAR	Start Date: April 2 /2026
Unit #: 519	Location: Slave Lake	End Date: April 2 2026
Grouch List Checked:	Grouch List Checked with Dave:	

250 hour service

- greased and performed inspection
- checked oil levels

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 1.5

Assigned Mechanic: YOSHI
Entered By: SHAY

Signature: _____

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

250 HRS Service Inspection Form

JAY-012

Hrs: _____

Date: April 2nd 2026 Unit # 519 Odometer: 589 323

Multipoint Inspection

Front Left			Front Right			Under Hood		
Pass	Fail		Pass	Fail		Pass	Fail	
✓		Headlight	✓		Headlight	✓		Horn
✓		Signal Light	✓		Signal Light	✓		Hood Light
✓		Hazard Light	✓		Hazard Light	✓		Drive Belt
✓		Windshield	✓		Windshield	✓		Radiator Condition
✓		Cracked	✓		Cracked	✓		Hose Clamps
✓		Chipped	✓		Chipped	✓		Heater Hose
✓		Washer System	✓		Washer System	Under Vehicle		
✓		Wiper	✓		Wiper		X	Suspension Comp
✓		Tire Tread	✓		Tire Tread	✓		Exhaust System
✓		Tire Pressure	✓		Tire Pressure	✓		Shocks
✓		PSI	✓		PSI	✓		Fuel Leaks
Rear Left			Rear Right					Oil Leaks
✓		Brake Light	✓		Brake Light	~~Y/N~~		~~Engine Oil Replaced~~
✓		Signal Light		X	Signal Light	Y/N		~~Oil Filter Replaced~~
✓		Hazard Light	✓		Hazard Light	Y/N		~~Replace Air Filter~~
✓		Back-Up Light	✓		Back-Up Light	(Y)/N		Torque all Wheels
✓		Tire Tread	✓		Tire Tread			
✓		Tire Pressure	✓		Tire Pressure			
✓		PSI	✓		PSI			

Fluids

Checked	Added	
Front Differential	(Y)/N	Y/N
Rear Differential	(Y)/N	Y/N
~~Transfer Case~~	~~Y/N~~	~~Y/N~~
Transmissions	(Y)/N	Y/N
Power Steering	(Y)/N	Y/N
~~Brake Fluid~~	~~Y/N~~	~~Y/N~~

Brakes

	Pass	Fail
Left Front		X
Left Rear	✓	
Right Front	✓	
Right Rear		X
Emergency Brake	✓	
~~Brake Cables~~		

Steering Components

Pass	Fail	
		Left Ball Joints/King Pins
		Right Ball Joints/King Pins
		Left Tie Rods Ends
		Right Tie Rods Ends
		Center Link
		Pitman Arm
✓		Steering Arm
		~~Stabilizer Shock~~
		~~Sway Bars~~
		Wheel Alignment

Drive Axle

Mechanic's Signature

Next Service Due:

Comments:

- All Air bags have lots of dry rot
- Trailer output right signal stays on
- Axle 2L and Axle 3R brake pots out
- fifth wheel ~~retainer~~ slides back and forth
- Headlight fault
- power steer reservoir needs cap
- Exhaust Leak behind turbo
- Coolant leaking from banjo hose below EGR pipe.
- P/ Lower motor busted

Reviewed By

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1091	Customer: JAYMAR	Start Date: March 18/2026
Unit #: 519	Location: Slave Lake	End Date:
Grouch List Checked:	Grouch List Checked with Dave:	

Fixing lights
- chase broken wire found at tail frame
- Repinned connecter, test lights and they work.

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 1

Assigned Mechanic: EDDIE
Entered By: SHAY

Signature: _____

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the tetorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1091	Customer: JAYMAR	Start Date: Mar 18 /2026
Unit #: 519	Location: Slave Lake	End Date: Mar 18 2026

Grouch List Checked:	Grouch List Checked with Dave:

Helping Eddie with light issue

- replaced light and connector because terminals were corroded
- cleaned up connections to other lights. Lights working
- traced back wiring for one of the marker lights not recieving power. found broken wire. repaired wire and installed heat shrink tube to secure connection. secured harnesses w/ electrical tape where required.

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 1.25

Assigned Mechanic: Yoshi **Signature:** _____

Entered By: Annette

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the gateway to safe working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 1003	Customer: JAYMAR	Start Date: ~~/2026~~
Unit #: 519	Location: Slave Lake	End Date: March 2 2026
		Requested by: Dave

Grouch List Checked:	Grouch List Checked with Dave:

- removed headlight cover
- removed bulb and ~~them~~ inspected
- bulb was broken
- ~~them~~ installed new bulb and tested light.
- light working
installed headlight cover.

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 0.25

Assigned Mechanic: Yoshi **Signature:** _____
Entered By: Katie

Qty	Parts Requested/Parts Nos. /Parts Details
1	bulb
3	Bolts
3	washers

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the gateway tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 3484	Customer: JAYMAR	Start Date: Feb 17/2026
Unit #: 519	Location: Slave Lake	End Date: Feb 17/26
Equip Desc: Semi	Year: 2017	Make: Kenworth
VIN: 1XKZDP0X8HJ986776	Plate #: 0BJ980	Model: T880
KM: 570,075	Hours: 9,996	Requested by: Dave
Grouch List Checked: yes.		Grouch List Checked with Dave:

Reattach light cord Replace Both male ends from truck to trailer, Test trailer cord and it was good
- Fab up Bracket above head jacke Rack and added a spring (New) to help hold the trailer cord
Replace Deck with MDNC, Fab up Tie down to hold deck in place

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 910

Assigned Mechanic: Eddie
Entered By: Shay

Signature: _____

Qty	Parts Requested/Parts Nos. /Parts Details
1	fender Kit page 3992 (Spring)
	did not find truck to trailer ends

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 3278	Customer: JAYMAR	Start Date: Dec 17 /2025
Unit #: 519	Location: Slave Lake	End Date: Dec 17/25
Equip Desc: Semi	Year: 2017	Make: Kenworth
VIN: 1XKZDP0X8HJ986776	Plate #: 0BJ980	Model: Tandem
KM: 567,012	Hours: 9917	Requested by: Dave
Grouch List Checked:		Grouch List Checked with Dave:
Fix air leak		
Install chain hangers		

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

changed air line fitting to PTO, took out DEF tank install chain hangers

CVIP Hours_____ **Repair Hours** 5

Assigned Mechanic: Trae **Signature:** _____
Entered By: Shay

Qty	Parts Requested/Parts Nos. /Parts Details
1	8841291O Splicer round 5/8
1	53510 Clamp #10
1	884147448 45° elbow Male

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

Dec 15/25

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 3262	**Customer:** JAYMAR	**Start Date:** Dec 12/2025
Unit #: 519	**Location:** Slave Lake	**End Date:** Dec 12 2025
Equip Desc: Semi	**Year:** 2017	**Make:** Kenworth
VIN: 1XKZDP0X8HJ986776	**Plate #:** 0BJ980	**Model:** Tandem drive
KM: 566,601	**Hours:** 9866	**Requested by:** Dave
Grouch List Checked:	**Grouch List Checked with Dave:**	

Helping Eddie with full service ✓

- Greased truck and inspected ✓
- torqued wheels ✓
- checked and topped up tire pressures as required ✓

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 1.25

Assigned Mechanic: Yoshi **Signature:** _____
Entered By: Sha

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

Dec 5/25

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 3261	Customer: JAYMAR	Start Date: Dec 12/2025
Unit #:519	Location: Slave Lake	End Date: Dec 12/25
Equip Desc: Semi	Year: 2017	Make: Kenworth
VIN:1XKZDP0X8HJ986776	Plate #: 0BJ980	Model: Tandem
KM: 566,601	Hours: 9866	Requested by: Dave
Grouch List Checked:		Grouch List Checked with Dave:

Full service

- Replace Oil and fuel filters
- D/S Back up light missing Replace with New
- splice open wire Rear bumper of truck

When installing USED parts, please specify.

Installed new bleeder screw for fuel system

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 4

Assigned Mechanic: Eddie **Signature:**
Entered By: Shay

Qty	Parts Requested/Parts Nos. /Parts Details
✓ 1	filterkit 1714364
✓ 42L	5W40 bulk
✓ 1	filter K3710L2
✓ 1	UNIL04232C

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

300 Hrs Service Inspection Form

JAY-013

Hrs: 9866

Date: Dec/225 Unit # 519 Odometer: 566601

Multipoint Inspection

Front Left			Front Right			Under Hood		
Pass	Fail		Pass	Fail		Pass	Fail	
✓		Headlight	✓		Headlight			Horn
✓		Signal Light	✓		Signal Light			Antifreeze Level
✓		Hazard Light	✓		Hazard Light			Drive Belt
✓		Windshield	✓		Windshield			Radiator Condition
		Cracked			Cracked	PSI	Duration	Coolant Pressure test
		Chipped			Chipped			
✓		Washer System	✓		Washer System	Under Vehicle		
✓		Wiper	✓		Wiper			Suspension Comp
✓		Tire Tread	✓		Tire Tread			Exhaust System
✓		Tire Pressure	✓		Tire Pressure			Shocks
100		PSI	100		PSI			Fuel Leaks
Rear Left			Rear Right					Oil Leaks
✓		Brake Light	✓		Brake Light	Y/N		Engine Oil Replaced
✓		Signal Light	✓		Signal Light	Y/N		Oil Filter Replaced
✓	✓	Hazard Light	✓		Hazard Light	Y/N		Replace Air Filter
	✓	Back-Up Light	✓		Back-Up Light	Y/N		Torque all Wheels
✓		Tire Tread	✓		Tire Tread	Fire Extinguisher (Check & Initial)		
✓		Tire Pressure	✓		Tire Pressure	Expiry Date:		
✓		PSI			PSI	CVIP Exp Date:		

Fluids	Checked	Added
Front Differential	Y/N	Y/N
Rear Differential	Y/N	Y/N
Transfer Case	Y/N	Y/N
Transmissions	Y/N	Y/N
Power Steering	Y/N	Y/N
~~Brake Fluid~~	~~Y/N~~	~~Y/N~~

Brakes	Pass	Fail
Left Front		
Left Rear		
Right Front		
Right Rear		
Emergency Brake		
Brake Cables		

Steering Components	Pass	Fail
Left Ball Joints/King Pins		
Right Ball Joints/King Pins		
Left Tie Rods Ends		
Right Tie Rods Ends		
Center Link		
Pitman Arm		
Steering Arm		
Stabilizer Shock		
Sway Bars		
Wheel Alignment		



Mechanic's Signature

Next Service Due:

Reviewed By:

Comments:

1/2

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 3175	**Customer: JAYMAR**	**Start Date: Nov 2/2025**
Unit #: 519	**Location: Slave Lake**	**End Date:** Nov 2/25
Equip Desc: Tandem	**Year: 2017**	**Make: Kenworth**
VIN: 1XKZDP0X8HJ986776	**Plate #: 0BJ980**	**Model:**
KM: 563,167	**Hours:** 9,800	**Requested by: Dave**
Grouch List Checked:		**Grouch List Checked with Dave:**
Called in		
Loosen PTO actuator Lube up spool shaft		

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours**_____

Assigned Mechanic: Dave
Entered By: Emmanuel

Signature:

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tire

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

29

Work Order Pending

WO # 3168	Customer: JAYMAR	Start Date: Oct/30/2025
Unit #: 519	Location: Slave Lake	End Date: Oct 30/25
Equip Desc: Tandem KW	Year: 2017	Make: Kenworth
VIN: 1XKZDP0X8HJ986776	Plate #: 0BJ980	Model: Tandem
KM: 349392	Hours: 9781	Requested by: Eddie
Grouch List Checked: Yes	Grouch List Checked with Dave:	

Fabrication code from truck to trailer for trailer's gate locks and Suspension dump
Used Quad Axle switch in ~~Da~~ dash

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 2

Assigned Mechanic: Eddie
Entered By: Basil

Signature: _____

Qty	Parts Requested/Parts Nos. /Parts Details
15'	4 wire blue 3603
2	male plug 150 7way 15830

I certify that the above unit was repaired under my supervision

Name:	Sign:

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2811	Customer: JAYMAR	Start Date: July 21/2025
Unit #: 519	Location: Slave Lake	End Date: July 21/2025
Equip Desc: Tandem	Year: 2017	Make: Kenworth
VIN: 1XKZDP0X8HJ986776	Plate #: 0BJ980	Model: T 880
KM: 555,928	Hours: 9,695	Requested by: Dave

Grouch List Checked:	Grouch List Checked with Dave:

Change 7 wire electrical cord

Replaced entire cord and both ~~female~~ ends

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ Repair Hours 1

Assigned Mechanic: John Signature: _____
Entered By: Emmanuel

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2722	Customer: JAYMAR	Start Date: June 23 /2025
Unit #: 519	Location: Slave Lake	End Date: Jan 23/25
Equip Desc: Semi truck	Year: 1XKZDP0X8HJ986776	Make: KW
VIN: 1XKZDP0X8HJ986776	Plate #: OBJ980	Model: Tandem
KM: 544,099	Hours: 9,526	Requested by: Dave
Grouch List Checked: Yes	Grouch List Checked with Dave: No	

Change Windshield washer pump

Tested Good

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours**_____

Assigned Mechanic: Dave **Signature:** _____
Entered By: Annette

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2710	Customer: JAYMAR	Start Date: June 19/2025
Unit #: 519	Location: Slave Lake	End Date:
Equip Desc: Tandem	Year: 2017	Make: Kenworth
VIN: 1XKZDP0X8HJ986776	Plate #: 0BJ980	Model: T 880
KM: 541,591	Hours: 9,493	Requested by: Dave
Grouch List Checked:		Grouch List Checked with Dave:

Fixing fender bracket

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 40 mins

Assigned Mechanic: John Rosaasen **Signature:** _____
Entered By: Emmanuel

☐ Check if you put on the retorque tags after working on tires

JAYMAR HAULING LTD.

702 OSP #:

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2621	**Customer:** JAYMAR	**Start Date:** May 20/2025
Unit #: 519	**Location:** Slave Lake	**End Date:** May 22/25
Equip Desc: Tandem	**Year:** 2017	**Make:** Kenworth
VIN: 1XKZDP0X8HJ986776	**Plate #:** 0BJ980	**Model:** T 880
KM: 540,046	**Hours:** 9,464	**Requested by:** Dave
Grouch List Checked: Yes		**Grouch List Checked with Dave:**

CVIP Wheel Off

Manifold has crack & hydraulic pump not working good

(4) ✓ Changed Shocks on rear Axles

(3)+(2) ✓ Changed B Shoes and Drums on both Steer Axle

✓ Reseated PTO

When installing USED parts, please specify.

Zac helped

EXCESSIVE TIME DESCRIPTION

CVIP Hours 19 **Repair Hours** _____

Assigned Mechanic: John Rosaasen **Signature:**

Entered By: Emmanuel

OSP #:

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2667	Customer: JAYMAR	Start Date: June 4 /2025
Unit #: 519	Location: Slave Lake	End Date: June 4/25
Equip Desc: Semi truck	Year: 2017	Make: KW
VIN: 1XKZDP0X8HJ986776	Plate #: 0BJ980	Model:
KM: 540408	Hours: 9474	Requested by: Dave
Grouch List Checked: Yes		Grouch List Checked with Dave:

Fix antifreeze leak above transmission

- Had to go threw the floor were the shifter is, the line from the Head to the Trans. cooler, Replace fitting on back of Head
- Plug the Second line that gose to the DEF Tank

When installing USED parts, please specify.

- Pressure test anti freeze check for leaks and found another leak and it was the line coming out of the Second line for the transmission cooler. Just tighten clamp and fix Leaks

EXCESSIVE TIME DESCRIPTION

Its a Hard place to get at

CVIP Hours_____ Repair Hours 8

Assigned Mechanic: Eddie Signature:
Entered By: Annette

OSP #:

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2591	Customer: JAYMAR	Start Date: May 12/2025
Unit #: 519	Location: Slave Lake	End Date:
Equip Desc: Tandem	Year: 2017	Make: Kenworth
VIN: 1XKZDP0X8HJ986776	Plate #: OBJ980	Model:
KM: 540,045	Hours: 9,464	Requested by: Dave
Grouch List Checked: Yes		Grouch List Checked with Dave:

Replace shift cover gasket

- Drain Transmisson fluid
- Remove PTO shifter cover
- cleaned old gasket off of PTO and shift cover

When installing USED parts, please specify.

- Put New Gasket
- Top up Transmission and put 20L

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ Repair Hours 8 4

Assigned Mechanic: Eddie Signature: _____
Entered By: Martine

OSP #:
3486, 3488
3487,

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2410	Customer: JAYMAR	Start Date: Feb 26/2025
Unit #: 519	Location: Slave Lake	End Date: feb 26/25
Equip Desc: Tandem	Year: 2017	Make:
VIN: 1XKZDP0X8HJ986776	Plate #: 0BJ980	Model: Kenworth
KM: 535,216	Hours: 9,369	Requested by: Dave
Grouch List Checked: Yes		Grouch List Checked with Dave:

✓ 500Hr Full service
- Grease truck
- Set brakes
- ✓ Change oil/oil filter 42(Ltrs) 3486
- When installing USED parts, please specify.
- ✓ Change fuel filters 3488 1 bottle of ATF
- Fill up coolant 3486
- ✓ Change driver door seal R421165 PG 3423512

✓

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ Repair Hours 7hrs

Assigned Mechanic: TY Signature: _____
Entered By: Martine

OSP #: 3459

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2353	Customer: JAYMAR	Start Date: Feb 12/2025
Unit #: 519	Location: Slave Lake	End Date: Feb 12/25
Equip Desc: Tandem	Year: 2007	Make: Kenworth
VIN: 1XKZDP0X8HJ986776	Plate #: CGK-6689	Model:
KM: 532,602	Hours: 9,304	Requested by: Dave
Grouch List Checked: Yes	Grouch List Checked with Dave:	

Check out starter

exiter wire was Broken ✓

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ Repair Hours 1

Assigned Mechanic: Zack Signature: _____

Entered By: Martine

JAYMAR HAULING LTD.

OSP #:

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2253	Customer: JAYMAR	Start Date: Jan 13 2025
Unit #: 519	Location: Slave Lake	End Date: Jan 13/25
Equip Desc: Tandem Kenworth	Year: 2017	Make: Tandem
VIN: 1XKZDP0X8HJ986776	Plate #: OBJ980	Model: Kenworth
KM: 527779	Hours: 9144	Requested by: Dave
Grouch List Checked: YES		Grouch List Checked with Dave:

Install new air charge cooler 2310286 GWKW
Evac & Recharge AC system
Set Brakes, Grease, Check fluids.
Top up transmission.

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ Repair Hours_____

Assigned Mechanic: Dave Signature:_____
Entered By: Martine

march 6

OSP #:

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2351	**Customer: JAYMAR**	**Start Date: Feb 12/2025**
Unit #: 519	**Location: Slave Lake**	**End Date:** Fe 5/26
Equip Desc: Tandem	**Year: 2017**	**Make: Kenworth**
VIN: 1XKZDP0X8HJ986776	**Plate #:** CGK-6689	**Model:**
KM: 532,601	**Hours:** 9,301	**Requested by: Dave**
Grouch List Checked: Yes		**Grouch List Checked with Dave:**

Changing Valve on air tank

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours_____ **Repair Hours** 20 min

Assigned Mechanic: Trae **Signature:** _____
Entered By: Martine