

J17-8
NOV



Solo Glass Services

38 15704 121A Avenue Northwest

Edmonton AB T5V 1B5

5879749639

ap.sologlass2022@gmail.com

INVOICE

BILL TO

MAP Water & Sewer

Services Ltd.

Edmonton AB

INVOICE # 8367

DATE 24/06/2026

DUE DATE 24/06/2026

TERMS Due on receipt

PURCHASE ORDER #

Ws189 1gc4ytey5lf184217

ACTIVITY

DW 2497 GTY

Front windshield replacement

QTY

AMOUNT

1

230.00

PAYMENT OPTIONS

[Cash]

[Credit] please follow link in email

[E-Transfer] Sologlass2022@gmail.com

SUBTOTAL

230.00

GST @ 5%

11.50

TOTAL

241.50

BALANCE DUE

\$241.50

POSTED

RECEIVED

JUN 26 2026

6400

M.A.P.

I appreciate your business and would like to thank you for being a valued client.
I look forward to my next opportunity to deliver exceptional results!



JIFFY LUBE #1105
GST# 708318928
14849 112th AVE
EDMONTON, AB T5M 4G1
780-487-8034

Page 1 of 1

DATE 6/16/2026 3:00 PM
TRANSACTION NO 26061600268748
INVOICE NO 01105-268748
VEHICLE ID AB-CFD9001

Customer and Vehicle Information

MAP Water & Sewer
14907 96 St. NW Frank Tymchuk
Edmonton, AB T5E 4B9

2020 Chevrolet Silverado 3500 HD LT
8Cyl 6.6L 403 MFI OHV DIESEL Turbo L5P 445hp Duramax (Y)
VIN 1GC4YTEY5LF184217 KILOMETERS 217983
ALT ID

Service History

DATE	KILOMETERS	SERVICES
6/16/26	217983	FSS AF RCF RRS RTS
2/18/26	205812	FSS RAF RFF RRS RTS
11/28/25	198243	FSS RAF RFF RRS RTS
8/27/25	186984	FSS RDS FDS TCS CAF RRS
5/8/25	174425	FSS FF AF RRD RTC RFD RCF
12/11/24	159258	FSS RAF RRD RTC RFD
9/26/24	146936	FSS RRD RTC RFD

Fleet Information

M.A.P. Water & Sewer Ltd.

14303-116 Avenue
Edmonton, AB T5M 4G2

PO# WS189

REMIT TO ADDRESS

Jiffy Lube Head Office
8860-60 Avenue
Edmonton, AB T6E 6A6

Employees

UPPER TECH LOWER TECH CASHIER
NC DW

Service Comments

COOLANT SENSOR IS READING
WRONG BOTH RES. ARE FULL -
Air box screws stripped on arrival

Service Checklist

AIR FILTER	REPLACED
CABIN AIR FILTER	REC. REPLACE
PCV VALVE	N/A
WIPER BLADES	CHECKED
BATTERY TESTED	N/A
BRAKE FLUID	CHECKED
POWER STEERING FLUID	CHECKED
TRANS/TRANSAXLE FLUID	REC. REPLACE
FRONT DIFF. FLUID	N/A
REAR DIFF. FLUID	N/A
TRANSFER CASE FLUID	N/A
ENGINE COOLANT	REC. REPLACE
MINDSHIELD WASHER FLUID	CHECKED
HEAD/TAIL LIGHTS	DECLINED
BELTS	CHECKED
SHOCKS/STRUTS	CHECKED
EXHAUST SYSTEM	CHECKED
AXLE BOOTS	CHECKED
TIRE WEAR/PRESSURE	F61 R80
LUBRICATE CHASSIS	SEALED

Description	Qty.	Price
F/S DIESEL FULL SYNTHETIC	1.00	259.99
PZ173 OIL FILTER	1.00	0.00
SHELL T6 FULL SYN 5W40	10.00	0.00
SHOP SUPPLIES/ENVIRO FEE	1.00	8.99
AF1515 AIR FILTER	1.00	69.99
REC. CABIN AIR FILTER	1.00	0.00
REC. RADIATOR SERVICE	1.00	0.00
REC. TRANSMISSION SERVICE	1.00	0.00
SUBTOTAL		\$338.97
SALE		\$338.97
GST 708318928		16.95
TOTAL		\$355.92
CHARGE		355.92
CHANGE		\$0.00

Warranty Statement

This Jiffy Lube centre warrants all workmanship against failure for 7 days from the service date. This warranty is void if the customer tampers with, alters the centre's products, alters the manufacturer's original equipment, or takes corrective action without prior written approval from this Jiffy Lube centre. The customer must present this limited warranty certificate and retain the product(s) involved. This warranty does not cover vehicle loss of use or loss of wages due to vehicle loss of use. All parts that have been removed and/or replaced will be discarded unless requested to be returned.

****POTENTIAL OIL RUNDOWN FROM SERVICE, DO NOT PARK IN DRIVEWAY/GARAGE FOR AT LEAST 24 HOURS****
JIFFY LUBE FOLLOWS A STRICT DOUBLE-CHECK PROCEDURE.
ALL PLUGS AND CAPS REMOVED DURING SERVICE ARE SECURELY REINSTALLED, TIGHTENED, AND DOUBLE-CHECKED BEFORE YOUR VEHICLE LEAVES OUR CENTRE.
jiffylubeservice.ca/roadtrip
Recommend next service on 09/14/2026 or 222983 km.

X

Cardholder acknowledges receipt of goods and/or services in the amount shown hereon and agrees to perform the obligations set forth in the Cardholder's agreement with the issuer



JIFFY LUBE #1105
GST# 708318928
14849 112th AVE
EDMONTON, AB T5M 4G1
780-487-8034

Page 1 of 2

DATE 2/18/2026 4:38 PM
TRANSACTION NO 26021800266484
INVOICE NO 01105-266484
VEHICLE ID AB-CFD9001

Customer and Vehicle Information		Service History	
MAP Water & Sewer 14907 96 St. NW Edmonton, AB T5E 4B9		DATE	KILOMETERS SERVICES
2020 Chevrolet Silverado 3500 HD LT 8Cyl 6.6L 403 MFI OHV DIESEL Turbo L5P 445hp Duramax (Y) VIN 1GC4YTEY5LF184217 ALT ID KILOMETERS 205812		2/18/26	205812 FSS RAF RFF RRS RTS
		11/28/25	198243 FSS RAF RFF RRS RTS
		8/27/25	186984 FSS RDS FDS TCS CAF RRS
		5/8/25	174425 FSS FF AF RRD RTC RFD RCF
		12/11/24	159258 FSS RAF RRD RTC RFD
		9/26/24	146936 FSS RRD RTC RFD
		7/18/24	140460 FSS AF CAF LGT

Fleet Information

M.A.P. Water & Sewer Ltd.

14303-116 Avenue
Edmonton, AB T5M 4G2

PO# PO# WS189

REMIT TO ADDRESS

Jiffy Lube Head Office
8860-60 Avenue
Edmonton, AB
T6E 6A6

Employees			Service Comments
UPPER TECH DW	LOWER TECH TN	CASHIER	AIR FILTER VERY DIRTY AIR FILTER HOUSING DAMAGED PRIOR

Service Checklist			Description	Qty.	Price
AIR FILTER	REC. REPLACE		F/S DIESEL FULL SYNTHETIC	1.00	239.99
CABIN AIR FILTER	DECLINED		OF1513 OIL FILTER	1.00	15.00
PCV VALVE	N/A		SHELL T6 FULL SYN 5W40	10.00	0.00
WIPER BLADES	CHECKED		SHOP SUPPLIES/ENVIRO FEE	1.00	7.99
BATTERY TESTED	N/A		REC. AIR FILTER	1.00	0.00
BRAKE FLUID	CHECKED		REC. FUEL FILTER	1.00	0.00
POWER STEERING FLUID	CHECKED		REC. RADIATOR SERVICE	1.00	0.00
TRANS/TRANSAXLE FLUID	REC. REPLACE		REC. TRANSMISSION SERVICE	1.00	0.00
FRONT DIFF. FLUID	CHECKED		SUBTOTAL		\$262.98
REAR DIFF. FLUID	CHECKED		(AIR)		-0.00
TRANSFER CASE FLUID	CHECKED		SALE		\$262.98
ENGINE COOLANT	REC. REPLACE				
WINDSHIELD WASHER FLUID	DECLINED		GST 708318928		13.15
HEAD/TAIL LIGHTS	DECLINED		TOTAL		\$276.13
BELTS	CHECKED		CHARGE		276.13
SHOCKS/STRUTS	CHECKED		CHANGE		\$0.00
EXHAUST SYSTEM	CHECKED				
AXLE BOOTS	CHECKED				
TIRE WEAR/PRESSURE	F55 R70				
LUBRICATE CHASIS	SEALED				

Warranty Statement

This Jiffy Lube centre warrants all workmanship against failure for 7 days from the service date. This warranty is void if the customer tampers with, alters the centre's products, alters the manufacturer's original equipment, or takes corrective action without prior written approval from this Jiffy Lube centre. The customer must present this limited warranty certificate and retain the product(s) involved. This warranty does not cover vehicle loss of use or loss of wages due to vehicle loss of use. All parts that have been removed and/or replaced will be discarded unless requested to be returned.



JIFFY LUBE #1105
GST# 708318928
14849 112th AVE
EDMONTON, AB T5M 4G1
780-487-8034

Page 2 of 2

DATE 2/18/2026 4:38 PM
TRANSACTION NO 26021800266484
INVOICE NO 01105-266484
VEHICLE ID AB-CFD9001

Customer and Vehicle Information		Service History	
MAP Water & Sewer 14907 96 St. NW Edmonton, AB T5E 4B9		DATE	KILOMETERS SERVICES
2020 Chevrolet Silverado 3500 HD LT 8Cyl 6.6L 403 MFI OHV DIESEL Turbo L5P 445hp Duramax (Y) VIN 1GC4YTEY5LF184217 ALT ID		2/18/26	205812 FSS RAF RFF RRS RTS
		11/28/25	198243 FSS RAF RFF RRS RTS
		8/27/25	186984 FSS RDS FDS TCS CAF RRS
		5/8/25	174425 FSS FF AF RRD RTC RFD RCF
		12/11/24	159258 FSS RAF RRD RTC RFD
		9/26/24	146936 FSS RRD RTC RFD
		7/18/24	140460 FSS AF CAF LGT
POTENTIAL OIL RUNDOWN FROM SERVICE, DO NOT PARK ON DRIVEWAY/GARAGE FOR AT LEAST 24 HOURS JIFFY LUBE FOLLOWS A STRICT DOUBLE-CHECK PROCEDURE. ALL PLUGS AND CAPS REMOVED DURING SERVICE ARE SECURELY REINSTALLED, TIGHTENED, AND DOUBLE-CHECKED BEFORE YOUR VEHICLE LEAVES OUR CENTRE. jiffylubeservice.ca/roadtrip Recommend next service on 05/19/2026 or 210812 km.		X Cardholder acknowledges receipt of goods and/or services in the amount shown hereon and agrees to perform the obligations set forth in the Cardholder's agreement with the issuer.	



JIFFY LUBE #1105
GST# 708318928
14849 112th AVE
EDMONTON, AB T5M 4G1
780-487-8034

Page 1 of 2

DATE 11/28/2025 3:34 PM
TRANSACTION NO 25112800264996
INVOICE NO 01105-264996
VEHICLE ID AB-CFD9001

Customer and Vehicle Information		Service History	
MAP Water & Sewer 14907 96 St. NW Edmonton, AB T5E 4B9		DATE	KILOMETERS SERVICES
2020 Chevrolet Silverado 3500 HD LT 8Cyl 6.6L 403 MFI OHV DIESEL Turbo L5P 445hp Duramax (Y) VIN 1GC4YTEY5LF184217 ALT ID		11/28/25	198243 FSS RAF RFF RRS RTS
		8/27/25	186984 FSS RDS FDS TCS CAF RRS
		5/8/25	174425 FSS FF AF RRD RTC RFD RCF
		12/11/24	159258 FSS RAF RRD RTC RFD
		9/26/24	146936 FSS RRD RTC RFD
		7/18/24	140460 FSS AF CAF LGT
		6/1/24	136212 FSS AF CAF
Fleet Information			
M.A.P. Water & Sewer Ltd.		14303-116 Avenue Edmonton, AB T5M 4G2	
PO# WS189			
REMIT TO ADDRESS			
Jiffy Lube Head Office 8860-60 Avenue Edmonton, AB T6E 6A6			
Employees		Service Comments	
UPPER TECH BB	LOWER TECH TN	CASHIER	
Service Checklist		Description	
AIR FILTER	REC. REPLACE	F/S DIESEL FULL SYNTHETIC	Qty. Price
CABIN AIR FILTER	CHECKED	OF1513 OIL FILTER	1.00 239.99
PCV VALVE	N/A	SHELL T6 FULL SYN 5W40	1.00 15.00
WIPER BLADES	CHECKED	SHOP SUPPLIES/ENVIRO FEE	10.00 0.00
BATTERY TESTED	N/A	REC. AIR FILTER	1.00 7.99
BRAKE FLUID	CHECKED	REC. FUEL FILTER	1.00 0.00
POWER STEERING FLUID	N/A	REC. RADIATOR SERVICE	1.00 0.00
TRANS/TRANSAXLE FLUID	REC. REPLACE	REC. TRANSMISSION SERVICE	1.00 0.00
FRONT DIFF. FLUID	N/A	SUBTOTAL	
REAR DIFF. FLUID	N/A	(AIR)	\$262.98
TRANSFER CASE FLUID	N/A	SALE	-0.00
ENGINE COOLANT	REC. REPLACE		\$262.98
WINDSHIELD WASHER FLUID	CHECKED		
HEAD/TAIL LIGHTS	CHECKED		
BELTS	CHECKED		
SHOCKS/STRUTS	CHECKED		
EXHAUST SYSTEM	CHECKED		
AXLE BOOTS	CHECKED		
TIRE WEAR/PRESSURE	F60 R80		
LUBRICATE CHASIS	SEALED		
		GST 708318928	13.15
		TOTAL	\$276.13
		CHARGE	276.13
		CHANGE	\$0.00

Warranty Statement

This Jiffy Lube centre warrants all workmanship against failure for 7 days from the service date. This warranty is void if the customer tampers with, alters the centre's products, alters the manufacturer's original equipment, or takes corrective action without prior written approval from this Jiffy Lube centre. The customer must present this limited warranty certificate and retain the product(s) involved. This warranty does not cover vehicle loss of use or loss of wages due to vehicle loss of use. All parts that have been removed and/or replaced will be discarded unless requested to be returned.



JIFFY LUBE #1105
GST# 708318928
14849 112th AVE
EDMONTON, AB T5M 4G1
780-487-8034

Page 2 of 2

DATE 11/28/2025 3:34 PM
TRANSACTION NO 25112800264996
INVOICE NO 01105-264996
VEHICLE ID AB-CFD9001

Customer and Vehicle Information		Service History	
MAP Water & Sewer 14907 96 St. NW Frank Tymchuk Edmonton, AB T5E 4B9		DATE	KILOMETERS SERVICES
2020 Chevrolet Silverado 3500 HD LT 8Cyl 6.6L 403 MFI OHV DIESEL Turbo L5P 445hp Duramax (Y) VIN 1GC4YTEY5LF184217 KILOMETERS 198243 ALT ID		11/28/25	198243 FSS RAF RFF RRS RTS
		8/27/25	186984 FSS RDS FDS TCS CAF RRS
		5/8/25	174425 FSS FF AF RRD RTC RFD RCF
		12/11/24	159258 FSS RAF RRD RTC RFD
		9/26/24	146936 FSS RRD RTC RFD
		7/18/24	140460 FSS AF CAF LGT
		6/1/24	136212 FSS AF CAF
POTENTIAL OIL RUNDOWN FROM SERVICE, DO NOT PARK ON DRIVEWAY/GARAGE FOR AT LEAST 24 HOURS JIFFY LUBE FOLLOWS A STRICT DOUBLE-CHECK PROCEDURE. ALL PLUGS AND CAPS REMOVED DURING SERVICE ARE SECURELY REINSTALLED, TIGHTENED, AND DOUBLE-CHECKED BEFORE YOUR VEHICLE LEAVES OUR CENTRE. jiffylubeservice.ca/roadtrip Recommend next service on 02/26/2026 or 203243 km.		X Cardholder acknowledges receipt of goods and/or services in the amount shown hereon and agrees to perform the obligations set forth in the Cardholder's agreement with the issuer.	



JIFFY LUBE #1105
GST# 708318928
14849 112th AVE
EDMONTON, AB T5M 4G1
780-487-8034

Page 1 of 2

DATE 8/27/2025 3:20 PM
TRANSACTION NO 25082700262963
INVOICE NO 01105-262963
VEHICLE ID AB-CFD9001

Customer and Vehicle Information		Service History		
MAP Water & Sewer 14907 96 St. NW Edmonton, AB T5E 4B9		DATE	KILOMETERS SERVICES	
2020 Chevrolet Silverado 3500 HD LT 8Cyl 6.6L 403 MFI OHV DIESEL Turbo L5P 445hp Duramax (Y) VIN 1GC4YTEY5LF184217 ALT ID KILOMETERS 186984		8/27/25	186984 FSS RDS FDS TCS CAF RRS	
		5/8/25	174425 FSS FF AF RRD RTC RFD RCF	
		12/11/24	159258 FSS RAF RRD RTC RFD	
		9/26/24	146936 FSS RRD RTC RFD	
		7/18/24	140460 FSS AF CAF LGT	
		6/1/24	136212 FSS AF CAF	
		4/10/24	130104 FSS AF RRD RTC RFD	
Fleet Information				
M.A.P. Water & Sewer Ltd.		14303-116 Avenue Edmonton, AB T5M 4G2		
PO# WS189		<div>REMIT TO ADDRESS</div> <div>Jiffy Lube Head Office</div> <div>8860-60 Avenue</div> <div>Edmonton, AB</div> <div>T6E 6A6</div>		
Employees		Service Comments		
UPPER TECH LOWER TECH NC TN	CASHIER			
Service Checklist		Description	Qty.	Price
AIR FILTER	CHECKED	F/S DIESEL FULL SYNTHETIC	1.00	239.99
CABIN AIR FILTER	REPLACED	OF1513 OIL FILTER	1.00	15.00
PCV VALVE	N/A	SHELL T6 FULL SYN 5W40	10.00	0.00
WIPER BLADES	CHECKED	SHOP SUPPLIES/ENVIRO FEE	1.00	7.99
BATTERY TESTED	N/A	REAR DIFF. CHANGE SYN.	1.00	139.99
BRAKE FLUID	CHECKED	SYNTHETIC 75/90 GEAR OIL	3.00	0.00
POWER STEERING FLUID	CHECKED	SHOP SUPPLIES/ENVIRO FEE	1.00	7.99
TRANS/TRANSAXLE FLUID	CHECKED	FRONT DIFF. CHANGE SPEC.	1.00	159.99
FRONT DIFF. FLUID	REPLACED	REDLINE 75/85 GEAR OIL	3.00	0.00
REAR DIFF. FLUID	REPLACED	SHOP SUPPLIES/ENVIRO FEE	1.00	7.99
TRANSFER CASE FLUID	REPLACED	TRANSFER CASE SERVICE SYN	1.00	139.99
ENGINE COOLANT	REC. REPLACE	FULL SYNTHETIC ATF	2.00	0.00
WINDSHIELD WASHER FLUID	CHECKED	SHOP SUPPLIES/ENVIRO FEE	1.00	7.99
HEAD/TAIL LIGHTS	DECLINED	C38224 CABIN AIR FILTER	1.00	49.99
BELTS	CHECKED	REC. RADIATOR SERVICE	1.00	0.00
SHOCKS/STRUTS	CHECKED	SUBTOTAL		\$776.91
EXHAUST SYSTEM	CHECKED	(AIR)		-0.00
AXLE BOOTS	CHECKED	SALE		\$776.91
TIRE WEAR/PRESSURE	CHECKED			
LUBRICATE CHASIS	F80 R80 SEALED	GST 708318928		38.85
		TOTAL		\$815.76
		CHARGE		815.76
		CHANGE		\$0.00



JIFFY LUBE #1105
GST# 708318928
14849 112th AVE
EDMONTON, AB T5M 4G1
780-487-8034

Page 2 of 2

DATE 8/27/2025 3:20 PM
TRANSACTION NO 25082700262963
INVOICE NO 01105-262963
VEHICLE ID AB-CFD9001

Customer and Vehicle Information		Service History	
MAP Water & Sewer 14907 96 St. NW Edmonton, AB T5E 4B9		DATE	KILOMETERS SERVICES
		8/27/25	186984 FSS RDS FDS TCS CAF RRS
		5/8/25	174425 FSS FF AF RRD RTC RFD RCF
		12/11/24	159258 FSS RAF RRD RTC RFD
		9/26/24	146936 FSS RRD RTC RFD
		7/18/24	140460 FSS AF CAF LGT
		6/1/24	136212 FSS AF CAF
		4/10/24	130104 FSS AF RRD RTC RFD
2020 Chevrolet Silverado 3500 HD LT 8Cyl 6.6L 403 MFI OHV DIESEL Turbo L5P 445hp Duramax (Y) VIN 1GC4YTEY5LF184217 KILOMETERS 186984 ALT ID			
Warranty Statement			
This Jiffy Lube centre warrants all workmanship against failure for 7 days from the service date. This warranty is void if the customer tampers with, alters the centre's products, alters the manufacturer's original equipment, or takes corrective action without prior written approval from this Jiffy Lube centre. The customer must present this limited warranty certificate and retain the product(s) involved. This warranty does not cover vehicle loss of use or loss of wages due to vehicle loss of use. All parts that have been removed and/or replaced will be discarded unless requested to be returned.			
POTENTIAL OIL RUNDOWN FROM SERVICE, DO NOT PARK ON DRIVEWAY/GARAGE FOR AT LEAST 24 HOURS JIFFY LUBE FOLLOWS A STRICT DOUBLE-CHECK PROCEDURE. ALL PLUGS AND CAPS REMOVED DURING SERVICE ARE SECURELY REINSTALLED, TIGHTENED, AND DOUBLE-CHECKED BEFORE YOUR VEHICLE LEAVES OUR CENTRE. jiffylubeservice.ca/roadtrip Recommend next service on 11/25/2025 or 191984 km.		X Cardholder acknowledges receipt of goods and/or services in the amount shown hereon and agrees to perform the obligations set forth in the Cardholder's agreement with the issuer.	



General Motors of Canada Company
500 Wentworth Street W
Oshawa, Ontario L1J 0C5

December 2024

Done
9/25/25
72

The applicable Vehicle Identification Number (VIN) can be found on the address label of the envelope.

Your vehicle is involved in **SAFETY RECALL N242454440**.
Transport Canada Recall # 2024-637

WS/89
Lennie

Dear General Motors Customer:

This notice is sent to you in accordance with the requirements of the *Motor Vehicle Safety Act*. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2020 – 2022 model year Chevrolet Silverado 1500 and GMC Sierra 1500; 2020 – 2022 model year Chevrolet Silverado 2500/3500 and GMC Sierra 2500/3500; and 2021 model year Cadillac Escalade and Escalade ESV, Chevrolet Suburban and Tahoe, and GMC Yukon and Yukon XL vehicles equipped with diesel engines. As a result, GM is conducting a safety recall.

IMPORTANT

- Your vehicle is involved in GM recall N242454440.

Why is your vehicle being recalled?

A transmission control valve in some of these vehicles may be susceptible to excess wear over time, resulting in a gradual loss of pressure within the valve that can cause harsh shifting and may cause the rear wheels to momentary lock up. If the rear wheels lock-up momentarily while driving, there is increased risk of a crash.

What will we do?

Parts to repair your vehicle are not currently available, but when parts are available, your General Motors dealer will install new transmission control module software that will monitor valve performance and detect excess wear approximately 16,000 kilometers (10,000 miles) before a wheel lock up condition could occur. Once detected, the transmission will be limited to fifth gear, preventing the possibility of a wheel lock up condition, which occurs in a downshift from eighth gear. A service engine light and reduced propulsion message will also display in the instrument panel. This service will be performed for you at **no charge**.

We are working as quickly as possible to correct this condition. When parts are available, we will send you another letter asking you to take your vehicle to your General Motors dealer to have your vehicle serviced. You can also check the status of any other possible recall and/or program for your vehicle at <https://experience.gm.ca/en/ownercenter/recalls>. If you have already paid for repairs for this condition, the reimbursement request process will be outlined in the next letter.

RECEIVED

JAN 28 2025

MAP



Compagnie General Motors du Canada
500 rue Wentworth O
Oshawa (Ontario) L1J 0C5

Décembre 2024

Le numéro d'identification du véhicule (NIV) applicable se trouve sur l'étiquette d'adresse de l'enveloppe.

Votre véhicule est touché par le **RAPPEL DE SÉCURITÉ** N242454440.
Rappel de Transports Canada n° 2024-637

Cher client de General Motors:

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile*. La présente a pour but de vous informer que votre véhicule est susceptible d'avoir un défaut qui pourrait porter atteinte à la sécurité humaine.

General Motors a déterminé qu'un défaut relatif à la sécurité des véhicules automobiles existe sur certains véhicules Chevrolet Silverado 1500 et GMC Sierra 1500 2020 à 2022; Chevrolet Silverado 2500/3500 et GMC Sierra 2500/3500 2020 à 2022; et Cadillac Escalade et Escalade ESV, Chevrolet Suburban et Tahoe, et GMC Yukon et Yukon XL 2021 équipés de moteurs diesel. Par conséquent, GM effectue un rappel de ces véhicules pour des raisons de sécurité.

I M P O R T A N T

- Votre véhicule est touché par le rappel GM N242454440.

Pourquoi votre véhicule fait-il l'objet d'un rappel?

Une soupape de commande de boîte de vitesses dans certains de ces véhicules peut être sujette à une usure excessive au fil du temps, ce qui entraîne une perte graduelle de pression dans la soupape qui peut causer des changements de vitesse brusques et peut causer un blocage momentané des roues arrière. Si les roues arrière se bloquent momentanément pendant la conduite, il y a un risque accru de collision.

Quelles mesures allons-nous prendre?

Les pièces pour réparer votre véhicule ne sont pas disponibles pour le moment. Quand elles le seront, votre concessionnaire General Motors installera un nouveau logiciel de module de commande de boîte de vitesses qui surveillera le rendement des soupapes et détectera l'usure excessive sur environ 16 000 km (10 000 mi) avant qu'un blocage de roue puisse se produire. Une fois détectée, la boîte de vitesses est limitée au cinquième rapport, ce qui empêche la possibilité d'un blocage de roue qui se produit lors d'une rétrogradation à partir du huitième rapport. Un témoin d'entretien du moteur et un message de propulsion réduite s'afficheront également sur le tableau de bord. Ce travail sera effectué pour vous **sans frais**.

Nous nous employons à corriger ce problème aussi rapidement que possible. Lorsque les pièces seront disponibles, nous vous ferons parvenir une autre lettre pour vous demander de conduire votre véhicule chez votre concessionnaire General Motors afin qu'il effectue les réparations nécessaires. Vous pouvez



Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320

reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO# WG178656

Printed 05/28/2024 2:08:05 PM

SERVICE ORDER CUSTOMER COPY



User C403 Page 1

Customer No	
M.A.P. Water And Sewer Services Ltd. 14303 - 116 Avenue Edmonton, AB T5M 4G2	
Home	Bus 453-6996
Cell	Today
Email	
Term Cash	

Advisor Bruce Kobylnyk	Promised 05/27/2024 5:30 PM	Tag# 4217
Shop S1	Opened 05/27/2024 10:50 AM	Location
Priority 4	Cashiered	PO # WS189

License	Odom In 135747	Odom Out 135747	In Service Date 02/05/2020	Stock No C4184217
Year 2020	Make CHEVROLET	Model SILVERADO 3500HD	Model Number CK30743	Colour NORTHSKY
Vehicle ID No 1GC4YTEY5LF184217	Selling Dealer 01	Extended Warranty GM	Delivery Date 02/05/2020	
Engine DURAMAX 6.6L TURBO-DIESEL V8,				

Request	Description	Job	CSR	Status
GENERAL	inspect and report rear pinion flange/yoke came apart note vehicle towed in	1	C403	Original
Labour	Description		Type	Amount
GENERAL	inspect and report rear pinion flange/yoke came apart note vehicle towed in		W	
Part	Description	Shp	SL	Bin
85111015	YOKE KIT	1		240403
Technician	C8233 -		Type W	Retail
Cause	Verified pinion yoke/balancer bushing separated from yoke. Requires new yoke			Price
Correction	Replaced rear yoke and pinion seal. Verified diff fluid level			Amount

Request	Description	Job	CSR	Status
DFUELFILT	DIESEL FUEL FILTER	2	C403	Original
Labour	Description		Type	Amount
DFUELFILT	DIESEL FUEL FILTER		CS	105.73
Part	Description	Shp	SL	Bin
13539108	FILTER KI	1		290207
ENVIRO	HNDL CHG	10	Type CQS	Retail
Technician	C8233 -		CQS	0.05
Cause	DIESEL FUEL FILTER			Price
Correction	DIESEL FUEL FILTER REPLACED			Amount
			Parts Total	74.22
			Labour Total	105.73
			Request Sub-total	179.95

Request	Description	Job	CSR	Status
GENERAL	INSPECT AND REPORT SES LIGHT ON	3	C403	Original
Labour	Description		Type	Amount
GENERAL	INSPECT AND REPORT SES LIGHT ON		W	
Technician	C8233 -			
Cause	P22F9 NOx sensor performance, slow response set as passed and failed in ECM. Verified no leak in induction or exhaust systems.			
Correction	IF code sets again, vehicle will require NOx sensor replacement			

Request	Description	Job	CSR	Status
FORMMPVI	Certified Service - Multipoint Vehicle Health Inspection	4	C403	Original
Labour	Description		Type	Amount
MPVI	Multipoint Vehicle Health Check as required by your Owners Manual every 12,000 km - a comprehensive assessment of your vehicle including: Tires Rotation and Inspection; Brake Inspection; Systems, Fluids & Visible Leak Inspection; Battery Condition and voltage test; Visible & Functional Inspections including: exhaust,		CS	89.95

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

TERMS
NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: 5% CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MIN. BE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____

DATE: _____

G.S.T # 7505857-3RT0001



Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320
reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO# WG178656

SERVICE ORDER CUSTOMER COPY



Printed 05/28/2024 2:08:05 PM

User C403 Page 2

Customer No
M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue
Edmonton, AB T5M 4G2

Home
Cell
Email

Bus 453-6996
Today

Term Cash

Advisor	Bruce Kobylnyk	Promised	05/27/2024 5:30 PM	Tag#	4217
Shop	S1	Opened	05/27/2024 10:50 AM	Location	
Priority	4	Cashiered		PO #	WS189
License		Odom In	135747	Odom Out	135747
Year	2020	Make	CHEVROLET	In Service Date	02/05/2020
Model		Model Number	SILVERADO 3500HD	Stock No	C4184217
Vehicle ID No	1GC4YTEY5LF184217	Selling Dealer	01	Colour	NORTHSKY
Engine	DURAMAX 6.6L TURBO-DIESEL V8,	Extended Warranty	GM	Delivery Date	02/05/2020
			WS189		

driveline, steering and suspension components, belts and hoses; Lubrication of Chassis, Weatherstripping, Door Hinges, Lock Cylinders.

Technician C8233 -
Cause RR plate bulb inop
Correction MPVI Complete.
Battery at 979CCA
Wipers good.
No leaks
Suspension good.
Front pads at 8mm
Rear pads at 7mm
Front tires at 7/32nds
Rear tires at 9/32nds

Labour Total 89.95
Request Sub-total 89.95

POSTED

Request	Description	Job	CSR	Status
BULB	Plate bulb replacement	5	C403	Approved
Labour	Description	Type	Amount	
BULB	Plate bulb replacement	CMAP	38.25	
Part	Description	Shp	SL	Bin
13503401	BULB	1		280911
STK		Type	Retail	Price
		CG13R	3.76	2.56
Technician	C8233 -			
Cause	Plate bulb replacement			
Correction	Plate bulb replaced. Verified bulb operation			
				Parts Total
				2.56
				Labour Total
				38.25
				Request Sub-total
				40.81
				Labour
				233.93
				Parts
				76.78
				Supplies
				0.00
				Sub-Total
				310.71
				GST
				15.54
				Total Invoice
				326.25

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

TERMS
NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

INDEBTNESS: I HEREBY ACKNOWLEDGE THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH. MAY BE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____

DATE: _____

G.S.T # 750585713RT0001



Certified Service

Multipoint Vehicle Health Inspection

Name: M.A.P. Water And Sewer Services Ltd. Year/Model: 2020 SILVERADO 3500HD Date 05/27/2024 11:02:

RO #: WG178656 VIN (last 8 digits): 1GC4YTEY5LF18 Odometer: 135747 Tag#: 4217 Lic. Plate #:

Service Consultant: Bruce Kobylnyk Technician: MELVIN BAYER

☒ CHECKED AND OK ☐ FUTURE ATTENTION REQUIRED ☐ IMMEDIATE MAINTENANCE/REPAIR REQUIRED

FLUID LEVEL INSPECTION

OK FILLED REQUIRES ATTENTION

☒ Windshield Washer ☐ R
☒ Inspect brake fluid level ☐ R
☒ Transmission (if equipped with dipstick) ☐ R
☒ Coolant recovery reservoir ☐ R
☒ Power steering ☐ R
☒ Engine oil ☐ R
☒ Diesel exhaust fluid (DEF) (if required) ☐ R

VISIBLE LEAK INSPECTION

☒ Fuel System (also including gas cap seating)
☒ Engine
☒ Transmission
☒ Drive axel
☒ Transfer case
☒ Engine cooling system
☒ Shocks and struts - also check operation

VISUAL AND FUNCTIONAL INSPECTIONS

☒ Belts: engine, accessory, serpentine, and/or V-drive
☒ Engine air cleaner filter
☒ Gas struts on hood or hatch for wear and hold open ability
☒ Suspension components
☒ Steering components and steering linkage
☒ CV drive axel boots or driveshafts and U-joints
☒ Exhaust system components and nearby heat shield
☒ Passenger compartment air filters
☒ Starter switch operation
☒ Ignition control operation
☒ Automatic transmission park mechanism holding ability
☒ Automatic transmission shift lock control functions
☒ Accelerator pedal damage, high effort or binding
☒ Safety belt reminder lights
☒ Safety belts, buckles, latches, plates & anchors

TIRE INSPECTION

☒ 6/32 or Greater ☐ 5/32 to 4/32 ☐ 3/32 or Less
LF ☒ Y ☒ R Set to 60 PSI RF ☒ Y ☒ R Set to 60 PSI
Tread Depth: 7/32 Tread Depth: 7/32
LR ☒ Y ☒ R Set to 80 PSI RR ☒ Y ☒ R Set to 80 PSI
Tread Depth: 9/32 Tread Depth: 9/32
☐ Tires Rotated ☐ Alignment Needed
☐ Balance Needed ☐ Wheel Lug Nut Check

BRAKE INSPECTION

☒ 6mm or Greater ☐ 5mm - 4 mm ☐ 3mm or Less
LF ☒ Y ☒ R Pad RF ☒ Y ☒ R Pad
Actual 8 mm Actual 8 mm
☒ Y ☒ R Rotor ☒ Y ☒ R Rotor
LR ☒ Y ☒ R Pad RR ☒ Y ☒ R Pad
Actual 7 mm Actual 7 mm
☒ Y ☒ R Rotor ☒ Y ☒ R Rotor
☐ Caliper Service Needed
☒ Brake system (including lines and hoses)
☒ Parking Brake

BATTERY INSPECTION

☒ Battery condition Measured CCA
☒ Battery cables & connections Spec 979 CCA

Malfunction Indicator Lamp

☐ Check Engine Lamp ☐ Warning Message ☐ Other

Additional Notes or Comments: