D15-2
DEC

QTY	PART NO. AND DESCRIPTION
2	308-9679 - fuel filter
1	326-1643 -fuel filter

NORTHPOINT ENTERPRISE LTD.

WORK ORDER NO. 2522

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK COMPLETED BY: Dylan			DATE Mar. 12. 2026
UNIT # G10	MAKE CAT	HOURS 14822	KMS

JOB DESCRIPTION

- Change fuel filters

JDC Print Shop 780-836-3810

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

WORK ORDER NO. 2521

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK COMPLETED BY: Dylan			DATE Mar. 11. 2026
UNIT # G10	MAKE CAT	HOURS 14809	KMS

JOB DESCRIPTION

- found rubbed through wires at articulation joint
- repair wires. hookup laptop and retest to see if grader will stall again

JDC Print Shop 780-836-3810

QTY	PART NO. AND DESCRIPTION
32L	10W40 oil
1	IR-1808 oil filter
3L	coolant
1	H3 24V light bulb

NORTHPOINT ENTERPRISE LTD.

WORK ORDER NO. 2517

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK COMPLETED BY: Dylan			DATE: Mar. 4. 2026
UNIT # G10	MAKE CAT	HOURS 14753	KMS

JOB DESCRIPTION

- change engine oil, oil filters
- top up coolant
- replace RR cab light bulb
- blow out air filters
- check oil levels

JDC Print Shop 780-836-3810

QTY	PART NO. AND DESCRIPTION
1	EN1-2935535 - SENSOR

NORTHPOINT ENTERPRISE LTD.

WORK ORDER NO. 2608

PO Box 930 Manning, AB T0H 2M0
Phone:780-836-0611 780-626-5753

WORK COMPLETED BY: Zeljko			DATE FEB. 18. 2026
UNIT # G10	MAKE CAT	HOURS 14585	KMS

JOB DESCRIPTION

- REPLACE OIL PRESSURE SENSOR
- REPLACE O-RING ON RH STEERING HOSE

780 Design Co

QTY	PART NO. AND DESCRIPTION
1	-6 ORF O'Ring.
3 gal	Hyd. Oil,

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK ORDER NO. 2177

WORK COMPLETED BY: Don Boyles			DATE Jan 2/26
UNIT # G10	MAKE Cat	HOURS 14479	KMS

JOB DESCRIPTION

Repair Hydraulic leak at steering cylinder.
Top up Hydraulics.
Remove shim from circle drive as moldboard was kicking out on operator.

JDC Print Shop 780-836-3810

QTY	PART NO. AND DESCRIPTION
4	-2656722 - COVER
2	2534646 - PLATE AS
4	2436652 - COVER
2	2761319 - WEAR STRIP
2	2761317 - WEAR STRIP
2	526-6469 - COLLAR
12	1900627 - SHIM
2	4661604 - SPACER
8	467-5183 - BEARING - SLEE
2	PINS
6	20R 5036 Reman Injectors
6	20R 4517 Reman Quills.
1	4M0189 O'Rings.
1	260-0113 Valve Cover Gasket
1	637-2653 wiring harness
1	349-4927 Hyd. hose
1	328-3655 TRANS Filter
1	338-3540 Hyd. Filter
2	308-9679 Fuel Filters
1	326-1643 Fuel Filter
1	1R-1808 oil Filter
5	282-3736 studs 2 needed with
1	6V5843 Bolt 5 New Inj harness
5	H324 bulbs

NORTHPOINT ENTERPRISE LTD.

WORK ORDER NO. 2262

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK COMPLETED BY: Thomas Dam.			DATE Dec 19/25
UNIT # G10	MAKE Cat	HOURS 14392	KMS

JOB DESCRIPTION

Change LH Blade lift hose
Change LH orings on Steer hose
Change hose on blade roll
- REPLACE BOTTOM AND TOP WEAR STRIP
- REPLACE SIDE WEAR STRIP COVER PLATES
- PUT BLADE BACK ON THE GRADER
- REPLACE THE SIDE PINS
- Replace 6 Injectors + Quills.
- Replace O'Ring on LH accessory drive
- Replace Injector wiring harness
- Replace 2 hoses over Drive shaft 1 cat 1 from Venture.
Change TRANS oil and Filter
change Hyd. Filter
change Engine oil + Filter
Change Fuel Filters.
check tire pressures LH Front down 5psi LH Rear Tandem down 25psi
Fit 3 light bulbs
clean out Rads
Grease.
Checked Tandem levels RH over Full, Parts ordered will bring back to Regi

JDC Print Shop 780-836-3810

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0745

WORK COMPLETED BY: Thomas			DATE Feb 17 25
UNIT # G 16	MAKE Cat	HOURS 13876	KMS

JOB DESCRIPTION

Chang both blade side shift hoses
Change circle side shift hose

QTY	PART NO. AND DESCRIPTION
1	20R 5036 Injector
1	20R 4517 Quill

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0666

WORK COMPLETED BY: Dan Boyles			DATE Jan 17/25
UNIT # G10	MAKE Cat	HOURS 13557	KMS

JOB DESCRIPTION

Diagnose Faulty injector in cyl # 5.
Replace Injector
check Valve lash while Top part is OFF.

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0693

WORK COMPLETED BY: Thomas			DATE Jan 11 25
UNIT # G10	MAKE Cat	HOURS 13538	KMS

JOB DESCRIPTION

Change Drive Pinion for circle
Change Duo cone seal
Change all sealing o rings
Shim the Clutches
Add 7L of duratran to gear box

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0661

WORK COMPLETED BY: Dan			DATE Jan 8/25
UNIT # G10	MAKE Cat	HOURS 13486	KMS

JOB DESCRIPTION

Put D.S. Front Fender back on.
Add Gear oil To P.S. Front wheel (Seal seeping slowly)

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK ORDER NO. 1800

WORK COMPLETED BY: Thomas			DATE Dec 30 24
UNIT # G10	MAKE Cat	HOURS 13307	KMS

JOB DESCRIPTION

Change tire front right tandem torque to 350
Lift dozer because of broken pan

QTY	PART NO. AND DESCRIPTION
84	BR4-348-9051-W6X ice picks

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK ORDER NO. 1786

WORK COMPLETED BY: DYLAN			DATE Dec. 22. 2024
UNIT # G10	MAKE CAT	HOURS 13340	KMS

JOB DESCRIPTION

- Replace Ice Picks

QTY	PART NO. AND DESCRIPTION
1	1R1808 oil Filter
32L	low 40 engine oil.

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1092

WORK COMPLETED BY: Dan Boyles			DATE Dec 17/24
UNIT # G-10	MAKE Cat	HOURS 13286	KMS

JOB DESCRIPTION

Change engine oil + Filter
check unit over.

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1587

WORK COMPLETED BY: Dan Boyles			DATE Dec 12/24
UNIT # 610	MAKE Cat	HOURS 13218	KMS

JOB DESCRIPTION

Diagnose steering system malfunction,
Alarm caused by 8V sensor circuit voltage too high. Fault was no longer active and could not duplicate the error.

QTY	PART NO. AND DESCRIPTION
1	H4-24V - LIGHT BULB

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK ORDER NO. 1670

WORK COMPLETED BY: Zeljko			DATE OCT. 12. 2024
UNIT # G10	MAKE CAT	HOURS 12908	KMS

JOB DESCRIPTION

- REPLACING HEADLIGHT BULB LH
- TIGHT ALL BOLTS ON PICK BLADES
- CHECK ALL LIQUIDS
- PUT BACK ON FRONT RH FENDER (WAS OFF)
- TIGHT UP HYDRAULIC HOSES
- CHECK ALL LIGHTS
- REPLACING ONE PICK
- ADD 7LIT HYDRAULIC OIL DURATRAN XL
- REPLACING SPILL KIT
- PUT BACK ON SERVICED FIRE EXTINGUISHER
- CHECK OIL LEVELS

QTY	PART NO. AND DESCRIPTION
1	255-4646 Shim Plate
1	276-1318 Shim
1	176-1319 Shim
1	3330960-00 Shim
2 16L	duratran XL
2	EM1-5P3863 O-ring

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK ORDER NO. 1618

WORK COMPLETED BY:			DATE July 23/24
UNIT # G10	MAKE CAT	HOURS	KMS

JOB DESCRIPTION

- Replace LH upper blade Shims
- replace 1 lower Shim and set circle
- remove Stump pan and wash underneath
- top up hydraulic oil
- grease grader
- remove top cover to check for leaks
- fix transmission leaks and top up oil
- install Stump Pan and top cover

QTY	PART NO. AND DESCRIPTION
1	H3 24V bulb
1	IR-1808 oil filter
1	326-1644 fuel filter
2	308-9679 fuel filter
32L	10W-40 oil
1	577-1435 air filter
1	331-8108 air filter
1	328-3655 transmission filter

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK ORDER NO. 1610

WORK COMPLETED BY: Dylan | DATE JULY.23

UNIT # G10 | MAKE CAT | HOURS 12903 | KMS

JOB DESCRIPTION

- Install new wing safety chain
- replace LH side light bulb
- replace LH cab light lens
- change oil and fuel filters
- replace air filters
- check cabin air filters
- replace steering/transmission filters
- check tire pressures
- replace sideshift cylinder cups
- replace RF hub cover plate
- replace cups/reshim lift cylinders
- reshim top plates on circle

Parts

1) 389-1076 steering filter
1) 338-3540 hydraulic filter
6) 2795267 cups ||||
1) 2J-8163 o-ring
1) 5T-0906 cover
4) 75W90 oil

NORTHPOINT ENTERPRISE LTD.

EQUIPMENT INSPECTION

50 Point Inspection

PM

☐ 250

☑ 1000

Date: JULY 23/24

Unit Number: G10

Hours: 12903 Kms: _____

Completed By: D YIAN

P *Indicates Satisfactory* **F** *Indicates Not Satisfactory* **N/A** *indicates Not Applicable*

P	F	ITEM	SERVICED
		GENERAL WALK AROUND	
✓		Grab Bars and Steps (Loose/Missing)	☐
✓		Sheet Metal (Damaged/Loose)	☐
✓		Glass & Mirrors (Missing/Broken/Loose)	☐
✓		Fender/Bumpers (Damaged/Loose)	☐
✓		Frame/Car Body/Rops/Mounting Bolts	☐
✓		Check Grease Nipples	☐
		WORK EQUIPMENT	
✓		Boom Arm, Push Arms	☑
✓		Get Condition (Worn/Missing) Pin/Bushing	☐
✓		Cylinders (Leaking, Damaged)	☐
✓		Cutting Edgewear	☐
		Other:	☐
		PRE-STARTUP	
✓		Engine Oil Level	☑
✓		Transmission/PT Oil Level	☐
		Hydraulic Oil Level	☑
✓		Final Drive/Differential Oil Levels	☐
✓		Swing Machinery Oil Level	☐
✓		Coolant Level	☑
		CAR INTERIOR	
		Monitor Panel Screen (Scratched/Broken)	☐
		Record Error Codes From Monitor Panel:	
✓		Rear Camera Functionality	☑
✓		Cab Lights, Bulbs,Fuses and Switches	☑
✓		Seat Operation and Safety Belt	☐
✓		Fire Extinguisher (Available/Good Charge)	☐
✓		Wiper Function and Blade Condition	☐
✓		Windows: Latches and Glass (Missing/Function)	☐
✓		Doors: Latches, Strikers, Hold Backs	☐
		AC/Heater Operation and Louvers	☐
✓		Horn and Back up Alarm (Function)	☐

P	F	ITEM	SERVICED
		START MACHINE	
✓		Lever Control Action & Accumulation	☐
✓		Ripper or Work Equipment	☐
		Boom (Function, Damaged) N/A	☐
		Arm (Function, Damaged) N/A	☐
		Bucket (Function, Damaged) N/A	☐
✓		Lift (Function, Damaged)	☑
✓		Tilt (Function, Damaged)	☑
		Dump (Function, Damaged) N/A	☐
✓		Parking Break (Function)	☐
✓		Brake Accumulation/Pedal Operation	☐
✓		Head Lamps (Function/Missing/Broken)	☑
		UNDERCARRIAGE	
		Bushings	☐
		Links N/A	☐
		Track Shoes	☐
		POWERTRAIN	
✓		Hoses (Leaking/Worn/Damaged)	☑
✓		Belts (Noisy, Worn, Missing)	☐
✓		Engine (Leaks)	☐
✓		Exhaust/Turbo (Leaks/Smoking)	☐
		Doser Piping (Lakes/Damaged) N/A	☐
		EGR Assembly (Leaks/Connected) N/A	☐
		DPF Assembly and Heating Shielding N/A	☐
		SCR System & Adblue/DEF Tank (Leaks) N/A	☐
✓		Transmission/Cooler and T/C (Leaks)	☐
		Final Drives or Differentials (Leaks)	☐
✓		Hydraulic Cooler	☐
✓		Radiator /Radiator Cap	☐
✓		Fan Motor/Blade (Leaks/Damaged)	☐
✓		Battery Electrolyte Level	☐
✓		Fuel Tank Cap (Missing/Leaking)	☐
✓		Air Filter (Plugged/Missing)	☑

During this inspection, were the defective items repaired? YES _____ NO _____

Additional Comments: _____

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1077

WORK COMPLETED BY: thomas			DATE Feb 27
UNIT # G10	MAKE Cat	HOURS ~~12~~ 1265	KMS

JOB DESCRIPTION

Change blower motor
Change cab filters

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1068

WORK COMPLETED BY: Thomas			DATE Feb 21 24
UNIT # G10	MAKE Cat	HOURS 12587	KMS

JOB DESCRIPTION

top up front ~~left~~ right steer hub
Changed lights
Changed outter air filter

QTY	PART NO. AND DESCRIPTION
1	oil Filter
1	Fuel Filter
1	Fuel Filter.

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1566

WORK COMPLETED BY: Dan Boyles			DATE Feb 17/24
UNIT # G10	MAKE Cat	HOURS	KMS

JOB DESCRIPTION

Do Service
change Oil + Filter
change Fuel Filters.

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1052

WORK COMPLETED BY: Thomas			DATE Feb 8 24
UNIT # G10	MAKE cat	HOURS 12403	KMS

JOB DESCRIPTION

Change air filter
Change lights
Inspect

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1047

WORK COMPLETED BY: Thomas			DATE Feb 5 24
UNIT # G10	MAKE cat	HOURS 12345	KMS

JOB DESCRIPTION

Put on shim cover plate
Change light

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1023

WORK COMPLETED BY: Dan Boyles			DATE Feb 4/24
UNIT # G10	MAKE Cat	HOURS 12328	KMS

JOB DESCRIPTION

Put blade shim Back in place.

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1043

WORK COMPLETED BY: Thomas			DATE Feb 2 24
UNIT # G10	MAKE Cat	HOURS 12 304	KMS

JOB DESCRIPTION

replace and set side shift shims
Change lights
Weld mulboard

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1031

WORK COMPLETED BY: Dan Boyles			DATE Jan 23/24
UNIT # G10	MAKE Cat	HOURS 10164	KMS

JOB DESCRIPTION

Replace O'Ring in hose at power steering Cylinder.

QTY	PART NO. AND DESCRIPTION
1	IR1808 oil Filter.
32L	Engine oil
8L	DuraTran

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1324

WORK COMPLETED BY: Dan + Zelko			DATE January 18/24
UNIT # G10	MAKE Cat	HOURS 12072	KMS

JOB DESCRIPTION

Change oil and Filter.
Add 8L To Transmission plus Dye.
Put air in Right Front drive tire
Reattach Right side Rear work light.

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0995

WORK COMPLETED BY: Thomas			DATE Dec 28 23
UNIT # G10	MAKE cat	HOURS 11877	KMS

JOB DESCRIPTION

exracted fender bolts
tightened wiper



QTY	PART NO. AND DESCRIPTION
1	H4 24v Bulb

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0977

WORK COMPLETED BY: Thomas			DATE Dec 18 23
UNIT # G 10	MAKE Cat	HOURS 11781	KMS

JOB DESCRIPTION

Change grease nipple for wheal lean pin
Change front headlight

EQUIPMENT INSPECTION

NORTHPOINT ENTERPRISE LTD.

50 Point Inspection

PM

☐ 250

☑ 1000

Date: Oct 25/23

Unit Number: G-10

Hours: 11695 Kms: _____

Completed By: Dan Boyles

P *Indicates Satisfactory* **F** *Indicates Not Satisfactory* **N/A** *indicates Not Applicable*

P	F	ITEM	SERVICED
		GENERAL WALK AROUND	
		Grab Bars and Steps (Loose/Missing)	☑
		Sheet Metal (Damaged/Loose)	☑
		Glass & Mirrors (Missing/Broken/Loose)	☑
		Fender/Bumpers (Damaged/Loose)	☑
		Frame/Car Body/Rops/Mounting Bolts	☑
		Check Grease Nipples	☑
		WORK EQUIPMENT	
		Boom Arm, Push Arms	☐
		Get Condition (Worn/Missing) Pin/Bushing	☑
		Cylinders (Leaking, Damaged)	☑
		Cutting Edgewear	☑
		Other:	☐
		PRE-STARTUP	
		Engine Oil Level	☑
		Transmission/PT Oil Level	☑
		Hydraulic Oil Level	☑
		Final Drive/Differential Oil Levels	☑
		~~Swing Machinery~~ Circle Oil Level	☑
		Coolant Level	☑
		CAR INTERIOR	
		Monitor Panel Screen (Scratched/Broken)	☑
		Record Error Codes From Monitor Panel:	
		Rear Camera Functionality	☑
		Cab Lights, Bulbs,Fuses and Switches	☑
		Seat Operation and Safety Belt	☑
		Fire Extinguisher (Available/Good Charge)	☑
		Wiper Function and Blade Condition	☑
		Windows: Latches and Glass (Missing/Function)	☑
		Doors: Latches, Strikers, Hold Backs	☑
		AC/Heater Operation and Louvers	☑
		Horn and Back up Alarm (Function)	☑

P	F	ITEM	SERVICED
		START MACHINE	
		Lever Control Action & Accumulation	☑
		Ripper or Work Equipment	☑
		Boom (Function, Damaged)	☐
		Arm (Function, Damaged)	☐
		Bucket (Function, Damaged)	☐
		Lift (Function, Damaged)	☑
		Tilt (Function, Damaged)	☑
		Dump (Function, Damaged)	☐
		Parking Break (Function)	☑
		Brake Accumulation/Pedal Operation	☑
		Head Lamps (Function/Missing/Broken)	☑
		UNDERCARRIAGE	
		Bushings	☐
		Links	☐
		Track Shoes	☐
		POWERTRAIN	
		Hoses (Leaking/Worn/Damaged)	☑
		Belts (Noisy, Worn, Missing)	☑
		Engine (Leaks)	☑
		Exhaust/Turbo (Leaks/Smoking)	☑
		Doser Piping (Lakes/Damaged)	☑
		EGR Assembly (Leaks/Connected)	☑
		DPF Assembly and Heating Shielding	☑
		SCR System & Adblue/DEF Tank (Leaks)	☐
		Transmission/Cooler and T/C (Leaks)	☑
		Final Drives or Differentials (Leaks)	☑
		Hydraulic Cooler	☑
		Radiator /Radiator Cap	☑
		Fan Motor/Blade (Leaks/Damaged)	☑
		Battery Electrolyte Level	☑
		Fuel Tank Cap (Missing/Leaking)	☑
		Air Filter (Plugged/Missing)	☑

During this inspection, were the defective items repaired? YES ✓ NO

Additional Comments: small leaks at diff on both sides.

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1167

WORK COMPLETED BY: Thomas			DATE June 22 2023
UNIT # G10	MAKE Cat	HOURS 11472	KMS

JOB DESCRIPTION

Charge a/c 3.5lbs Held a 24 in of Hg vaccum/ held and balanced out at 67 PSi 0°C air blowing
Tightened hose clamps for heater topped off coolant
Checked fluids

QTY	PART NO. AND DESCRIPTION
1	FR 1808 oil filter
1	326-1644 fuel filter
2	308 9679 fuel filter
1	245 6375

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1158

WORK COMPLETED BY: Thomas			DATE June 6 2023
UNIT # G10	MAKE Cat	HOURS 11411	KMS

JOB DESCRIPTION

Change Oil + filter
Change fuel filters
Install new Blades
Checked for braze + circulepity
Checked all fluids + circle gear box
Topped off coolant
Blew out rads
Checkes front Belt
Installed GPS
Changed air filter

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 1131

WORK COMPLETED BY: Dan Boyles			DATE May 19/23
UNIT # 610	MAKE Cat	HOURS	KMS

JOB DESCRIPTION

Go to Km 114.5 on chin and Tighten Fuel Fitting at common Rail pump.

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0966

WORK COMPLETED BY: Dan Boyles			DATE 9 Mar 17/23
UNIT # G-10	MAKE Cat	HOURS 11197.3	KMS

JOB DESCRIPTION

Tighten Bolts on Pick board.

QTY	PART NO. AND DESCRIPTION
1	H3-24 Light bulb.

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0949

WORK COMPLETED BY: Dan Boyles			DATE Mar 12/23
UNIT # G10	MAKE Cat	HOURS 11096.5	KMS

JOB DESCRIPTION

Change Bulb in work light

QTY	PART NO. AND DESCRIPTION
1	IR1808 oil Filter
1	326-1644 Fuel Filter
2	308-9679 Fuel Filter
32L	10W40 Engine oil
20L	TRANS oil
3	H3-24 Bulbs.

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0944

WORK COMPLETED BY: Day + Thomas + Harrison			DATE Mar 8/23
UNIT # G10	MAKE Cat	HOURS 11012.4	KMS

JOB DESCRIPTION

Change oil, oil Filter, and Fuel Filter. Add 20L To get TRANS to ~~Expired~~ Top of operating Range. Fix Hyd. leak at Valve Bank. Replace Bulbs in 3 work lights.

QTY	PART NO. AND DESCRIPTION
1	577-1435 air filter
1 liter	of Dura. XL
1	H3 24V

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0937

WORK COMPLETED BY: Harry			DATE Mar. 6
UNIT # 610	MAKE Cat	HOURS 10984.9	KMS

JOB DESCRIPTION

Stopped to see Rob at 106 and changed his air filter / light checked circle drive fluid topped up.

QTY	PART NO. AND DESCRIPTION
1	RM100160 - Alternator.

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0899

WORK COMPLETED BY: Dan Bowles			DATE Feb 22/23
UNIT # G 10	MAKE John Deere	HOURS 12180.9	KMS

JOB DESCRIPTION

Go and Replace the Alternator I Put on Yesterday because pulley came loose. Remove Flat Tire.

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0633

WORK COMPLETED BY: Thomas			DATE Feb 11 2023
UNIT # G10	MAKE Cat	HOURS 10757	KMS

JOB DESCRIPTION

Replaced busted fuel line

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0842

WORK COMPLETED BY: Thomas			DATE Feb 7 2023
UNIT #G-10	MAKE Cat	HOURS 10750	KMS

JOB DESCRIPTION

Tightened bolts for circle and replaced 2

QTY	PART NO. AND DESCRIPTION
1	IR1808 oil Filter
2	308-9679 Fuel Filters
1	326-1644 Fuel Filter
32L	Engine oil
4L	Coolant
1	H3-24 Bulb
1	H4-24 Bulb

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0832

WORK COMPLETED BY: Dan Boyles.			DATE Feb 2/23
UNIT # G10	MAKE Cat	HOURS 10693	KMS

JOB DESCRIPTION

Change Engine oil, oil Filter, and Fuel Filters. Replace Left Side Headlight Bulb and Right side work light. Adjust shims on circle. Help change picks on mulboard.

0835

QTY	PART NO. AND DESCRIPTION

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0804

WORK COMPLETED BY: Thomas			DATE Jan 27 2023
UNIT # G10	MAKE Cat	HOURS	KMS

JOB DESCRIPTION

replaced snow wing sheer pin ~~tightened a few~~
tightened a few bolts on the blade.

JO DOT COM - 780-836-3810

QTY	PART NO. AND DESCRIPTION
4	279-5267
1	H3-24V

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0784

WORK COMPLETED BY: Thomas			DATE Jan 19 2023
UNIT # G10	MAKE cat	HOURS 10 518	KMS

JOB DESCRIPTION

Changed blade lift cups
Changed 1 light

QTY	PART NO. AND DESCRIPTION
1	1R-1808
1	326-1643
2	308-9679

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0600

WORK COMPLETED BY: Thomas			DATE Jan 6
UNIT # G10	MAKE Cat	HOURS 10372	KMS

JOB DESCRIPTION

Changed oil + filter
Changed all 3 fuel filters
Changed outter air filters
Checked fluids
Put cotter pin in wing blade pin

QTY	PART NO. AND DESCRIPTION
1	1 INCH - 14 FOOT
1	3/8 - 14 FOOT
1	5/8 - 16 FOOT

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0517

WORK COMPLETED BY: Zeljko			DATE NOV. 28. 2022
UNIT # G10	MAKE CAT	HOURS 10047.2	KMS

JOB DESCRIPTION

REPLACING THREE HOSES WHAT GOING THROUGH THE NECK TO THE BACK END

CHECK CIRCLE DRIVE OIL

CHECK FOR OTHER LEAKS

EQUIPMENT INSPECTION

NORTHPOINT ENTERPRISE LTD.

50 Point Inspection

PM

☐ 250

☐ 1000

Date: Nov 8 2022

Unit Number: G10

Hours: 10,022 Kms: _____

Completed By: Dan + Thomas

P *Indicates Satisfactory* **F** *Indicates Not Satisfactory* **N/A** *indicates Not Applicable*

P	F	ITEM	SERVICED
		GENERAL WALK AROUND	
P		Grab Bars and Steps (Loose/Missing)	☑
P		Sheet Metal (Damaged/Loose)	☑
P		Glass & Mirrors (Missing/Broken/Loose)	☑
P		Fender/Bumpers (Damaged/Loose)	☑
P		Frame/Car Body/Rops/Mounting Bolts	☑
P		Check Grease Nipples	☑
		WORK EQUIPMENT	
N/a		Boom Arm, Push Arms	☐
N/a		Get Condition (Worn/Missing) Pin/Bushing	☐
P		Cylinders (Leaking, Damaged)	☑
P		Cutting Edgewear	☑
		Other:	☐
		PRE-STARTUP	
P		Engine Oil Level	☑
P		Transmission/PT Oil Level	☑
P		Hydraulic Oil Level	☑
P		Final Drive/Differential Oil Levels	☑
P		Swing Machinery Oil Level circle	☑
	F	Coolant Level	☑
		CAR INTERIOR	
P		Monitor Panel Screen (Scratched/Broken)	☐
		Record Error Codes From Monitor Panel:	
P		Rear Camera Functionality	N/A
P		Cab Lights, Bulbs, Fuses and Switches	☑
P		Seat Operation and Safety Belt	☑
P		Fire Extinguisher (Available/Good Charge)	☑
P		Wiper Function and Blade Condition	☑
P		Windows: Latches and Glass (Missing/Function)	☑
P		Doors: Latches, Strikers, Hold Backs	☑
P		AC/Heater Operation and Louvers	☐
	F	Horn and Back up Alarm (Function)	☑

P	F	ITEM	SERVICED
		START MACHINE	
N/a		Lever Control Action & Accumulation	☐
P		Ripper or Work Equipment	☐
N/a		Boom (Function, Damaged)	☐
N/a		Arm (Function, Damaged)	☐
N/a		Bucket (Function, Damaged)	☐
P		Lift (Function, Damaged)	☐
P		Tilt (Function, Damaged)	☐
P		Dump (Function, Damaged)	☐
P		Parking Break (Function)	☐
N/a		Brake Accumulation/Pedal Operation	☐
P		Head Lamps (Function/Missing/Broken)	☐
		UNDERCARRIAGE	
N/a		Bushings	☐
N/a		Links	☐
N/a		Track Shoes	☐
		POWERTRAIN	
	F	Hoses (Leaking/Worn/Damaged)	☑
P		Belts (Noisy, Worn, Missing)	☐
P		Engine (Leaks)	☐
P		Exhaust/Turbo (Leaks/Smoking)	☐
N/a		Doser Piping (Lakes/Damaged)	☐
N/a		EGR Assembly (Leaks/Connected)	☐
N/a		DPF Assembly and Heating Shielding	☐
N/a		SCR System & Adblue/DEF Tank (Leaks)	☐
P		Transmission/Cooler and T/C (Leaks)	☐
P		Final Drives or Differentials (Leaks)	☐
P		Hydraulic Cooler	☐
P		Radiator /Radiator Cap	☐
P		Fan Motor/Blade (Leaks/Damaged)	☐
P		Battery Electrolyte Level	☐
P		Fuel Tank Cap (Missing/Leaking)	☐
	F	Air Filter (Plugged/Missing)	☑

During this inspection, were the defective items repaired? YES ✓ NO ____

Additional Comments: _____

QTY	PART NO. AND DESCRIPTION
1	331-8108 A/F Inner
1	577-1435 A/F outer.
1	H3 24V Bulb
3	1/4 NPT Grease Nipple

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0491

WORK COMPLETED BY: Dan B. Thomas			DATE Nov 8
UNIT #G10	MAKE Cat	HOURS 10,022.3	KMS

JOB DESCRIPTION

Grease
Check Fluid levels
Change Air Filters.
Replace mounting bolts on Hyd. Valve Body.
Locate Broken Hyd. line.
Fix coolant leak on top of the motor
Checked belt and pulleys
Replace Hyd. line
Replace Bonnet
Washed
Changed all picks
Changed side shift Shims RH Side
Changed cups RH Side
Tightened Side Shift Sims LH Side
Mounted Snow Wing/greased
hose Wrapped on Snow wing hyd line
Changed burnt out work lights
fixed Broken fender bolts
Checked cab air filter

QTY	PART NO. AND DESCRIPTION
2	4 FOOT BLADES
10	BOLTS FOR BLADES

NORTHPOINT ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK ORDER NO. 0462

Zeljko

G

WORK COMPLETED BY: Zeljko			DATE SEP. 08. 2022
UNIT # G10	MAKE CAT	HOURS 9784.6	KMS

JOB DESCRIPTION

- REAPLACE TWO END BLADES
- PUT BACK EXTENSION ON THE BLADE
- CHECK ALL LIGHTS
- REAPLACE TWO LIGHT BULBS ON THE CAB & FLUD LIGHT
- CHECK FINAL DRIVE OIL
- CHECK FRONT WHEEL HUB OIL
- CHECK FRONT END
- ADJUST SHIMS ON BLADE

RE-TORQUE WHEELS

GREASING

TIGHT BERINGS ON CIRCLE DRIVE

NORTHPOINT ENTERPRISE LTD.
780-836-9341
MANNING, AB

WORK ORDER NO. 0351

Jelco
2 HRS

QTY	PART NO. AND DESCRIPTION	PRICE
1	326-1643 - WATER SEPARATOR	
2	FF5319 - FUEL FILTERS	
1	LFG91A - OIL FILTER	
1	328-3655 - TRANSMISSION FILTER	
	TOTAL PARTS	
POS	TIRES & WHEELS	

DATE	UNIT NO.	MAKE	MILEAGE	HOUR METER
AUG. 30. 2022	G 10	CAT		9776.7

JOB DESCRIPTION

- CHANGING ENGINE OIL
- CHANGING OIL FILTER
- CHANGING FUEL FILTERS
- CHANGING TRANSMISSION FILTER
- WASH THE RAD
- BLOW OUT AIR FILTER

Valley Printers #14010

WORK ORDER NO. 0402

NORTHPOINT ENTERPRISE LTD.

780-836-9341

MANNING, AB

Thomas

QTY	PART NO. AND DESCRIPTION	PRICE
1	Coolant elbow hose	
	333-6504/ From G7	
	New on order	
4ft	# 1/2 Coolant hose	
32L	Coolant	
	TOTAL PARTS	
POS	TIRES & WHEELS	

DATE	UNIT NO.	MAKE	MILEAGE	HOUR METER
Jul 6 2022	G10	Cat		9587

JOB DESCRIPTION

Changed upper Block coolant hose
Changed coolant hose from reservoir to block
Pressure tested System at 15 PSI Pressure
didnt budge for 10 minutes
refilled coolant reservoir
Blew out rad and outter air filter
Blew out cab filter

Valley Printers #14010

NORTHPOINT ENTERPRISE LTD.

SAFETY MANAGEMENT SYSTEM
CHECKLIST
PREVENTATIVE MAINTENANCE VEHICLE INSPECTION

Functional Area: **ALL**

Document: **CHK-013**

SECTION 1 GENERAL INFORMATION	
Unit Number: C01	**Date:** APRIL, 14. 2022
Inspector: Jeyro	**Work Order #:** 0415

SECTION 2- SPECIFIC REQUIREMENTS

STATUS:	N/A Not Applicable to This Unit P: Passes A: Added (Show Number)	M: Passed but Maintenance Required R: Rejected- Replacement Necessary

	ENGINE	STATUS
1	Engine Oil ___Litres	P
2	Radiator	P
3	Radiator Hoses	P
4	Drive Belt	P
5	Air Filter	P
6	Brake Adjustment	P
7	Brake Fluid ___Litres	N/A
8	Transmission	P
9	Transmission Fluid ___Litres	
10	Power Steering Fluid ___Litres	N/A
	START ENGINE	**STATUS**
11	Parking Brake (Micro-lock)	P
12	Oil Pressure (Gauge/light)	
13	Temperature	P
14	Fuel Level	P
15	Back-Up Alarm	P
16	Horn	P
	INSIDE VEHICLE	**STATUS**
17	Cab Clean	P
18	Instrument Panel	P
19	Glass (Broken or Cracked)	M
20	Wipers & Washer	M
21	Heater/Defrost	
22	Mirrors (Inside & Out)	
23	Steering (Excess Play)	
24	Fire Extinguisher	P
25	Hazard Warning Kit	

	REAR OF VEHICLE	STATUS
26	Tail Lights	N/A
27	Brake Lights	N/A
28	Turn Signals	N/A
29	4 Way Flashers	N/A
30	Clearance/Marker Lights	N/A
31	Reflectors	N/A
32	Mud Flaps	N/A
33	License Plate	N/A
34	Compartments Closed/Locked	M
35	Dents/Scratches	M
	OUTSIDE FRONT OF VEHICLE	**STATUS**
36	Headlights	P
37	Clearance/Marker Lights	N/A
38	Turn Signals	N/A
39	4 Way Flashers	N/A
40	Fog Lights	N/A
41	Dents/Scratches	M
	OTHER	**STATUS**
42	Front Differential	/
43	Rear Differential	
44	Front Steering Hub Oils (80/90 Synthetic Oil)	
	GREASING	**STATUS**
45	Driveline	N/A
46	Rollers	P
47	Winch	P
	TORQUE WHEELS	**STATUS**
48	Torque Right Side Front	N/A
49	Torque Right Side Rear	N/A
50	Torque Left Side Front	N/A
51	Torque Left Side Rear	N/A

Original Issued – August 30, 2016
PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED.
© Strategic HSE Systems Inc.

LEFT SIDE OF VEHICLE		STATUS
52	Fuel Tank Cap On	
53	Side Marker Lights	
54	Reflectors	
55	Tires & Wheels	
56	Lugs Tight	
57	Compartments Closed	
58	Dents/Scratches	
RIGHT SIDE OF VEHICLE		**STATUS**
59	Fuel Tank Cap On	
60	Side Marker Lights	
61	Reflectors	
62	Tires & Wheels	
63	Lugs Tight	
64	Compartments Closed	
65	Dents/Scratches	

MISCELLANEOUS		STATUS
66	Spare Tire	
67	Tire Jack & Wrench	
68	Insurance & Registration	

SECTION 3 COMMENTS- CORRECTIVE ACTION MEASURES/PLAN

Comments/Action (Include # identifier)	Due Date	By Whom	Date Done

Inspection Conducted by (Print):	Management Review Conducted by (Print):
Signature:	Signature:

Original Issued – August 30, 2016
PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED.
© Strategic HSE Systems Inc.

QTY	PART NO. AND DESCRIPTION	PRICE
6	3T3434 - RUBER PLUG	
1	8C3089 - SEAL - O - RING	
1	9Y-6089 - GUSCAT	
2	19.1 MM HOSES	
	TOTAL PARTS	
POS	TIRES & WHEELS	

NORTHPOINT ENTERPRISE LTD
780-836-9341
MANNING, AB

WORK ORDER NO. 0416

Jeff 4.

DATE	UNIT NO.	MAKE	MILEAGE	HOUR METER
APRIL. 21. 2022	G10	CAT		9389

JOB DESCRIPTION

- CHANGING RUBER PLUGS, O-RING AND GUSCAT ON THE STARTER
- APRIL. 25. 2022
REPLACE TWO TRANSMISSION COOLANT HOSES

Valley Printers #14010

NORTHPOINT ENTERPRISE LTD.

SAFETY MANAGEMENT SYSTEM
CHECKLIST
PREVENTATIVE MAINTENANCE VEHICLE INSPECTION

Functional Area: **ALL**

Document: **CHK-013**

SECTION 1 GENERAL INFORMATION	
Unit Number: G 10	**Date:** MAR. 28. 2022
Inspector: Zeljko	**Work Order #:**

SECTION 2- SPECIFIC REQUIREMENTS

STATUS:	N/A Not Applicable to This Unit P: Passes A: Added (Show Number)	M: Passed but Maintenance Required R: Rejected- Replacement Necessary

ENGINE		STATUS	REAR OF VEHICLE		STATUS
1	Engine Oil 30 Litres	SERVICE	26	Tail Lights	P
2	Radiator	P	27	Brake Lights	P
3	Radiator Hoses	P	28	Turn Signals	P
4	Drive Belt	P	29	4 Way Flashers	P
5	Air Filter	SERVICE	30	Clearance/Marker Lights	P
6	Brake Adjustment	N/A	31	Reflectors	P
7	Brake Fluid ___Litres	N/A	32	Mud Flaps	P
8	Transmission	SERVICE	33	License Plate	N/A
9	Transmission Fluid 65 Litres	SERVICE	34	Compartments Closed/Locked	P
10	Power Steering Fluid ___Litres	N/A	35	Dents/Scratches	P
START ENGINE		**STATUS**	**OUTSIDE FRONT OF VEHICLE**		**STATUS**
11	Parking Brake (Micro-lock)	P	36	Headlights	P
12	Oil Pressure (Gauge/light)	P	37	Clearance/Marker Lights	P
13	Temperature	P	38	Turn Signals	P
14	Fuel Level	P	39	4 Way Flashers	P
15	Back-Up Alarm	P	40	Fog Lights	P
16	Horn	P	41	Dents/Scratches	P
INSIDE VEHICLE		**STATUS**	**OTHER**		**STATUS**
17	Cab Clean	P	42	Front Differential	
18	Instrument Panel	P	43	Rear Differential	
19	Glass (Broken or Cracked)	P	44	Front Steering Hub Oils (80/90 Synthetic Oil)	
20	Wipers & Washer	P	**GREASING**		**STATUS**
21	Heater/Defrost	P	45	Driveline	P
22	Mirrors (Inside & Out)	P	46	Rollers	
23	Steering (Excess Play)	P	47	Winch	
24	Fire Extinguisher	P	**TORQUE WHEELS**		**STATUS**
25	Hazard Warning Kit	P	48	Torque Right Side Front	
			49	Torque Right Side Rear	
			50	Torque Left Side Front	
			51	Torque Left Side Rear	

Original Issued – August 30, 2016
PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED.
© Strategic HSE Systems Inc.

LEFT SIDE OF VEHICLE		STATUS
52	Fuel Tank Cap On	
53	Side Marker Lights	
54	Reflectors	
55	Tires & Wheels	
56	Lugs Tight	
57	Compartments Closed	
58	Dents/Scratches	
RIGHT SIDE OF VEHICLE		**STATUS**
59	Fuel Tank Cap On	
60	Side Marker Lights	
61	Reflectors	
62	Tires & Wheels	
63	Lugs Tight	
64	Compartments Closed	
65	Dents/Scratches	

MISCELLANEOUS		STATUS
66	Spare Tire	
67	Tire Jack & Wrench	
68	Insurance & Registration	

SECTION 3 COMMENTS- CORRECTIVE ACTION MEASURES/PLAN

Comments/Action (Include # identifier)	Due Date	By Whom	Date Done

Inspection Conducted by (Print):	Management Review Conducted by (Print):
Signature:	Signature:

Original Issued – August 30, 2016
PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED.
© Strategic HSE Systems Inc.

NORTHPOINT ENTERPRISE LTD.
780-836-9341
MANNING, AB

WORK ORDER NO. 0404

Thomas Zielko

DATE	UNIT NO.	MAKE	MILEAGE	HOUR METER
MAR. 25. 2022	G10	CAT		9389

QTY	PART NO. AND DESCRIPTION	PRICE
1	H3 / 24V	
	LIGHT BULB	
1	577-1435	
	AIR FILTER	
1	331-8108	
	INNER AIR FILTER	
1	338-3540	
	HYDRAULIC FILTER	
1	328-3655	
	TRANSMISSION FILTER	
2	308-9679	
	FUEL FILTER	
1	326-1643	
	WATER SEPARATOR	
1	LF691A	
	OIL FILTER	
1	149-1912	
	CAB FILTER	
1	211-2660	
	CAB FILTER	
	TOTAL PARTS	
POS	TIRES & WHEELS	

JOB DESCRIPTION

- WASHING UNIT
- GREASING
- CHECK OIL IN CIRCLE DRIVE
- CHECK OIL IN FINAL DRIVE
- CHANGE OIL IN FINAL DRIVE (163 LIT) DURATRAN XL
- CHECK ENGINE BELT
- REAPLACE LIGHT BULB ON WORK LIGHT

MARCH. 28. 2022

- CHANG TRANSMISSION OIL + FILTER (65 LIT. DURATRAN XL)	2 HRS.
- CHANG ENGINE OIL + FILTER (30 LIT. 10W40)	1 HRS.
- CHANG FUEL FILTERS	20 MIN.
- CHANG AIR FILTERS	10 MIN.
- REAPLACE CAB FILTERS	10 MIN.
- CHECK FRONT WHEEL OIL HUB	

March 31 2022

Change lift cups reshim	1hr
Change side tilt cupsi reshim	1hr
Change mulboard side ~~shim~~ shims tighten	1.5hr

Valley Printers #14010

NORTHPOINT ENTERPRISE LTD.
780-836-9341
MANNING, AB

WORK ORDER NO. 0368

Thomas

QTY	PART NO. AND DESCRIPTION	PRICE
1	1 R-1808 Oil	
1	326-1643 fuel	
2	308-9674 fue	
1	577-1435 Air	
1	558-021-329 Seal Kit	
	TOTAL PARTS	
POS	TIRES & WHEELS	

DATE 2022	UNIT NO.	MAKE	MILEAGE	HOUR METER
Mar 10	G10	CAT		9316

JOB DESCRIPTION

Changed engine oil and filter
Changed all fuel filters
Changed air filters ~~topped up tran~~.
Topped up tran oil
re sealed wing ram
Changed LH high beam

Valley Printers #14010

QTY	PART NO. AND DESCRIPTION	PRICE
	TOTAL PARTS	
POS	TIRES & WHEELS	

NORTHPOINT ENTERPRISE LTD.

780-836-9341

MANNING, AB

WORK ORDER NO. 0467

DATE	UNIT NO.	MAKE	MILEAGE	HOUR METER
Febll 2022	G10	CaT	Na	3920

JOB DESCRIPTION

Changed oil and filter
changed air filter
Checked fluids
-added 1 jug to Tran
Checked blockheater
-Seems to be working

Valley Printers #14010

X05-2

NORTHPOINT ENTERPRISE LTD.

780-836-9341

MANNING, AB

WORK ORDER NO. 0490

Trevor Thomas

QTY	PART NO. AND DESCRIPTION	PRICE
	TOTAL PARTS	
POS	TIRES & WHEELS	

DATE	UNIT NO.	MAKE	MILEAGE	HOUR METER
Jan. 15/22	G10	160M CAT	8534 hours	

JOB DESCRIPTION

Serviced unit
- changed engine oil/filters
- changed fuel filters
- changed air filters.

Valley Printers #14010