

Former Allstar Energy Ltd. 141/03-24-029-27 W3M
Well site located on the SW ¼ 24-029-27 W3M

1. The completed drilling date for the well was March 14, 2006
2. The current status for the well is abandoned
 1. Abandonment date was November 25, 2025
3. In September 2023, Montrose completed a Phase II Environmental Site Assessment;
 1. Results indicated that there was no contamination onsite due to well operations and the site was to proceed to surface reclamation
4. In October 2024: surface reclamation activities to the well lease and access road were completed.
 1. Culverts were removed from the access road
 2. Topsoil was stripped, subsoil was contoured on both the lease and access, topsoil was replaced
 3. Teine had abandoned their flowline riser on lease prior to surface reclamation on lease.
5. Now that surface reclamation has been completed, during the vegetation growing season of 2025 Montrose completed a vegetation assessment. It was determined that the vegetation was not mature enough to complete a detailed site assessment.
6. Plans going forward:
 1. During the 2026 vegetation growing season Montrose will complete a vegetation assessment to determine if vegetation will meet passing detailed site assessment (DSA) criteria. Once a passing DSA is completed, Montrose will reach out to the landowner (please let me know if that is still going to be you) for signoff on reclamation. Once landowner signoff is received Montrose can proceed with closure.

Jesse Milton, B.Sc.RRM., AAg
Environmental Scientist
Montrose Environmental
Kindersley, SK | Central Standard Time
Office: +1-306-463-2190 | Mobile: +1-306-430-1451
jmilton@montrose-env.ca | montrose-env.com