



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GH08922
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21156996

Inspection Result:
PASS

FACILITY:	MODERN DIESEL TRUCK REPAIR LTD. S15400	INSP. TYPE:	Complete	INSP. START:	2024-Nov-26 02:00 PM PST
INSPECTOR:	Aujla, Gagandeep / 300544	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2024-Nov-26 04:00 PM PST
WORK ORDER #:		INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	13485851	VIN:	5V8VC5325MM101473
PLATE #:	70358J	UNIT/FLEET#:	1033	OWNER/LESSEE NAME:	TRIDENT ROADLINES GROUP LTD.,
LICENCED GVW(kg):	0	BODY STYLE:	Van Trailer	ADDRESS:	212-12380 80 AVE, 212-12380 80 AVE Surrey, British Columbia V3W3A3, Canada
VEHICLE YEAR:	2021	ODOMETER:			
MAKE:	VANGUARD	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) 4 BRAKES REPLACED
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Repaired (same day) 1 HUB SEAL LEAK REPLACED
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	28	28
2	Clamp	30	Automatic	28	29

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
1	6	8	8	8	
2	10	11	11	10	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	20	20
2	20	20

Comment:

Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
1	Lining (Shoe)	22	22
2	Lining (Shoe)	22	22

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
1	Drum		
2	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Inspector: Aujla, Gagandeep

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Nov-26 04:28 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g., regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

11/28/2024 4:28:40 PM PST

