



Commercial Vehicle Inspection Report

Decal Number: GL12109
Decal Expiry Date: 2026-Oct-31
Inspection Number: 21546344

Inspection Result:
PASS

FACILITY:	FIRST TRUCK CENTRE INC. / S20099	INSP. TYPE:	Complete	INSP. START:	2025-Oct-28 08:00 AM -07
INSPECTOR:	LILLICO, JARED LAWRENCE / 112948	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Oct-28 10:05 AM -07
WORK ORDER #:	37462	INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	09739380	VIN:	1HTSDADR7YH674545
PLATE #:	7879DK	UNIT/FLEET#:	E1	OWNER/LESSEE NAME:	PEACE RIVER REGIONAL DISTRI, PEACE RIVER REGIONAL DISTRI
LICENCED GVW(kg):	16429	BODY STYLE:	Pumper Truck	ADDRESS:	PO BOX 810 STN MAIN
VEHICLE YEAR:	2000	ODOMETER:	37139 KM		Dawson Creek, British Columbia
MAKE:	INTERNATNA	HUB ODOMETER:			V1G4H8, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Repaired (same day)	TOP UP ENGINE COOLANT REPAIR A FEW AIR LINE FITTING LEAKS
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	31.8	31.8	12			13	✓
2	Clamp	30	Automatic	38.1	38.1	12	12	12	12	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	25	25	Lining (Shoe)	19.1	19.1	Drum		
2	40	40	Lining (Shoe)	15.9	15.9	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: LILLICO, JARED LAWRENCE Signature:

This Inspection Report was submitted to CVSE on 2025-Oct-28 10:07 AM -07
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.