

03994519

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Standards and Inspections
Box 45064 Regent Postal Office
Winnipeg, MB, R2C 5C7
1-204-985-0920



C005895

Date Inspection Started: 23 DAY, 09 MO., 25 YR.
 Date Inspection Completed: 24 DAY, 09 MO., 25 YR.
 Inspection Expiry Date: 30 DAY, 09 MO., 26 YR.

Station Number: A5302
 Station Name: VIRDEN TRUCK & TRA
 City: VIRDEN
 Mechanic Number: 11016216
 Mechanic Signature: [Signature]
 Station Phone Number: (204) 748-6887

Vehicle Owner: BOYES CONTRACTING
 Address: BOX 63 HARTNEY MB
 City: HARTNEY
 Province: MB
 Postal Code: R0M 0X0
 Phone: [Blank]

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Licence Number: 512219312
 Prov: MB
 NSC #: [Blank]

Odometer Reading: [Blank]
 Odom. Type: km mi

Vehicle Identification Number: 2D1EGED1Z311D119291469
 Make: DOEP KER
 Model: END DUMP
 Year: 2013
 Unit #: [Blank]

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any)

Section 2 Suspension: Defects (if any)

Section 3 - Brake Systems: 3H 3A
 Defects (if any) Circle Brake Type
 15C BRAKE SHOE LINING THICKNESS LESS THAN LEGAL LIMIT.
 20A ABS LAMP STAYING ON AFTER BUS CYCLING.

Axle	Lining		Drum/Rotor		Stroke		
	L	R	L	R	L	R	
1	.50	.52	16.53	16.54	1.5	1.5	
2	.52	.54	16.54	16.55	1.5	1.5	
3	.80	.80	16.50	16.50	1.5	1.5	
4							
5							
Final Measurement						INCHES	

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any)

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any)

Section 9 - Tire & Wheel: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	18	18	20	20	100	100	100	100
2	18	18	13	13	100	100	100	100
3	9	11	12	11	100	100	100	100
4								
5								

Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date: