

03927136

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920



Date Inspection Started: DAY 06, MO. 03, YR. 25
 Date Inspection Completed: DAY 06, MO. 03, YR. 25
 Inspection Expiry Date: DAY 31, MO. 03, YR. 26

Station Number: A5302
 Station Name: VIRDEN TRUCK & TRAILERS
 City: Virden
 Mechanic Number: 10626
 Mechanic Signature: [Signature]
 Station Phone Number: (204) 748-6887
 Vehicle Owner: BOYES CONTRACTING
 Address: BOX 63
 City: HARTNEY MB
 Province: MB
 Postal Code: R0M 0X0
 Phone: [Blank]

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Licence Number: SY4568
 Prov. MB
 NSC # [Blank]
 Odometer Reading [Blank]
 Odom. Type: km mi

Vehicle Identification Number: 11E9309297CE1111293
 Make: ETN
 Model: DEEP LOCK
 Year: 2012
 Unit #: [Blank]

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																																										
X		Section 1 - Power Train: Defects (if any)																																																																																										
X		Section 2 Suspension: Defects (if any)																																																																																										
X	X	Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type 15C 2 AXLE MT BELOW MIN LEGAL LIMIT. 16A CAMSHAFT MOVEMENT ABOVE LEGAL LIMIT. 16D ADJUSTER BROKEN Brake Inspection Type: A (B) C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																																										
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>.40</td> <td>.41</td> <td>16.57</td> <td>16.57</td> <td>1</td> <td>1</td> </tr> <tr> <td>2</td> <td>.42</td> <td>.82</td> <td>16.58</td> <td>16.50</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>3</td> <td>.42</td> <td>.34</td> <td>16.56</td> <td>16.56</td> <td>1</td> <td>1</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table> <p style="text-align: right;">Final Measurement INCHES</p>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	.40	.41	16.57	16.57	1	1	2	.42	.82	16.58	16.50	1.5	1.5	3	.42	.34	16.56	16.56	1	1	4							5																																																
Axle	Lining			Drum/Rotor		Stroke																																																																																						
	L	R	L	R	L	R																																																																																						
1	.40	.41	16.57	16.57	1	1																																																																																						
2	.42	.82	16.58	16.50	1.5	1.5																																																																																						
3	.42	.34	16.56	16.56	1	1																																																																																						
4																																																																																												
5																																																																																												
X		Section 4 - Steering: Defects (if any)																																																																																										
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																										
X		Section 6 - Lamps: Defects (if any)																																																																																										
X		Section 7 - Electrical System: Defects (if any)																																																																																										
X		Section 8 - Body: Defects (if any)																																																																																										
X		Section 9 - Tire & Wheel: Defects (if any)																																																																																										
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>18</td> <td>18</td> <td>10</td> <td>10</td> <td>80</td> <td>80</td> <td>75</td> <td>75</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>8</td> <td>17</td> <td>15</td> <td>15</td> <td>80</td> <td>80</td> <td>75</td> <td>75</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>13</td> <td>20</td> <td>9</td> <td>4</td> <td>80</td> <td>80</td> <td>75</td> <td>75</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	18	18	10	10	80	80	75	75	100	100	100	100	2	8	17	15	15	80	80	75	75	100	100	100	100	3	13	20	9	4	80	80	75	75	100	100	100	100	4													5												
Axle	Tread Depth				Air Pressure																																																																																							
	Initial			Corrected		Initial		Corrected																																																																																				
	L	R	L	R	L	R	L	R																																																																																				
1	18	18	10	10	80	80	75	75	100	100	100	100																																																																																
2	8	17	15	15	80	80	75	75	100	100	100	100																																																																																
3	13	20	9	4	80	80	75	75	100	100	100	100																																																																																
4																																																																																												
5																																																																																												
X		Section 10 - Coupling Devices: Defects (if any)																																																																																										

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: NOTE! 3 AXLE OUTER RIGHT TIRES CLOSE TO MIN LEGAL LIMIT.

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.
Vehicle received without repairs by: [Signature] Date: [Blank]