04162202

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

C149403

Date Inspection Started	02 DAY	11 MO.	26 YR.
Date Inspection Completed	03 DAY	11 MO.	26 YR.
Inspection Expiry Date	30 DAY	11 MO.	27 YR.

Station Number: A53411 — Station Name: 5496633 Manitoba — City: [illegible]

Mechanic Number: M7772 — Mechanic Signature: [signature] — Station Phone Number: 204-999-3179

Vehicle Owner: 10192300 Manitoba Ltd

Address | City | Province | Postal Code | Phone

[X] Pass/Safe Vehicle
[X] Fail/Unsafe Vehicle
[ ] Fail/Hazardous

Licence Number: Not Plated — Prov. — NSC # — Odometer Reading: 111840 — Odom. Type: [X] km [ ] mi

Vehicle Identification Number: 3AKJHHDR7LSKW91116 — Make: FRHT — Model: Cascadia — Year: 2020 — Unit #

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR ___ KGS [X] Truck Tractor ___Trailer ___Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X	X	**Section 3 - Brake Systems:** 3H (3A) Defects (if any) 13(A) Both Gladhand Seals Broken — Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X	X	**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any) 7(B) Both wiper blade Broken
X	X	**Section 6 - Lamps:** Defects (if any) 1(L) Lic plate light Broken
X	X	**Section 7 - Electrical System:** Defects (if any) 2(A) Battery Cables Corrosion
X	X	**Section 8 - Body:** Defects (if any) 1(C) Right Side Hood Shock Broken
X	X	**Section 9 - Tire & Wheel:** Defects (if any) 4(A) All Tire Air Pressure Lower then Recommended. 1(B) RRD Both Tire Tread 2/32"
X	X	**Section 10 - Coupling Devices:** Defects (if any) 7(D) 5th wheel has play over 1/2"

Brake Inspection Type: A B (C) D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	9/16	9/16			1 1/4	1 1/4
2	1/2	1/2			1 1/2	1 1/2
3	1/2	1/2			1 1/2	1 1/2
4						
5						
Final Measurement						

Tread Depth — Initial 7/32

Axle	Initial L	Initial L	Initial R	Initial R	Corrected L	Corrected L	Corrected R	Corrected R
1		8	8					
2	10	10	10	10				
3	6	4	2	2				
4								
5								

Air Pressure — Initial PSI — Corrected PSI

Axle	Initial L	Initial L	Initial R	Initial R	Corrected L	Corrected L	Corrected R	Corrected R
1		90	90			100	100	
2	90	90	85	90	100	100	100	100
3	90	90	90	85	100	100	100	100
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: All Repair Done by Anytime Truck and Trailer Ltd

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature: Gurdeep [illegible] Date: 02/11/26

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE

| | | |