

N07-1



Commercial Vehicle Inspection Report

Decal Number: PY08343
Decal Expiry Date: 2026-Apr-30
Inspection Number: 21334536

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN / 106407
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2025-Apr-30 10:00 AM MST
INSP. COMPLETE: 2025-Apr-30 11:00 AM MST

VEHICLE JUR: British Columbia
PLATE #: 01453J
LICENCED GVW(kg): 0
VEHICLE YEAR: 2013
MAKE: MANAC
MODEL:

REGI: 12828357
UNIT/FLEET#: H12-13
BODY STYLE: High Boy Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2M5131615D1130639
OWNER/LESSEE NAME: RAPIER HOLDINGS, LTD
ADDRESS: 8805-111 AVE
Fort St John, British Columbia
V1J0A2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	27	26	10	10	14	10	
2	Clamp	30	Automatic	27	28	15	14	14	11	
3	Clamp	30	Automatic	28	29	6	7	7	9	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	89	88
2	79	80
3	80	93

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	10	11
Lining (Shoe)	12.5	12
Lining (Shoe)	12	11

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: CHRISTIANSON, LESLIE RYAN

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-01 01:00 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014
5/1/2025 1:00:49 PM MST