



Delivery Note

INVOICE TO

Jack Goddard
EODO
968 Rockley Road
Bathurst NSW 2795

INVOICE NO. 1619

DATE 30/11/2019

JOB NO.
MGC340

MACHINE
Komatsu D65

DATE	DESCRIPTION	QTY
05/11/2019	Services Machine: Komatsu D65, Serial: 67516 Seat slides and repairs Install seat Blow out air cleaner and cab filters Replace equaliser bar grease nipples Check cutting edges Diagnose unplugged wire for seat compressor and connect - 05 Nov 2019 2:00 hrs Investigate parts availability - 06 Nov 2019 1:00 hrs Collect parts - 21 Nov 2019 0:30 hrs Remove seat Remove old slides and clean seat Install new slides and bolts Install seat with all new bolts supplied with seat Test ok - 21 Nov 2019 3:00 hrs	6.50
21/11/2019	Travel Rate Travel to Dam - 21 Nov 2019 0:30 hrs	0.50
21/11/2019	Parts MGC340 Seat slide kit	1
21/11/2019	Consumables Consumables needed to complete task.	2



Delivery Note

INVOICE TO

Jack Goddard
EODO
968 Rockley Road
Bathurst NSW 2795

INVOICE NO. 1742

DATE 12/03/2020

JOB NO.
MGC484

MACHINE
Komatsu D65EX-15 9500HR

JOB DETAILS
500hr service & AC repairs

DATE	DESCRIPTION	QTY
28/02/2020	Services Serial: 67516 Hours: 9500 Order parts - 24 Feb 2020 0:30 hrs Collect oil and pack truck - 28 Feb 2020 0:30 hrs Complete 500hr service Please see service sheet provided Complete A/C service and recharge 900g of R134a - 28 Feb 2020 5:30 hrs Service dozer and charge A/C - 28 Feb 2020 4:00 hrs	10.50
28/02/2020	Travel Rate Travel to dam - 28 Feb 2020 0:30 hrs (3 trades)	1.50
28/02/2020	Parts MGC484 Receiver dryer A/C	1
28/02/2020	R134a Gas R134a Refrigerant Gas	0.90
28/02/2020	Oil- MGC484 Rx Super X2 20lt	1
28/02/2020	Parts MGC484 Cartridges Oil filter Elements Filter Aircon	1
28/02/2020	Consumables Consumables needed to complete task.	2



Delivery Note

INVOICE TO

Jack Goddard
EODO
968 Rockley Road
Bathurst NSW 2795

INVOICE NO. 2046

DATE 23/09/2020

JOB NO.
MGC679

MACHINE
Komatsu D65

JOB DETAILS
Engine bay latch

DATE	DESCRIPTION	QTY
16/06/2020	Services Serial: 67516 Hours: 9483 Order and collect parts Fit new latch to bonnet door - 21 Aug 2020 1:00 hrs	1
16/06/2020	Parts MGC679 Lock assy Machine Keys	1
16/06/2020	Parts MGC679 M5 bolts and nuts	4



Delivery Note

INVOICE TO

Jack Goddard
EODO
968 Rockley Road
Bathurst NSW 2795

INVOICE NO. 2489

DATE 28/07/2021

JOB NO.
MGC1264

MACHINE
Komatsu D-65

JOB DETAILS
Hydraulic Oil leak

DATE	DESCRIPTION	QTY
29/06/2021	Services Hours: 9499 Travel to site Inspect machine to find oil leak Remove mud from tracks to access leaking area Remove gaards from right hand track frame tilt hoses between chassis and track frame Remove hoses Get hoses made Travel back to site Fit hoses and new o-rings Test for leaks Install gaards Fill hyd oil 40 litres - 29 Jun 2021 4:00 hrs	4
29/06/2021	Parts MGC1264 Hose and fittings Hyd 68 x2 Orings	1
29/06/2021	Consumables Consumables needed to complete task.	2



Delivery Note

INVOICE TO

Jack Goddard
EODO
968 Rockley Road
Bathurst NSW 2795

INVOICE NO. 2504

DATE 28/07/2021

JOB NO.
MGC1272

MACHINE
Komatsu D-65

JOB DETAILS
Hyd oil cooler leak

DATE	DESCRIPTION	QTY
30/06/2021	Services Hours: 9503 Travel to site Inspect machine for oil leak Hydraulic oil cooler leaking and will need replacing - 30 Jun 2021 0:30 hrs Remove and replace hydraulic cooler. Tested ok Top up hydraulic oil - 07 Jul 2021 1:30 hrs	2
30/06/2021	Parts MGC1272 Oil cooler (used)	1
30/06/2021	Consumables Consumables needed to complete task.	1
30/06/2021	Hydraulic 68 Hydraulic 68	4



Delivery Note

INVOICE TO

Jack Goddard
EODO
968 Rockley Road
Bathurst NSW 2795

INVOICE NO. 3426

DATE 19/12/2022

JOB NO.

MGC2229

MACHINE

740Dump truck/ Komatsu D65

JOB DETAILS

Gas pipeline machine repairs

DATE	DESCRIPTION	QTY
17/11/2022	Services Inspect seat operation on 740 dump truck, checked fuse, checked power to seat supply, jacked and propped up seat, checked wiring to switch and compressor in seat and found wire not connected on compressor motor, squashed electrical connector and refit, tested seat operation. - 17 Nov 2022 1:00 hrs	2.50
	Komatsu D65 Purchased flashing light for D65EX dozer, removed old flashing light, mounted new flashing light and wire up, tested operation of light and installed guard. - 17 Nov 2022 1:30 hrs	
17/11/2022	Parts MGC2229 Beacon Bulb	1
17/11/2022	Consumables Consumables needed to complete task.	1



Delivery Note

INVOICE TO

Jack Goddard
EODO
968 Rockley Road
Bathurst NSW 2795

INVOICE NO. 3559

DATE 01/03/2023

JOB NO.
MGC2382

MACHINE
Komatsu D65EX-15

JOB DETAILS
Replace air filter

DATE	DESCRIPTION	QTY
21/02/2023	Services Serial/Rego: 67516 Travel to site Replace air filter and repair restriction sensor Complete machine grease and check over Tighten alt belts Check all fluids (transmission was low) - 21 Feb 2023 1:30 hrs	1.50
21/02/2023	Parts MGC2382 Air filter	1
21/02/2023	Oil- MGC2382 Trans 30W	1
21/02/2023	Grease Grease	1
21/02/2023	Consumables Consumables needed to complete task.	0.50



Delivery Note

INVOICE TO

Jack Goddard
EODO
968 Rockley Road
Bathurst NSW 2795

INVOICE NO. 4142

DATE 18/12/2023

JOB NO.
MGC 2970

MACHINE
Komatsu Dx65 -15

JOB DETAILS
Complete service / Repairs

DATE	DESCRIPTION	QTY
14/11/2023	Services Serial/Rego: 067516 Hours/Kms: 9660 hrs - Inspect dozer - check pressure sensor / oil level - 14 Nov 2023 1:00 hrs - Pack truck - Research machine - Travel to site - Log in to screen and check pressure switch - remove panels - Screw gauge into oil pressure passage - Check oil pressure at idle and high idle - All ok - Fix up aircon hose - Make Bolt to fit v clamp on turbo - Fit bolt - Get filter numbers / Pack up - 15 Nov 2023 3:30 hrs - fix seat compressor - 17 Nov 2023 1:00 hrs - Inspect ac system - travel back to workshop - 21 Nov 2023 1:30 hrs - Suck gas out of machine weighing the amount - Inspect circuit for pressure switch - Test for power at switch / Fuse - install new air cleaners/ Ac filter - Pack up Travel back to town - 22 Nov 2023 2:30 hrs -research pressure switch - 22 Nov 2023 0:30 hrs	27.50

DATE	DESCRIPTION	QTY
	<ul style="list-style-type: none"> - Remove dash panels - remove bolts holding engine cover on - Pack up - Travel back to site - 22 Nov 2023 2:00 hrs - Travel to site - Move vehicle off road - Remove bonnet off dozer - Remove air cleaner - Remove front cab panels - Inspect thermistor - remove more dash panels and pull wiring harness - remove hvac unit - Test circuits - Bypass pressure switch and measure 24 bolts at compressor - Pack up - Reinstall bonnet to stop rain - 23 Nov 2023 5:00 hrs - fill pc350 with fuel and bleed fuel system - Pack up - Travel back to workshop - 23 Nov 2023 1:00 hrs - Disassemble hvac unit - wash out evaporator and heater core - install new thermistor in panels - Pack up - 23 Nov 2023 1:15 hrs 	
	Unpack truck from all Eodo jobs - 24 Nov 2023 1:00 hrs	
	<ul style="list-style-type: none"> - Put Hvac unit back together with new tx valve and pressure switch - Pack up - 28 Nov 2023 1:00 hrs - Pack truck - Travel to site - Reinstall hvac unit - Hook all wires up /plump up lines - Reinstall all covers - Gas air con - Test air con - Pack up - 01 Dec 2023 6:00 hrs 	
	Unpack truck - 04 Dec 2023 0:15 hrs	
14/11/2023	Parts MGC2970 Tank Orings Switch Valve	1
14/11/2023	Oil- MGC2970 Engine oil	1
14/11/2023	Parts MGC2970 Switch Cartridge	1
14/11/2023	Parts	1

DATE	DESCRIPTION	QTY
	MGC2970 Switch Filters	
14/11/2023	Parts MGC2970 Thermistor A22-8515	1
14/11/2023	R134a Gas R134a Refrigerant Gas	0.85
14/11/2023	Consumables Consumables needed to complete task.	3