

Service Date	Job Number	Equipment Code	Make	Model	Serial Number	Description	Meter Read Hours
13/07/2024	31140	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Repair & replace handrails as orderd & required	5870
25/06/2024	31036	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Investigate hydraulics squealing	0
8/03/2024	30575	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace 2 x batteries	5869
5/07/2023	29424	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace batteries - auto electrician to go to site after as machine shut down & wouldn't start	5819
15/03/2023	28711	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace smashed rear view mirror on driver's side	0
13/03/2023	28950	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	GPS Upgrade	5810
8/02/2023	28509	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace damaged RH side mirror and repair damaged handrail RH side	5629
23/11/2022	28087	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace broken front r/h mirror.	5629
1/11/2022	27717	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Carry out 500 hour service	5565
6/10/2022	27708	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace Lower Front Slide In Glass	5512
6/09/2022	27470	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Travel to site and re-calibrate GPS system	5420
25/08/2022	27434	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Check and test both fire extinguishers & tag if ok - replace if required	5381
16/08/2022	27361	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Travel to site and investigate fault codes	5324
14/07/2022	27133	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace cabin filters due to contaminated areas at Bradbury Park	5155
16/06/2022	26935	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Travel to site and investigate fault codes E15 & CA428	5047
13/06/2022	26653	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace quick hitch compliance plate	5016
2/06/2022	26875	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Machine out of calibration - remeasure and calibrate	4994
1/06/2022	26818	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Investigate fault codes E15 & CA428	4985
4/05/2022	26694	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Travel to site and Investigate hydraulic leak	4830
29/04/2022	26674	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Carry out repairs from end of hire. Remove and replace damaged TS1 and cable, repair blade cylinder cover mount and straighten plate, get paint damage touched up.	4960
26/04/2022	26628	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Carry out 1000hr service	4963
4/04/2022	26433	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace cab filter and outer air filter	4822
23/03/2022	26449	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Travel to site investigate oil leak at grab. Clean out cooler packs and top up hydraulic oil as required.	4792
19/03/2022	26416	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	check hydraulic oil level and inspect cooler packs	4758
14/03/2022	26358	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Travel to site and weld up broken hydraulic steel line and straighten into bracket	4724
7/01/2022	25991	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace ball valve fittings with 45 degree fittings	4590
11/11/2021	25740	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Carry out 500 hour service	4504
16/08/2021	25093	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Carry out repairs to damages from site	4331
22/07/2021	24894	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	remove blade cylinder covers and repair mounts , drill broken bolt and tap	4156
29/06/2021	24678	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace hose fitting to suit tungsten saw - operator to fit	4093
10/06/2021	24526	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	fit new 9kg extinguisher and bracket to machine	4005
1/06/2021	24444	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	carry out 2000hr service	3987
13/04/2021	24083	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	carry out 500 hr service (replace final drive oil and top up hydraulic oil)	3684
23/02/2021	23747	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	calibrate gps on machine, reading out by 4mm	3276
3/02/2021	23531	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	top up hydraulic oil	3269
15/12/2020	23210	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	replace aftermarket washer motor with genuine	3178
8/10/2020	22555	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace hydraulic hose on grab	2989
30/09/2020	22425	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Repair GPS L/H hat cable & windscreen washer motor	2948
29/09/2020	22426	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Scheduled Service - 1000 Hour	2948
16/07/2020	21654	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	2 Year service fire suppression system	0
30/06/2020	21497	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Scheduled Service - 500 Hour	2768
4/06/2020	21266	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Turn cutting edge & replace corner tips	2594
14/03/2020	20188	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Scheduled Service - 1000 Hour	2188
5/03/2020	20184	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace mirrors	2143
3/03/2020	20157	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Top up hydraulic oil	2142
10/01/2020	19590	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace rock screen	1958
11/12/2019	19418	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Top up hydraulic oil	1881
7/11/2019	18937	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace 2 x batteries	1723
11/10/2019	17956	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	500 Hour Service	1460
11/10/2019	18661	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Fit tracker	1723
17/09/2019	18443	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Check function of beacon	1623
2/08/2019	17957	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Diagnose electrical fault	1460
19/07/2019	17858	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Fit rock screen	1408
21/06/2019	17705	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Repair cooling system leak	1408
13/05/2019	17417	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	1000 Hour Service	1036
5/03/2019	17094	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Rewire boom solenoid to ignition	756
24/01/2019	16708	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	fit rubber track pads	721
16/01/2019	16635	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Repair Front E-Stop Mounting Plate	717
16/01/2019	16636	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Refit Tilt Bucket pedal Rubber	717
8/11/2018	16192	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Fire Suppression System 6 Monthly Service	586
18/10/2018	16056	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Fit GPS to machine	559
3/09/2018	15724	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Scheduled Service - 500 Hour	513
20/06/2018	15240	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Fit boom height switch	301
15/05/2018	15000	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Replace handrail bolts, top up coolant, top up hyd oil, clean down and get ready for hire	105
3/04/2018	14762	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	Fit Fire Suppression System	0
3/04/2018	14767	PN1040	KOMATSU	PC228USLC-8	KMTPC226CJC052290	New Preparation	10