A263405

SGI

Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A263405

Station #: 71852

Technician #: 92288

Signing Officer #: 92414

Station Name: 5K Truck and Trailer Repair Ltd.

Technician Name: Felix Japay

Signing Officer Name: Gurpreet Kaur

Customer Details:

Name: I Load Trucking LTD

Address: 5308 Green Alder Way E, Regina, Saskatchewan, S4V 3M7

Inspection Completed Date: 02Dec2025

Inspection Expiry Date: 31Dec2026

Vehicle Details:

VIN: 1JJV532D2PL414177

Year: 2023

Plate: 342 MTW

Unit: 88082

Hubometer Reading:

Vehicle Make/Model: WABASH TRAILER/

Jurisdiction: Saskatchewan

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



SGI

Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71852

Station Name: 5K Truck and Trailer Repair Ltd.

Technician #: 92288

Technician Name: Felix Japay

Signing Officer #: 92414

Signing Officer Name: Gurpreet Kaur

Customer Details:

Name: I Load Trucking LTD

Address: 5308 Green Alder Way E, Regina, Saskatchewan, S4V 3M7

Vehicle Details:

VIN: 1JJV532D2PL414177

Hubometer Reading:

Year: 2023

Vehicle Make/Model: WABASH TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
			x	Fire Extinguisher (5)	N/A
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
			x	Attached Equipment (8)	N/A
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
			x	Fuel System (1)	N/A
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
			x	Hyd Brake System/Component (3.1)	N/A
		x		Air Brake System/Component (3.2)	REAR AXLE DRIVER SIDE BRAKE CHAMBER REPLACED.
			x	Elec Brake System/Components (3.1)	N/A
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
			x	Self-Steering Axle (2&4)	N/A
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
			x	Exhaust/Emission System (1)	N/A
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 14 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 20 mm • Cam Rotation: 32.7 degrees • Brake Stroke: 1 5/8 in
Wheel2 : Tire Tread Depth: 14 mm
Brake(1): No Brake
N/A
Wheel3 : Tire Tread Depth: 14 mm
Brake(1): No Brake
N/A
Wheel4-On : Tire Tread Depth: 14 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 14 mm • Cam Rotation: 92.7 degrees • Brake Stroke: 1 5/8 in

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 14 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 20 mm • Cam Rotation: 32.4 degrees • Brake Stroke: 1 5/8 in
Wheel2 : Tire Tread Depth: 14 mm
Brake(1): No Brake
N/A
Wheel3 : Tire Tread Depth: 14 mm
Brake(1): No Brake
N/A
Wheel4-On : Tire Tread Depth: 14 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 17 mm • Cam Rotation: 64.9 degrees • Brake Stroke: 1 5/8 in

PASS - vehicle passes inspection	Decal # A263405	Inspection Completed Date: 02Dec2025