



# Commercial Vehicle Inspection Report

Decal Number: GK18259  
Decal Expiry Date: 2026-Jan-31  
Inspection Number: 21432183

N10-1  
Inspection Result:  
**PASS**

**FACILITY:** COASTAL TRUCK & EQUIPMENT / S4765  
**INSPECTOR:** SIDHU, BALWINDER SINGH / 203083  
**WORK ORDER #:**

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
**INSP. REASON:** Semi-annual

**INSP. START:** 2025-Jul-20 04:00 PM PDT  
**INSP. COMPLETE:** 2025-Jul-20 06:00 PM PDT

**VEHICLE JUR:** British Columbia  
**PLATE #:** SH8764  
**LICENCED GVW(kg):** 26500  
**VEHICLE YEAR:** 2008  
**MAKE:** MACK  
**MODEL:**

**REGI:** 14228911  
**UNIT/FLEET#:** 13  
**BODY STYLE:** Dump Truck  
**ODOMETER:** 549151 KM  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:** Diesel

**VIN:** 1M2AX16C68M001810  
**OWNER/LESSEE NAME:** LTD., SS GREWAL TRUCKING  
**ADDRESS:** 5895 137B ST, 5895 137B ST  
Surrey, British Columbia  
V3X 3K9, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) #1 R/S WHEEL SEAL REPLACED
Section 3A - Air Brakes	Repaired (same day) AIR LEAK FIXED NEAR TRANNY
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	30	31	18			18	✓
2	Clamp	30L	Automatic	34	34	11	11	11	11	
3	Clamp	30L	Automatic	34	34	12	12	11	11	

Comment:

Comment:

## Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	62	63
2	54	55
3	81	82

Comment:

## Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	17	17
Lining (Shoe)	13	13

Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

## Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: SIDHU, BALWINDER SINGH

Signature:

This Inspection Report was submitted to CVSE on 2025-Jul-20 09:36 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVSE0014

7/20/2025 9:36:15 PM PDT