



Vehicle History Report # 70921194
Report Date: June 29, 2026 | 4:42 p.m. EDT
Report Status: Complete

2019 FORD EXPLORER XLT

Sport utility vehicle | 6 Cylinders | Gas
1FM5K8D85KGA65639
Country of Assembly: United States
Last Reported Odometer: 168,476 KM



No Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



9 Service Records Found



No U.S. History Found



4 Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of June 29, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

✔ There are no accidents/damage reported on this vehicle.



Registration

✔ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2018 Dec 14		Ferrari Maserati of Ontario Woodbridge, Ontario, Canada	Vehicle serviced - Pre-delivery inspection completed - Wheel locks installed - Vehicle washed/detailed
2018 Dec 21		Meadowvale Ford Mississauga, Ontario, Canada	Vehicle serviced Pre-delivery inspection completed
2021 Jan 29	63,574 KM	Pine Tree Ford Lincoln Woodbridge, Ontario, Canada	Vehicle serviced
2021 Mar 19	65,243 KM	Pine Tree Ford Lincoln Woodbridge, Ontario, Canada	Vehicle serviced - Antifreeze/coolant flushed/changed - Cooling system checked - Crankshaft oil seal(s) replaced - Oil and filter changed - Rear wheel bearing(s)/hub(s) replaced - Water pump gasket replaced - Water pump replaced
2022 Feb 3	70,547 KM	Pine Tree Ford Lincoln Woodbridge, Ontario, Canada	Vehicle serviced - Antifreeze/coolant flushed/changed - Cooling system checked - Oil and filter changed - Water pump gasket replaced - Water pump replaced
2022 Feb 25	71,064 KM	Pine Tree Ford Lincoln Woodbridge, Ontario, Canada	Vehicle serviced - Catalyst monitor sensor replaced - Catalytic converter replaced - Computer(s) checked - Engine/powertrain computer/module checked - Oxygen sensor replaced

ODOMETER		SOURCE	DETAILS
2022 May 24	78,256 KM	Pine Tree Ford Lincoln Woodbridge, Ontario, Canada	Vehicle serviced • Drivability/performance checked • Vehicle washed/detailed
2024 Feb 27	157,181 KM	Pine Tree Ford Lincoln Woodbridge, Ontario, Canada	Vehicle serviced
2024 Aug 1	168,476 KM	Kal Tire Vaughan, Ontario, Canada	Vehicle serviced • One tire balanced



Open Recalls

Recall #: 21S22 | ROOF RACK TRIM DETACHMENT Recall Date: 2021 Jun 06

Recall Description

THE ROOF RAIL COVERS MAY BECOME DETACHED FROM YOUR VEHICLE.

Remedy

PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT AND SECURE THE ROOF RAIL COVER FREE OF CHARGE PARTS AND LABOR.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit [Ford's website](https://www.ford.ca/support/recalls/). (<https://www.ford.ca/support/recalls/>)

Recall #: 24S02 | EXTERIOR A-PILLAR APPLIQUE MOLDING INSPECTION Recall Date: 2024 Jan 23

Recall Description

IN SOME OF THE AFFECTED VEHICLES, IT MAY BE POSSIBLE THAT SOME OF THE EXTERIOR A-PILLAR APPLIQUE TRIM CLIP ATTACHMENTS ARE NOT PROPERLY ENGAGED DUE TO IMPROPER ASSEMBLY OR REPAIR. IF THIS OCCURS, THE A-PILLAR APPLIQUE TRIM, WHICH BORDERS THE RIGHT AND LEFT SIDE OF THE WINDSHIELD, MAY BE LOOSE, MISSING OR BECOME DETACHED.

Remedy

FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT AND REPAIR ANY LOOSE OR MISSING EXTERIOR A-PILLAR TRIM MOLDINGS FREE OF CHARGE PARTS AND LABOR. A TEMPORARY REPAIR MAY ALSO BE COMPLETED AS NEEDED.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit [Ford's website](https://www.ford.ca/support/recalls/). (<https://www.ford.ca/support/recalls/>)

Recall #: 26S08 | REAR SUSPENSION TOE LINK REPLACEMENT Recall Date: 2026 Feb 25

Recall Description

ON YOUR VEHICLE, THE REAR SUSPENSION TOE LINK COULD FRACTURE. IF A TOE LINK FRACTURES, YOU MAY EXPERIENCE A CLUNK NOISE,

UNUSUAL HANDLING, AND OR A MISALIGNED REAR WHEEL.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit [Ford's website](https://www.ford.ca/support/recalls/). (https://www.ford.ca/support/recalls/)

Recall #: 25E10 | POWERTRAIN CONTROL MODULE PCM REPROGRAMMING Recall Date: 2026 Mar 25

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit [Ford's website](https://www.ford.ca/support/recalls/). (https://www.ford.ca/support/recalls/)



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Dec 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial Vehicle colour noted as gray
2018 Dec 14		Ferrari Maserati of Ontario Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2018 Dec 21		Meadowvale Ford Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2020 Jun 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2021 Jan 29	63,574 KM	Pine Tree Ford Lincoln Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2021 Mar 19	65,243 KM	Pine Tree Ford Lincoln Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2021 Jun 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as gray
2021 Jun 6		FORD	Recall	Manufacturer Recall Issued Recall # 21S22

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2022 Feb 3	70,547 KM	Pine Tree Ford Lincoln Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2022 Feb 25	71,064 KM	Pine Tree Ford Lincoln Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2022 May 24	78,256 KM	Pine Tree Ford Lincoln Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2024 Jan 23		FORD	Recall	Manufacturer Recall Issued Recall # 24S02
2024 Feb 27	157,181 KM	Pine Tree Ford Lincoln Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2024 Apr 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2024 Aug 1	168,476 KM	Kal Tire Vaughan, Ontario, Canada	Service Record	Vehicle serviced
2026 Feb 25		FORD	Recall	Manufacturer Recall Issued Recall # 26S08
2026 Mar 25		FORD	Recall	Manufacturer Recall Issued Recall # 25E10



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2026 CARFAX Canada ULC. All rights reserved.



1FM5K8D85KGA65639