NHVR

HEAVY VEHICLE INSPECTION SCHEME (HVIS)
Inspection Report (Truck, Bus and Trailer)

Inspection Report: **AZ3089240**

1. HVIS Location

Site Name: **Dubbo HVIS**

2. Vehicle Class Truck [X] Bus [ ] Trailer [ ] Other [ ]

3. Reason for Inspection

Renew Registration [X] Other (Please Indicate) [ ]

4. Replacement Vehicle

[ ] Yes [X] No Registration Number [ ]

The vehicle inspected is a replacement to that originally booked. You must advise the Transport for NSW of this change so that inspection credits are deducted from the current vehicle.

5. Vehicle Details

Registration Number	Odometer Reading	VIN or Chassis
XN72HG	895269	JLFFN63FU0KJ25120

Vehicle make: **MITSUBISHI**

Body type: **GOODS VEHICLE - RIGI**

6. Inspection Checklist [P] = pass; [F] = fail; [N] = not applicable / not available

VIN / Chassis Number	P	Lights and Reflectors	P
Brakes	P	Mirrors, Windscreen & Windows	P
Tow Couplings	N	Engine & Driveline	P
Steering	P	Fuel System	P
Suspension	F	Public Vehicle Fittings	N
Wheels Tyres & Hubs	P	Exhaust System Visual	P
Structure & Bodywork	P	Exhaust System Detailed (meter)	N
Seats & Seatbelts	P	Modifications	N

7. Repairs Needed

Defect Notice Issued	Yes	X	No		Defect Notice Numbers	AHV1649546

8. Comments

9. SCO Certification I certify that this is true record of the vehicle's compliance with the inspection standards of the *National Heavy Vehicle Inspection Manual* and *Road Transport (Vehicle Registration) Regulation 2017* or *Heavy Vehicles (Vehicle Standards) National Regulation* at the time of Inspection and all details are correct.

Inspection	SCO Number	Office Number	Date	Signature
[X] Passed [ ] Failed	1044	3600	13/11/2026	

Note: This report indicates whether or not the vehicle met NSW registration standards at the time of inspection. It is not a comprehensive report on the condition of the vehicle, nor is it a guarantee that the vehicle is not stolen. For all types of checks a 'passed' inspection result may be accepted for registration for 3 months after the inspection, except where the Transport for NSW is informed that the vehicle is not roadworthy. Any alterations to the details of this report after its issue will render the document invalid.

B46FB873E750515D7C9797D3B9D1F8A4D138049AF1313D91C80F1192CABB41244093FC

Original Copy

Vehicle Defect Notice

Defect No. **AHV1649546**

NHVR

Vehicle Registration No.	Tick if NSW City Bus or Motor Cycle	Make and Type of Vehicle	Odometer Reading
XN72HG		MITSUBISHI 2R3	895269

State of Registration	Expiry(Mth/Yr)	Driver/Registered Operator	Licence No.	State
NSW	12/26	DUNDULLIMAL HOLDINGS PTY LIMITED		

VIN/Chassis/ Engine No. **JLFFN63FU0KJ25120**

Permit No. *(if applicable)*

Date of Issue	Time of Issue	Street and Place of Issue	Infringement / Penalty Notice / Breach Report No.	Vehicle unattended
13/11/2026	11:43	Yarrandale Road Dubbo		Yes [ ] No [X]

Inspection Carried Out - Random [ ] Audit [ ] Other [ ] H.V.I.S [X] Report No. **AZ3089240**

Defect Report I have inspected this vehicle and found that repairs or adjustments are necessary to enable the vehicle to comply with the conditions of the *Road Transport Act 2013* and the *Road Transport (Vehicle Registration) Regulation 2017* or the *Heavy Vehicle National Law (NSW)* and the *Heavy Vehicle (Vehicle Standards) National Regulation (NSW)*.

You are required to have repaired Brakes 01 [ ] Wheels/Tyres 02 [ ] Oil/Fuel Leaks 03 [ ] Exhaust/Noise Emissions 04 [ ]
Steering 05 [ ] Suspension 06 [X] Body/Chassis 07 [ ] Tow Couplings 08 [ ] Ancillary Equipment 09 [ ] Other 10 [ ]
(eg. lights, markings, mirrors, etc.)

The following details were found:

[X] the vehicle is a defective heavy vehicle

[ ] a number plate of the vehicle is wholly or partly obscured, defaced or otherwise not legible

1. On Axle 3 -- Shock absorber leaking - on left

Conditions

Location vehicle is directed to

Issued By *(Signature)* Date **13/11/2026** Authority **NHVR** No. **1044**

Home Station/ Headquarters **3600** Region No. **3510**

Associated Defect Notice/ Continuation No. *if any*

Defect Category: **Self Clearing** [X] **Minor** [ ] **Major** [ ]

Type of label issued None [X] Yellow [ ]

This vehicle may only be used on a road up to the due time/day being [ ] from the time and date of issue of the defect notice.

In relation to heavy vehicles, if the notice is not cleared under section 530 of the *Heavy Vehicle National Law (NSW)*, the vehicle's registration may be suspended and subsequently cancelled by a registration authority under an Australian road law. Self-clearing defect notices do not require clearing at HVAIS or HVIS.

The defect must be cleared by a: Full Inspection [ ] Part Inspection [ ]

at a: Light Vehicle [ ] Heavy Vehicle [ ]

Authorised Inspection Station (AIS) [ ] Authorised Unregistered Vehicle Inspection Station (AUVIS) [ ]

Authorised Taxi Inspection Station (ATIS) [ ] Any NHVR Heavy Vehicle Inspection Station (HVIS) [ ]

Inspection Report

I am satisfied that the vehicle I inspected is the same vehicle for which the defect notice was issued and have found that the defect(s) specified have been properly rectified and any labels affixed have been removed or defaced by me.

Date [ ] Town where inspection was made

AUVIS / AIS / ATIS Inspection *(Indicate type)* [ ] **Police Inspection** [ ] **NHVR Inspection** [ ]

Office Stamp

Station Number Examiner No. Restricted [ ] Unrestricted [ ]

Name of Examiner *(printed)* Inspection Report No.

If Police/NHVR Inspection: Officer's/Inspector's Designation No. Headquarters

Signature of Examiner/Officer and Proprietor *(if not examiner)*