



Commercial Vehicle Inspection Report

Decal Number: PY28009
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21635325

Inspection Result:

PASS

FACILITY: NORTHERN B.C. TRUCKERS / N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN / 106407
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Jan-20 06:00 AM MST
INSP. COMPLETE: 2026-Jan-20 07:20 AM MST

VEHICLE JUR: British Columbia
PLATE #: Jv3674
LICENCED GVW(kg): 59200
VEHICLE YEAR: 2015
MAKE: KENWORTH
MODEL:

REGI: 11475462
UNIT/FLEET#: 117
BODY STYLE: Tank
ODOMETER: 431361 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1NKDX4TX8FJ971567
OWNER/LESSEE NAME: Fort St. John water . .
ADDRESS: 11697 Maclean rd
Fort St John, British Columbia
V1j8b3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) Abs repair
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) Windows
Section 9A - Tires	Passed Recent tires axle 1
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	26	28
2	Clamp	30	Automatic	36	37
3	Clamp	30	Automatic	38	37
4	Clamp	30	Automatic	34	36

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
16			16	✓
9	12	6	8	
12	12	10	11	
13	11	16	15	

Comment:

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVIP at the Commercial Vehicle Safety Enforcement

CVSE014

1/20/2026 7:27:01 AM MST



Commercial Vehicle Inspection Report

Decal Number: PY28009
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21635325

Inspection Result:

PASS

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	63	58
2	58	64
3	60	69
4	69	65

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	17
Lining (Shoe)	16.5	16
Lining (Shoe)	16	15
Lining (Shoe)	15	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: CHRISTIANSON, LESLIE RYAN

Signature: 

This Inspection Report was submitted to CVSE on 2026-Jan-20 07:26 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

1/20/2026 7:27:01 AM MST