



**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	T'Ruckin Oilfield Services		
Address:	po box 448 stn main		
City:	Grande Prairie	Province:	AB
		Postal Code:	T8V3A7
Telephone Number:	(780) 876-4448		
Vehicle Identification Number:	2N9HB60327E065224		
Make:	ETM	Model:	HIBOY
Year:	2007	Unit Number:	TH03
Odometer:	KM	Licence Plate Number:	5NJ857
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
MVR Mechanical Ltd.	16216
Inspection Technician Name:	Technician Number:
Michael Van Rootselaar	B5527
Inspection Technician Signature:	
Inspection Date:	2026/02/04

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

Section 5 - Instruments and Auxiliary Equipment		P	F	NA	P	F	NA
Component	Component						
5.1. Fire Extinguisher							

NOTES:

Section 6 - Lamps		P	F	NA	P	F	NA
Component	Component						
6.1. Required Lamps							
6.2. Reflex Reflector							
6.3. Retro-Reflective Marking							

NOTES:

Section 7 - Electrical System		P	F	NA	P	F	NA
Component	Component						
7.1. Wiring							
7.2. Battery							
7.3. Trailer Cord (output to towed vehicle)							

NOTES:

Section 8 - Body		P	F	NA	P	F	NA
Component	Component						
8.5. Cargo Body							
8.6. Frame Rails & Mounts							
8.7. Utilized Body Elements							
8.8. Cab or Cargo Door							
8.9. Cargo Tank or Vessel							
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle							

NOTES:

Section 9 - Tires and Wheels		P	F	NA	P	F	NA
Component	Component						
9.1. Tire Tread Depth							
9.2. Tire Tread Condition							
9.3. Tire Sidewall & Manufacturer Markings							
9.4. Tire Inflation Pressure							
9.5. Wheel Hub							
9.6. Wheel Bearing							

NOTES:

Section 10 - Couplers and Hitches		P	F	NA	P	F	NA
Component	Component						
10.1. Hitch Assembly, Structure & Attaching Components							
10.2. Secondary Attachment (Safety Chain or Cable)							
10.3. Pin/Head Hook, Pin Hitch, or Coupler Holes							
10.4. Ball Type Hitch							
10.5. Ball-Coupling Hitch							

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

Identification The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #6552001) the Inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2005 and the applicable Inspection Manual.	
Date of Inspection	2026/02/04
Technician Number	B5527
Facility Number	16216
Signature	
Date (Year/Month/Day)	2026/02/04
Customer Acknowledgment	
I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the date of inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is presented for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.	
Customer Signature	