

04080488

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



003-1

Box 45064 Regent Postal Out
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba



C072295

Date Inspection Started DAY: 19 MO: 04 YR: 26	Station Number A5293	Station Name JAZ MECHANICAL LTD WPC	City Winnipeg
Date Inspection Completed DAY: 21 MO: 04 YR: 26	Mechanic Number M3970	Mechanic Signature <i>[Signature]</i>	Station Phone Number 204 9976075
Inspection Expiry Date DAY: 30 MO: 04 YR: 27	Vehicle Owner _____		
Address _____		City _____	Province _____
Postal Code _____		Phone _____	

☒ Pass/Safe Vehicle	Licence Number _____	Prov. MB	NSC # _____	Odometer Reading _____	Odom. Type km ☐ mi ☐
☒ Fail/Unsafe Vehicle	Vehicle Identification Number 2A9073730E A003669		Make ARNEJ	Model END DUMP	Year 2014
☐ Fail/Hazardous	☒ Confirmed legible Vehicle Identification Number on vehicle		Unit # 1158T		

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach B

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																																										
X		Section 1 - Power Train: Defects (if any)																																																																																										
X		Section 2 Suspension: Defects (if any)																																																																																										
X	X	Section 3 - Brake Systems: 3H <u>3A</u> Defects (if any) Circle Brake Type 15E-1ST AXLE DRUMS WORN 15C-1ST AXLE SHOES BELOW SPEC 15C-2ND AXLE SHOES BELOW SPEC 15E-3RD AXLE RIGHT DRUM WORN 15F-1ST+2ND AXLE LEFT WHEEL SEAL LEVEL 2 LEAK 15F-3RD AXLE RIGHT WHEEL SEAL LEVEL 2 LEAK Section 4 - Steering: Defects (if any)																																																																																										
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																										
X		Section 6 - Lamps: Defects (if any)																																																																																										
X		Section 7 - Electrical System: Defects (if any)																																																																																										
X		Section 8 - Body: Defects (if any)																																																																																										
X	X	Section 9 - Tire & Wheel: Defects (if any) 4A-TIRE PSI LOW <table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>12</td> <td>12</td> <td>12</td> <td>12</td> <td>80</td> <td>88</td> <td>78</td> <td>98</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>14</td> <td>14</td> <td>15</td> <td>15</td> <td>76</td> <td>96</td> <td>100</td> <td>98</td> <td>100</td> <td>100</td> <td></td> <td>100</td> </tr> <tr> <td>3</td> <td>6</td> <td>6</td> <td>7</td> <td>6</td> <td>94</td> <td>94</td> <td>96</td> <td>92</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	12	12	12	12	80	88	78	98	100	100	100	100	2	14	14	15	15	76	96	100	98	100	100		100	3	6	6	7	6	94	94	96	92	100	100	100	100	4													5												
Axle	Tread Depth				Air Pressure																																																																																							
	Initial			Corrected		Initial		Corrected																																																																																				
	L	R	L	R	L	R	L	R																																																																																				
1	12	12	12	12	80	88	78	98	100	100	100	100																																																																																
2	14	14	15	15	76	96	100	98	100	100		100																																																																																
3	6	6	7	6	94	94	96	92	100	100	100	100																																																																																
4																																																																																												
5																																																																																												
X		Section 10 - Coupling Devices: Defects (if any)																																																																																										