Alberta Government

CV8664427

80087300008664427

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	**Seating Capacity:**			
GVW:	kg	**Brake Type:**	Air		
Owner Name:	PVT ENERGY GROUP INC.				
Address:	#93 - 721071 RR53				
City:	COUNTY OF GP NO.1	**Province:**	AB	**Postal Code:**	T8X0N4
Telephone Number:	(780) 830-0045				
Vehicle Identification Number:	10BFB7423DF0C6714				
Make:	**Brenner**	**Model:**	**Quad Wagon**		
Year:	**2013**	**Unit Number:**	**TQ0010**		
Odometer:	KM	**Licence Plate Number:**	6SJ257	**Province:**	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	**Facility Number:**
Barr None Mechanical Ltd.	**20069**
Inspection Technician Name:	**Technician Number:**
Cory Moreau	**C2813**
Inspection Technician Signature:	
Inspection Date:	**2026/08/25**

Version No:1

Alberta Government

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle	Gross Vehicle Weight registered
Trailer	kg

Vehicle Information

VIN	1	0	B	F	B	7	4	2	3	D	F	0	C	6	7	1	4

Unit Number	Year	Make	Model	Odometer
TQ0010	2013	Brenner	Quad Wagon	

Registered Owner's Name	Plate Number
PVT ENERGY GROUP INC.	6SJ257

Address	Postal Code	Phone Number
#93 - 721071 RR53	T8X0N4	(780) 830-0045

Drum Brakes: Disc Brakes: D-Full Inspection Wheel Removed

	LEFT		FRONT	RIGHT		
100 psi / 16 mm	100 psi / 13 mm	40.03 mm / 8 mm / N/A mm	Drums/Rotors / Linings/Pads / Push Rod Travel	39.26 mm / 9 mm / N/A mm	100 psi / 16 mm	100 psi / 11 mm
100 psi / 17 mm	100 psi / 15 mm	42.00 mm / 7 mm / N/A mm	Drums/Rotors / Linings/Pads / Push Rod Travel	43.12 mm / 12 mm / N/A mm	100 psi / 13 mm	100 psi / 13 mm
100 psi / 9 mm	100 psi / 9 mm	42.62 mm / 15 mm / N/A mm	Drums/Rotors / Linings/Pads / Push Rod Travel	36.75 mm / 14 mm / N/A mm	100 psi / 10 mm	100 psi / 8 mm
100 psi / 8 mm	100 psi / 8 mm	42.50 mm / 10 mm / N/A mm	Drums/Rotors / Linings/Pads / Push Rod Travel	38.20 mm / 10 mm / N/A mm	100 psi / 7 mm	100 psi / 7 mm
psi / mm	psi / mm	mm / mm / mm	Drums/Rotors / Linings/Pads / Push Rod Travel	mm / mm / mm	psi / mm	psi / mm
psi / mm	psi / mm	mm / mm / mm	Drums/Rotors / Linings/Pads / Push Rod Travel	mm / mm / mm	psi / mm	psi / mm

Park Brake Lining Left N/A mm Right N/A mm Trans N/A mm

Wheel Torque Checked ✓ Inner N/A ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements			✓	8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door			✓	8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel	✓			8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle			✓	8.25. Rear Impact Guard (RIG)	✓		

NOTES:
8.21 - RR FENDER REPAIRED.

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System			✓
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts,& Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:
9.2 - TWO TIRES ON #1 AXLE HAVE BEEN REPLACED.
9.4 - ONE TIRE WITH VALVE CORE LEAK HAS BEEN REPAIRED.
9.5 - TWO HUB GASKETS HAVE BEEN REPLACED.

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)	✓			10.7. Fifth Wheel Coupler			✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch	✓			10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				