



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY08914
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21347775

Inspection Result:

PASS

FACILITY: NORTHERN B.C. TRUCKERS' /
N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN /
106407

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW
5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2025-May-11 08:00 AM MST
INSP. COMPLETE: 2025-May-11 09:30 AM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: RF2082
LICENCED GVW(kg): 18990
VEHICLE YEAR: 2008
MAKE: PETERBILT
MODEL:

REGI: 12966779
UNIT/FLEET#: 260
BODY STYLE: Flat Deck
ODOMETER: 12141 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel

VIN: 2NPRHN8X08M760815
OWNER/LESSEE NAME: MACRO INDUSTRIES, INC
ADDRESS: PO BOX 6781
Fort St John, British Columbia
V1J 4J2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) NEW DRAG LINK
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) NEW DRIVE TIRES
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)		Inner R	Outer R	Steering
						Outer L	Inner L			
1	Clamp	24	Automatic	32	30	18			18	
2	Clamp	30	Automatic	34	36	24	24	24	24	✓

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	32	30
2	34	36

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	18
Lining (Shoe)	19	20

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: CHRISTIANSON, LESLIE RYAN

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-12 11:32 AM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCAVP at the Commercial Vehicle Safety Enforcement.

CVSE014

5/12/2025 11:32:41 AM MST