04006732

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

004-4

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba A998827

	DAY	MO.	YR.
Date Inspection Started	09	10	25
Date Inspection Completed	14	10	25
Inspection Expiry Date	31	10	26

Station Number: A [illegible] 6 — Station Name: Travers Transport — City: [illegible]

Mechanic Number: [illegible] 29 — Mechanic Signature: [illegible] — Station Phone Number: 204 697 5500

Vehicle Owner: WildCoast Excavation INC

Address — City — Province — Postal Code — Phone

- [ ] Pass/Safe Vehicle
- [ ] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: [illegible] 3 — Prov. MB — NSC # — Odometer Reading — Odom. Type [ ] km [ ] mi

Vehicle Identification Number: [illegible] — Make: [illegible] — Model: [illegible] — Year: 15 — Unit #: 123

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR KGS ____Truck Tractor ____Trailer __X__Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
		Section 1 - Power Train: Defects (if any)
		Section 2 Suspension: Defects (if any)
	X	**Section 3 - Brake Systems:** 3H (3A) Defects (if any) — Circle Brake Type: 2-4R Axle tank leaking; 2-1SC LF LR RF brake shoes worn
		Section 4 - Steering: Defects (if any)
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
	X	**Section 6 - Lamps:** Defects (if any) 2-1C Tail Lite
		Section 7 - Electrical System: Defects (if any)
		Section 8 - Body: Defects (if any)
		Section 9 - Tire & Wheel: Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	3/4	3/4	11.5	11.5	1.25	1.25
2	7/8	3/4	11.5	11.5	1.25	1.25
3	7/8	7/8	11.5	11.5	1.25	1.25
4						
5						
	Final Measurement					

32 PSI

	Tread Depth								Air Pressure							
	Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1	10	11	12	10					100	100	100	100				
2	12	11	10	11					100	100	100	100				
3	11	11	11	12					100	100	100	100				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-09/15)

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION