



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY08912
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21347747

Inspection Result:

PASS

FACILITY: NORTHERN B.C. TRUCKERS /
N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN /
106407
WORK ORDER #:
INSR. TYPE: Complete
INSR. CLASS: Class 2 - Heavy Vehicle with LGVW
5501 kg or more
INSR. REASON: Semi-annual
INSR. START: 2025-May-10 03:30 PM MST
INSR. COMPLETE: 2025-May-10 05:00 PM MST

VEHICLE JUR: British Columbia
PLATE #: PA9928
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2014
MAKE: KENWORTH
MODEL:
REGI: 10882377
UNIT/FLEET#: 245
BODY STYLE: Truck Tractor
ODOMETER: 1033511 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel
VIN: 1NKDL40X5ER966990
OWNER/LESSEE NAME: MACRO INDUSTRIES, INC
ADDRESS: PO BOX 6781
Fort St John, British Columbia
V1J 4J2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	24	Automatic	30	31	16			17	
2	Clamp	30	Automatic	36	33	22	22	21	21	✓
3	Clamp	30	Automatic	36	37	21	21	20	20	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	62	60
2	58	55
3	62	57

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	17	17
Lining (Shoe)	16	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date:

Inspector: CHRISTIANSON, LESLIE RYAN Signature: _____

Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-12 11:26 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

CVSE014
5/12/2025 11:27:03 AM MST