

004-8



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY08913
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21347763

Inspection Result:

PASS

FACILITY: NORTHERN B.C. TRUCKERS' /
NS398
INSPECTOR: CHRISTIANSON, LESLIE RYAN /
106407
WORK ORDER #:
INSR. TYPE: Complete
INSR. CLASS: Class 2 - Heavy Vehicle with LGVW
5501 kg or more
INSR. REASON: Semi-annual
INSR. START: 2025-May-10 11:00 AM MST
INSR. COMPLETE: 2025-May-10 12:30 PM MST

VEHICLE/JUR: British Columbia
PLATE #: PA9943
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2015
MAKE: KENWORTH
MODEL:
REGI: 11448882
UNIT/FLEET#: 239
BODY STYLE: Truck Tractor
ODOMETER: 731482 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel
VIN: 1NKDL40X0FR976988
OWNER/LESSEE NAME: MACRO INDUSTRIES, INC
ADDRESS: PO BOX 6781
Fort St John, British Columbia
V1J 4J2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) WINDOWS
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Tire Tread Depth (mm)		Tire Tread Depth (mm)				Steering
				Left	Right	Outer L	Inner L	Inner R	Outer R	
1	Clamp	24	Automatic	30	29	16			16	
2	Clamp	30	Automatic	38	39	22	22	22	22	✓
3	Clamp	30	Automatic	40	42	24	24	24	24	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	61
2	60	59
3	58	62

Comment:

Brake Lining/Pad (mm)

Lining/Pad		Left	Right
Lining (Shoe)		16.5	16
Lining (Shoe)		16	16.5
Lining (Shoe)		17	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum		Left	Right
Rotor/Drum			
Drum			
Drum			
Drum			

Comment: Air Brake Camshaft Rotation performed, Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: CHRISTIANSON, LESLIE RYAN
Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-12 11:29 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVI at the Commercial Vehicle Safety Enforcement

CVSE014

5/12/2025 11:29 AM MST