



Commercial Vehicle Inspection Report

Decal Number: GP84433
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21960904

Inspection Result:

PASS

FACILITY: NAHANNI TRUCK & TRAILER / S5800
INSPECTOR: Vasquez Cruz, Rafael Antonio / 111688
WORK ORDER #: 94303
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2026-Oct-20 10:15 AM PDT
INSP. COMPLETE: 2026-Oct-20 03:15 PM PDT

VEHICLE JUR: British Columbia
PLATE #: VE6677
LICENCED GVW(kg): 56000
VEHICLE YEAR: 2019
MAKE: KENWORTH
MODEL:
REGI: 12909658
UNIT/FLEET#: h1895
BODY STYLE: Truck Tractor
ODOMETER: 330220 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1XKDD40X8KJ949354
OWNER/LESSEE NAME: A.O.K EQUIPMENT LTD, AOK EQUIPMENT LTD
ADDRESS: 7025 DOUMONT RD
Nanaimo, British Columbia
V9T6G9, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) REPLACED SLACK ADJUSTER#2 AXLE L/S
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) REPLACE STEERING SHAFT JOINTS
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	25	25	14.3			15.1	✓
2	Clamp	30L	Automatic	38	38	8.7	9.5	9.5	9.5	
3	Clamp	30L	Automatic	38	38	13.5	13.5	11.1	11.1	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	60
2	55	53
3	75	65

Comment:

Brake Lining/Pad (mm)

	Left	Right
Lining/Pad		
Lining (Shoe)	15	15
Lining (Shoe)	15	15
Lining (Shoe)	12	14

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Left	Right
Rotor/Drum		
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: Vasquez Cruz, Rafael Antonio

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Oct-20 03:34 PMPDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 218 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement.

CVSED014

10/20/2026 3:35:01 PM PDT