



Commercial Vehicle Inspection Report

Decal Number: GP84432
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21960175

005-
Inspection Result:
PASS

FACILITY: NAHANNI TRUCK & TRAILER / S5800
INSPECTOR: Vasquez Cruz, Rafael Antonio / 111688
WORK ORDER #: 94301
INSPECTION TYPE: Complete
INSPECTION CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSPECTION REASON: Semi-annual
INSPECTION START: 2026-Oct-15 02:15 PM PDT
INSPECTION COMPLETE: 2026-Oct-19 03:45 PM PDT
VEHICLE JUR: British Columbia
PLATE #: VE6675
LICENCED GVW(kg): 47500
VEHICLE YEAR: 2018
MAKE: KENWORTH
MODEL:
REGI: 12347726
UNIT/FLEET#: ht898
BODY STYLE: Truck Tractor
ODOMETER: 115654 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1XZD49X6J992342
OWNER/LESSEE NAME: A.O.K equipment ltd, A.O.K equipment ltd
ADDRESS: 7025 doumont rd
Nanaimo, British Columbia
v9t6g9, Canada

Vehicle Identification (VIN) Passed
Section 1 - Power Train Passed
Section 2 - Suspension Repaired (same day) replaced front shackle pins and bushings
Section 3 - Brake System Passed
Section 3A - Air Brakes Passed
Section 3H - Hydraulic Brakes Not Applicable
Section 4 - Steering Passed
Section 5 - Instruments and Auxiliary Equipment Passed
Section 6 - Lamps Passed
Section 7 - Electrical System Passed
Section 8 - Frame and Body Passed
Section 9A - Tires Passed
Section 9B - Wheels Passed
Section 10 - Coupling Devices Passed
Section 11 - Other Vehicle Components Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	25	25	8.7			11.1	✓
2	Clamp	30L	Automatic	38	38	10.3	9.5	10.3	10.3	
3	Clamp	30L	Automatic	38	38	9.5	9.5	7.9	7.9	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	25	25
2	40	53
3	50	55

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	20	20
Lining (Shoe)	18	15
Lining (Shoe)	15	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: Vasquez Cruz, Rafael Antonio

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Oct-20 11:12 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

10/20/2026 11:12:06 AM PDT