

CUSTOMER # 228648

731726

INVOICE



JSP CONSTRUCTION
PO BOX 24252
TEMPE, AZ 85285-4252

PAGE 1

2121 N. Arizona Ave. · Chandler, AZ 85225
(480) 899-0131

www.earnhardtchevroletaz.com

HOME: 480-766-8437 CONT: 480-766-8437
BUS: 480-250-6722 CELL: 480-553-3324

SERVICE ADVISOR: 54 RICHARD HAMILTON

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	96	CHEVROLET KODIAKC450	1GBJ7H1P8TJ105172		117343/117343	T1043	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN96 DD			17:00 26NOV21		0.00	CASH	21DEC21
R.O. OPENED		BOOKED		OPTIONS: ENG:5.7_LITER_MFI_WRN			
09:16 11OCT21		14:24 21DEC21					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A C/S THE RADIATOR CRACKED AND LEAKED COOLANT OUT AND OVER HEATED CAUSE: INSPECTED COOLING SYSTEM COMPONENTS AND FOUND RADIATOR DRAIN PETCOCK BROKEN. WHEN REPLACED PETCOCK PRESSURE TESTED COOLING SYSTEM AND FOUND COOLANT LEAKING INTO CYLINDERS. SENT CYLINDER HEADS TO BE MACHINED AND WHEN CYLINDER HEADS REINSTALLED PRESSURE TESTED COOLING SYSTEM AGAIN TO VERIFY AND FOUND HAIRLINE CRACK IN ENGINE BLOCK S120 HEAVY LINE ENTER CONCERN HERE							
			335 CFLT	0.00		0.00	0.00
1	PO143485		DRAIN PLUG		5.81	4.94	4.94
1	88862587		LUBRICANT		31.84	27.06	27.06
1	88866165		78VGHR140		179.95	152.96	152.96
	CORE CHARGE C					11.00	11.00
-1	88866165		CORE RETURN		11.00	11.00	-11.00
1	PO144952		BATTERY BOLT 2 PACK		6.60	5.61	5.61
1	PO145813		OIL SWITCH		71.17	60.49	60.49
1	19385578	(S)	FILTER		16.09	13.68	13.68
	EN30 Cylinder Head Gasket Replace					1562.50	1562.50
			335 CFLT 12:50				
1	88864346		SEALANT		15.72	13.36	13.36
2	12346290		COOLANT		23.70	20.14	40.28
2	10126727	(S)	GASKET		66.81	56.79	113.58
1	10108445	(S)	GASKET		1.52	1.29	1.29
16	10114119	F- (S)	SEAL		11.78	10.01	160.16
24	10141204	(S)	BOLT		4.83	4.11	98.64
2	12551449	(S)	GASKET		27.64	23.49	46.98
10	10141205	(S)	BOLT		5.23	3.56	35.60
2	PO143703		HEAD GASKET		43.00	43.00	86.00
1	PO143703		INTAKE GASKET		55.36	47.06	47.06
1	PO144166		EXH VALVE		24.99	21.24	21.24
1	PO144641		PUSHROD		7.64	7.64	7.64
1	PO144641		PUSHROD		7.96	7.96	7.96
	TU10 Spark Plugs - Replace					150.00	150.00
			335 CFLT 1.50				



TERMS OF SALE:
DETAILS AND LIMITATIONS OF WARRANTIES, DISCLAIMER OF WARRANTIES AND
EXPLANATIONS OF SUPPLY CHARGES ARE ON THE REVERSE SIDE HEREOF.

BUYER AND SELLERMUTUALLY AGREE THAT ANY DISPUTE ARISING AS A RESULT
OF THIS SALE WILL BE ARBITRATED UNDER THE RULES OF THE AMERICAN
ARBITRATION ASSOCIATION AND THAT THE DECISION MADE WILL BE FINAL. IT IS
FURTHER AGREED THAT IN THE EVENT THIS IS A CHARGE SALE OR A SALE PAID BY
CHECK THAT ANY COSTS INCURRED BY SELLER TO SECURE PAYMENT WILL BE
PAID BY BUYER.

I AGREE FURTHER THAT I AM RESPONSIBLE FOR ALL CHARGES NOT COVERED BY
MANUFACTURER'S WARRANTY.

CUSTOMER SIGNATURE

X

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
ADJUSTMENTS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER # 228648
JSR CONSTRUCTION
PO BOX 24252
TEMPE, AZ 85285-4252

731726

INVOICE



PAGE 2

2121 N. Arizona Ave. · Chandler, AZ 85225
(480) 899-0131

www.earnhardtchevroletaz.com

HOME: 480-766-8437 CONT: 480-766-8437
BUS: 480-250-6722 CELL: 480-553-3324

SERVICE ADVISOR: 54 RICHARD HAMILTON

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
	96	CHEVROLET KODIAKC450		1GBJ7H1P8TJ105172		117343/117343		T1043
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
01JAN96 DD			17:00 26NOV21		0.00	CASH	21DEC21	
R.O. OPENED		BOOKED		OPTIONS: ENG:5.7 LITER MFI WRN				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
8	19417094	(S)	SPARK PLUG		3.36	2.86	22.88
1	12346290		COOLANT		23.70	20.14	20.14
TU23 Spark Plug Wire Sets - Replace							
	335	CFLT	1.50			150.00	150.00
1	19170843	W-	(S)WIRE KIT		119.32	101.42	101.42
1	19166099	(S)	CAP		47.20	40.12	40.12
1	10477219	(S)	ROTOR		48.24	41.00	41.00
1	10096181	(S)	SENSOR		37.20	31.62	31.62
MA11 Oil, Filter and Lube							
	335	CFLT	0.40			14.35	14.35
1	25160561	(S)	FILTER		7.41	6.30	6.30
10	19419532		OIL		7.68	6.53	65.30
MISC gm ovn freight part#10114119							
	CFLT					25.56	25.56
MISC gm ovn freight part#10141204							
	CFLT					23.87	23.87
MISC gm ovn freight part#10141205							
	CFLT					12.78	12.78
SUBL DAY AUTO VENDER#4563 INV#736828 PO#144166							
	CFLT					785.00	785.00
PARTS: 1273.31 LABOR: 1876.85 OTHER: 847.21 TOTAL LINE A:							3997.37

117343 INSPECTED COOLING SYSTEM COMPONENTS AND FOUND RADIATOR DRAIN PETCOCK BROKEN. WHEN REPLACED PETCOCK PRESSURE TESTED COOLING SYSTEM AND FOUND COOLANT LEAKING INTO CYLINDERS. SENT CYLINDER HEADS TO BE MACHINED AND WHEN CYLINDER HEADS REINSTALLED PRESSURE TESTED COOLING SYSTEM AGAIN TO VERIFY AND FOUND HAIRLINE CRACK IN ENGINE BLOCK 15.90 REPLACED RADIATOR DRAIN PETCOCK, RESURFACED CYLINDER HEADS AND FOUND CRACK IN ENGINE BLOCK ALLOWING COOLANT INTO THE CRANKCASE. ENGINE REQUIRED.

B PERFORM WORLD CLASS MULTI-POINT VEHICLE INSPECTION
MPI PERFORM WORLD CLASS MULTI-POINT VEHICLE
INSPECTION

335 ICS 0.30

(N/C)

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
ADJUSTMENTS	
SALES TAX	
PLEASE PAY THIS AMOUNT	



TERMS OF SALE:
DETAILS AND LIMITATIONS OF WARRANTIES, DISCLAIMER OF WARRANTIES AND EXPLANATIONS OF SUPPLY CHARGES ARE ON THE REVERSE SIDE HEREOF.

BUYER AND SELLERMUTUALLY AGREE THAT ANY DISPUTE ARISING AS A RESULT OF THIS SALE WILL BE ARBITRATED UNDER THE RULES OF THE AMERICAN ARBITRATION ASSOCIATION AND THAT THE DECISION MADE WILL BE FINAL. IT IS FURTHER AGREED THAT IN THE EVENT THIS IS A CHARGE SALE OR A SALE PAID BY CHECK THAT ANY COSTS INCURRED BY SELLER TO SECURE PAYMENT WILL BE PAID BY BUYER.

I AGREE FURTHER THAT I AM RESPONSIBLE FOR ALL CHARGES NOT COVERED BY MANUFACTURER'S WARRANTY.

CUSTOMER SIGNATURE

X

CONFIDENTIAL
CUSTOMER #: 228648
NAPA
WAB CONSTRUCTION
PO BOX 24252
TEMPE, AZ 85285-4252

738361

INVOICE



PAGE 1

2121 N. Arizona Ave. · Chandler, AZ 85225
(480) 899-0131

www.earnhardtchevroletaz.com

HOME: 480-766-8437 CONT: 480-766-8437
BUS: 480-250-6722 CELL: 480-553-3324

SERVICE ADVISOR: 54 RICHARD HAMILTON

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	96	CHEVROLET KODIAKC450	1GBJ7H1P8TJ105172		117592/117592	T1731	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN96 DD			17:00 17FEB22		0.00	CASH	25FEB22
R.O. OPENED		BOOKED	OPTIONS: ENG:5.7_LITER_MFI_WRN				
08:43 17FEB22		08:36 25FEB22					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A C/S THERE IS A LOUD SQUEALING NOISE FROM ENGINE WHILE RUNNING. SEE
LAST VISIT.

CAUSE: FOUND LOUD SQUEALING NOISE FROM ENGINE TO BE BELTS
S120 HEAVY LINE ENTER CONCERN HERE

335 CFLT	0.00		0.00	0.00			
1 PO148161 V-BELT		45.00	38.25	38.25			
1 PO148166 SERPENTINE BELT		57.83	49.16	49.16			
PARTS:	87.41	LABOR:	0.00	OTHER:	0.00	TOTAL LINE A:	87.41
117592 FOUND LOUD SQUEALING NOISE FROM ENGINE TO BE BELTS 1.50							
REPLACED BOTH BELTS AND SQUEAL WENT AWAY.							

B C/S THE A/C IS NOT BLOWING COLD SINCE LAST VISIT.

CAUSE: FOUND AC WIRE CRUNCHED.

S120 HEAVY LINE ENTER CONCERN HERE

335 CFLT	1.50		187.50	187.50
-1 PO148242 COMPRESSOR		574.98	488.73	488.73
32 134A5 FREON OZ		1.00	0.85	27.20
PARTS: 515.93	LABOR: 187.50	OTHER: 0.00	TOTAL LINE B: 703.43	
117592 FOUND AC WIRE CRUNCHED. 2.70 REPLACED AC COMPRESSOR AND EVACUATED AND RECHARGED AC SYSTEM. RETESTED AND ALL OK AT THIS TIME.				

Thank you for choosing Earnhardt Chevrolet.
You may receive an email survey from GM
Customer Satisfaction about your visit. We
appreciate you taking the time to respond.
If for any reason you are not completely
satisfied, please call Doug Miller
(480)814-1214 to share your concern.



TERMS OF SALE:
DETAILS AND LIMITATIONS OF WARRANTIES, DISCLAIMER OF WARRANTIES AND
EXPLANATIONS OF SUPPLY CHARGES ARE ON THE REVERSE SIDE HEREOF.

BUYER AND SELLERMUTUALLY AGREE THAT ANY DISPUTE ARISING AS A RESULT
OF THIS SALE WILL BE ARBITRATED UNDER THE RULES OF THE AMERICAN
ARBITRATION ASSOCIATION AND THAT THE DECISION MADE WILL BE FINAL. IT IS
FURTHER AGREED THAT IN THE EVENT THIS IS A CHARGE SALE OR A SALE PAID BY
CHECK THAT ANY COSTS INCURRED BY SELLER TO SECURE PAYMENT WILL BE
PAID BY BUYER.

I AGREE FURTHER THAT I AM RESPONSIBLE FOR ALL CHARGES NOT COVERED BY
MANUFACTURER'S WARRANTY

CUSTOMER SIGNATURE

X

DESCRIPTION	TOTALS
LABOR AMOUNT	187.50
PARTS AMOUNT	603.34
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	790.84
ADJUSTMENTS	0.00
SALES TAX	47.06
PLEASE PAY THIS AMOUNT	837.90

CONFIDENTIAL
CUSTOMER #: 228648
PO BOX 24252
TEMPE, AZ 85285-4252
HOME: 480-766-8437
BUS: 480-250-6722
CELL: 480-766-8437

745057

INVOICE

DUPLICATE 1
PAGE 1



2121 N. Arizona Ave. · Chandler, AZ 85225
(480) 899-0131

www.earnhardtchevroletaz.com

SERVICE ADVISOR: 42 AJ PENTZ

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	96	CHEVROLET KODIAC 450	1GBJ7H1P8TJ105172		118036/118036	T2137	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN96 DD			17:00 10AUG22		0.00	CASH	26AUG22
R.O. OPENED		BOOKED		OPTIONS: ENG:5.7 LITER MFI WRN 1)SAMS 480-250-6722 2)JASON 480-766-8437			
13:26 26JUL22		13:42 26AUG22					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A Customer states vehicle wont pass emissions due to hydro carbons
please advise.

S160 DRIVABILITY AND ELECTRICAL

229 CFLT 2.00

270.00 270.00

PARTS: 0.00 LABOR: 270.00 OTHER: 0.00 TOTAL LINE A: 270.00

118036 Interrogated fault memory and found no active or stored
dtcs. Monitored fuel trims and exhaust to confirm hydro carbon count.
Performed adjustments to timing and plug wires while monitoring
exhaust. After making adjustments verified proper emissions output and
took vehicle through emission, passed. Vehicle operating as designed at
this time.

B PERFORM WORLD CLASS MULTI-POINT VEHICLE INSPECTION

MPI PERFORM WORLD CLASS MULTI-POINT VEHICLE
INSPECTION

229 IMPI 0.30

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

Thank you for choosing Earnhardt Chevrolet.
You may receive an email survey from GM
Customer Satisfaction about your visit. We
appreciate you taking the time to respond.
If for any reason you are not completely
satisfied, please call Doug Miller
(480)814-1214 to share your concern.



TERMS OF SALE:
DETAILS AND LIMITATIONS OF WARRANTIES, DISCLAIMER OF WARRANTIES AND
EXPLANATIONS OF SUPPLY CHARGES ARE ON THE REVERSE SIDE HEREOF.

BUYER AND SELLERMUTUALLY AGREE THAT ANY DISPUTE ARISING AS A RESULT
OF THIS SALE WILL BE ARBITRATED UNDER THE RULES OF THE AMERICAN
ARBITRATION ASSOCIATION AND THAT THE DECISION MADE WILL BE FINAL. IT IS
FURTHER AGREED THAT IN THE EVENT THIS IS A CHARGESALE OR A SALE PAID BY
CHECK THAT ANY COSTS INCURRED BY SELLER TO SECURE PAYMENT WILL BE
PAID BY BUYER.

I AGREE FURTHER THAT I AM RESPONSIBLE FOR ALL CHARGES NOT COVERED BY
MANUFACTURER'S WARRANTY.

CUSTOMER SIGNATURE

X

DESCRIPTION	TOTALS
LABOR AMOUNT	270.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	270.00
ADJUSTMENTS	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	270.00



AUTO CENTERS

AUTHORIZATION AND ACKNOWLEDGMENT

I authorize the work described in this repair order and authorize the use of any supplies or materials necessary to accomplish that work. A mechanic's lien on the vehicle is expressly acknowledged to secure payment for the materials, parts and/or services provided in connection with the work.

I grant you and your employees permission to operate the vehicle, including on public streets or highways, for purposes of testing and/or inspection. I acknowledge that any rental car provided must be returned upon my receipt of notice that the work has been completed. I authorize you to endorse and cash any draft or other instrument made payable to me for the work. I acknowledge that you are not responsible for articles left in the vehicle, or for any loss or damage to the vehicle, in case of fire, theft or any other cause beyond your control.

ENVIRONMENTAL COMPLIANCE AND SHOP SUPPLIES CHARGE

Maintaining and repairing vehicles involves the use of chemicals and generates wastes that must be stored, managed and disposed of in strict compliance with federal, state and local environmental regulations. Complying with these regulations increases the cost of providing service for your vehicle. Additionally, many miscellaneous supplies and materials are used each time a vehicle is serviced. Ordinarily the costs of environmental compliance and supplies would result in an increase in the hourly labor charge. Instead, we add a standard charge for compliance and supplies on each repair order. The charge is the greater of \$3.23, or 8.0% of the total labor charges and 8.0% of the total charges for parts. The charge in no instance exceeds \$49.23 per repair order. The charge is clearly disclosed in the lower right corner of the repair order. If you would like a list of some of the procedures and material covered by this charge, please ask your service advisor.

LIMITATION ON AND DISCLAIMER OF WARRANTIES

Any warranties on parts or accessories, whether express or implied and including any warranty of merchantability or fitness for a particular purpose, are limited to those offered by the manufacturer. **Dealer disclaims all warranties, whether express or implied, on parts or accessories, including any warranty of merchantability or fitness for a particular purpose.** You may obtain warranty service from any provider associated with or authorized by the manufacturer. If given the opportunity to serve you, we will serve you in the same professional and ethical manner in which we have built our reputation.

WARRANTY ON LABOR AND PARTS

Dealer warrants the workmanship of its agents for 24 months or unlimited miles, whichever comes first. Any repair performed pursuant to this warranty shall be performed in dealer's service center. This warranty does not include consequential damages and is voided in the event any repair performed by dealer has been tampered with by any person not authorized by dealer. Any warranties implied by state law shall be limited to the period of this written warranty.