



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GJ00279
Decal Expiry Date: 2025-Sep-30
Inspection Number: 21263056

Inspection Result:

PASS

FACILITY: ARSARA DIESEL TRUCK / S5708 INSP. TYPE: Complete INSP. START: 2025-Mar-05 05:41 PM PST
INSPECTOR: Bhachu, Sukhjinder Singh / 201670 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2025-Mar-07 07:37 PM PST
WORK ORDER #:

VEHICLE JUR: British Columbia REGI: 10500433 VIN: 2A90730263A003254
PLATE #: 79866K UNIT/FLEET#: OWNER/LESSEE NAME: GNA CONTERCTING LTD.,
LICENCED GVW(kg): 999999 BODY STYLE: Dump Trailer ADDRESS: 9123 147A ST
VEHICLE YEAR: 2003 ODOMETER: Surrey, British Columbia
MAKE: ARNES HUB ODOMETER: V3R3V9, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) AIR BAG VALVE REPLACED
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) 2ND XLRIS MAXI REPLACED MAXI AIR LINES SECURE FROM RUBBING
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) REAR ONE MARKER LIGHT FIX
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) LANDING GEAR X MEMBER WELDING REPAIR
Section 9A - Tires	Passed with Caution 2ND XL LIS OUTER TIRE
Section 9B - Wheels	Repaired (same day) 2ND XL LIS WHEEL OIL HUB CAP REPLACED
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	30	30
2	Clamp	30	Automatic	30	35

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
12	12	17	17	
4	17	12	7	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	85	80
2	80	85

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	13	13
Lining (Shoe)	14	13


Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed, Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date:  Road Tester:
Inspector: Bhachu, Sukhjinder Singh Signature:

This Inspection Report was submitted to CVSE on 2025-Mar-07 07:37 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

3/7/2025 7:37:34 PM PST