

Vehicle Details					
Registration	XA40AB	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	N/A
Model	K104	Engine #	06R0611798	Air	Yes
Model Series		VIN	421078	Cyl	0
Model Code		Build Date		Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	872584	Prod	

Invoice No.	Date	Odometer	Description	Type
2094	17/10/2024	872584	Annual Inspection	Invoice

RMS INSPECTIONnull

Annual inspection				
-------------------	--	--	--	--

1587	29/03/2023	816308	A Service	Invoice
	CONS		General Consumables Used	
	LAB		Labour	

A Service				
-----------	--	--	--	--

1192	25/07/2021	109984	a service	Invoice
	LAB		Labour	

A service				
-----------	--	--	--	--

1078	09/12/2020	766610	Annual Inspection	Invoice
	839310		Bushing	
	73D2002		Shock Rubbers	
	11R22.5		11R 22.5 tyre	
	LAB		Labour	

Annual inspection Replace rear torque rod bushes x 4 Replace left front drive tyres				
---	--	--	--	--

1077	13/07/2020	0	Indicator Switch	Invoice
	K103-395		Turn signal switch	

Replace turn signal switch				
----------------------------	--	--	--	--

933	18/06/2020	757705	B service	Invoice
	LF3620		Detroit Oil Filter	
	FF5206		Fuel Filter	
	FF5207		fuel filter	
	VECTON		Vecton 15W40 Engine Oil	
	KSMA2124707QP		Brake Shoes Meritor Drive	
	47693		Wheel Seal	
	CONS		General Consumables Used	
	LAB		Labour	

B Service				
-----------	--	--	--	--

Vehicle Details

Registration	XA40AB	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	N/A
Model	K104	Engine #	06R0611798	Air	Yes
Model Series		VIN	421078	Cyl	0
Model Code		Build Date		Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	872584	Prod	

Invoice No.	Date	Odometer	Description	Type
Replace brake on left front drive wheel (oil contamination)				
788	09/01/2020	740059	A Service	Invoice
	LAB		Labour	
	CONS		General Consumables Used	
A Service				
745	08/11/2019	732436	Jack Shaft	Invoice
	6.82.1341.7		shaft YK 1710 Jack Shaft rear	
	5.280X		1710 universal joint kit	
	LAB		Labour	
Replace Rear of jack shaft & both uni joints				
741	22/10/2019	732436	Annual Inspection	Invoice
	LAB		Craig	
Annual inspection				
650	25/06/2019	724717	C Service	Invoice
	WBK4SUCR		Wheel Bearing Kit	
	T2000SK-P		Air Dryer Kit	
	TFC410		10w gear oil	
	TFC450		Gear oil	
	AP85W140		Diff oil	
	186917		V Clamp Exhaust	
	2306-JW		Flange Exhaust Lipped 5"	
	SSFBKEN102-335		Exhaust Flex Stainless Steel	
	2547/JW		5" exhaust clamp	
	LAB		Craig & Nick	
	K374-41KIT		Shock Absorber	
	73D2002		Shock Rubbers	
	281-2114-01		Clamshell bracket Top	
	CA1516-7310		Cab ram	
	N70ZZHMF		Battery	
	VECTON		Vecton 15W40 Engine Oil	
	LF3620		Detroit Oil Filter	
	FF5206		Fuel Filter	
	FF5207		fuel filter	
	AF1968M		Air filter	
• C service • Replace cab rams • Replace Batteries • Replace Front drive shock absorbers • Replace leaking exhaust flange on turbo & fit new exhaust flex. • Replace drivers seat with used seat KAB				
525	29/03/2019	712613	A Service	Invoice
	LAB		Jimmy	
	CONS		General Consumables Used	

Vehicle Details

Registration	XA40AB	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	N/A
Model	K104	Engine #	06R0611798	Air	Yes
Model Series		VIN	421078	Cyl	0
Model Code		Build Date		Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	872584	Prod	

Invoice No.	Date	Odometer	Description	Type
A Service Remove front wheels & tyres Check & top up balance beads & replace tyres & wheels				
374	15/11/2018	698714	B service LF3620 WF2077 FS19624 VECTON SK2105/15 SK215/19 SK2121/07 LAB LAB Detroit Oil Filter Water filter no DCA Fuel Water Seperator Vecton 15W40 Engine Oil Lock Jaw JSK turntable Wear Ring Jost Bolt wear pad retainer Josh Jimmy Craig	Invoice
B Service Fit new turntable jaw & wear ring.				
348	26/10/2018	693431	Annual Inspection LAB Labour	Invoice
Annual inspection				
251	19/06/2018	685708	A Service LAB CONS Labour General Consumables Used	Invoice
A Service				
186	16/05/2018	0	Cab Jack LAB HP50034204 Labour Cab Jack Pump Assy	Invoice
Replace Cab jack assembly				

CORKHILL BROS

CANBERRA

Vehicle History

Vehicle Details

Registration	XA40AB	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	N/A
Model	K104	Engine #	06R0611798	Air	Yes
Model Series		VIN	421078	Cyl	0
Model Code		Build Date		Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	872584	Prod	

Invoice No.	Date	Odometer	Description	Type
2094	17/10/2024	872584	Annual Inspection	Invoice
Annual inspection				
1587	29/03/2023	816308	A Service	Invoice
A Service				
1192	25/07/2021	109984	a service	Invoice
A service				
1078	09/12/2020	766610	Annual Inspection	Invoice
Annual inspection Replace rear torque rod bushes x 4 Replace left front drive tyres				
1077	13/07/2020	0	Indicator Switch	Invoice
Replace turn signal switch				
933	18/06/2020	757705	B service	Invoice
B Service Replace brake on left front drive wheel (oil contamination)				
788	09/01/2020	740059	A Service	Invoice
A Service				
745	08/11/2019	732436	Jack Shaft	Invoice
Replace Rear of jack shaft & both uni joints				
741	22/10/2019	732436	Annual Inspection	Invoice
Annual inspection				
650	25/06/2019	724717	C Service	Invoice
• C service • Replace cab rams • Replace Batteries • Replace Front drive shock absorbers				

Vehicle Details

Registration	XA40AB	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	N/A
Model	K104	Engine #	06R0611798	Air	Yes
Model Series		VIN	421078	Cyl	0
Model Code		Build Date		Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	872584	Prod	

Invoice No.	Date	Odometer	Description	Type
• Replace leaking exhaust flange on turbo & fit new exhaust flex. • Replace drivers seat with used seat KAB				
525	29/03/2019	712613	A Service	Invoice
A Service Remove front wheels & tyres Check & top up balance beads & replace tyres & wheels				
374	15/11/2018	698714	B service	Invoice
B Service Fit new turntable jaw & wear ring.				
348	26/10/2018	693431	Annual Inspection	Invoice
Annual inspection				
251	19/06/2018	685708	A Service	Invoice
A Service				
186	16/05/2018	0	Cab Jack	Invoice
Replace Cab jack assembly				