

Vehicle Details

Registration	YGF60E	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	N/A
Model	T404 SAR	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TIPPER
Colour	Corkhills	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
2010	03/09/2024	0	Clutch Link	Invoice

VFS6G-8

Rod End Clutch Link

Replace clutch rod end & Adjust clutch

1324	03/12/2021	0	Spring pack	Invoice
	140KK100		King Pin Kit	
	K179-536		Pin threaded	
	K179-537		Pin threaded	
	8200308		Starter motor 39MT	

Replace front spring pack left side
Replace both kin pins
Replace spring pin bushes right side

1279	16/06/2021	63704	B service	Invoice
	LF3620		Detroit Oil Filter	
	FF5206		Fuel Filter	
	FF5207		fuel filter	
	VECTON		Vecton 15W40 Engine Oil	
	AS95410		Air Spring Kenworth	
	K066-310		Shock Rubbers	
	AF1968M		Air filter	
	47693		Wheel Seal	
	KSMA2124715QP		Brake Shoe Kit Front Axle KW	
	11R22.5 MAXXIS DRIVE		11r22.5 Maxxix Drive UL387	
	NPN01		tyre disposal	
	110889		Axle shaft	
	15-730S		Trailer Plug	
	N70ZZHMF		Battery	
	NPN03		Quick release couplings	

- B Service
- Replace two air bags on left side
- Replace shock rubbers on left front drive
- Replace brake lining & wheel seal right rear drive
- Replace broken drive axle
- Replace 7 pin plug on trailer
- Repair lights on truck & trailer
- Replace two drive tyres
- 4 Batteries

1181	28/01/2021	0	Power steer tank	Invoice
------	------------	---	------------------	---------

Vehicle Details

Registration	YGF60E	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	N/A
Model	T404 SAR	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TIPPER
Colour	Corkhills	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
91410J			Reservoir Power Steering	

Replace power steer tank

1083	30/11/2020	34015	B service & Annual Inspection	Invoice
	LAB		Labour	
	LF3620		Detroit Oil Filter	
	FF5206		Fuel Filter	
	FF5207		fuel filter	
	VECTON		Vecton 15W40 Engine Oil	
	73D2002		Shock Rubbers	
	839310		Bushing	
	NPN03		Mud flaps	
	NPN03		Head light LED	

B Service & Annual inspection

- Replace 8 rear torque rod bushes
- Replace 3 sets rear shock rubbers
- Fit new power steer pump
- Replace right head light LED

1020	18/09/2020	16363	A Service & Repairs	Invoice
	NPN01		tyre disposal	
	KSMA2124720QP		Shoe kit meritor steer	
	A24-3275M1079PZ		Auto Slack Adjuster 5.5" 28	
	PS28020-131105		TGW Power steer pump	
	4988280		Gasket flange	
	11R22.5 MAXXIS DRIVE		11r22.5 Maxxix Drive HAR518	
	8-22-285P1		Wheel Alloy 285X10	
	KIT8042		S Cam bush kit	
	91674		LED Number Plate Light	
	K066-310		Shock Rubbers	
	LAB		Labour	

A Service

- Replace brakes on all drive wheels
- Fit auto slack adjusters
- replace 6 x shock rubbers
- replace number plate lights
- fit 4 drive tyres
- fit one new rim to right rear drive
- Check & repair lights & coolant leaks
- Order power steer pump

964	06/07/2020	870	C Service	Invoice
	TRP5003980		Check Valve	
	TRPN15759BA		Valve Pressure protection	
	800839		Check Valve	
	AX50		Drive belt	
	13A1320		Belt	
	090-2209SP2B		Shock Absorber Kenworth 104	
	LAB		Labour	
	803901P		803901P	

Vehicle Details

Registration	YGF60E	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	N/A
Model	T404 SAR	Engine #	06R0777284	Air	Yes
Model Series		VIN	427003	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour	Corkhills	Odometer	63704	Prod	

Invoice No.	Date	Odometer	Description	Type
	23532437		Thermostat 180 deg	
	TFC410		10w gear oil	
	TFC450		Gear oil	
	AP85W140		Diff oil	
	WF2077		Water filter no DCA	
	HF6107		Oil Filter	
	LF3620		Detroit Oil Filter	
	FF5206		Fuel Filter	
	FF5207		fuel filter	
	VECTON		Vecton 15W40 Engine Oil	
	K152-551-1G		Speedometer 120 KPH Gold series	
	800839		Check Valve	
	T2000SK-P		Air Dryer Kit	
	WBK4SUCR		Wheel Bearing Kit	
	KSMA2124720QP		Shoe kit meritor steer	

C Service
• Replace speedo • Replace thermostats 180 deg • Replace front shock absorbers • Replace coolant switch • Replace 2 x check valves & pressure protection valve • Steer Brake linings

951	22/06/2020	9877	Water Pump	Invoice
	LAB		Labour	
	COOLANT		Coolant	
	295/80R22.5		Tyre AH22R	
	8-22-285P1		Wheel Alloy 285X10	
	NPN01		Tyre Disposal	

Travel to William Hovell Dr and check for water leak. Fill with water & bring back to workshop Replace water pump

950	25/05/2020	0	Electrical Faults	Invoice
	SUBLET		Sublet	

900	08/04/2020	996574	A service & repairs	Invoice
	LAB		Labour	
	AS95410		Air Spring Kenworth	
	N70ZZMF		Battery Century HP	
	SUBLET		Windscreen	

A Service
• Replace windscreen

Vehicle Details

Registration	YGF60E	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	N/A
Model	T404 SAR	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TIPPER
Colour	Corkhills	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
• Replace leaking air bag Right Rear • Replace faulty Battery • Replace clutch ball joint • Repair Head lights & Clearance lights				

839	10/02/2020	981234	Oil Leak, B service & Repairs	Invoice
	LAB		Craig	
	NPN03		1 1/2 Suction hos & Clamps	
	8-22-285P1		Wheel Alloy 285X10	
	WWBG-12		Dust blower	
	CONS		General Consumables Used	
	LF3620		Detroit Oil Filter	
	FF5206		Fuel Filter	
	FF5207		fuel filter	
	WF2077		Water filter no DCA	
	K066-310		Shock Rubbers	
	286171		Brake treadle valve	
	101AUSKIT		Ring Feeder Service kit	
	11R22.5 D'COIN RLB400		11R22.5 D'Coin RLB400	
	NPN01		tyre disposal	

Replace Suction hose to PTO

- B Service
- Replace brake treadle valve & one way check valve
- Remove Charge cooler & clean out radiator & cooler
- Replace bottom shock bushes
- Kit ring feeder
- Replace trailer couplings
- Replace front drive tyres
- Check radio connections
- Check & tighten fuel tank pick up
- Fit new cab blower

809	23/11/2019	962420	A Service	Invoice
	A4740		Transmission Regulator	
	K2170		Fulter Reg kitn	
	LAB		Craig & Zane	
	3016		Flasher unit	

- A service
- Replace leaking governor / filter for transmission
- Replace flasher unit for indicators

757	24/10/2019	952906	Annual Inspection	Invoice
	LAB		Craig	
	DB015TRP		Brake Drum Merritor Drive	
	KSMA3124707QP		Brake Shoe Kit Meritor	
	K1T8042		S Cam Bush Kit (2 wheels)	
	11R22.5 DRIVE		Double Coin drive tyre	
	NPN01		Tyre disposal	
	K066-310		Shock Rubbers	
	AS95410		Air Spring Kenworth	

Vehicle Details

Registration	YGF60E	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	N/A
Model	T404 SAR	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TIPPER
Colour	Corkhills	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

- Annual inspection
- 4 front drive air springs.
- Rear drive brake shoes & drums
- 4 drive tyres rear drive
- 3axle shock rubbers
- front left drive s cam bushes

732	01/10/2019	947606	Front Spring & B Service	Invoice
------------	-------------------	---------------	-------------------------------------	----------------

LAB	Craig
VECTON	Vecton 15W40 Engine Oil
LF3620	Detroit Oil Filter
FF5206	Fuel Filter
FF5207	fuel filter
HK1073-200	Spring front Taper leaf
K324-430R	Bracket Shock Absorber
K179-536	Pin threaded
K179-537	Pin threaded
TXX3015	TX Valve (Block valve female)
RDX52	Receiver Dryer KW
K301-401	Switch A/C high pressure fan switch
15-326S	Trailer Socket

- B Service
- Replace right front spring pack
- Service A/C
- Replace broken trailer socket for tarp control
- Replace TX valve & receiver dryer

687	07/08/2019	0	A Service	Invoice
------------	-------------------	----------	------------------	----------------

LAB	Labour
KSMA3124720QP	Brake Shoe Kit Front Axle KW
TF1657B	Brake Drum Drive KW
47693	Wheel Seal
K345-5287-0-000-111	Lock Kit 3 Keys

- A Service
- Replace door lock & ignition barrels
- Replace front drive brake shoes & drums
- Replace leaking wheel seals

644	26/07/2019	0	Running repairs	Invoice
------------	-------------------	----------	------------------------	----------------

3016	Flasher unit
F093400	Horton Solenoid & Filter assy

Replace Horton solenoid for engine fan
Replace flasher unit on indicators

623	23/05/2019	917404	B service & repairs	Invoice
------------	-------------------	---------------	--------------------------------	----------------

LF3620	Detroit Oil Filter
FF5206	Fuel Filter
FF5207	fuel filter

Vehicle Details

Registration	YGF60E	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	N/A
Model	T404 SAR	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TIPPER
Colour	Corkhills	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
	K301-421-3		Rocker switch Engine fan	
	AE4018		Aerial 64 cm HD	
	F093400		Horton Solenoid & Filter assy	
	LAB		Labour	
	Q347137		Dip Stick Gauge	
	803901P		803901P	
	K123-61		Elbow rubber 6" x 90 deg	
	8PK915		Drive Belt	
	38502		Tensioner Belt gates	
	AF1968M		Air filter	
	VECTON		Vecton 15W40 Engine Oil	

B Service
 Replace belt tensioner & alternator belt
 Fit new air cleaner
 Tighten wipers
 Fit new engine fan switch
 Replace engine fan temp control
 Fit new engine fan solenoid

571	24/04/2019	910303	Air Spring	Invoice
	295/80R22.5 AH 31		Hankook Steer Tyre AH31	
	NPN03		duo coupler	
	NPN03		Duo coupler	
	SK554BHRS		KAB Seat Cover with seat-belt hole	
	AS95410		Air Spring Kenworth	
	S78-1074-62111		Seat KAB 554 Driver	

- Replace left rear air spring
- Fit new drivers seat
- Re-position rear coupler plate so to stop rubbing on air spring
- fit new duo coupler

495	19/03/2019	899835	A Service	Invoice
	LAB		Sean & Matt	
	11R22.5 COUGAR		11R22.5 Austyre Cougar II	
	NPN01		tyre disposal	
	CONS		General Consumables Used	
	090-2209SP2B		Shock Absorber Kenworth 104	

- A Service
- Replace 4 drive tyres
- Tighten speedo
- Replace right rear shock absorber

468	18/02/2019	892242	General Repairs	Invoice
	LAB		Labour	
	CONS		General Consumables Used	

Adjust clutch & Clutch brake

Vehicle Details

Registration	YGF60E	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	N/A
Model	T404 SAR	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TIPPER
Colour	Corkhills	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
Adjust brakes & grease truck & trailer				
467	26/01/2019	0	Power Steer hose & horton solenoid	Invoice
	F093400		Horton Solenoid & Filter assy	
	201-10		Dash 10 hose / metre	
Replace Horton fan solenoid Replace leaking power steer hose				
451	17/12/2018	883635	B Service & General Repairs	Invoice
	2760P/JW		Stack Curved 5" x 2' chrome	
	23920-10-10		Swivel Elbow Dash 10	
	K294-418		Handle Assy	
	201-10		Dash 10 hose / metre	
	K179-449		Locating Pin bonnet	
	K251-420		Filter Air Duct	
	S63-1001		Pad Clutch Pedal	
	LF3620		Detroit Oil Filter	
	FF5206		Fuel Filter	
	FF5207		fuel filter	
	VECTON		Vecton 15W40 Engine Oil	
	LAB		Craig Jimmy	
	LAB		Service Josh	
	CONS		General Consumables Used	
	R134A		Refrigerant Gas	
	LAB		Craig	
	K338-108		Fan Assy	
• Replace Heater fan assy • tighten left step • replace bolt in left chassis rail • replace oil cooler hose to transmission • fit new exhaust stack • repair heater controls and clean out heater box, cleaning dirt from heater core & evaporator. • fit new window handle • B Service • Replace gear box oil cooler hose				
387	23/11/2018	873262	A Service	Invoice
	LAB		Ash Josh	
	NPN03		Fire Extinguisher	
	NPN03		Mounting bracket	
	CONS		General Consumables Used	
• A Service • Mount new fire extinguisher • Repair clearance light				
363	15/11/2018	870955	Park Light on truck	Invoice

Vehicle Details

Registration	YGF60E	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	N/A
Model	T404 SAR	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TIPPER
Colour	Corkhills	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

LAB

Craig

Reinstate Circuit breaker & tighten left wiper arm

352	29/10/2018	865342	Annual Inspection	Invoice
------------	-------------------	---------------	--------------------------	----------------

11R22.5 DRIVE

Double Coin drive tyre

LAB

Labour

CONS

General Consumables Used

- Annual Inspection
- Replace left front drive tyres
- Replace radiator cap & check coolant for leaks

277	30/08/2018	854186	C Service	Invoice
------------	-------------------	---------------	------------------	----------------

8PK915

Drive Belt

TDR08204

LED worklite Square 6 LEDs

AF1968M

Air filter

LAB

Labour

VECTON

Vecton 15W40 Engine Oil

LF3620

Detroit Oil Filter

FF5206

Fuel Filter

FF5207

fuel filter

LF637

Oil Filter Power steer

HF6107

Oil Filter

85W140

Hypoid Diff Oil

TFC450

Gear oil

WBK4SUCR

Wheel Bearing Kit

15-720S

7 Pin Plug truck Side

- C Service
- Replace 7 pin plug

263	09/07/2018	0	Water Pump	Invoice
------------	-------------------	----------	-------------------	----------------

LAB

Labour

COOLANT

Coolant

SUBLET

Wire up park brake alarm

R23539929

Water Pump S 60

LAB

Labour

Replace Water pump & Coolant

253	09/07/2018	0	A service & Jacob Brakes	Invoice
------------	-------------------	----------	-------------------------------------	----------------

32146

Tune Up kit Jacobs

1024612

Solenoid Jake brake

R85-1236R

Support Hood

LAB

Labour

RD-5-8857-0P

Valve assy water 5/8

- A Service
- Install service kit to Jacob units
- Replace Jake Solenoid
- Replace heater tap on Fire wall.

Vehicle Details

Registration	YGF60E	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	N/A
Model	T404 SAR	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TIPPER
Colour	Corkhills	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
224	26/06/2018	843938	Park Brake Warning Alarm	Invoice
	HBA1224		Hand Brake Alarm 12/24V	
	CONS		General Consumables Used	
	LAB		Labour	
	12V RELAY		12 V Change over relay	
	NPN03		Diode blocking	
	K029-280		Pitman Arm	
	K301-419-3		Switch Low Air N/C 75 psi	
• Install hand brake warning alarm • Replace park brake switch • Replace Pitman Arm				
178	15/05/2018	830821	A & B service & repairs	Invoice
	LAB		Labour	
	OIL ENGINE		Lubeolloy	
	LF3620		Detroit Oil Filter	
	FF5206		Fuel Filter	
	FF5207		fuel filter	
	WF2072		Water Filter	
	295/80R22.5		Tyre AH22R	
	TX4500S		GME UHF Radio	
	B4515PTQCK		Brake Shoe Kit	
	23539103		Gasket Detroit Sump (Black)	
	KSMA3124720QP		Brake Shoe Kit Front Axle KW	
	TF1657B		Brake Drum Drive KW	
• B service. • Replace front brake shoes & linings. Replace rear drive brake shoes & drums. Replace cracked & leaking sump. Replace Steer tyres				
179	15/05/2018	830821	Labour For B Service inv 178	Invoice
	LAB		Labour	
Labour charge on invoice 178				
152	20/04/2018	824140	Lighting faults	Invoice
	LAB		Labour	
	CONS		General Consumables Used	
• Rectify fault in left rear stop light • Repair broken wire on right centre clearance light on trailer • Grease truck & adjust brakes • Hand wash truck & trailer				
132	04/04/2018	821995	Replace Brake Relay Valve	Invoice
	LAB		Labour	

Vehicle Details

Registration	YGF60E	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	N/A
Model	T404 SAR	Engine #	06R0777284	Air	Yes
Model Series		VIN	427003	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour	Corkhills	Odometer	63704	Prod	

Invoice No.	Date	Odometer	Description	Type
	106165		Valve brake relay	
	NPN03		Miscellaneous Parts (Non Stock)	
	COOLANT		Coolant	
	CONS		General Consumables Used	

- Replace Park Brake relay valve (leaking air)
- Reseal leaking fitting from water pump to coolant filter.

CORKHILL BROS

CANBERRA

Vehicle History

Vehicle Details

Registration	YGF60E	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	N/A
Model	T404 SAR	Engine #	06R0777284	Air	Yes
Model Series		VIN	427003	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour	Corkhills	Odometer	63704	Prod	

Invoice No.	Date	Odometer	Description	Type
2010	03/09/2024	0	Clutch Link	Invoice
Replace clutch rod end & Adjust clutch				
1324	03/12/2021	0	Spring pack	Invoice
Replace front spring pack left side Replace both kin pins Replace spring pin bushes right side				
1279	16/06/2021	63704	B service	Invoice
• B Service • Replace two air bags on left side • Replace shock rubbers on left front drive • Replace brake lining & wheel seal right rear drive • Replace broken drive axle • Replace 7 pin plug on trailer • Repair lights on truck & trailer • Replace two drive tyres • 4 Batteries				
1181	28/01/2021	0	Power steer tank	Invoice
Replace power steer tank				
1083	30/11/2020	34015	B service & Annual Inspection	Invoice
B Service & Annual inspection • Replace 8 rear torque rod bushes • Replace 3 sets rear shock rubbers • Fit new power steer pump • Replace right head light LED				
1020	18/09/2020	16363	A Service & Repairs	Invoice
A Service • Replace brakes on all drive wheels • Fit auto slack adjusters • replace 6 x shock rubbers • replace number plate lights • fit 4 drive tyres • fit one new rim to right rear drive • Check & repair lights & coolant leaks				

Vehicle Details

Registration	YGF60E	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	N/A
Model	T404 SAR	Engine #	06R0777284	Air	Yes
Model Series		VIN	427003	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour	Corkhills	Odometer	63704	Prod	

Invoice No.	Date	Odometer	Description	Type
• Order power steer pump				
964	06/07/2020	870	C Service	Invoice
C Service • Replace speedo • Replace thermostats 180 deg • Replace front shock absorbers • Replace coolant switch • Replace 2 x check valves & pressure protection valve • Steer Brake linings				
951	22/06/2020	9877	Water Pump	Invoice
Travel to William Hovell Dr and check for water leak. Fill with water & bring back to workshop Replace water pump				
950	25/05/2020	0	Electrical Faults	Invoice
900	08/04/2020	996574	A service & repairs	Invoice
A Service • Replace windscreen • Replace leaking air bag Right Rear • Replace faulty Battery • Replace clutch ball joint • Repair Head lights & Clearance lights				
839	10/02/2020	981234	Oil Leak, B service & Repairs	Invoice
Replace Suction hose to PTO • B Service • Replace brake treadle valve & one way check valve • Remove Charge cooler & clean out radiator & cooler • Replace bottom shock bushes • Kit ring feeder • Replace trailer couplings • Replace front drive tyres • Check radio connections • Check & tighten fuel tank pick up • Fit new cab blower				
809	23/11/2019	962420	A Service	Invoice

Vehicle Details

Registration	YGF60E	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	N/A
Model	T404 SAR	Engine #	06R0777284	Air	Yes
Model Series		VIN	427003	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour	Corkhills	Odometer	63704	Prod	

Invoice No.	Date	Odometer	Description	Type
• A service • Replace leaking governor / filter for transmission • Replace flasher unit for indicators				
757	24/10/2019	952906	Annual Inspection	Invoice
• Annual inspection • 4 front drive air springs. • Rear drive brake shoes & drums • 4 drive tyres rear drive • 3axle shock rubbers • front left drive s cam bushes				
732	01/10/2019	947606	Front Spring & B Service	Invoice
• B Service • Replace right front spring pack • Service A/C • Replace broken trailer socket for tarp control • Replace TX valve & receiver dryer				
687	07/08/2019	0	A Service	Invoice
• A Service • Replace door lock & ignition barrels • Replace front drive brake shoes & drums • Replace leaking wheel seals				
644	26/07/2019	0	Running repairs	Invoice
Replace Horton solenoid for engine fan Replace flasher unit on indicators				
623	23/05/2019	917404	B service & repairs	Invoice
B Service Replace belt tensioner & alternator belt Fit new air cleaner Tighten wipers Fit new engine fan switch Replace engine fan temp control Fit new engine fan solenoid				
571	24/04/2019	910303	Air Spring	Invoice
• Replace left rear air spring • Fit new drivers seat • Re-position rear coupler plate so to stop rubbing on air spring • fit new duo coupler				

Vehicle Details

Registration	YGF60E	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	N/A
Model	T404 SAR	Engine #	06R0777284	Air	Yes
Model Series		VIN	427003	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour	Corkhills	Odometer	63704	Prod	

Invoice No.	Date	Odometer	Description	Type
495	19/03/2019	899835	A Service	Invoice
• A Service • Replace 4 drive tyres • Tighten speedo • Replace right rear shock absorber				
468	18/02/2019	892242	General Repairs	Invoice
Adjust clutch & Clutch brake Adjust brakes & grease truck & trailer				
467	26/01/2019	0	Power Steer hose & horton solenoid	Invoice
Replace Horton fan solenoid Replace leaking power steer hose				
451	17/12/2018	883635	B Service & General Repairs	Invoice
• Replace Heater fan assy • tighten left step • replace bolt in left chassis rail • replace oil cooler hose to transmission • fit new exhaust stack • repair heater controls and clean out heater box, cleaning dirt from heater core & evaporator. • fit new window handle • B Service • Replace gear box oil cooler hose				
387	23/11/2018	873262	A Service	Invoice
• A Service • Mount new fire extinguisher • Repair clearance light				
363	15/11/2018	870955	Park Light on truck	Invoice
Reinstate Circuit breaker & tighten left wiper arm				
352	29/10/2018	865342	Annual Inspection	Invoice
• Annual Inspection • Replace left front drive tyres • Replace radiator cap & check coolant for leaks				
277	30/08/2018	854186	C Service	Invoice

Vehicle Details

Registration	YGF60E	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	N/A
Model	T404 SAR	Engine #	06R0777284	Air	Yes
Model Series		VIN	427003	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour	Corkhills	Odometer	63704	Prod	

Invoice No.	Date	Odometer	Description	Type
• C Service • Replace 7 pin plug				
263	09/07/2018	0	Water Pump	Invoice
Replace Water pump & Coolant				
253	09/07/2018	0	A service & Jacob Brakes	Invoice
• A Service • Install service kit to Jacob units • Replace Jake Solenoid • Replace heater tap on Fire wall.				
224	26/06/2018	843938	Park Brake Warning Alarm	Invoice
• Install hand brake warning alarm • Replace park brake switch • Replace Pitman Arm				
178	15/05/2018	830821	A & B service & repairs	Invoice
• B service. • Replace front brake shoes & linings. Replace rear drive brake shoes & drums. Replace cracked & leaking sump. Replace Steer tyres				
179	15/05/2018	830821	Labour For B Service inv 178	Invoice
Labour charge on invoice 178				
152	20/04/2018	824140	Lighting faults	Invoice
• Rectify fault in left rear stop light • Repair broken wire on right centre clearance light on trailer • Grease truck & adjust brakes • Hand wash truck & trailer				
132	04/04/2018	821995	Replace Brake Relay Valve	Invoice
• Replace Park Brake relay valve (leaking air) • Reseal leaking fitting from water pump to coolant filter.				