



# DIESEL VEHICLE INSPECTION REPORT

## VEHICLE OWNER INFORMATION

Date of Test 11/17/2025

Name LLD Construction INC  
Address 8065 Krameria st  
City commerce city State CO Zip Code 80022

## EMISSIONS TEST FACILITY INFORMATION

Station Number 13435 Station Name Rocky Mountain Diesel Emissions Serial # 1343579462  
Inspection Cost \$ 110 Station Address 9999 Brighton Rd.  
Henderson, CO 80640

## VEHICLE INFORMATION

Vehicle Identification Number 2HSCHAPR55C001474

Model Year 2005	Vehicle Make INTL		Vehicle License Plate BSU167
GVWR 52000	Vehicle Class HD		Non CO. License Plate NO
# of Cylinders 6	Engine Make CUMM	Engine Type TURBO	Odometer 751359
Transmission Type MAN	Vehicle smoke repairs last 60 days? NO		DR2365 NO

FIRST TEST		Inspector Number 21492	AFTER REPAIRS TEST		Inspector Number 21492
Heavy duty vehicle dynamometer lug down test			Heavy duty vehicle dynamometer lug down test		
Snap	48% OPACITY		Snap	53% OPACITY	
Zero Shift	0% OPACITY		Zero Shift	0% OPACITY	
Engine Rate	1% OPACITY		Engine Rate	0% OPACITY	
90%	1% OPACITY		90%	20% OPACITY	
80%	1% OPACITY		80%	0% OPACITY	
70%	1% OPACITY		70%	0% OPACITY	
Zero Shift	1% OPACITY		Zero Shift	0% OPACITY	
Results PASS			Results PASS		

EMISSIONS CONTROL SYSTEMS		FIRST	FINAL	REPAIR INFORMATION
Pump Seals Air Fuel Adjustment		NA	NA	Fail Repair Cost \$ 0.00
Boost Compensation / Aneroid		NA	NA	Re-insp. Cost \$ 110
Electronic Engine Controls		FAIL	PASS	
Trap / Catalytic Converter		NA	NA	Date of Retest 01/12/2026
Positive Crankcase Ventilation System		NA	NA	
Exhaust Gas Recirculation System		PASS	PASS	

OVERALL RESULTS		CERTIFICATE OF EMISSIONS COMPLIANCE		
Initial Test FAIL		Date Of Test 01/12/2026	Test Results	PASS
Retest PASS		VIN 2HSCHAPR55C001474	GVWR	52000
Waiver		Verification # 1344520105	CDOR	COLORADO Department of Revenue