

Vehicle Details

Registration	XA42AC	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	K104	Engine #	06R085S765	Air	Yes
Model Series		VIN	431370	Cyl	0
Model Code		Build Date	02/2006	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	399839	Prod	

Invoice No.	Date	Odometer	Description	Type
2468	02/07/2025	399839	B Service	Invoice

LF3620

FS19764

11R22.5 DRIVE

NPN01

839310

AS95410

LAB

VECTON

Detroit Oil Filter

Fuel Water Separator

Double Coin drive tyre

Tyre Disposal

Bushes Torque

Air Spring Kenworth

Labour

Vecton 15W40 Engine Oil

B Service
6 Drive tyres front axle & Right second drive 3,4,5,6,7 &
Front torque rod bush
RH front drive rear bag
Repair hole in inlet pipe

2492	02/07/2025	399839	Repair Inlet Pipe	Invoice
	SUBLET		Baxters Inv 62874	

Repair Inlet Pipe (not on previous work order)

2393	21/05/2025	389832	Water Leak	Invoice
	LAB		Zane	
	TAI K06JF12		K06JF12	
	TAI K06JF1290		K06JF1290	
	TAI 100R2GP06		100R2GP06	
	ASSY		Assembly	
	COOLANT		Coolant	

Travel to Yass & replace leaking water pipe from Compressor to Water suction on water pump

2355	26/03/2025	380315	A Service	Invoice
	GREASE 20KG		Black Tack 20kg	
	CONS		General Consumables Used	
	LAB		Labour	
	GW21-1		Adapter Window washer	
	VECTON		Vecton 15W40 Engine Oil	
	295/80R22.5 S200 GOODYEAR		Goodyear Steer tyre	
	NPN01		Tyre disposal	
	C81-1005		Air Spring Kenworth	
	LAB		Labour	

A Service

A service Completed

Vehicle Details				
Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
- Engine Oil topped up - LHS Steer tyre changed (Goodyear S200 295/80R22.5) - Window washer barbs on cab replaced due to corrosion, lines blown out and sprayers cleared. Washers now work - Power Steering oil topped up 3rd Axle RHS Leaking Airbag - Set ride height				

2307	03/03/2025	0	Batteries & A/c	Invoice
	N70ZZHMF		Battery	

Replace Batteries Check A/C Pressures & function				
---	--	--	--	--

2262	14/11/2024	0	door repairs	Invoice
	NPN03		Adhesive for door trim	
	K218-1045R		Sill Door outer RH	
	SUBLET		Paint Drivers door (N V Panel & Paint)	
	SUBLET		Austec weld door	

Repair drivers side door				
--------------------------	--	--	--	--

2057	30/09/2024	0	B service	Invoice
	LF3620		Detroit Oil Filter	
	FS19764		Fuel Water Separator	
	VECTON		Vecton 15W40 Engine Oil	
	GREASE 20KG		Black Tack 20kg	
	NPN03		U Bolt Air tank	
	5.281		1810 universal joint full round	
	H2024		Brake Hose	

B Service Replace universal joints in front drive shaft Replace left front drive Service brake air line Replace broken air tank U Bolt Annual inspection				
--	--	--	--	--

2067	24/09/2024	425232	Left Rear Air Bag	Invoice
	RD8324		Receiver Dryer KW 409	
	R134A		Refrigerant Gas	
	C81-1005		Air Spring Kenworth	

Replace Left rear air bag (leaking) Re-gas A/C & replace receiver dryer				
--	--	--	--	--

1947	12/08/2024	347744	A Service Windscreen	Invoice
	57Y4910		Shock Rubber Pin	
	TRANSMAX OFFROAD 10W		10w gear oil	
	NPN03		Windscreen	
	GREASE		Black tack 450 gm	
	CONS		General Consumables Used	

A Service Replace right front drive shock				
--	--	--	--	--

Vehicle Details

Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
Replace drivers window				
1863	01/07/2024	337284	fire extinguisher	Invoice
	NPN03 CONS		4.50 kg ABE fire extinguisher General Consumables Used	
Repair fire extinguisher bracket Replace Fire Extinguisher Check Right front wheel for noise				
1881	11/06/2024	0	Truck Wash	Invoice
	SUBLET		Hume Truck Wash	
Truck Wash				
1732	23/11/2023	295735		Invoice
	M100580 LF3620 FS19764 VECTON		Muffler 5" Detroit Oil Filter Fuel Water Separator Vecton 15W40 Engine Oil	
B Service Replace right muffler & muffler bell				
1817	18/01/2023	256711	Jake brake switch	Invoice
	K103-453 KHT20 K-4148 ACX3342 30/30 HC6030B CONS		ENGINE BRAKE SWITCH Chamber Service brake type 20 Speed sensor transmission Starter Motor Slave solenoid 12V Spring Brake Chamber Cab Shock Spring over General Consumables Used	
• Replace engine brake switch • Replace right front cab shock(Leaking) • Replace remote starter solenoid • Replace transmission speed sensor (broken connector) • Replace right steer brake chamber & left rear spring brake chamber				
1532	26/10/2022	230952	B service	Invoice
	LF3620 FS19764 VECTON		Detroit Oil Filter Fuel Water Separator Vecton 15W40 Engine Oil	
B Service				
1456	07/10/2022	431370	Annual inspection	Invoice
	HC6030B		Cab Shock Spring over	
Annual Inspection Replace front cab shocks				
1435	26/08/2022	0	Steering box seal & Cab light	Invoice
	5000KLED TAS000001		Cab roof light Seal Kit power steer input	

Vehicle Details

Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

Fit seal kit to input shaft
 Replace cab light
 Replace right front drive shock absorber
 Adjust ride heights on rear axle

1357	21/07/2022	201637	B service	Invoice
	LF3620		Detroit Oil Filter	
	FS19764		Fuel Water Separator	
	VECTON		Vecton 15W40 Engine Oil	
	KSMA3124720QP		Brake Shoe Kit Front Axle KW	
	KSMA2124715QP		Brake Shoe Kit Front Axle KW	
	CONS		General Consumables Used	

B Service

- Adjust ride height valves
- Check for engine oil leak at filter area
- Check brake pressures, trailer truck ratios
- Check radius rod bushes for wear
- Replace steer Brake linings
- Replace right rear drive linings

1326	16/03/2022	172684	B service & repairs	Invoice
	112201		Williams valve Trailer control	
	LAB		Labour	
	LF3620		Detroit Oil Filter	
	FS19764		Fuel Water Separator	
	VECTON		Vecton 15W40 Engine Oil	
	EX23536348		Turbo 14L Detroit	

B Service
 Check for low power
 Replace turbo charger
 Replace leaking Williams valve (trailer control)

1301	02/02/2022	158158	A Service	Invoice
	LAB		Labour	
	KSMA3124707QP		Brake Shoe Kit Meritor	
	287280N		Valve trailer control Red Button	
	CONS		General Consumables Used	

A Service

- Replace roll pin in check strap on drivers door
- Adjust ride height & equalize air pressure valves
- Replace Red trailer valve
- Replace brake shoes on left rear wheel

1300	03/12/2021	143625	B service	Invoice
	FD20-31112-5PSI		Switch Pressure 5 psi NC	
	LF3620		Detroit Oil Filter	
	FS19764		Fuel Water Separator	
	VECTON		Vecton 15W40 Engine Oil	
	CONS		General Consumables Used	

Vehicle Details

Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

LAB

Labour

B Service
Replace hob switch on cruise control

1272	19/07/2021	0	Low power	Invoice
-------------	-------------------	----------	------------------	----------------

NPN03	Head gasket set
NPN03	Exhaust manifold 1 piece ceramic
NPN03	Turbo mounting
FREIGHT	Freight charges
NPN03	Service cylinder head

- Replace cylinder head gasket
- fit new 1 piece exhaust manifold
- Service Cylinder head

1146	08/04/2021	109975	C Service Batteries	Invoice
-------------	-------------------	---------------	----------------------------	----------------

LAB	Labour
VECTON	Vecton 15W40 Engine Oil
LF3620	Detroit Oil Filter
FS19764	Fuel Water Separator
AP85W140	Diff oil
TFC450	Gear oil
TFC410	10w gear oil
NPN03	shocks
KSMA3124707QP	Brake Shoe Kit Meritor
DB015TRP	Brake Drum Merritor Drive
A3380W1687	Merritor Diff Filter
17237	Eaton Transmission Filter
WBK4SCHB	Wheel Bearing Kit H/D Kenworth
N70ZZHX	Battery severe service

C Service

- Front drive brake shoes & brake drum
- Fire extinguisher
- Front drive shocks
- New batteries

1145	19/03/2021	103104	injectors	Invoice
-------------	-------------------	---------------	------------------	----------------

NPN03	6 x injectors
FREIGHT	Freight charges
LAB	Labour

Replace injectors

1110	09/02/2021	909223	B service	Invoice
-------------	-------------------	---------------	------------------	----------------

VECTON	Vecton 15W40 Engine Oil
LF3620	Detroit Oil Filter
FS19764	Fuel Water Separator
CONS	General Consumables Used
LAB	Labour

Vehicle Details

Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
B Service				
1109	13/01/2021	82026	General Repairs A Service	Invoice
	LAB		Labour	
	K374-44		Shock Absorber	
	R134A		Refrigerant Gas	
	CONS		General Consumables Used	
• Re set injectors & tappets • Replace rear drive shock absorbers • Repair suction hose to A/C compressor & regas • Replace damaged water bleed off line to top of radiator				
1108	30/10/2020	0	B service & Clutch	Invoice
	K241-584		U Bolt Air tank	
	LF3620		Detroit Oil Filter	
	FS19764		Fuel Water Separator	
	VECTON		Vecton 15W40 Engine Oil	
	308935515		Clutch Kit	
	6306-2RS2		Bearing Transmission	
	SUBLET		Machine flywheel	
	LAB		Labour	
	5.281		1810 universal joint full round	
	106C939		Clutch Release Shaft 10 Spline	
	106C1498		Clutch Release Shaft 6.5"	
	LAB		Labour	
	R134A		Refrigerant Gas	
	CONS		General Consumables Used	
B Service				
• Replace clutch • Air tank strap • 1810 series universal joint at power divider • Regas A/C (leak at high pressure port)				
1012	02/09/2020	43248	A Service & Annual Inspection	Invoice
	LAB		Labour	
A Service & annual inspection				
958	23/07/2020	30952	B service	Invoice
	LF3620		Detroit Oil Filter	
	FS19764		Fuel Water Separator	
	VECTON		Vecton 15W40 Engine Oil	
	LAB		Labour	
	K068-7329		Probe assy & Harness	
B Service				
• Replace exhaust probe • Replace broken u bolt on air tank				

Vehicle Details

Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
917	09/06/2020	14652	A Service	Invoice

LAB Labour
VECTON Vecton 15W40 Engine Oil
CONS General Consumables Used

A Service

- Check for pyrometer operation
- Top up engine oil
- Replace tank rubber
- Un-Block window washers

871	15/04/2020	0	Clutch link	Invoice
	K202-2509		Rod Clutch link	

Replace clutch link in chassis

867	08/04/2020	0	B service	Invoice
-----	------------	---	-----------	---------

LAB Labour
VECTON Vecton 15W40 Engine Oil
LF3620 Detroit Oil Filter
FS19764 Fuel Water Separator
359-5990 Vent Plug front hub cap
NPN03 Tank Rubber
K180-20403 Pipe Air Intake

B Service

- Replace connector on fuel sender
- Fit new window washer union drivers side cab
- Replace Fuel tank straps left side tank
- Replace intake pipe

845	04/03/2020	984545	A Service	Invoice
-----	------------	--------	-----------	---------

108470 Bushing Dipstick Rubber
RDX524 Receiver Drier
TX9015 TX Valve
CM7949 A/C Compressor
R134A Refrigerant Gas
LAB Labour
CONS General Consumables Used
NPN03 Fittings & No 10 hose

A Service

Replace compressor, receiver drier , TX Valve & compressor inlet hose
Replace dip stick rubber
Repair light on mirror

841	30/01/2020	0	Oil Leak turbo drain	Invoice
-----	------------	---	----------------------	---------

LAB Craig
8929285 Gasket

Vehicle Details

Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
23515354			Tube turbo drain	
Replace turbo drain tube (leaking)				
791	17/01/2020	966218	B service	Invoice
	VECTON		Vecton 15W40 Engine Oil	
	LF3620		Detroit Oil Filter	
	FS19764		Fuel Water Separator	
	11R22.5 DRIVE		Double Coin drive tyre	
	KSMA3124707QP		Brake Shoe Kit Meritor	
B Service • Replace drive tyres front drive • Replace rear axle brake lining • Adjust truck hide height				
789	05/12/2019	957167	Fuel Lines / low power	Invoice
	LAB		Craig	
	K241-584		U Bolt Air tank	
	NPN03		Fuel Hose	
Replace fuel lines from fuel tank tor engine & return Clean out fuel filter housing & check valve Replace broken air tank u bolt				
764	27/11/2019	956316	Starter Motor	Invoice
	K241-584		U Bolt Air tank	
	LAB		Labour	
	8201063		Starter 12V Delco 39MT 11 Tooth	
Replace starter motor Replace broken air tank strap				
744	19/11/2019	954355	Accident Damage	Invoice
	LAB		Labour	
	NPN03		Windscreen K104	
	AE4018		Aerial 64 cm HD	
	SUBLET		Truck Hire	
Accident repair after chain thrown from oncoming vehicle • Replace both windscreens • Replace antenna • Truck hire				
734	01/11/2019	947980	A service ,Driving Light, A/C & Steer	Invoice
	295/80R22.5 AH 31		Hankook Steer Tyre AH31	
	R134A		Refrigerant Gas	
	LAB		Craig & Stuart	
	11R22.5 DRIVE		Double Coin drive tyre	
	KSMA2124707QP		Brake Shoes Meritor Drive	
	R824004		Slack adjuster Fine	

Vehicle Details

Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
A Service Right front drive brake shoes & slack adjuster Repair wire on alternator for Tacho Repair driving lights Steer tyres Left rear drive tyres				
733	30/09/2019	0	Front end clunk	Invoice
	SC1SR1BHRSB		iSRI SEAT COVERS 6800 DRIVER	
	SC1SR1BHLSB		Seat Cover KW ISIRI 6800 PASSENGER	
	CH6030B		Cab Shock Absorber front Cabover	
	LAB		Labour	
• Supply Seat covers • Replace Cab shocks at front of cab				
673	17/09/2019	934883	B service & repairs	Invoice
	VECTON		Vecton 15W40 Engine Oil	
	LF3620		Detroit Oil Filter	
	FS19764		Fuel Water Separator	
	LAB		Craig & Nick	
	839310		Bushing	
	090-2209SP2B		Shock Absorber Kenworth 104	
	K374-44		Shock Absorber	
	K066-310		Shock Rubbers	
• B Service • Replace rear sway bar bushes • Straighten right front mud guard • Annual Inspection • Fit all new shock absorbers				
672	09/09/2019	931709	Ride Height valve	Invoice
	H00500C		Ride Height Valve universal	
	LAB		Craig	
• Replace ride height valves •				
658	15/08/2019	921792	A Service	Invoice
	LAB		Craig & nick	
	11R22.5 DRIVE		Double Coin drive tyre	
	CONS		General Consumables Used	
• A Service • Repair water leak at de-aeration hose • Replace left front drive tyres				

Vehicle Details

Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
633	03/07/2019	905188	C Service	Invoice

TFC450 Gear oil
 AP85W140 Diff oil
 TFC410 10w gear oil
 VECTON Vecton 15W40 Engine Oil
 T224P Air Dryer filter
 LF3620 Detroit Oil Filter
 FS19764 Fuel Water Separator
 WF2077 Water filter no DCA
 R23537686 Fuel Pump Exchange
 23516918 Valve non return fuel
 WBK4SCHB Wheel Bearing Kit H/D Kenworth
 AF1969M Air filter

C Service
 Replace fuel pump & non return valve

629	21/06/2019	900289	Fuel Start Problem & Cab Mounts &	Invoice
-----	------------	--------	-----------------------------------	---------

25006900 Pin assy latch upper
 K274-166 Wear Pad
 M100580 Muffler 5"
 LAB Craig

- Replace fuel valve in rear of cylinder head
- Replace left muffler.
- fit new cab bush / mount & wear plates to left rear cab
- Supply new fuel cap left side

583	04/06/2019	895455	A Service	Invoice
-----	------------	--------	-----------	---------

LAB Craig
 CONS General Consumables Used

A service

567	15/04/2019	431370	Exhaust manifold & B service	Invoice
-----	------------	--------	------------------------------	---------

LAB Craig
 VECTON Vecton 15W40 Engine Oil
 LF3620 Detroit Oil Filter
 WF2077 Water filter no DCA
 FS19624 Fuel Water Separator
 23511221 Manifold exhaust front
 23511222 Exhaust manifold end
 23532122 Manifold Exhaust
 23539193 Gasket exhaust manifold
 HPS60-TM Kit turbo mounting
 8929529 Gasket turbo base S 60

- B Service
- Replace cracked exhaust manifold & gaskets

529	01/04/2019	870710	A Service	Invoice
-----	------------	--------	-----------	---------

Vehicle Details

Registration	XA42AC	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	K104	Engine #	06R085S765	Air	Yes
Model Series		VIN	431370	Cyl	0
Model Code		Build Date	02/2006	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	399839	Prod	

Invoice No.	Date	Odometer	Description	Type
	LAB CONS		Labour General Consumables Used	
A Service				
536	15/03/2019	0	Head Light	Invoice
	K103-314 SUBLET LAB		Head light switch Adams Autos Labour	
Locate & repair fault in head light circuit				
483	04/03/2019	860692	Craig	Invoice
	LAB AS95410 770214		Craig Air Spring Kenworth Pressure Switch	
Fit New Airbags to left front drive Fit new gearbox oil pressure switch.				
460	07/02/2019	848901	B Service & Front springs	Invoice
	LF3620 VECTON HE8701 FS19624 WF2077 B81-1034 K2214826 K179-536 K179-537 LAB		Detroit Oil Filter Vecton 15W40 Engine Oil Host turbo hump hose Fuel Water Separator Water filter no DCA Front spring pack Spacer Axle centering Pin threaded Pin threaded Craig Josh	
• B Service • Replace front spring packs & Shackle plates • Replace turbo boost hose				
376	12/11/2018	818277	B service & repairs	Invoice
	R23523998 295/80R22.5 MICHELIN 11R22.5 DRIVE LAB LF3620 FS19624 WF2077 VECTON 38502 AU1540422		Accessory Drive Detroit Michelin 152/149M XMLTZ Double Coin drive tyre Josh Craig Sean Detroit Oil Filter Fuel Water Seperator Water filter no DCA Vecton 15W40 Engine Oil Tensioner Belt gates Pump air assist cab jack	
• B service • replace cab jack (leaking) • Replace right steer tyre • Replace belt tensioner • Replace Left front drive tyres				

Vehicle Details

Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
332	15/10/2018	803913	A Service & Annual Inspection	Invoice
	LAB 11R22.5 DRIVE		Matt & Jimmy Double Coin drive tyre	
• A Service • Annual inspection • Replace right rear drive tyres • Change rego plates				
329	20/09/2018	795017	Engine Mount Bracket	Invoice
	CONS SUBLET K159-986 LAB		General Consumables Used Capital Thread Repair Engine Mount Bracket Todd	
• Remove broken engine mount on left rear • Sub let (drill out broken bolt) • Fit new bolts & engine bracket				
290	29/08/2018	784576	B service & Muffler	Invoice
	UC50UZP M100580 2182/JW LAB VECTON LF3620 FS19624 WF2071 11R22.5		Exhaust Clamp 5" U Muffler 5" Exhaust Bell cab connect Labour Vecton 15W40 Engine Oil Detroit Oil Filter Fuel Water Seperator Water Filter 11R 22.5 tyre	
• B Service • Replace left rear drive tyres • Replace right side muffler				
256	30/07/2018	772388	A Service	Invoice
	43764S KSMA2124715QP LAB CONS		ScotSeal Brake Shoe Kit Front Axle KW Labour General Consumables Used	
• A Service • Re-Do right front wheel seal & Brake linings (seal incorrectly installed)				
199	05/06/2018	753144	C Service & Repairs	Invoice
	T2000SK-P VECTON K066-488 K066-489 K066-490 K179-541		Air Dryer Kit Vecton 15W40 Engine Oil Bush Cab Mount Bush Cab Suspension Bush Cab Suspension Pin Cab Hinge	

Vehicle Details

Registration	XA42AC	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	K104	Engine #	06R085S765	Air	Yes
Model Series		VIN	431370	Cyl	0
Model Code		Build Date	02/2006	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	399839	Prod	

Invoice No.	Date	Odometer	Description	Type
	LF3620		Detroit Oil Filter	
	WF2071		Water Filter	
	AF1969M		Air filter	
	GHDVR359		Dash Cam Gator	
	LAB		Labour	
	LAB		Jared Call Out	
	HYDRAULIC OIL		Hydraulic oil	
	TFC450		Gear oil	
	85W140		Hypoid Diff Oil	
	NPN03		Fire Extinguisher	
	WBK4SCHB		Wheel Bearing Kit H/D Kenworth	

C service
 Replace cab mount bushes. replace high pressure pump at PTO. Drain & flush hydraulic tank & hoses. Fit new dash cam .
 Fit new Dash Cam. Replace Fire extinguisher.

212	05/06/2018	753144	PTO Pump	Invoice
	XP80		PTO Pump high pressure	

Supply & fit new PTO Pump
 See job 199

145	17/04/2018		Wiper blade assembly	Invoice
	1362060DC04		Wiper blade assembly	

140	10/04/2018	728823	A & B Service	Invoice
	WF2071		Water Filter	
	LF3620		Detroit Oil Filter	
	AF1969M		Air filter	
	OIL ENGINE		Lubeolloy	
	295/80R22.5		Tyre AH22R	
	91530		Light Sealed number plate	
	FS19624		Fuel Water Seperator	
	LAB		Labour	

- A & B service
 - Replace left steer tyre

CORKHILL BROS

CANBERRA

Vehicle History

Vehicle Details

Registration	XA42AC	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	K104	Engine #	06R085S765	Air	Yes
Model Series		VIN	431370	Cyl	0
Model Code		Build Date	02/2006	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	399839	Prod	

Invoice No.	Date	Odometer	Description	Type
2468	02/07/2025	399839	B Service	Invoice
B Service 6 Drive tyres front axle & Right second drive 3,4,5,6,7 & Front torque rod bush RH front drive rear bag Repair hole in inlet pipe				
2492	02/07/2025	399839	Repair Inlet Pipe	Invoice
Repair Inlet Pipe (not on previous work order)				
2393	21/05/2025	389832	Water Leak	Invoice
Travel to Yass & replace leaking water pipe from Compressor to Water suction on water pump				
2355	26/03/2025	380315	A Service	Invoice
A Service A service Completed • Engine Oil topped up • LHS Steer tyre changed (Goodyear S200 295/80R22.5) • Window washer barbs on cab replaced due to corrosion, lines blown out and sprayers cleared. Washers now work • Power Steering oil topped up • 3rd Axle RHS Leaking Airbag • Set ride height				
2307	03/03/2025	0	Batteries & A/c	Invoice
Replace Batteries Check A/C Pressures & function				
2262	14/11/2024	0	door repairs	Invoice
Repair drivers side door				
2057	30/09/2024	0	B service	Invoice
B Service Replace universal joints in front drive shaft Replace left front drive Service brake air line Replace broken air tank U Bolt Annual inspection				

Vehicle Details

Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
2067	24/09/2024	425232	Left Rear Air Bag	Invoice
Replace Left rear air bag (leaking) Re-gas A/C & replace receiver dryer				
1947	12/08/2024	347744	A Service Windscreen	Invoice
A Service Replace right front drive shock Replace drivers window				
1863	01/07/2024	337284	fire extinguisher	Invoice
Repair fire extinguisher bracket Replace Fire Extinguisher Check Right front wheel for noise				
1881	11/06/2024	0	Truck Wash	Invoice
Truck Wash				
1732	23/11/2023	295735		Invoice
B Service Replace right muffler & muffler bell				
1817	18/01/2023	256711	Jake brake switch	Invoice
• Replace engine brake switch • Replace right front cab shock(Leaking) • Replace remote starter solenoid • Replace transmission speed sensor (broken connector) • Replace right steer brake chamber & left rear spring brake chamber				
1532	26/10/2022	230952	B service	Invoice
B Service				
1456	07/10/2022	431370	Annual inspection	Invoice
Annual Inspection Replace front cab shocks				
1435	26/08/2022	0	Steering box seal & Cab light	Invoice
Fit seal kit to input shaft Replace cab light Replace right front drive shock absorber Adjust ride heights on rear axle				
1357	21/07/2022	201637	B service	Invoice
B Service • Adjust ride height valves • Check for engine oil leak at filter area • Check brake pressures, trailer truck ratios • Check radius rod bushes for wear				

Vehicle Details

Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
			- Replace steer Brake linings - Replace right rear drive linings	
1326	16/03/2022	172684	B service & repairs	Invoice
			B Service Check for low power Replace turbo charger Replace leaking Williams valve (trailer control)	
1301	02/02/2022	158158	A Service	Invoice
			A Service - Replace roll pin in check strap on drivers door - Adjust ride height & equalize air pressure valves - Replace Red trailer valve - Replace brake shoes on left rear wheel	
1300	03/12/2021	143625	B service	Invoice
			B Service Replace hob switch on cruise control	
1272	19/07/2021	0	Low power	Invoice
			- Replace cylinder head gasket - fit new 1 piece exhaust manifold - Service Cylinder head	
1146	08/04/2021	109975	C Service Batteries	Invoice
			C Service - Front drive brake shoes & brake drum - Fire extinguisher - Front drive shocks - New batteries	
1145	19/03/2021	103104	injectors	Invoice
			Replace injectors	
1110	09/02/2021	909223	B service	Invoice
			B Service	
1109	13/01/2021	82026	General Repairs A Service	Invoice
			- Re set injectors & tappets - Replace rear drive shock absorbers - Repair suction hose to A/C compressor & regas	

Vehicle Details

Registration	XA42AC	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	K104	Engine #	06R085S765	Air	Yes
Model Series		VIN	431370	Cyl	0
Model Code		Build Date	02/2006	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	399839	Prod	

Invoice No.	Date	Odometer	Description	Type
Replace damaged water bleed off line to top of radiator				
1108	30/10/2020	0	B service & Clutch	Invoice
B Service - Replace clutch - Air tank strap 1810 series universal joint at power divider - Regas A/C (leak at high pressure port)				
1012	02/09/2020	43248	A Service & Annual Inspection	Invoice
A Service & annual inspection				
958	23/07/2020	30952	B service	Invoice
B Service - Replace exhaust probe - Replace broken u bolt on air tank				
917	09/06/2020	14652	A Service	Invoice
A Service - Check for pyrometer operation - Top up engine oil - Replace tank rubber - Un-Block window washers				
871	15/04/2020	0	Clutch link	Invoice
Replace clutch link in chassis				
867	08/04/2020	0	B service	Invoice
B Service - Replace connector on fuel sender - Fit new window washer union drivers side cab - Replace Fuel tank straps left side tank - Replace intake pipe				
845	04/03/2020	984545	A Service	Invoice
A Service Replace compressor, receiver drier , TX Valve & compressor inlet hose Replace dip stick rubber Repair light on mirror				

Vehicle Details

Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
841	30/01/2020	0	Oil Leak turbo drain	Invoice
Replace turbo drain tube (leaking)				
791	17/01/2020	966218	B service	Invoice
B Service • Replace drive tyres front drive • Replace rear axle brake lining • Adjust truck hide height				
789	05/12/2019	957167	Fuel Lines / low power	Invoice
Replace fuel lines from fuel tank tor engine & return Clean out fuel filter housing & check valve Replace broken air tank u bolt				
764	27/11/2019	956316	Starter Motor	Invoice
Replace starter motor Replace broken air tank strap				
744	19/11/2019	954355	Accident Damage	Invoice
Accident repair after chain thrown from oncoming vehicle • Replace both windscreens • Replace antenna • Truck hire				
734	01/11/2019	947980	A service ,Driving Light, A/C & Steer	Invoice
A Service Right front drive brake shoes & slack adjuster Repair wire on alternator for Tacho Repair driving lights Steer tyres Left rear drive tyres				
733	30/09/2019	0	Front end clunk	Invoice
• Supply Seat covers • Replace Cab shocks at front of cab				
673	17/09/2019	934883	B service & repairs	Invoice
• B Service • Replace rear sway bar bushes • Straighten right front mud guard • Annual Inspection				

Vehicle Details

Registration	XA42AC	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	K104	Engine #	06R085S765	Air	Yes
Model Series		VIN	431370	Cyl	0
Model Code		Build Date	02/2006	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	399839	Prod	

Invoice No.	Date	Odometer	Description	Type
			Fit all new shock absorbers	
672	09/09/2019	931709	Ride Height valve	Invoice
			- Replace ride height valves	
658	15/08/2019	921792	A Service	Invoice
			- A Service - Repair water leak at de-aeration hose - Replace left front drive tyres	
633	03/07/2019	905188	C Service	Invoice
			C Service Replace fuel pump & non return valve	
629	21/06/2019	900289	Fuel Start Problem & Cab Mounts &	Invoice
			- Replace fuel valve in rear of cylinder head - Replace left muffler. - fit new cab bush / mount & wear plates to left rear cab - Supply new fuel cap left side	
583	04/06/2019	895455	A Service	Invoice
			A service	
567	15/04/2019	431370	Exhaust manifold & B service	Invoice
			- B Service - Replace cracked exhaust manifold & gaskets	
529	01/04/2019	870710	A Service	Invoice
			A Service	
536	15/03/2019	0	Head Light	Invoice
			Locate & repair fault in head light circuit	
483	04/03/2019	860692	Craig	Invoice
			Fit New Airbags to left front drive Fit new gearbox oil pressure switch.	
460	07/02/2019	848901	B Service & Front springs	Invoice
			- B Service - Replace front spring packs & Shackle plates	

Vehicle Details

Registration	XA42AC	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	K104	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
			Replace turbo boost hose	
376	12/11/2018	818277	B service & repairs	Invoice
			- B service - replace cab jack (leaking) - Replace right steer tyre - Replace belt tensioner - Replace Left front drive tyres	
332	15/10/2018	803913	A Service & Annual Inspection	Invoice
			- A Service - Annual inspection - Replace right rear drive tyres - Change rego plates	
329	20/09/2018	795017	Engine Mount Bracket	Invoice
			- Remove broken engine mount on left rear - Sub let (drill out broken bolt) - Fit new bolts & engine bracket	
290	29/08/2018	784576	B service & Muffler	Invoice
			- B Service - Replace left rear drive tyres - Replace right side muffler	
256	30/07/2018	772388	A Service	Invoice
			- A Service - Re-Do right front wheel seal & Brake linings (seal incorrectly installed)	
199	05/06/2018	753144	C Service & Repairs	Invoice
			C service Replace cab mount bushes. replace high pressure pump at PTO. Drain & flush hydraulic tank & hoses. Fit new dash cam . Fit new Dash Cam. Replace Fire extinguisher.	
212	05/06/2018	753144	PTO Pump	Invoice
			Supply & fit new PTO Pump See job 199	
145	17/04/2018		Wiper blade assembly	Invoice
140	10/04/2018	728823	A & B Service	Invoice
			- A & B service - Replace left steer tyre	

Vehicle Details

Registration	XA42AC	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	K104	Engine #	06R085S765	Air	Yes
Model Series		VIN	431370	Cyl	0
Model Code		Build Date	02/2006	Body	PRIMEMOVER
Colour	Reid & Stevens	Odometer	399839	Prod	

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------