



BRITISH  
COLUMBIA

# Commercial Vehicle Inspection Report

Decal Number: GJ43419  
Decal Expiry Date: 2025-Oct-31  
Inspection Number: 21329977

011-4

Inspection Result:

**PASS**

<b>FACILITY:</b>	WEST COAST DIESEL TECH LTD. / S20163	<b>INSP. TYPE:</b>	Complete	<b>INSP. START:</b>	2025-Apr-29 09:00 AM PDT
<b>INSPECTOR:</b>	Gill, Harpal Singh / 203084	<b>INSP. CLASS:</b>	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	<b>INSP. COMPLETE:</b>	2025-Apr-29 11:00 AM PDT
<b>WORK ORDER #:</b>	412	<b>INSP. REASON:</b>	Semi-annual		

  

<b>VEHICLE JUR:</b>	British Columbia	<b>REGI:</b>	14129156	<b>VIN:</b>	1FVACXDT2EHFL7848
<b>PLATE #:</b>	VA4278	<b>UNIT/FLEET#:</b>	128	<b>OWNER/LESSEE NAME:</b>	VANMARS, DRILLING LTD
<b>LICENCED GVW(kg):</b>	16000	<b>BODY STYLE:</b>	Box Truck	<b>ADDRESS:</b>	1330 RIVERSIDE RD, 1330 RIVERSIDE RD
<b>VEHICLE YEAR:</b>	2014	<b>ODOMETER:</b>	294330 KM		Abbotsford, British Columbia
<b>MAKE:</b>	FREIGHTLIN	<b>HUB ODOMETER:</b>			V2S 7P1, Canada
<b>MODEL:</b>		<b>BRAKE TYPE:</b>	Air		
		<b>FUEL TYPE:</b>	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	30	30
2	Clamp	30	Automatic	34	34
Comment:					

## Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
8.7			8.7	✓
12.7	13.5	15.9	15.1	
Comment:				

## Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	50	50
2	55	55
Comment:		

## Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	15	15
Comment:		

## Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

## Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Harpal Singh Road Tester:  
Inspector: Gill, Harpal Singh Signature: Harpal Singh

This Inspection Report was submitted to CVSE on 2025-Apr-29 12:09 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

4/29/2025 12:09:56 PM PDT