

Vehicle Details

Registration	XA05AM	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	T358R	Engine #	9 DG 10907	Air	Yes
Model Series		VIN	442985	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour		Odometer/Hr	204110 / 11	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
2639	01/08/2025	0	Batteries	Invoice

N70ZZHMF

Battery

Fit 2 x batteries

1760	27/12/2023	226974	C Service	Invoice
------	------------	--------	-----------	---------

CONS

General Consumables Used

C Service
lh 3rd axle shock
2 suspension bushes
Tyres LH 4 axle

1815	22/08/2023	204110	A Service	Invoice
------	------------	--------	-----------	---------

KSMA3124720QP
A24-3275M1079PZ

Brake Shoe Kit Front Axle KW
Auto Slack Adjuster 5.5" 28

A Service
Replace left front slack adjuster & brake linings

1684	18/07/2023	196288	Injector	Invoice
------	------------	--------	----------	---------

20R-8968

Injector C9

Replace No 6 injector because of mis-fire

1640	27/05/2023	187432	B service	Invoice
------	------------	--------	-----------	---------

VECTON
1R-1808
1R0751
5134490
275/70 R22.5 HIFLY
NPN01
K066-310
AC4001
275707

Vecton 15W40 Engine Oil
Oil Filter
Fuel filter
Fuel filter
Hifly HAR515 275/70 R 22.5
Tyre disposal
Shock Rubbers
Air dryer filter TRP
Governor Valve D 2

B Service

- Replace front shock rubbers & tighten bolt
- Replace right front steer tyre
- Replace pedal roller

Vehicle Details

Registration	XA05AM	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	T358R	Engine #	9 DG 10907	Air	Yes
Model Series		VIN	442985	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour		Odometer/Hr	204110 / 11	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
			• Replace air lines to compressor & repair air leaks to Clutch fan • Clean out unloader valve in compressor head • Fit new governor valve • Kit air dryer	

1611	11/02/2023	165689	B service Hughie Pump	Invoice
	1R0751		Fuel filter	
	1R-1808		Oil Filter	
	5134490		Fuel filter	
	VECTON		Vecton 15W40 Engine Oil	
	KSMA3124720QP		Brake Shoe Kit Front Axle KW	
	KSMA2124720QP		Shoe kit meritor steer	
	WBK3DCRV		Wheel Bearing Kit Merritor Drive	
	35066S		Wheel Seal Scot Seal	
	275/70 R22.5 HIFLY		Hifly HAR515 275/70 R 22.5	
	NPN01		Tyre disposal	

Replace Hughie pump
B Service
Replace brake lining on all wheels
Replace wheel bearings on Left rear drive
Replace front seals on right front & left second steer
Replace Right front steer tyre

1546	12/01/2023	0	A Service	Invoice
	K066-310		Shock Rubbers	
	K229-1527-643		Step Access	
	CONS		General Consumables Used	

A Service

- Replace all rear shock rubbers
- Replace all front lower shock rubbers
- Replace drivers side top step

1501	07/12/2022	145830	B service	Invoice
	1R-1808		Oil Filter	
	1R0751		Fuel filter	
	VECTON		Vecton 15W40 Engine Oil	
	275707		Governor Valve D 2	
	CONS		General Consumables Used	

B Service
Replace governor valve

1383	25/07/2022	121023	C Service	Invoice
	VECTON		Vecton 15W40 Engine Oil	
	TFC450		Gear oil	
	TFC410		10w gear oil	
	AP85W140		Diff oil	
	1R-1808		Oil Filter	
	C81-1004		Air Spring Kenworth	
	KSMA3124707QP		Brake Shoe Kit Meritor	
	1R0751		Fuel filter	

Vehicle Details

Registration	XA05AM	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	T358R	Engine #	9 DG 10907	Air	Yes
Model Series		VIN	442985	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour		Odometer/Hr	204110 / 11	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
	5134490		Fuel filter	
	17237		Eaton Transmission Filter	
	A3380W1687		Merritor Diff Filter	
	LF637		Oil Filter Power steer	

C Service
Replace air bag
Replace boost hose

1382	07/06/2022	114362	B service & repairs	Invoice
	NPN03		timing gear /lifters & gaskets	
	1R-1808		Oil Filter	
	VECTON		Vecton 15W40 Engine Oil	

B Service
(found metal in sump, timing gear had teeth missing)
Replace timing gear , cam followers.

1340	28/01/2022	94955	B service &Annual inspection New floor	Invoice
	LAB		Labour	
	VECTON		Vecton 15W40 Engine Oil	
	1R-1808		Oil Filter	

B Service
Fit new floor liner

1271	25/11/2021	70127	Air bags	Invoice
	C81-1004		Air Spring Kenworth	

Replace 2 air bags

1270	30/10/2021	0	Starter Motor	Invoice
	82S1063B		Starter Motor 39MT	

Replace Starter Motor

1221	11/08/2021	71763	B service & Annual Inspection	Invoice
	M110PCR3		Steering box	
	TFC410		10w gear oil	
	R134A		Refrigerant Gas	
	1R-1808		Oil Filter	
	1R0751		Fuel filter	
	5134490		Fuel filter	
	VECTON		Vecton 15W40 Engine Oil	
	A05-0383		Air Dryer Filter	

b Service

- Replace o ring on A/C compressor
- Replace receiver dryer
- Replace steering box

Vehicle Details

Registration	XA05AM	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	T358R	Engine #	9 DG 10907	Air	Yes
Model Series		VIN	442985	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour		Odometer/Hr	204110 / 11	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
1205	27/07/2021	68348	Brake holding on	Invoice
	44-120113-04		Draglink End	
	44-120123-02		Draglink end LH	
	106165		Valve brake relay	
Replace second steer drag link ends Replace service brake relay valve				
1190	16/06/2021	63460	B service	Invoice
	1R-1808		Oil Filter	
	1R0751		Fuel filter	
	5134490		Fuel filter	
	VECTON		Vecton 15W40 Engine Oil	
	LAB		Labour	
	KSMA2124715QP		Brake Shoe Kit Front Axle KW	
B Service Replace rear drive brakes				
1119	05/03/2021	49266	B service	Invoice
	CONS		General Consumables Used	
	1R0751		Fuel filter	
	5134490		Fuel filter	
	275/70R22.5 ST04		Maxxis	
	LAB		Labour	
	1R-1808		Oil Filter	
	VECTON		Vecton 15W40 Engine Oil	
B Service • Replace left front drive tyres • Replace left headlight globe				
1178	15/01/2021	0	Compressor	Invoice
	20R-0176		Compressor C9 CAT	
	209-0762		Gasket	
	SUBLET		Enzed Hose	
	NPN03		Power steer pump	
Replace Compressor & power steering pump				
1072	25/11/2020	34214	B service	Invoice
	1R-1808		Oil Filter	
	1R0751		Fuel filter	
	5134490		Fuel filter	
	VECTON		Vecton 15W40 Engine Oil	
	LAB		Labour	
B Service				
1014	21/09/2020	20707	C Service	Invoice
	WBK4SUCR		Wheel Bearing Kit	
	T2000SK-P		Air Dryer Kit	
	TFC450		Gear oil	

Vehicle Details

Registration	XA05AM	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	T358R	Engine #	9 DG 10907	Air	Yes
Model Series		VIN	442985	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour		Odometer/Hr	204110 / 11	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
	AP85W140		Diff oil	
	TFC410		10w gear oil	
	HF6107		Oil Filter	
	LAB		Labour	
	VECTON		Vecton 15W40 Engine Oil	
	1R-1808		Oil Filter	
	1R0751		Fuel filter	
	5134490		Fuel filter	
	WF2077		Water filter no DCA	
	A3380W1687		Merritor Diff Filter	
	17237		Eaton Transmission Filter	
	A24-3275M1079PZ		Auto Slack Adjuster 5.5" 28	
	275/70R22.5		275/70/22.5 Double Coin RT 500 all position	
	30/30		Spring Brake Chamber	

C service

- Fit new auto slack adjusters
- Replace right front brake booster
- Fit 2 front steer tyres

963	21/07/2020	7805	B service	Invoice
	VECTON		Vecton 15W40 Engine Oil	
	1R-1808		Oil Filter	
	R801073		Auto Slack adjuster	
	LAB		Labour	
	KSMA3124707QP		Brake Shoe Kit Meritor	
	R801073		Auto Slack adjuster	
	TRPWN133Y		Wheel nut indicators 33mm over chrome nut	
	SA52		Convex Mirror Kit	
	1R0751		Fuel filter	
	5134490		Fuel filter	

B Service

- Fit steer slack adjusters
- Fit wheel indicators
- Fit bonnet mirror
- Fit rear axle brake linings

929	15/06/2020	4439	Annual Inspection	Invoice
	LAB		Labour	

Annual inspection
Tighten front shocks

878	20/04/2020	11	B service	Invoice
	LAB		Labour	
	275/70R22.5		275/70/22.5 Double Coin RLB490 Drive	
	NPN01		Tyre disposal	
	1R-1808		Oil Filter	
	5134490		Fuel filter	
	1R-0749		Filter AS-FU	
	VECTON		Vecton 15W40 Engine Oil	
	K152-551-1B		Speedometer 120KM/H	

Vehicle Details

Registration	XA05AM	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	T358R	Engine #	9 DG 10907	Air	Yes
Model Series		VIN	442985	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour		Odometer/Hr	204110 / 11	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
-------------	------	------------------	-------------	------

- B Service
- Replace speedometer
- Repair lights & park lights
- Replace left rear drive tyres

770	27/11/2019	674220	B service	Invoice
	TX4500S		GME UHF Radio	
	VECTON		Vecton 15W40 Engine Oil	
	1R-1808		Oil Filter	
	5134490		Fuel filter	
	1R-0749		Filter AS-FU	
	LAB		Craig & Zane	

B Service
Replace UHF radio

769	27/09/2019	662926	B service	Invoice
	5134490		Fuel filter	
	1R-0749		Filter AS-FU	
	275/70R22.5		275/70/22.5 Double Coin RLB490 Drive	
	K374-26		Shock absorber Front	
	VECTON		Vecton 15W40 Engine Oil	
	LAB		Nick	
	1R-1808		Oil Filter	

- B Service
- Replace rear drive tyres
- fit new shocks to front steer & front drive

649	29/07/2019	652436	B service	Invoice
	SA003TRP		Shock Absorber TRP	
	274-6719		Sensor Oil Pressure	
	VECTON		Vecton 15W40 Engine Oil	
	1R-1808		Oil Filter	
	5134490		Fuel filter	
	1R0751		Fuel filter	
	LAB		Craig	
	CONS		General Consumables Used	

B Service
Replace rear axle shock absorbers
Replace oil pressure sender unit (leaking oil)

626	06/06/2019	642540	B service & Annual Inspection	Invoice
	LAB		Craig	
	VECTON		Vecton 15W40 Engine Oil	
	1R-1808		Oil Filter	
	10R8900		Fuel Pump Hyd High pressure	
	227-5904		Seal O Ring	
	5134490		Fuel filter	
	1R0751		Fuel filter	
	CONS		General Consumables Used	

Vehicle Details

Registration	XA05AM	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	T358R	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TIPPER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
-------------	------	------------------	-------------	------

- B Service
- Annual inspection
- Replace hughie fuel pump
- Replace worn rocker bump stops to steer axle rockers
- Repair wiring for low air buzzer & Light

577	28/05/2019	641423	Batteries	Invoice
------------	-------------------	---------------	------------------	----------------

N70ZZHMF
1613CR
CONS
Battery
Cap Front Hub Black Plastic
General Consumables Used

Replace Batteries x 2
replace leaking hub cap left second steer
fill with oil

528	08/04/2019	633679	B Service	Invoice
------------	-------------------	---------------	------------------	----------------

LAB
CONS
1R-1808
5134490
1R0751
VECTON
billy
General Consumables Used
Oil Filter
Fuel filter
Fuel filter
Vecton 15W40 Engine Oil

- B Service
- Replace loose bolt in rear of tarp
- Remove Heater core to clean terminal onto heater fan

477	11/02/2019	623115	B Service	Invoice
------------	-------------------	---------------	------------------	----------------

1R-1808
5134490
1R0751
VECTON
NPN03
LAB
CONS
1202K046
S63-1001
Oil Filter
Fuel filter
Vecton 15W40 Engine Oil
Rubber Hammer
Jimmy & Jash
General Consumables Used
Shock Absorber Cabin
Pad Clutch Pedal

B Service
Replace cab shock
fit clutch pedal rubber

474	07/12/2018	0	Transmission & Clutch New Body	Invoice
------------	-------------------	----------	---	----------------

226-4757
9X-4576
160-2283
9Y-0810
SUBLET
LAB
J91-6000-100
TR1174C
RT1209A6
7103
Seal
Seal O Ring
Gasket
Sleeve
Machine Flywheel
Ash Josh
Steering Wheel
Cover lug-nut chrome
Hub Cap
Hub Cap 8" Chrome

Vehicle Details

Registration	XA05AM	Next Service	Litres	
Make	Kenworth	Rego Due	Trans	MANUA
Model	T358R	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TIPPER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
	308935.515PAC		Clutch Kit	
	E55-1128		Lever Clutch Control	
	6306-2RS2		Bearing Transmission	
	K036-235		bearing bellcrank	
	VFS6G-8		Rod End Clutch Link	
	7709		Marker Plates Plain	
	SUBLET		Rebuild 18 speed transmission	
	10-01750-11		Dash Cam Garmin	
	CONS		General Consumables Used	

- Remove Transmission & Clutch assy
- Replace rear main oil seal and mounting gasket
- Send Transmission to "Truck Transmissions"
- Machine Flywheel
- Fit new clutch assy with new bell crank bearing & rod ends
- Replace rebuilt transmission
- Fit Garman dash cam
- Replace steering wheel
- Fit new nut covers & hub caps
- Fit new tipper body
-

408	19/10/2018	612788	B service & Defect Clearance	Invoice
	LAB		Labour	
	VECTON		Vecton 15W40 Engine Oil	
	1R-1808		Oil Filter	
	1R0751		Fuel filter	
	5134490		Fuel filter	
	WF2072		Water Filter	
	CONS		General Consumables Used	

- A & B Service
- Repair & Replace left side bumper
- Wash under side of truck
-

254	26/07/2018	602253	C Service	Invoice
	1R-1808		Oil Filter	
	1R-0755		Oil Filter Cat	
	5134490		Fuel filter	
	WBK4SUCR		Wheel Bearing Kit	
	T2000SK-P		Air Dryer Kit	
	VECTON		Vecton 15W40 Engine Oil	
	PT50 GEAR OIL		Gear oil	
	85W140		Hypoid Diff Oil	
	LF689		Oil Filter	
	RT1209A6		Hub Cap	
	LAB		Labour	
	137-5541		Pump hand Primer	
	1P-0436		Gasket	

Vehicle Details

Registration	XA05AM	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	T358R	Engine #	9 DG 10907	Air	Yes
Model Series		VIN	442985	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour		Odometer/Hr	204110 / 11	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
• C Service • Replace lift pump				
226	20/06/2018	599318	Replace Compressor	Invoice
	1P-0436		Gasket	
	LAB		Labour	
	20R-0176		Compressor C9 CAT	
Replace Compressor (leaking air back through unloader valve)				
201	14/06/2018	599318	B service & Annual Inspection Replace	Invoice
	1R0751		Fuel filter	
	5134490		Fuel filter	
	WF2072		Water Filter	
	VECTON		Vecton 15W40 Engine Oil	
	LAB		Labour	
	LAB		Labour	
	1R1808		Oil Filter	
	10900965001		Clutch Fan Kysor	
Replace Fan Hub				
B Service & Annual Inspection				
160	09/04/2018	590993	A & B Service & Replace tyres	Invoice
	275/70R22.5		Tyre TH06Z Hankook	
	LAB		Labour	
	1R1808		Oil Filter	
	1R0751		Fuel filter	
	5134490		Fuel filter	
	WF2072		Water Filter	
	OIL ENGINE		Lubeolloy	
	D2		D 2 Governor	
	H3		H 3 Globe Driving light	
	CONS		Park Light Globe	
	NPN03		Alloy For Repairs	
	LAB		Pete	
	LAB		Bonnet	
	LAB		Service	
• Replace all Drive tyres .A & B service. Adjust clutch & Clutch brake • Repair bonnet hinge. Repair holes in floor				

Vehicle Details

Registration	XA05AM	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	T358R	Engine #	9 DG 10907	Air	Yes
Model Series		VIN	442985	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour		Odometer/Hr	204110 / 11	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
2639	01/08/2025	0	Batteries	Invoice
Fit 2 x batteries				
1760	27/12/2023	226974	C Service	Invoice
C Service lh 3rd axle shock 2 suspension bushes Tyres LH 4 axle				
1815	22/08/2023	204110	A Service	Invoice
A Service Replace left front slack adjuster & brake linings				
1684	18/07/2023	196288	Injector	Invoice
Replace No 6 injector because of mis-fire				
1640	27/05/2023	187432	B service	Invoice
B Service • Replace front shock rubbers & tighten bolt • Replace right front steer tyre • Replace pedal roller • Replace air lines to compressor & repair air leaks to Clutch fan • Clean out unloader valve in compressor head • Fit new governor valve • Kit air dryer				
1611	11/02/2023	165689	B service Hughie Pump	Invoice
Replace Hughie pump B Service Replace brake lining on all wheels Replace wheel bearings on Left rear drive Replace front seals on right front & left second steer Replace Right front steer tyre				
1546	12/01/2023	0	A Service	Invoice

Vehicle Details

Registration	XA05AM	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	T358R	Engine #	9 DG 10907	Air	Yes
Model Series		VIN	442985	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour		Odometer/Hr	204110 / 11	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
A Service				
• Replace all rear shock rubbers • Replace all front lower shock rubbers • Replace drivers side top step				
1501	07/12/2022	145830	B service	Invoice
B Service Replace governor valve				
1383	25/07/2022	121023	C Service	Invoice
C Service Replace air bag Replace boost hose				
1382	07/06/2022	114362	B service & repairs	Invoice
B Service (found metal in sump, timing gear had teeth missing) Replace timing gear , cam followers.				
1340	28/01/2022	94955	B service &Annual inspection New floor	Invoice
B Service Fit new floor liner				
1271	25/11/2021	70127	Air bags	Invoice
Replace 2 air bags				
1270	30/10/2021	0	Starter Motor	Invoice
Replace Starter Motor				
1221	11/08/2021	71763	B service & Annual Inspection	Invoice
b Service				
• Replace o ring on A/C compressor • Replace receiver dryer • Replace steering box				
1205	27/07/2021	68348	Brake holding on	Invoice
Replace second steer drag link ends Replace service brake relay valve				
1190	16/06/2021	63460	B service	Invoice
B Service Replace rear drive brakes				

Vehicle Details

Registration	XA05AM	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	T358R	Engine #	9 DG 10907	Air	Yes
Model Series		VIN	442985	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour		Odometer/Hr	204110 / 11	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
1119	05/03/2021	49266	B service	Invoice
B Service • Replace left front drive tyres • Replace left headlight globe				
1178	15/01/2021	0	Compressor	Invoice
Replace Compressor & power steering pump				
1072	25/11/2020	34214	B service	Invoice
B Service				
1014	21/09/2020	20707	C Service	Invoice
C service • Fit new auto slack adjusters • Replace right front brake booster • Fit 2 front steer tyres				
963	21/07/2020	7805	B service	Invoice
B Service • Fit steer slack adjusters • Fit wheel indicators • Fit bonnet mirror • Fit rear axle brake linings				
929	15/06/2020	4439	Annual Inspection	Invoice
Annual inspection Tighten front shocks				
878	20/04/2020	11	B service	Invoice
• B Service • Replace speedometer • Repair lights & park lights • Replace left rear drive tyres				
770	27/11/2019	674220	B service	Invoice
B Service Replace UHF radio				
769	27/09/2019	662926	B service	Invoice
• B Service • Replace rear drive tyres • fit new shocks to front steer & front drive				

Vehicle Details

Registration	XA05AM	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	T358R	Engine #	9 DG 10907	Air	Yes
Model Series		VIN	442985	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour		Odometer/Hr	204110 / 11	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
649	29/07/2019	652436	B service	Invoice
B Service Replace rear axle shock absorbers Replace oil pressure sender unit (leaking oil)				
626	06/06/2019	642540	B service & Annual Inspection	Invoice
• B Service • Annual inspection • Replace hughie fuel pump • Replace worn rocker bump stops to steer axle rockers • Repair wiring for low air buzzer & Light				
577	28/05/2019	641423	Batteries	Invoice
Replace Batteries x 2 replace leaking hub cap left second steer fill with oil				
528	08/04/2019	633679	B Service	Invoice
• B Service • Replace loose bolt in rear of tarp • Remove Heater core to clean terminal onto heater fan				
477	11/02/2019	623115	B Service	Invoice
B Service Replace cab shock fit clutch pedal rubber				
474	07/12/2018	0	Transmission & Clutch New Body	Invoice
• Remove Transmission & Clutch assy • Replace rear main oil seal and mounting gasket • Send Transmission to "Truck Transmissions" • Machine Flywheel • Fit new clutch assy with new bell crank bearing & rod ends • Replace rebuilt transmission • Fit Garman dash cam • Replace steering wheel • Fit new nut covers & hub caps • Fit new tipper body •				
408	19/10/2018	612788	B service & Defect Clearance	Invoice
• A & B Service • Repair & Replace left side bumper • Wash under side of truck •				

Vehicle Details

Registration	XA05AM	Next Service		Litres	
Make	Kenworth	Rego Due		Trans	MANUA
Model	T358R	Engine #	9 DG 10907	Air	Yes
Model Series		VIN	442985	Cyl	0
Model Code		Build Date		Body	TIPPER
Colour		Odometer/Hr	204110 / 11	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
254	26/07/2018	602253	C Service	Invoice
- C Service - Replace lift pump				
226	20/06/2018	599318	Replace Compressor	Invoice
Replace Compressor (leaking air back through unloader valve)				
201	14/06/2018	599318	B service & Annual Inspection Replace	Invoice
Replace Fan Hub B Service & Annual Inspection				
160	09/04/2018	590993	A & B Service & Replace tyres	Invoice
- Replace all Drive tyres .A & B service. Adjust clutch & Clutch brake - Repair bonnet hinge. Repair holes in floor				