

### Vehicle Details

<b>Registration</b>	T2018C	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	Corkhills	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	3 axle dog	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEDAN
<b>Colour</b>		<b>Odometer</b>	<b>Prod</b>	

Invoice No.	Date	Odometer	Description	Type
1187	15/07/2021	0	<b>Tyres</b>	Invoice
	11R22.5 DOUBLE COIB RR99		Double coin RR99 148/145 all position	
	NPN01		Tyre disposal	
	LAB		Labour	

Replace left center axle tyres

1084	24/11/2020	0	<b>B service &amp; Annual Inspection</b>	Invoice
	0509146320BH95		Brake shoe Kit	
	TRP19032/36		kit brake shoe BPW	

Service & Annual inspection

- Replace middle axle brake shoes
- Replace middle axle left wheel bearings

1032	29/09/2020	0	<b>Air Bag</b>	Invoice
	47Y2228		BPW Air bag assy After market	
	LAB		Labour	

Replace two lift axle air bags

1021	18/09/2020	0	<b>Service</b>	Invoice
	0509146320BH95		Brake shoe Kit	
	LAB		Labour	

Replace brake linings on 4 x wheels

965	13/07/2020	0	<b>C Service</b>	Invoice
	LAB		Labour	
	47Y2503		Levelling valve kit	
	0509146320BH95		Brake shoe Kit	

C service

- Replace center axle brake linings
- Adjust ride height & fit repair kit to levelling valve

948	04/05/2020	0	<b>Rewire trailer &amp; replace pulleys</b>	Invoice
	LAB		Labour	
	CONS		General Consumables Used	

- Rewire trailer to taillights

## Vehicle Details

<b>Registration</b>	T2018C	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	Corkhills	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	3 axle dog	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEDAN
<b>Colour</b>		<b>Odometer</b>	<b>Prod</b>	

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

- Fit new 100mm dia pulleys to front of tarp
- Fit new trailer plugs

<b>870</b>	<b>08/04/2020</b>	<b>0</b>	<b>A Service &amp; repairs</b>	<b>Invoice</b>
------------	-------------------	----------	--------------------------------	----------------

TA DBS  
LAB  
CONS  
Springs Draw Bar  
Labour  
General Consumables Used

### A Service

- Replace Draw bar springs
- Repair air tank support bracket

<b>869</b>	<b>04/03/2020</b>	<b>0</b>	<b>Electric Tarp</b>	<b>Invoice</b>
------------	-------------------	----------	----------------------	----------------

15-326S  
RT10278  
LAB  
Trailer Socket  
Tarp Motor & Gearbox 12/24 volt  
Labour

Replace Socket & plug on tarp plug  
Replace tarp motor

<b>840</b>	<b>10/02/2020</b>	<b>0</b>	<b>B service &amp; repairs</b>	<b>Invoice</b>
------------	-------------------	----------	--------------------------------	----------------

LAB  
TRP5003980  
TRP19032/36  
10996597  
11R22.5 DOUBLE COIB RR99  
NPN01  
Craig  
Check Valve  
kit brake shoe BPW  
Ring Feeder eye bush Standard 50mm  
Double coin RR99 148/145 all position  
tyre disposal

- Replace 8 tyres
- Replace ring feeder eye bush
- Replace rear axle brake shoes
- 

<b>758</b>	<b>30/10/2019</b>	<b>0</b>	<b>Annual Inspection</b>	<b>Invoice</b>
------------	-------------------	----------	--------------------------	----------------

02.0316.90.00  
NPN03  
LAB  
11R22.5 DOUBLE COIB RR99  
NPN01  
05.429.43.66.0  
LAB  
Bush BPW Spring eye Large  
1m x 1 1/2 brite steel rod  
Craig  
Double coin RR99 148/145 all position  
Tyre disposal  
Air Bag type 30  
Zane, Liam

Annual Inspection  
Replace leaking air spring  
fit 4 tyres  
4/11/19  
Replace tailgate two way pin  
Weld crack in sub chassis between 2 rear axles  
23/11/19

## Vehicle Details

<b>Registration</b>	T2018C	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	Corkhills	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	3 axle dog	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEDAN
<b>Colour</b>		<b>Odometer</b>	<b>Prod</b>	

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

Replace spring pin eye bush left dolly

<b>689</b>	<b>01/10/2019</b>	<b>0</b>	<b>B service</b>	<b>Invoice</b>
------------	-------------------	----------	------------------	----------------

LAB  
11R22.5 DOUBLE COIB RR99

Labour  
Double coin RR99 148/145 all position

B Service  
Replace right center axle tyres

<b>688</b>	<b>06/08/2019</b>	<b>0</b>	<b>A Service</b>	<b>Invoice</b>
------------	-------------------	----------	------------------	----------------

47Y0004BPW  
LAB  
BRAKE LINING BPW  
03.212.25.31.0

Spring alignment plate  
Labour  
Meritor B95  
BPW hub cap Eco Plus

- A Service
- Replace brake lining on dolly
- Replace brake lining in middle axle
- Re align middle axle
- Replace safety strap on left middle axle

<b>646</b>	<b>08/07/2019</b>	<b>0</b>	<b>Brake Valve &amp; tyres</b>	<b>Invoice</b>
------------	-------------------	----------	--------------------------------	----------------

11R22.5 DOUBLE COIB RR99  
02.4310.24.00  
LAB

Double coin RR99 148/145 all position  
Charging Valve / Regulator  
Craig

Replace left center axle tyres  
Fit new charging valve  
Fit new maxi control valve

<b>556</b>	<b>29/04/2019</b>	<b>0</b>	<b>Chassis Rail</b>	<b>Invoice</b>
------------	-------------------	----------	---------------------	----------------

CONS  
NPN03  
NPN03  
LAB

General Consumables Used  
1/2 bolts  
Alloy chassis  
Pete

Replace right side chassis rail & bolts  
Repair crack in frame right had side

<b>497</b>	<b>19/03/2019</b>	<b>0</b>	<b>A Service</b>	<b>Invoice</b>
------------	-------------------	----------	------------------	----------------

LAB  
CONS  
NPN03

Sean & Matt  
General Consumables Used  
LED Clearance light

Repair light on right side of trailer  
Fit 2 tyres to rear axle  
A Service

<b>469</b>	<b>18/02/2019</b>	<b>0</b>	<b>General Repairs</b>	<b>Invoice</b>
------------	-------------------	----------	------------------------	----------------

LAB  
CONS

Labour  
General Consumables Used

Replace Right rear outside tyre with run out  
repair left indicator / Hard wire in new plug to indicator  
Repair wiring to left side clearance light

## Vehicle Details

<b>Registration</b>	T2018C	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	Corkhills	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	3 axle dog	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEDAN
<b>Colour</b>		<b>Odometer</b>	<b>Prod</b>	

Invoice No.	Date	Odometer	Description	Type
496	10/01/2019	0	Tarp & Tarp Motor & Gearbox 12/24 volt	Invoice

NPN03  
 NPN03  
 CONS  
 LAB  
 15-326S  
 15-336S  
 RT10278  
 YAR205-2F  
 SYJ505

20x20x6 RHS  
 Remote control kit  
 Wire & Consumables  
 Labour  
 Trailer Socket  
 Socket trailer plug 2 pin  
 Tarp Motor & Gearbox 12/24 volt  
 Y Bearing  
 Y Bearing

Fit new Polly tarp  
 Fit new motor & gearbox  
 Fit new pulley shaft and bearings  
 Service trailer

389	23/11/2018	0	A Service	Invoice
	LAB CONS		Ash Josh Sean General Consumables Used	

- A Service

388	10/11/2018	0	Rear Brakes	Invoice
-----	------------	---	-------------	---------

TRP19032/36  
 0980106890  
 0509700KIT  
 CONS  
 LAB  
 LAB  
 8-22-285P1  
 11R22.5 Y785  
 0310967080  
 CONS

kit brake shoe BPW  
 Wheel Bearing Kit BPW 10T  
 Cam shaft kit  
 General Consumables Used  
 Craig  
 Billy & Jimmy  
 Wheel Alloy 285X10  
 Yokohama L Duty tyre  
 BPW brake drum  
 12 mm joiner

- Replace rear axle brake drums & linings
- Replace s cam kit
- New wheel & tyre left rear
- Fit new wheel bearings to left rear wheel

351	29/10/2018	0	Annual Inspection	Invoice
	LAB NPN03		Josh R12 Relay Valve	

- Annual Inspection
- Replace leaking relay valve

336	18/10/2018	0	Dolly Brake	Invoice
-----	------------	---	-------------	---------

Vehicle Details				
Registration	T2018C	Next Service	Litres	
Make	Corkhills	Rego Due	Trans	N/A
Model	3 axle dog	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEDAN
Colour		Odometer	Prod	
		0		

Invoice No.	Date	Odometer	Description	Type
	TRP19032/36		kit brake shoe BPW	
	LAB		Ash	
	CONS		General Consumables Used	
<div>Left Dolly wheel, brake sticking on due to kinked hose.</div> <div> <ul style="list-style-type: none"> <li>Replace and re position brake hose</li> <li>Replace brake shoes on Left Front Dolly Wheel</li> </ul> </div>				
278	30/08/2018	0	C Service	Invoice
	LAB		Labour	
	CONS		General Consumables Used	
<div> <ul style="list-style-type: none"> <li>C Service</li> <li>Tighten 2nd axle spring eye bolts</li> </ul> </div>				
180	15/05/2018	0	A & B Service	Invoice
	NPN03		3/8 Air hose	
	LAB		Labour	
<div> <ul style="list-style-type: none"> <li>A &amp; B Service  replace air line to dog lock</li> </ul> </div>				

### Vehicle Details

<b>Registration</b>	T2018C	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	Corkhills	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	3 axle dog	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEDAN
<b>Colour</b>		<b>Odometer</b>	<b>Prod</b>	

Invoice No.	Date	Odometer	Description	Type
1187	15/07/2021	0	Tyres	Invoice
Replace left center axle tyres				
1084	24/11/2020	0	B service & Annual Inspection	Invoice
Service & Annual inspection <ul style="list-style-type: none"> <li>• Replace middle axle brake shoes</li> <li>• Replace middle axle left wheel bearings</li> </ul>				
1032	29/09/2020	0	Air Bag	Invoice
Replace two lift axle air bags				
1021	18/09/2020	0	Service	Invoice
Replace brake linings on 4 x wheels				
965	13/07/2020	0	C Service	Invoice
C service <ul style="list-style-type: none"> <li>• Replace center axle brake linings</li> <li>• Adjust ride height &amp; fit repair kit to levelling valve</li> </ul>				
948	04/05/2020	0	Rewire trailer & replace pulleys	Invoice
<ul style="list-style-type: none"> <li>• Rewire trailer to taillights</li> <li>• Fit new 100mm dia pulleys to front of tarp</li> <li>• Fit new trailer plugs</li> </ul>				
870	08/04/2020	0	A Service & repairs	Invoice
A Service <ul style="list-style-type: none"> <li>• Replace Draw bar springs</li> <li>• Repair air tank support bracket</li> </ul>				
869	04/03/2020	0	Electric Tarp	Invoice

## Vehicle Details

<b>Registration</b>	T2018C	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	Corkhills	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	3 axle dog	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEDAN
<b>Colour</b>		<b>Odometer</b>	<b>Prod</b>	

Invoice No.	Date	Odometer	Description	Type
Replace Socket & plug on tarp plug Replace tarp motor				
840	10/02/2020	0	B service & repairs	Invoice
<ul style="list-style-type: none"> <li>• Replace 8 tyres</li> <li>• Replace ring feeder eye bush</li> <li>• Replace rear axle brake shoes</li> <li>•</li> </ul>				
758	30/10/2019	0	Annual Inspection	Invoice
Annual Inspection Replace leaking air spring fit 4 tyres 4/11/19 Replace tailgate two way pin Weld crack in sub chassis between 2 rear axles 23/11/19 Replace spring pin eye bush left dolly				
689	01/10/2019	0	B service	Invoice
B Service Replace right center axle tyres				
688	06/08/2019	0	A Service	Invoice
<ul style="list-style-type: none"> <li>• A Service</li> <li>• Replace brake lining on dolly</li> <li>• Replace brake lining in middle axle</li> <li>• Re align middle axle</li> <li>• Replace safety strap on left middle axle</li> </ul>				
646	08/07/2019	0	Brake Valve & tyres	Invoice
Replace left center axle tyres Fit new charging valve Fit new maxi control valve				
556	29/04/2019	0	Chassis Rail	Invoice
Replace right side chassis rail & bolts Repair crack in frame right had side				
497	19/03/2019	0	A Service	Invoice
Repair light on right side of trailer Fit 2 tyres to rear axle A Service				
469	18/02/2019	0	General Repairs	Invoice

## Vehicle Details

<b>Registration</b>	T2018C	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	Corkhills	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	3 axle dog	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEDAN
<b>Colour</b>		<b>Odometer</b>	<b>Prod</b>	

Invoice No.	Date	Odometer	Description	Type
Replace Right rear outside tyre with run out repair left indicator / Hard wire in new plug to indicator Repair wiring to left side clearance light				
496	10/01/2019	0	Tarp & Tarp Motor & Gearbox 12/24 volt	Invoice
Fit new Polly tarp Fit new motor & gearbox Fit new pulley shaft and bearings Service trailer				
389	23/11/2018	0	A Service	Invoice
<ul style="list-style-type: none"> <li>A Service</li> </ul>				
388	10/11/2018	0	Rear Brakes	Invoice
<ul style="list-style-type: none"> <li>Replace rear axle brake drums &amp; linings</li> <li>Replace s cam kit</li> <li>New wheel &amp; tyre left rear</li> <li>Fit new wheel bearings to left rear wheel</li> </ul>				
351	29/10/2018	0	Annual Inspection	Invoice
<ul style="list-style-type: none"> <li>Annual Inspection</li> <li>Replace leaking relay valve</li> </ul>				
336	18/10/2018	0	Dolly Brake	Invoice
Left Dolly wheel, brake sticking on due to kinked hose. <ul style="list-style-type: none"> <li>Replace and re position brake hose</li> <li>Replace brake shoes on Left Front Dolly Wheel</li> </ul>				
278	30/08/2018	0	C Service	Invoice
<ul style="list-style-type: none"> <li>C Service</li> <li>Tighten 2nd axle spring eye bolts</li> </ul>				
180	15/05/2018	0	A & B Service	Invoice
<ul style="list-style-type: none"> <li>A &amp; B Service replace air line to dog lock</li> </ul>				