

Vehicle Details

Registration	T5663A	Next Service	Litres	
Make	Corkhills	Rego Due	Trans	N/A
Model	4 axle dog	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	AV00WJ	Build Date	Body	TIPPER
Colour	Corkhills		Prod	

Invoice No.	Date	Odometer	Description	Type
2005	03/09/2024	0	B service	Invoice
CONS GREASE 20KG				General Consumables Used Black Tack 20kg
B Service				
1912	12/07/2024	0	Tail Lights & Tarp retract	Invoice
ISL100R CONS				LED Stop tail ZEON General Consumables Used
Replace inoperative Stop Tail Lights Tarp does not retract or extend - replace 2 x brake/park combo lights - replace R/H grain lock - repair loose terminals on tarp motor - replace both eyelets on tarp motor (16-6 lugs)				
1809	12/07/2023	0	Accident damage	Invoice
LAB 05.429.43.66.0				Labour Air Bag type 30
Straighten & weld rear tail light assy Replace 2 x tail lights & 1 x indictor light Replace left rear air bag				
1659	05/07/2023	0	A Service & Air bag	Invoice
05.429.43.66.0 CONS				Air Bag type 30 General Consumables Used
Replace air bag on dolly A service				
1338	29/06/2022	0	Rear Axles	Invoice
05.082.13.59.0 05.348.30.05.0 05.429.43.66.0 NPN03				Spring Pack / Trailing arm Retaining Strap BPW Air Bag type 30 10 tonne trailer axles inv no 22006501
Replace 2 x rear axles Replace rear axle spring leaves & spring straps Clean out lift axle control valves				

Vehicle Details

Registration	T5663A	Next Service	Litres	
Make	Corkhills	Rego Due	Trans	N/A
Model	4 axle dog	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	AV00WJ	Build Date	Body	TIPPER
Colour	Corkhills		Prod	

Invoice No.	Date	Odometer	Description	Type
Replace lift axle air bag				
1337	17/08/2021	0	Wheel bearing	Invoice
	0980102720TSSC		Wheel bearing kit 9 ton axle	
Replace wheel bearing on left lift up axle				
1123	05/03/2021	0	Annual Inspection	Invoice
	LAB		Labour	
	09.801.06.33.0		Guide pin repair kit BPW	
	CONS		General Consumables Used	
Annual inspection Repair third axle left brake caliper Replace tyres on same wheel				
997	24/08/2020	0	Service	Invoice
	275/70R22.5		275/70/22.5 Double Coin RLB490 Drive	
	LAB		Labour	
	18G7901		Drain Tap	
Service trailer				
- Replace 4 tyres on dolly - Replace drain valve on air tank				
996	06/08/2020	0	General Repairs	Invoice
	09.801.08.15.0		Brake Pad Kit Axle Set	
	F34-001		Brake rotor BPW Knorr	
	LAB		Labour	
- Repair Puncture - Replace brake pads & rotor 2 left Dolly				
979	24/04/2020	0	A Service & Repairs	Invoice
	05.444.40.0		Brake booster BPW 16/24	
	09.801.08.15.0		Brake Pad Kit Axle Set	
	02.3506.02.00		Bump Stop	
	LAB		Labour	
- Replace 3rd axle brakes - Replace 4th axle left side booster - Replace lift axle bump stop - A Service				
995	06/11/2019	0	B service	Invoice
	CONS		General Consumables Used	
B service Replace left rear hub & bearing				
582	30/05/2019	0	Tarp	Invoice

Vehicle Details

Registration	T5663A	Next Service	Litres	
Make	Corkhills	Rego Due	Trans	N/A
Model	4 axle dog	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	AV00WJ	Build Date	Body	TIPPER
Colour	Corkhills		Prod	

Invoice No.	Date	Odometer	Description	Type
	NPN03 LAB CONS		hoop tarp Shadecloth Pete General Consumables Used	
Replace hoop tarp				
398	29/11/2018	0	B Service	Invoice
	CONS LAB		General Consumables Used Craig Ash Josh	
• B Service • Repair air leak at rear axle				
305	12/09/2018	0	Repair Cracks in chassis & body	Invoice
	LAB CONS 265/70R19.5 OGREENS		Labour General Consumables Used 265/70 R 19.5 O Greens AG735	
• Repair cracks in rear of body, hoist well, tail gate,and chassis. • Replace tyres on left 3rd axle & move good tyres to left 2nd axle.				
222	02/07/2018	0	A Service & brake pads	Invoice
	09.801.08.15.0 LAB		Brake Pad Kit Axle Set Labour	
A Service Replace rear axle brake pads				
164	16/04/2018	0	A Service & Annual inspection	Invoice
	1530S CONS NPN03 LAB		7 Pin Plug General Consumables Used Alloy Plate Labour	
Repair holes in floor. Repair cracks in rear x member. replace trailer electrical plug. Annual inspection				
126	26/03/2018		Tyres	Invoice
	275/70R22.5 LAB		Tyre TH06Z Hankook Labour	
Replace 4 x tyres on rear of dolly Replace 1 tyre on right front outside on dolly				

CORKHILL BROS

CANBERRA

Vehicle History

Vehicle Details

Registration	T5663A	Next Service		Litres	
Make	Corkhills	Rego Due		Trans	N/A
Model	4 axle dog	Engine #		Air	Yes
Model Series		VIN	6W9TTBB4D4C052001	Cyl	0
Model Code	AV00WJ	Build Date		Body	TIPPER
Colour	Corkhills			Prod	

Invoice No.	Date	Odometer	Description	Type
2005	03/09/2024	0	B service	Invoice
B Service				
1912	12/07/2024	0	Tail Lights & Tarp retract	Invoice
Replace inoperative Stop Tail Lights Tarp does not retract or extend • replace 2 x brake/park combo lights • replace R/H grain lock • repair loose terminals on tarp motor • replace both eyelets on tarp motor (16-6 lugs)				
1809	12/07/2023	0	Accident damage	Invoice
Straighten & weld rear tail light assy Replace 2 x tail lights & 1 x indicator light Replace left rear air bag				
1659	05/07/2023	0	A Service & Air bag	Invoice
Replace air bag on dolly A service				
1338	29/06/2022	0	Rear Axles	Invoice
Replace 2 x rear axles Replace rear axle spring leaves & spring straps Clean out lift axle control valves Replace lift axle air bag				
1337	17/08/2021	0	Wheel bearing	Invoice
Replace wheel bearing on left lift up axle				
1123	05/03/2021	0	Annual Inspection	Invoice
Annual inspection Repair third axle left brake caliper Replace tyres on same wheel				
997	24/08/2020	0	Service	Invoice

Vehicle Details

Registration	T5663A	Next Service	Litres	
Make	Corkhills	Rego Due	Trans	N/A
Model	4 axle dog	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	AV00WJ	Build Date	Body	TIPPER
Colour	Corkhills		Prod	

Invoice No.	Date	Odometer	Description	Type
Service trailer • Replace 4 tyres on dolly • Replace drain valve on air tank				
996	06/08/2020	0	General Repairs	Invoice
• Repair Puncture • Replace brake pads & rotor 2 left Dolly				
979	24/04/2020	0	A Service & Repairs	Invoice
• Replace 3rd axle brakes • Replace 4th axle left side booster • Replace lift axle bump stop • A Service				
995	06/11/2019	0	B service	Invoice
B service Replace left rear hub & bearing				
582	30/05/2019	0	Tarp	Invoice
Replace hoop tarp				
398	29/11/2018	0	B Service	Invoice
• B Service • Repair air leak at rear axle				
305	12/09/2018	0	Repair Cracks in chassis & body	Invoice
• Repair cracks in rear of body, hoist well, tail gate, and chassis. • Replace tyres on left 3rd axle & move good tyres to left 2nd axle.				
222	02/07/2018	0	A Service & brake pads	Invoice
A Service Replace rear axle brake pads				
164	16/04/2018	0	A Service & Annual inspection	Invoice
Repair holes in floor. Repair cracks in rear x member. replace trailer electrical plug. Annual inspection				
126	26/03/2018		Tyres	Invoice
Replace 4 x tyres on rear of dolly Replace 1 tyre on right front outside on dolly				

Vehicle Details

Registration	T5663A	Next Service		Litres	
Make	Corkhills	Rego Due		Trans	N/A
Model	4 axle dog	Engine #		Air	Yes
Model Series		VIN	6W9TTBB4D4C052001	Cyl	0
Model Code	AV00WJ	Build Date		Body	TIPPER
Colour	Corkhills			Prod	

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------