



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY03827
Decal Expiry Date: 2025-Dec-31
Inspection Number: 21401842

Inspection Result:

PASS

FACILITY:	NORTHERN B.C. TRUCKERS' / N5398	INSP. TYPE:	Complete	INSP. START:	2025-Jun-23 07:00 AM MST
INSPECTOR:	CHRISTIANSON, LESLIE RYAN / 108407	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Jun-23 08:30 AM MST
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	01655170	VIN:	904943C
PLATE #:	VK2592	UNIT/FLEET#:		OWNER/LESSEE NAME:	DOWD LANCE DOUGLAS, NA
LICENCED GVW(kg):	44500	BODY STYLE:	Truck Tractor	ADDRESS:	7903 92ST
VEHICLE YEAR:	1979	ODOMETER:	341 KM		Fort St John, British Columbia
MAKE:	KENWORTH	HUB ODOMETER:			V1J1H6, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Not Applicable	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	NEW GPS SPEEDO SET TO 105
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Repaired (same day)	NEW DRIVE TIRES
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Not Applicable	NA	Not Applicable	0	0	15			15	✓
2	Clamp	30	Manual	30	33	24	24	24	24	
3	Clamp	30	Manual	32	33	24	24	24	24	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	0	0	Lining (Shoe)	0	0	Drum			
2	47	53	Lining (Shoe)	18	17.5	Drum			
3	45	58	Lining (Shoe)	18	17	Drum			
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: CHRISTIANSON, LESLIE RYAN

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jun-24 12:34 PM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NBCVP at the Commercial Vehicle Safety Enforcement.

CVSE014

6/24/2025 12:34:26 PM MST