

016-1



Commercial Vehicle Inspection Report

Decal Number: PX23049
Decal Expiry Date: 2025-Sep-30
Inspection Number: 21091290

Inspection Result:
PASS

FACILITY:	DON MANN EXCAVATING LTD. / P1156	INSP. TYPE:	Complete	INSP. START:	2024-Sep-24 08:00 AM PDT
INSPECTOR:	BEALE, RONNIE ALAN / 111253	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2024-Sep-24 02:30 PM PDT
WORK ORDER #:		INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	08807588	VIN:	2HSFMAHTXRC090614
PLATE #:	RX1583	UNIT/FLEET#:	54	OWNER/LESSEE NAME:	Mann, Don
LICENCED GVW(kg):	25400	BODY STYLE:	Flat Deck	ADDRESS:	4098 Lochside Dr, 4098 Lochside Dr
VEHICLE YEAR:	1994	ODOMETER:	4217757 KM		Victoria, British Columbia
MAKE:	INTERNATNA	HUB ODOMETER:			V8X2C8, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) repair high beam indicator lamp replace flasher unit
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	35	35	12			17	✓
2	Clamp	30	Automatic	35	35	18	18	15	15	
3	Clamp	30	Automatic	35	35	20	20	20	20	
Comment: removed 1st axle drums						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	0	0	Lining (Shoe)	17	17	Drum		
2	50	70	Lining (Shoe)	17	15	Drum		
3	70	80	Lining (Shoe)	14	13	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured. did not remove rear drums		

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Ron Beale Road Tester:

Inspector: BEALE, RONNIE ALAN Signature: Ron Beale

This Inspection Report was submitted to CVSE on 2024-Oct-01 01:47 PMPDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.