

Maintenance History Report

Report Generated on 15/05/26 07:58 AM

2459 International 4x4 Fuel Truck

Job No	Job Title	Start Date	Status
J0341433/0	Prepare For Operation	07/03/19	C
P0051819/0	Yearly Inspection of Pressure Vessels	13/03/19	C
J0341950/0	Fire Risk Assessment	13/03/19	C
J0342335/0	Intro to Site Ravensworth	19/03/19	C
J0342801/0	Tyres Replaced Pos 3,4,5,6.S/S-10597	26/03/19	C
J0343156/0	Drivers Seat Inspection	01/04/19	C
J0343459/0	Intro to Site (Multiple)	04/04/19	C
J0343807/0	Reduce quick fill flow speed	09/04/19	C
J0343808/0	Quick fill ball valve leaking	09/04/19	C
J0343737/0	Speed test	09/04/19	C
J0344030/0	Repair isolator wiring	11/04/19	C
J0344056/0	Brakes smoking	12/04/19	C
J0344158/0	Install & wire heated mirror circuit	15/04/19	C
J0344183/0	Coolant loss from overflow bottle	15/04/19	C
J0344463/0	Electric horn not working	18/04/19	C
S0000657/0	Safety Inspection 2018/2019	23/04/19	C
J0345102/0	Remove white paint splatter	03/05/19	C
J0345385/0	LH rear work light not working	07/05/19	C
J0345472/0	Repair access ladder	08/05/19	C
P0052402/0	2000hr servcie	09/05/19	C
J0345997/0	Check Front Diff Oil Leak	15/05/19	C
J0345998/0	Install Fire Ext Brackets	15/05/19	C
J0345999/0	Fit flagpole to LH corner of front bumper	15/05/19	C
J0346096/0	Repair navman ignition cycle	16/05/19	C
J0346203/0	SOS fuel for contamination	17/05/19	C
J0346252/0	Airdryer blowing off regularly	20/05/19	C
C0000609/0	Install Datafuel Console	13/06/19	C
J0347964/0	Hyd Breather Cap Leaks	14/06/19	C
J0348944/0	Engine not starting	27/06/19	C
S0000975/0	Safety Inspection 2019-2020	05/07/19	C
J0349388/0	RH headlight n/w	05/07/19	C
J0349389/0	Check hard start	05/07/19	C
J0349814/0	Bearing noise in driveline	12/07/19	C
J0351003/0	Pump 1 n/w intermittantly	29/07/19	C
J0351471/0	Tyres rotated - Pos 1,2.S/S-10901	06/08/19	C
J0351817/0	Paint steer wheel rims	12/08/19	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0352269/0	LHR hub slight oil leak	19/08/19	C
J0353094/0	Various stickers peeling off	29/08/19	C
J0353451/0	Pre-delivery inspection	04/09/19	C
J0353735/0	Front driving light n/w	09/09/19	C
J0354465/0	Air tank stickers replace	18/09/19	C
J0354611/0	101527 - Still waiting on speed limiter	20/09/19	C
J0354916/0	Prepare for Wambo	25/09/19	C
J0354967/0	Repair passenger seat	26/09/19	C
J0354969/0	Adjsut steps safety chain	26/09/19	C
J0354970/0	Lubricate drivers door lock	26/09/19	C
J0355165/0	Change quick fill nozzle	30/09/19	C
P0054082/0	500hr Service (International)	03/10/19	C
J0355591/0	Replace rear marker decals	04/10/19	C
J0356202/0	Intro to Site (Wambo)	16/10/19	C
J0356308/0	Stickers replace	17/10/19	C
J0356309/0	Washer jets blocked	17/10/19	C
J0356313/0	Dash cluster lights N/W	17/10/19	C
J0356645/0	Datafuel calibration	23/10/19	C
J0358893/0	Replace Air Fitting For Safety Rail	26/11/19	C
J0360424/0	Upgrade Datafuel Console	19/12/19	C
J0361453/0	Pump 1 Locking	17/01/20	C
J0362359/0	Turbo replaced, low power	03/02/20	C
J0362580/0	Brake Test 2020	06/02/20	C
J0362767/0	101532 - Tank Ladder Mounts	07/02/20	C
J0363223/0	101533 - Quick Fill Leaking/Replace	14/02/20	C
J0363224/0	101533 - Check Front Suspension Noise	14/02/20	C
J0363265/0	Date Fuel Add Dip N/W	17/02/20	C
J0363416/0	Tyres replaced - Pos 1,2,3,4,5,6.S/S11520	18/02/20	C
J0364093/0	Repair tank access ladder mounts	27/02/20	C
J0364353/0	Replace Air Filter Regulator Assy	03/03/20	C
J0364391/0	Air leak on compressor pipe fitting	04/03/20	C
P0055659/0	Yearly Inspection of Pressure Vessels	13/03/20	C
P0055903/0	Yearly MAC compliance & safety related control function audit	23/03/20	C
P0055889/0	1000hr Service (International)	25/03/20	C
J0365998/0	Wambo Non-Conformances	28/03/20	C
J0366090/0	Replace A/C Controller	30/03/20	C
J0366244/0	Brake test	01/04/20	C
J0366474/0	Handrail Cable	04/04/20	C
J0367080/0	LH Drive Axle Leaking	15/04/20	C
J0367116/0	Oil Leak From L/H/R	16/04/20	C
J0367202/0	Engine Light On, Low Power	17/04/20	C
J0367988/0	Replace Stickers	28/04/20	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0367913/0	Replace Driver Boosters	28/04/20	C
J0368069/0	S.O.S Transfer Case	29/04/20	C
J0368515/0	Transfer Box Issue	06/05/20	C
J0368784/0	101534 & 101537 - RH Rearview Mirror Cracked	08/05/20	C
J0368901/0	Horn Stuck On	11/05/20	C
J0368992/0	LH Top Worklight N/W	13/05/20	C
J0368995/0	Replace Banlaw Quick Fill Nozzle	13/05/20	C
J0368996/0	Retension Wheels	13/05/20	C
J0369691/0	101536 - Ad Blue Tank Flap Torn	21/05/20	C
J0369592/0	101536 - Replace RH Toolbox Locks	21/05/20	C
J0371312/0	Fuel Pump Starting Fault	16/06/20	C
J0371530/0	Turbo Oil Feed Gasket Leak	18/06/20	C
J0371902/0	Refit LH Inner Guard	25/06/20	C
J0371903/0	Change Fill Point Fittings	25/06/20	C
J0371925/0	101534 - Losing Air From Drivers Seat For 1st Half Of Shift	25/06/20	C
J0372005/0	Reverse Alarm Staying On	26/06/20	C
S0001287/0	Safety Inspection 2020-2021	02/07/20	C
J0372508/0	Air Leak At Quick Fill Valve	06/07/20	C
J0372556/0	Float truck to NCV Beresfield for repairs	06/07/20	C
J0372958/0	Prep for Site	14/07/20	C
J0373288/0	Brake Failure pos 4/rear axle brake reline/wheel retension pos 3/4/5/6	20/07/20	C
J0373989/0	101540 - Reverse Alarm Inop	30/07/20	C
J0373990/0	R/H mirror cracked	30/07/20	C
J0374009/0	500hr Service (International)	15/08/20	C
J0375921/0	RHR Brake Overstoking	28/08/20	C
J0376387/0	101540 & 101542 - Quick Fill Flow Meter Not Working	03/09/20	C
J0376388/0	Beacon, Navman & Reverse Camera Not Working	03/09/20	C
J0376294/0	101542 - Drivers Seat Losing Air	03/09/20	C
J0376386/0	101542 - Worklights Not Working	04/09/20	C
J0376490/0	Set Up For Mt Arthur South	04/09/20	C
J0376560/0	Check Transmission Fault	08/09/20	C
J0377082/0	101540 & 101543 - Check AC, Noisy	15/09/20	C
J0377083/0	101543 - Quick Feel Meter Not Reading	15/09/20	C
J0377288/0	Brake Test 2020	17/09/20	C
J0378109/0	Repair Air Leaks	30/09/20	C
J0378110/0	Rear Compartment Bolts Loose	30/09/20	C
J0378933/0	Intro to Site (MACH Energy)	15/10/20	C
J0379463/0	fuel tank sensor to be replaced	23/10/20	C
J0380058/0	Battery Replacement	03/11/20	C
J0380207/0	101545 - Check AC Vents Poor Flow	05/11/20	C
J0380298/0	101545 - Fuel Leak At Gun	06/11/20	C
J0381089/0	stalled and will not restart towed to Iveco	19/11/20	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0381730/0	replace Navman screen	01/12/20	C
J0382190/0	Repair lights	08/12/20	C
J0382368/0	Repalce A/C hose	11/12/20	C
J0383222/0	101549 - Replace Hyd Tank Cap	07/01/21	C
J0383264/0	101548 & 101550 - Data Fuel Inop	08/01/21	C
J0383844/0	Repair exhuaast leak	19/01/21	C
P0058771/0	2000hr Service (International)	23/01/21	C
J0384180/0	Check UHF operation	25/01/21	C
J0384193/0	101539 - Rear Work Lights Inop	25/01/21	C
J0384300/0	Repair A/C system	28/01/21	C
J0389834/0	500hr Service (International)	31/01/21	C
J0384604/0	System in over ride	03/02/21	C
J0385765/0	broken gas strutt on rear door	19/02/21	C
J0385906/0	Check for vibration	23/02/21	C
J0386006/0	Front main seal leak	24/02/21	C
J0386007/0	Rear marker plates worn	24/02/21	C
J0386078/0	Replace fuel counter	25/02/21	C
P0059423/0	Yearly Inspection of Pressure Vessels	13/03/21	C
J0387024/0	Repair 90% fuel shut off	15/03/21	C
P0059515/0	Yearly MAC compliance & safety related control function audit	23/03/21	C
J0387690/0	120032 - Replace drivers seat belt	26/03/21	C
J0387742/0	Check engine blowing smoke	26/03/21	C
J0387743/0	Repair ladder bracket	26/03/21	C
J0387759/0	Check emergency stops	28/03/21	C
J0388288/0	Repair driving lights	08/04/21	C
J0388425/0	120032 - Header tank cracked	09/04/21	C
J0388426/0	120032 - Powersteer reservoir leaking	09/04/21	C
J0388733/0	Engine Misfire Repair	14/04/21	C
J0388708/0	120033 - Replace UHF microphone	15/04/21	C
J0388885/0	120032, 120033 - Secure tank step tread plate/ Handrail	19/04/21	C
J0388886/0	120033 - Toolbox strut arm insecure	19/04/21	C
J0389142/0	Check Engine Fault Light	21/04/21	C
J0389543/0	Drive mudflaps missing and mudgaurd pole loose	29/04/21	C
J0389665/0	120032 - Install extended diff breather kit	30/04/21	C
J0389784/0	Headlight backings u/s	03/05/21	C
J0389831/0	120032 - Dash & foot well light lights inop	04/05/21	C
J0390104/0	120034 - Eng bay guard mount broken	07/05/21	C
J0390597/0	120033 - Engine light on intermitant fault	18/05/21	C
J0390932/0	Tyres replaced at Pos 3,4,5,6	21/05/21	C
J0390949/0	Air leak at front of engine bay	21/05/21	C
J0390951/0	Inspect engine oil leak	21/05/21	C
J0391463/0	Replace engine belts	31/05/21	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0391535/0	Brake Test 2021	01/06/21	C
J0391536/0	120034 - No odometer or hours on dash cluster	01/06/21	C
J0391759/0	Accelerator pedal broken	03/06/21	C
J0391963/0	120036 - data fuel fault (Activation Switches) repaired by ryan	08/06/21	C
J0391995/0	Datafuel fault (Intermittant fuel recording)	08/06/21	C
J0392213/0	air tank drain valves	11/06/21	C
J0392214/0	tighten step plate	11/06/21	C
J0392617/0	Inspect seat fault	21/06/21	C
S0001623/0	Safety Inspection 2021-2022	01/07/21	C
J0393391/0	RHR tail light inop	02/07/21	C
J0394486/0	120037 - Engine miss intermittant	22/07/21	C
J0394763/0	120038 - LH work light and reverse camer inop	28/07/21	C
J0395202/0	120039 - UHF not recieving	04/08/21	C
J0395254/0	120039 - Fuel nozzle leaking at swivel	05/08/21	C
J0395256/0	Repair bent LHR shock mount	05/08/21	C
J0395259/0	Repair tank access ladder	05/08/21	C
J0395504/0	Rear toolbox locks require replacement	10/08/21	C
J0396063/0	Hydrostatic testing	18/08/21	C
P0062280/0	NHVR Annual Heavy Vehicle Inspection	01/09/21	C
P0061107/0	1000hr Service (International)	07/09/21	C
J0397414/0	Drivers sunvisor insecure LH mount	13/09/21	C
J0397612/0	120030 - RH drive guard needs to repositioned	15/09/21	C
J0397613/0	120030 - Centre console needs resucring	15/09/21	C
J0397621/0	Damaged safety decals	16/09/21	C
J0397676/0	Flush fuel hoses after hydrostatic test	17/09/21	C
J0398012/0	Boost hoses worn	23/09/21	C
J0399105/0	Front Diff Lock Not Working	15/10/21	C
J0399106/0	Mine radio cradle not charging	15/10/21	C
J0399092/0	Refit steer shaft plastics	15/10/21	C
J0399181/0	Annual MACH Energy ITS	19/10/21	C
J0399475/0	Adjust & Test Brakes	20/10/21	C
J0399845/0	Repair Roof Triangle Mounts	25/10/21	C
J0399846/0	Replace heated mirror switch	25/10/21	C
J0399582/0	Radiator leaking	26/10/21	C
J0399586/0	Bonnet side indicator inop	26/10/21	C
J0399595/0	112902 - Datafuel fault	26/10/21	C
J0399811/0	Inspect noise in front diff	29/10/21	C
J0400076/0	112904 -tail light inop	03/11/21	C
J0400219/0	112903 & 112904 - meter on quick fill broken cancel button	05/11/21	C
J0400347/0	112904- inspect a/c temp	08/11/21	C
J0400473/0	112904 - Exhaust repair	10/11/21	C
J0401074/0	Eng stalled, No Start Bengalla rd	19/11/21	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0401199/0	Heater core leaking	23/11/21	C
P0062279/0	500hr Service (International)	28/11/21	C
J0401429/0	Oil in cooling system	29/11/21	C
J0402872/0	Low engine power	23/12/21	C
J0404407/0	Replace fire extinguisher	03/02/22	C
J0405119/0	Coolant hose leaking	16/02/22	C
J0405239/0	Repair rear door mount	18/02/22	C
J0405256/0	Replace steer tyres	18/02/22	C
J0405264/0	Repair various lights	18/02/22	C
J0405720/0	rebuild spare banlaw fuel nozzel	01/03/22	C
P0063038/0	Yearly Inspection of Pressure Vessels	13/03/22	C
J0406396/0	stalled and will not start	14/03/22	C
J0406928/0	112905 - Engine Misfire	22/03/22	C
J0406929/0	112905 - A/C Mod needed	22/03/22	C
P0063039/0	Yearly MAC compliance and safety related control function audit	23/03/22	C
J0407934/0	Engine running rough	04/04/22	C
J0407953/0	Replace injector harness	08/04/22	C
J0408181/0	Reverse Camera N/W	13/04/22	C
J0408659/0	Replace Batteries (3)	28/04/22	C
J0408722/0	Drivers window wont go up	29/04/22	C
J0410021/0	Reverse alarm inop	24/05/22	C
J0411796/0	Repair A/C and lights	27/06/22	C
J0411898/0	Inspect PTO Operation	28/06/22	C
S0001832/0	Safety Inspection 2022-2023	01/07/22	C
J0412058/0	Repair Right Rear Mudflap	01/07/22	C
J0413938/0	Repair Leaking Fuel Hose	08/08/22	C
J0413940/0	Repair A/C Blower Fan	08/08/22	C
J0413941/0	Repair Front Diff	08/08/22	C
J0414352/0	Replace Front Wheel Bearings	12/08/22	C
J0414503/0	Overhaul Front Differential	16/08/22	C
J0415005/0	Replace LH kingpin bearing	22/08/22	C
P0064596/0	2000hr Service (International)	27/08/22	C
J0415651/0	Check hard steering	03/09/22	C
J0415936/0	Replace Clock Spring	07/09/22	C
J0416010/0	Replace adblue reel	09/09/22	C
J0416506/0	lubes from J415651	19/09/22	C
J0417661/0	Tyres replaced Pos 1,2,3,4,5,6	13/10/22	C
J0418025/0	Front diff pinion seal leak	20/10/22	C
J0418027/0	Replace radiator hoses	20/10/22	C
J0418073/0	Repair Adblue system fault	20/10/22	C
J0418445/0	Replace drive mudflaps	27/10/22	C
J0418581/0	Replace Water Pump	31/10/22	C

<p>Status Codes N - New A - Active P - Pending C - Completed</p>
--

Maintenance History Report

Job No	Job Title	Start Date	Status
J0418912/0	Intro To Site Inspections VAR	04/11/22	C
J0419528/0	Engine wont start	15/11/22	C
J0419738/0	Non conformance repairs	18/11/22	C
J0419764/0	Horn fault	18/11/22	C
J0419963/0	Adjust downshift programming on transmission	23/11/22	C
J0420123/0	Paint rear compartment door and replace lower tail lghts	25/11/22	C
J0420472/0	Repair Dash	01/12/22	C
J0422557/0	Engine Not Starting	17/01/23	C
J0413939/0	Non Conformance Repairs	23/01/23	C
J0422823/0	Replace AdBlue Pump	24/01/23	C
P0067624/0	500hr Service (International)	01/02/23	C
J0423601/0	Repair Window Fault	07/02/23	C
P0067626/0	NHVR Annual Heavy Vehicle Inspection	17/02/23	C
J0424186/0	D/S window reg	17/02/23	C
P0066747/0	Yearly Inspection of Pressure Vessels	13/03/23	C
J0425681/0	ITS For Bulga, HVO, MAC BHP, UWJVOC	14/03/23	C
P0066886/0	Yearly MAC compliance and safety related control function audit	23/03/23	C
J0426386/0	Replace Right Mirror	27/03/23	C
J0427163/0	Eng oil in coolant	13/04/23	C
J0428082/0	Replace Data Fuel Modem	01/05/23	C
P0068996/0	1000hr Service (International)	17/05/23	C
J0429542/0	Repair Aux Fuel Pump	27/05/23	C
J0429669/0	Engine Light (Int. shutting down and running rough)	30/05/23	C
J0430071/0	4871 Electrical Audit SLAM Engineering	06/06/23	C
S0002235/0	Safety Inspection 2023-2024	01/07/23	C
J0431539/0	Rear door seal	05/07/23	C
J0431639/0	Replace Aux fuel nozzles	06/07/23	C
J0432373/0	Repair Window Winder	20/07/23	C
J0432854/0	Tie Rod Bent	24/07/23	C
J0432855/0	Drivers door frame rusty	24/07/23	N
J0432856/0	Front Axle Seals Leaking	24/07/23	C
J0432590/0	Left Drive Spring broken	25/07/23	C
J0432736/0	Repair No Start	26/07/23	C
J0432757/0	Replace Rear Hydraulic Hoses	26/07/23	C
J0432673/0	Driving lights inop	27/07/23	C
J0432965/0	Non-Conformance Repairs	27/07/23	C
J0433044/0	RH drive hub seal leaking	02/08/23	C
J0434714/0	Hydraulics Overheating	04/09/23	C
J0434780/0	Tank access lader repairs	06/09/23	C
J0436280/0	Intro to Site Inspection Bulga HVO MAC UWJVOC BMC PCP Mangoola MTW & MDG15	04/10/23	C
J0439134/0	LHR Brake Booster Leaking	24/11/23	C
J0439135/0	Tail Lights Not Working	24/11/23	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0439124/0	Coolant leak	25/11/23	C
J0439376/0	Replace Exhaust Flex	29/11/23	C
J0439377/0	Replace Front Bump Stops	29/11/23	C
J0439379/0	Inspect Diesel Site Glass	29/11/23	C
J0439380/0	Replace NHVAS Label	29/11/23	C
J0440262/0	Data Fuel Wont Power Up	14/12/23	C
P0070057/0	500hr Service (International)	04/01/24	C
J0441160/0	RH Drive Spring Broken	10/01/24	C
J0441112/0	Stuck in hi range	10/01/24	C
P0070509/0	Fire Risk Reassessment	06/02/24	C
J0442528/0	Hydrostatic Test & Recertification	06/02/24	C
J0443684/0	Install Navman TN360	23/02/24	C
J0444107/0	Triangle Mount Bracket Loose On ROPS	29/02/24	C
J0445227/0	LH Mirror Bracket Loose On Cab	19/03/24	C
J0445348/0	RH Window Reg Stripped	19/03/24	C
J0445338/0	Install Tank Vent	21/03/24	C
J0445504/0	Reverse Alarm Not Working	25/03/24	C
J0445566/0	RH Drive Spring Centre Bolt Broken	26/03/24	C
J0446270/0	Directional Valve repair	11/04/24	C
J0447815/0	Fuel Meter Not Reading	09/05/24	C
J0448767/0	Hydraulics slow	28/05/24	C
J0450150/0	Repair No Start	21/06/24	C
J0450309/0	Quick fill hose leaking	24/06/24	C
S0002523/0	Safety Inspection 2024-2025	01/07/24	C
P0072214/0	NHVR Annual Heavy Vehicle Inspection	24/07/24	C
J0453986/0	Intro to Site Inspection MAC & MDG15	29/08/24	C
J0454045/0	RHR Hub Seal Leaking	30/08/24	C
J0455347/0	Bulga ITS Non-conformance Repairs	23/09/24	C
J0455720/0	Front Tank Sight Glass Leaking	30/09/24	C
P0073160/0	2000hr Service (International)	17/10/24	C
J0457560/0	LH Drive Mudguard Replaced	06/11/24	C
J0465116/0	112909 - LH Door Switch	31/03/25	C
J0465117/0	112909 - Repair Roof Interior Light	31/03/25	C
P0074878/0	Biennial Pressure Vessel Inspection	30/04/25	C
J0467048/0	Dash Lights Not Working	30/04/25	C
J0467050/0	Windscreen Washers Not Working	30/04/25	C
J0467051/0	Top Radiator Hose Leaking	30/04/25	C
J0467053/0	A/C Not Cold	30/04/25	C
J0467054/0	Engine fan solenoid fault	30/04/25	N
J0467047/0	Reair Various Air Leaks	01/05/25	C
J0467064/0	Reseal axle shaft Pos 2	06/05/25	N
J0467066/0	Passenger window winder	06/05/25	N

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0470450/0	Jump Start	02/07/25	C
S0002856/0	Safety Inspection 2025-2026	04/07/25	N
J0470563/0	Replace cab leveling valve	04/07/25	N
J0470583/0	Repair service defect list	04/07/25	N
J0472598/0	ITS Inspection MAC BHP MPO & MDG15	08/08/25	C
J0475639/0	Daracon Pre-Delivery	08/10/25	N
J0475648/0	Prepare for site	08/10/25	N
J0476766/0	PTO N/W	29/10/25	C
J0476785/0	Data fuel key reader n/w	30/10/25	C
J0482316/0	Datafuel fault	23/02/26	N
P0079043/0	NHVR Annual Heavy Vehicle Inspection	30/04/26	N