

Maintenance History Report

Report Generated on 15/05/26 08:02 AM

7220 Muscat B Double Side Tipper B Trailer

Job No	Job Title	Start Date	Status
J0036817/0	Prepare vehicle for operations	30/01/09	C
J0039136/0	INITIAL REGISTRATION COSTS	03/03/09	CA
J0039712/0	Carry out A Service	06/03/09	C
J0039732/0	Tighten side worklamp	07/03/09	C
J0041350/0	RIGHT FRONT CLEARANCE LIGHT OUT, REVERSE LIGHTS AND BEEPER NOT WORKING	26/03/09	C
J0042512/0	Wash trailer	09/04/09	C
J0043936/0	WEEKLY GREASING AND INSPECTING FOR MAY 209	01/05/09	C
J0044227/0	Tighten rear axle brake booster hoses	01/05/09	C
J0044234/0	Wash trailer	01/05/09	C
J0044788/0	Wash Trailer	06/05/09	C
J0045888/0	Repair booster hose leaks	21/05/09	C
J0046702/0	GREASE & INSPECTION FOR JUNE 2009	02/06/09	C
J0047334/0	Fit wheel savers	04/06/09	C
J0047342/0	Air leak at turntable	04/06/09	C
J0047667/0	Wash trailer	10/06/09	C
J0049183/0	Grease & Inspections - July 09	01/07/09	C
J0049531/0	Wash trailer	01/07/09	C
J0050064/0	AIR LEAK UNDER REAR OF VEHICLE	09/07/09	C
J0051022/0	Check and tension all axle u-bolts & nuts to 550ft/lbs	22/07/09	C
J0051232/0	WHEEL ALIGNMENT	24/07/09	C
J0051757/0	Grease & Inspections - August 09	01/08/09	C
P0004051/0	B-SERVICE	04/08/09	C
J0053068/0	103 INSPECTION	11/08/09	C
J0053305/0	Wash Trailer - August 2009	11/08/09	C
J0053358/0	Straighten & align fron axle & tension all 'U' bolts	12/08/09	C
J0053506/0	Replace tyre tags	18/08/09	C
J0054886/1	Fit wheel stud markers	01/09/09	C
J0054886/0	Grease & Inspection - September 2009	01/09/09	C
J0055043/0	Tension 'u' bolts	01/09/09	C
J0055758/0	Replace tyres P23, 24, 25 & 26	10/09/09	C
J0056097/0	Wash Trailer - Sep 09	10/09/09	C
J0056496/0	Resecure hinge pin	15/09/09	C
P0004441/0	'B' Service	17/09/09	C
J0057577/0	Grease & Inspections - October 2009	01/10/09	C
J0058948/0	Steam clean trailer	13/10/09	C

<p>Status Codes N - New A - Active P - Pending C - Completed</p>
--

Maintenance History Report

Job No	Job Title	Start Date	Status
J0059425/0	Turntable cover broken off	26/10/09	C
J0059492/0	Repair broken mudflap and frames	27/10/09	C
J0059847/0	Airbags won't inflate	02/11/09	C
J0060752/0	Steam clean trailer	03/11/09	C
J0060266/0	Torn mudflap	06/11/09	C
J0060443/0	B service	10/11/09	C
J0061280/0	Replace tyre P31	11/11/09	C
J0061018/1	Adjust wheel bearing left front	17/11/09	C
J0061018/0	Pre 103 Inspection	17/11/09	C
J0061414/0	Tighten all trailing arm bolts	19/11/09	C
J0061479/0	Fit NHVAS sticker	20/11/09	C
J0061676/0	Grease & Inspections - November 2009	24/11/09	C
J0061812/0	Rear door hinge pin loose	25/11/09	C
J0062349/0	LHR pedestal damaged	02/12/09	C
J0062954/0	Steam clean/wash trailer	03/12/09	C
J0062791/0	Grease and Inspection - December 2009	08/12/09	C
J0064154/0	B service	21/12/09	C
J0064351/0	Replace tyres at POS19,20,21,22	24/12/09	C
J0066076/0	GREASE & INSPECTION FAR JAN 2010	01/01/10	C
J0065151/0	ABS plug out	07/01/10	C
J0065321/0	Tarp not working	08/01/10	C
J0066266/0	FRONT TARP ARM DAMAGED	19/01/10	C
J0067244/0	GREASE & INSPECTION FOR FEB 2010	02/02/10	C
J0067267/0	GREASE & INSPECTION FOR FEB 2010	02/02/10	C
J0067487/0	FIT REGO LABEL	04/02/10	C
J0067600/0	103 INSPECTION	05/02/10	C
J0067600/1	RIGHT FRONT SPRING SAFET STRAP DAMAGED	09/02/10	C
J0068190/0	REAR LEFT TYRE U/S	10/02/10	C
J0068353/0	RE-TENSION WHEEL NUTS	11/02/10	C
J0068373/0	Replace tyres at POS23	11/02/10	C
J0068782/0	B-SERVICE	16/02/10	C
J0068782/1	LOAD LIGHT INOP	16/02/10	C
J0068782/2	WHEEL BEARING LOOSE	16/02/10	C
J0070203/0	GREASE & INSPECTION FOR MARCH 2010	01/03/10	C
J0070187/0	DOORS POP OPEN ABOUT 3" WHEN LOADING, BIN IS SLOW TO TIP	03/03/10	C
J0070188/0	mudflap missing	03/03/10	C
J0070472/0	FIT "SHEDDER" TO TOP GUNNEL	05/03/10	C
J0071592/0	NHVAS Annual Inspection and Service @ Volvo	22/03/10	C
J0072220/0	Replace tyres Pos 27,28	29/03/10	C
J0072596/0	Retension wheels	30/03/10	C
J0072560/0	Grease and inspection Apr 2010	09/04/10	C
J0073339/0	Grease and inspection Apr 2010	13/04/10	C

<p>Status Codes N - New A - Active P - Pending C - Completed</p>
--

Maintenance History Report

Job No	Job Title	Start Date	Status
J0076145/0	Replace tyres Pos 29/30	11/05/10	C
J0076158/0	Grease and inspection May 2010	11/05/10	C
J0076703/0	Replace U/S LH rear brake booster	20/05/10	C
J0077135/0	AB Service	25/05/10	C
J0077670/0	grease and inspection may 2010	31/05/10	C
J0079914/0	replace mudflaps	25/06/10	C
P0006731/0	grease and inspection june 2010	25/06/10	C
P0006893/0	Bi Monthly Grease & Inspection	01/07/10	C
J0081395/0	safety straps on axles missing	14/07/10	C
J0083427/0	tighten wheel brg	06/08/10	C
J0086016/0	suspension repair	01/09/10	C
P0007763/0	Bi Monthly Grease & Inspection	01/09/10	C
J0085878/0	Square wheels & re-tighten 'U' bolts	06/09/10	C
J0087827/0	tarp n/w	28/09/10	C
J0088004/0	Clearance lights n/w	01/10/10	C
J0088317/0	wheel retension	01/10/10	C
P0008591/0	Bi Monthly Grease & Inspection	01/11/10	C
J0093302/0	remove trailers and fit to 7230	01/12/10	C
J0093740/0	brakes slow in actuation	13/12/10	C
J0094885/0	Tyres - fit runout tyre	01/01/11	C
J0094927/0	Tarp	01/01/11	C
P0009390/0	Bi Monthly Grease & Inspection	01/01/11	C
P0008958/0	Rego Inspection	04/01/11	C
J0097304/0	Lights n/w	02/02/11	C
J0097312/0	Air leaks	02/02/11	C
J0097313/0	Shock absorber	02/02/11	C
P0015650/0	Rego Renewal	04/02/11	C
P0010327/0	Bi Monthly Grease & Inspection	28/02/11	C
J0100647/0	brake reline	01/03/11	C
J0101318/0	Shock absorbers	01/03/11	C
J0101321/0	Tyres - Replace POS25,26	30/03/11	C
J0102057/0	Spare Rims for Unit	10/04/11	C
J0104338/0	Tyres - Replace POS27,28	01/05/11	C
J0105020/0	Tarp n/w	01/05/11	C
J0105049/0	Not tipping correctly	01/05/11	C
P0011277/0	Bi Monthly Grease & Inspection	01/05/11	C
J0105610/0	Tyres - Repalce POS19,20,21,22	23/05/11	C
J0106924/0	Replace nhvas label	01/06/11	C
J0107066/0	Repair tarp electrical problem	15/06/11	C
J0108827/0	Air bag leaking at feet	01/07/11	C
J0108964/0	Reline Brakes - All Axles	01/07/11	C
J0109090/0	Replace brake pads	01/07/11	C

<p>Status Codes N - New A - Active P - Pending C - Completed</p>
--

Maintenance History Report

Job No	Job Title	Start Date	Status
J0109892/0	Replace lift ram	01/07/11	C
P0012291/0	Bi Monthly Grease & Inspection	01/07/11	C
J0108838/0	Change tyre POS 18	06/07/11	CA
J0112705/0	Front axle wheel bearings loose.	15/08/11	C
P0012893/0	1000hr Service	15/08/11	C
J0113386/0	Check spring eye bushes	22/08/11	C
J0113387/0	Change air bag	22/08/11	C
J0114336/0	Check booster	31/08/11	C
P0013387/0	Bi Monthly Grease & Inspection	31/08/11	C
J0114517/0	Repair tip signal valve	02/09/11	C
J0116879/0	Reverse lights inoperative	28/09/11	C
J0117495/0	Repair tarp	01/10/11	C
P0014688/0	Bi Monthly Grease & Inspection	01/11/11	C
J0118876/0	AB Service	05/11/11	C
J0120567/0	Replace tyres at POS25,26	07/11/11	C
J0120550/0	Weld bumper bar	08/11/11	C
J0123533/0	Rear axle spring eye bushes	09/12/11	C
J0124705/0	replace safety signs	20/12/11	C
P0015300/0	Bi Monthly Grease & Inspection	01/01/12	C
J0125362/0	Replace near side rear tyres	02/01/12	C
J0125391/0	Retension wheel nuts	02/01/12	C
J0125743/0	Replace tyres at POS19,20	03/01/12	C
J0130914/0	Fit reverse alarm	23/02/12	C
P0016432/0	Bi Monthly Grease & Inspection	01/03/12	C
J0132662/0	Tailights n/w	12/03/12	C
J0133142/0	Tarp n/w	12/03/12	C
J0133510/0	Indicators n/w	20/03/12	C
J0133758/0	l/h indicator n/w	22/03/12	C
J0135394/0	Adjust brakes	03/04/12	C
J0136752/0	replace tyres pos 27 28	16/04/12	C
P0017635/0	Bi Monthly Grease & Inspection	01/05/12	C
J0138681/0	Adjust wheel bearing l/front	07/05/12	C
J0138682/0	replace brake booster	07/05/12	C
P0018266/0	AB Service	18/06/12	C
P0018735/0	Bi Monthly Grease & Inspection	01/07/12	C
J0144886/0	wheel retension p 19 20 21 22	02/07/12	C
J0144712/0	Tyres replaced pos 23 24 25 26	03/07/12	C
J0145722/0	Change 4x mudflaps	16/07/12	C
J0146796/0	Bi Monthly Truck Washing	25/07/12	C
J0147665/0	tarp n/w	01/08/12	C
J0147935/0	Replace damaged tarp	01/08/12	C
J0149125/0	Shock absorber mounts loose	13/08/12	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
P0019871/0	Bi Monthly Grease & Inspection	01/09/12	C
J0152764/0	Tyres replaced at POS 19, 20, 21, 22	17/09/12	C
J0153235/0	Tyres replaced at POS	21/09/12	C
J0153610/0	replace brake linings	24/09/12	C
J0153671/0	repair rear bumper bar	24/09/12	C
J0151857/0	Bi Monthly Truck Washing	01/10/12	C
J0158281/0	tarp n/w	12/11/12	C
J0158416/0	Replace damaged tarp	12/11/12	C
P0021231/0	Trailer Service	14/11/12	C
J0159704/0	Bi Monthly Truck Washing	01/12/12	C
P0021527/0	Bi Monthly Grease & Inspection	01/12/12	C
J0160318/0	reline rear axle and repack bearings	03/12/12	C
J0160707/0	Wheel retension pos 23,26	10/12/12	C
J0162939/0	replace mudguard	07/01/13	C
P0022550/0	Bi Monthly Grease & Inspection	30/01/13	C
J0164739/0	Bi Monthly Truck Washing	01/02/13	C
J0165519/0	tarp overloading on circuit breaker	04/02/13	C
P0022307/0	Rego Renewal	04/02/13	C
J0170327/0	Bi Monthly Truck Washing	01/04/13	C
P0023971/0	Trailer Service	18/05/13	C
J0175822/0	Load of coal dumped in tarp	27/05/13	C
J0175996/0	Bi Monthly Truck Washing	01/06/13	C
J0177029/0	Wheel retension pos 15 16	10/06/13	C
J0177347/0	Inspect all hydraulic hoses	17/06/13	C
J0177701/0	Tarp inop	25/06/13	C
J0177912/0	Replace r/h front axle air bag	27/06/13	C
P0026002/0	Bi monthly safety inspection	01/08/13	C
S0000164/0	Bi monthly safety inspection	01/08/13	CA
J0183714/0	Clearance lights n/w	02/09/13	C
J0183814/0	Tyres repaired at POS 23, 24	04/09/13	C
J0185888/0	Wheel retension pos v 25 26	01/10/13	C
J0185721/0	Tyres replaced at POS 25, 26	02/10/13	C
J0187532/0	Ride height too low	21/10/13	C
J0187595/0	Tarp n/w replace cable	21/10/13	C
J0189945/0	Repair clearance lights	18/11/13	C
J0190727/0	Bi Monthly Truck Washing	25/11/13	C
J0194039/0	wheel retension pos 23 24	13/01/14	C
J0193878/0	Tyres replaced at POS 23, 14	15/01/14	C
P0028318/0	Rego Renewal	23/01/14	C
J0200588/0	Side loading light to be fitted	31/03/14	C
J0200710/0	Install tarp position indicator lights	01/04/14	C
J0202168/0	Repair air leak at airbag fitting	14/04/14	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0203821/0	Replace NHVAS label	05/05/14	C
P0030600/0	Trailer service	01/06/14	C
J0206349/0	adjust wheel bearings	02/06/14	C
J0209081/0	Truck Washing 2014/2015	01/07/14	C
P0031020/0	Safety Inspection 2014/2015	01/07/14	C
J0211566/0	Green tarp warning light n/w	28/07/14	C
J0211810/0	Tyres replaced at POS 25, 26	04/08/14	C
J0211816/0	replace leaking air bags	04/08/14	C
J0212255/0	Tyres replaced at POS 21, 22	06/08/14	C
P0031784/0	Trailer Service - B-Double Side Tipper	04/09/14	C
J0216018/0	wheel retension 25/26	08/09/14	C
J0216019/0	flat tyre pos 25	08/09/14	C
P0033880/0	Rego Renewal	04/02/15	C
J0246188/0	lights inop	08/10/15	C
J0246197/0	change tyres pos 31/32	08/10/15	C
J0246204/0	grease inspection	08/10/15	C
J0246206/0	torn mudflap	08/10/15	C
P0038781/0	Rego Renewal	04/02/16	C
J0256447/0	Repair door rams	23/02/16	C
J0266699/0	wash trailer 2016/2017	06/07/16	C
J0268557/0	MARATHON fit tyres to Pos 23,24	29/07/16	C
J0269531/0	JRAE repaired inop lights and test	10/08/16	C
J0272562/0	Prepare trailer for operations	19/08/16	C
J0272364/0	Green tarp position lights n/w	16/09/16	C
J0272365/0	Worklight n/w	16/09/16	C
J0272445/0	Paint chassis	19/09/16	C
J0273496/0	tarp tripping out	04/10/16	C
J0275787/0	brake test	05/11/16	C
J0276725/0	inspect air leak	17/11/16	C
J0277684/0	repair inop clearance lights	30/11/16	C
J0279888/0	Marathon fit tyres Pos 29,30 Daracon retension	09/01/17	C
P0041545/0	Rego Renewal	30/01/17	C
J0282243/0	MARATHON fit tyres Pos 23,24 Daracon retension	09/02/17	C
J0283246/0	MARATHON fit tyres Pos 25,26 Daracon retension	21/02/17	C
J0283285/0	rewire L/H taillight	21/02/17	C
P0043695/0	Trailer Service - B-Double Side Tipper	02/03/17	C
J0286511/0	adjust trailer height	04/04/17	C
J0287939/0	Retension wheels aqnd fit indicators	21/04/17	C
J0288183/0	replace green light	28/04/17	C
J0288635/0	safety inspection 2016/2017	03/05/17	C
J0288876/0	inspect tipping fault	06/05/17	C
J0288887/0	repair brake lights	06/05/17	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0289707/0	tarp not working clean anderson plugs	16/05/17	C
P0044687/0	Trailer Service - B-Double Side Tipper	17/05/17	C
J0290702/0	mount flow devider and change hoses	30/05/17	C
J0293645/0	Trailer Wash 2017-2018	01/07/17	C
J0294284/0	Safety Inspection 2017/2018	01/07/17	C
J0293911/0	fit number plate	11/07/17	C
J0300326/0	MARATHON fit tyres Pos 29,30 Daracon retension	28/07/17	C
P0045703/0	Trailer Service - B-Double Side Tipper	31/07/17	C
P0046801/0	Trailer Service - B-Double Side Tipper	31/07/17	C
P0047443/0	Trailer Service - B-Double Side Tipper	31/07/17	C
P0057970/0	Trailer Service - B-Double Side Tipper	31/07/17	C
P0061586/0	Trailer Service - B-Double Side Tipper	31/07/17	C
P0065726/0	Trailer Service - B-Double Side Tipper	31/07/17	C
P0066768/0	Trailer Service - B-Double Side Tipper	31/07/17	C
P0067549/0	Trailer Service - B-Double Side Tipper	31/07/17	C
P0070034/0	Trailer Service - B-Double Side Tipper	31/07/17	C
J0301045/0	MARATHON fit tyres Pos 23,24,27,28 Daracon retension	04/08/17	C
J0302742/0	green light on all the time	28/08/17	C
J0305102/0	replace broken tarp drive bolt	26/09/17	C
J0307969/0	marker plates damaged	04/11/17	C
J0309840/0	tarp keeps tripping out	30/11/17	C
J0311543/0	inspect and order tarp	21/12/17	C
J0312370/0	repair torn tarp	11/01/18	C
J0313238/0	replace worn tyres Pos 21,22	23/01/18	C
J0315118/0	MARATHON fit tyres Pos 27,28,29,30/wheel retension	14/02/18	C
J0315086/0	rear axle brake reline	15/02/18	C
J0316240/0	repair inop clearance lights	01/03/18	C
J0317764/0	repair spray suppression	21/03/18	C
P0048732/0	Trailer Service - B-Double Side Tipper	16/05/18	C
J0323640/0	repair green lights flashing	15/06/18	C
J0323642/0	tarp not working at Bengalla	15/06/18	C
S0000573/0	Safety Inspection 2018-2019	01/07/18	C
S0000574/0	Trailer Washing 2018-2019	01/07/18	C
J0326152/0	MARATHON fit tyres Pos 23,24	23/07/18	C
J0327356/0	torn mud flaps	10/08/18	C
J0327939/0	replace leaking lift cylinder	17/08/18	C
J0328345/0	replace electrical plugs	24/08/18	C
J0329675/0	replace tarp	12/09/18	C
P0050014/0	Trailer Service - B-Double Side Tipper	20/09/18	C
J0331159/0	carry out brake test	03/10/18	C
J0332866/0	JSL modify tarp wiring	25/10/18	C
J0333113/0	1st axle brakes/rotors/bearings	31/10/18	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
S0000994/0	Safety Inspection 2019-2020	05/07/19	C
S0000995/0	Trailer Washing 2019-2020	05/07/19	C
S0001339/0	Safety Inspection 2020-2021	03/07/20	C
S0001340/0	Trailer Washing 2020-2021	03/07/20	C
J0374752/0	Check & adjust wheel bearings	11/08/20	C
J0374754/0	Install amber tipping lights	12/08/20	C
J0374832/0	Replace door & tipping hoses	12/08/20	C
J0374837/0	Replace hi-vis fleet numbers	12/08/20	C
J0374850/0	Replace LH trailing arm bushes	13/08/20	C
J0375127/0	Pos 27,28,29,30 tyres replaced	17/08/20	C
J0384230/0	Tyres replaced - Pos 15,16,17,18.S/S-11769	27/01/21	C
J0384462/0	Rims replaced - Pos 19,22,23,26.S/S-11778	01/02/21	C
J0385955/0	Replace height control valve	23/02/21	C
J0387669/0	Replace marker plates	25/03/21	C
J0387671/0	Rear tarp struts replaced	25/03/21	C
J0391245/0	Fit scales	27/05/21	C
J0391939/0	Tarp not working	07/06/21	C
J0392496/0	Tarp wiring rubbed through near plug	18/06/21	C
J0392653/0	Repair tarp lights	21/06/21	C
J0392657/0	ABS sensor mounting on RHS broken	21/06/21	C
S0001655/0	Safety Inspection 2021-2022	01/07/21	C
S0001656/0	Trailer Washing 2021-2022	01/07/21	C
J0374775/0	Weld cracks front & rear hinges,r/h front body chassis	12/07/21	C
J0395278/0	Tyres runout on - Pos 19,20.S/S-13998	05/08/21	C
J0395613/0	Tyres replaced - Pos 20.S/S-13903	11/08/21	C
J0396559/0	Weld repair axle stops	26/08/21	C
J0396575/0	Daracon pre-delivery inspection	27/08/21	C
P0061587/0	NHVR Annual Heavy Vehicle Inspection	01/09/21	C
J0399735/0	Tyre runout on - Pos 21	28/10/21	C
J0400145/0	93560 - RH Clearance light	04/11/21	C
J0406864/0	Tarp won't lower at rear	21/03/22	C
J0411828/0	Pre delivery inspection	29/06/22	C
S0001964/0	Safety Inspection 2022-2023	01/07/22	C
S0001965/0	Trailer Washing 2022-2023	01/07/22	C
P0064443/0	Yearly Pressure Vessel Inspection	18/07/22	C
J0414360/0	Tyres replaced - Pos 19,20,21,22.S/S-12673	12/08/22	C
J0416526/0	Replace RH 1st axle brake booster	19/09/22	C
P0065727/0	NHVR Annual Heavy Vehicle Inspection	30/09/22	C
J0421039/0	Tyres replaced - Pos 23,24.S/S-15224	13/12/22	C
J0421923/0	Tyres replaced - Pos 25,26.S/S-15238	09/01/23	C
J0426683/0	Replace mudflap	30/03/23	C
J0426684/0	Repair trailer lighting wiring	30/03/23	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0426994/0	Weld hoist cylinder mount	06/04/23	C
J0429638/0	Accident damage IN79453	29/05/23	C
S0002298/0	Safety Inspection 2023-2024	01/07/23	C
S0002299/0	Trailer Washing 2023-2024	01/07/23	C
J0431726/0	RH 1st axle brake caliper	07/07/23	C
J0432405/0	Replace clearance lights	21/07/23	C
J0434708/0	Tarp not working	05/09/23	C
J0435853/0	Tyres replaced - Pos 25,26.S/S-16034	25/09/23	C
J0437455/0	Tyres replaced - Pos 22,23.S/S-16084	25/10/23	C
J0437844/0	Replace rear mudflaps	01/11/23	C
J0440280/0	Tyres replaced - Pos 19,20.S/S-16284	15/12/23	C
J0441748/0	Tarp N/W	22/01/24	C
J0442343/0	fit plate	03/02/24	C
J0444324/0	LHR wheel nut rounded	06/03/24	C
J0444397/0	Tyre repair on - Pos 23.S/S-16393	07/03/24	C
J0444404/0	Tyre runout on - Pos 23.S/S-16394	07/03/24	C
J0448091/0	LHR Clearance Light not working	14/05/24	C
S0002651/0	Safety Inspection 2024-2025	01/07/24	C
S0002652/0	Trailer Washing 2024-2025	01/07/24	C
J0454825/0	RH Indicator repeater not working	13/09/24	C
J0459317/0	Repair Cracks on Rear Bar	06/12/24	C
S0002959/0	Safety Inspection 2025-2026	04/07/25	N
S0002960/0	Trailer Washing 2025-2026	04/07/25	N