

Maintenance History Report

Report Generated on 15/05/26 07:52 AM

3813 Hitachi ZX65 Excavator

Job No	Job Title	Start Date	Status
J0360961/0	Prepare For Operation	09/01/20	C
J0361493/0	Replace Quick Hitch Hose	17/01/20	C
C0000624/0	Modify Sleeper Grabs	21/01/20	C
P0055501/0	250hr service	14/02/20	C
J0367524/0	Inspect For Hyd Leaks	22/04/20	C
J0367839/0	Supply Hitachi Coolant	27/04/20	C
P0055937/0	500hr service	28/04/20	C
J0368185/0	Repair Tilting Hitch Wiring	01/05/20	C
J0368314/0	Rail Support May 2nd	04/05/20	C
J0368333/0	Pre-delivery Inspection	04/05/20	C
J0371255/0	Rail support May 19th	15/06/20	C
P0056838/0	750hr service	18/06/20	C
J0371986/0	Inspect Hyd Oil Leak	26/06/20	C
J0377264/0	Replace Hitch Hyd Hose	17/09/20	C
P0057706/0	1000hr service	23/09/20	C
J0377850/0	Repair Hyd Oil Leak	25/09/20	C
J0378352/0	Replace Flat Battery	06/10/20	C
J0378990/0	Tilt Head Electrical Fault	13/10/20	C
J0381722/0	Auxillary Hyd Joystick Fault	27/10/20	C
P0058545/0	250hr service	26/11/20	C
J0382061/0	Replace Tilt Head Cable	07/12/20	C
J0382512/0	Replace Hydraulic Hose	14/12/20	C
P0058944/0	Yearly Hi Rail Recertification	01/01/21	C
J0383555/0	Replace Tilt Head Cable	04/01/21	C
J0383793/0	Fit Door Mount Fire Ext	19/01/21	C
J0383794/0	Replace Base Edge	19/01/21	C
J0383795/0	Replace Track Pad (12)	19/01/21	C
J0383796/0	Inspect Engcon Head Play	19/01/21	C
J0383797/0	Replace Battery Isolator	19/01/21	C
J0383798/0	Replace Hi-Rail Sensors	19/01/21	C
J0383800/0	Entry to Workshop Inspection	19/01/21	C
J0384736/0	Repair Sleeper Grab Leak	19/01/21	C
J0383922/0	Replace Tape & Decals	20/01/21	C
J0383928/0	Replace Precleaner Bowl	20/01/21	C
J0383977/0	Check Headlights Staying On	21/01/21	C
J0384768/0	Intro to Site MACH Energy ITS	04/02/21	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0385739/0	Intro to Site UWJVOC ITS	19/02/21	C
J0386544/0	Bulga ITS Renewal	05/03/21	C
J0390273/0	Replace A/C & Air Filters	11/05/21	C
J0390535/0	Replace Hydraulic Hoses	17/05/21	C
P0059795/0	500hr service	29/05/21	C
J0392284/0	Replace Fuel Hoses	13/06/21	C
J0392466/0	Intro To Site Bulga Projects	17/06/21	C
J0394443/0	Change Beacon Colour	21/07/21	C
J0396256/0	Replace Hyd Couplings	23/08/21	C
J0397182/0	Intro To Site (Wambo)	07/09/21	C
P0061152/0	750hr service	13/09/21	C
P0063149/0	250hr service	14/10/21	C
J0399018/0	Replace Rubber Track Pads	14/10/21	C
J0399019/0	Replace Sleeper Grab Pads	14/10/21	C
J0399020/0	Modify Sleeper Grab Hitch	14/10/21	C
J0399406/0	Hitch Grab Cylinder IN77177	21/10/21	C
J0399427/0	Replace Final Drive Fill Plugs	22/10/21	C
J0399439/0	Replace Cutting Edge	22/10/21	C
J0399497/0	Check In Inspection	25/10/21	C
J0399707/0	Non-Conformances Repairs	28/10/21	C
J0399774/0	Pre-delivery & Check Out	29/10/21	C
J0399959/0	Replace Broom Head Brushes	02/11/21	C
J0401043/0	Replace Hydraulic Fittings	18/11/21	C
J0401010/0	Replace Battery N100	18/11/21	C
J0401067/0	Replace Battery N70ZZL	19/11/21	C
P0062155/0	2000hr service	30/11/21	C
J0401708/0	Fab Sleeper Grab Hitch	02/12/21	C
J0401935/0	Inspect Hitch Grease Nipples	08/12/21	C
J0402353/0	Replace Hydraulic Hoses	15/12/21	C
J0402694/0	Install Sleeper Grab Lock Valve	21/12/21	C
J0402696/0	Non-Conformance Repair Bulga	21/12/21	C
J0403102/0	Repair Blade Pivot Mount	09/01/22	C
P0062326/0	Yearly Hi Rail Recertification	27/01/22	C
J0404624/0	Repair Hitch Oil Leak	07/02/22	C
J0405850/0	Check-In & Minor Repairs	02/03/22	C
J0405943/0	ITS Inspection (Mangoola, Mt Owen, Ulan)	04/03/22	C
J0406348/0	Replace Starter Isolator	11/03/22	C
J0407630/0	Hitch Grab Cylinder IN58556	05/04/22	C
J0408398/0	Check In Inspection	22/04/22	C
J0408431/0	Replace All Air Filters	22/04/22	C
J0408432/0	Replace Fire Extinguishers	22/04/22	C
J0408437/0	Replace Hitch Hyd Hose	22/04/22	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0408509/0	Replace Grease Nipples	26/04/22	C
J0408510/0	Boom Guard & Stick Damage	26/04/22	C
J0409276/0	Pre-delivery Inspection	11/05/22	C
J0410058/0	Repair Rotary Head Fault	24/05/22	C
J0410239/0	Remove Hitch Grab & Cylinder	27/05/22	C
J0412499/0	Replace Beacon Lights	13/07/22	C
J0412659/0	Repair Quick Hitch Crack	16/07/22	C
J0414796/0	Modify Sleeper Grab	17/08/22	C
J0415907/0	Replace Sleeper Grab Hose	07/09/22	C
J0416377/0	Non-Conformances Bulga	16/09/22	C
J0417235/0	Hi Rail Proxy Switch Fault	03/10/22	C
J0417353/0	Replace Hitch Hyd Hose	04/10/22	C
J0418702/0	Replace Tilt Hitch Fitting	02/11/22	C
P0065872/0	500hr Service	28/11/22	C
J0421621/0	Reseal Quick Hitch Leak	28/12/22	C
P0065998/0	Yearly Hi Rail Recertification	27/01/23	C
J0423042/0	Repair Hi Rail Frame Crack	30/01/23	C
J0423045/0	Replace Worn Hi Rail Axles & Bearings	30/01/23	C
J0423187/0	Annual ITS Inspection VAR	31/01/23	C
J0424390/0	Repair Hitch Switch & Hose	22/02/23	C
J0425980/0	Replace Grab Cylinder	20/03/23	C
J0426079/0	Concrete Sleeper Grab Jaw Pads	21/03/23	C
J0426447/0	Replace Joystick Roller	28/03/23	C
J0427893/0	Replace A/C Cab Filters	28/04/23	C
J0427900/0	Repair Hi-Rail Sensor Fault	28/04/23	C
J0430181/0	Replace Cutting Edge	08/06/23	C
J0430883/0	Engcon Hitch Swivel Fault	22/06/23	C
J0432966/0	UGL Rail Recertification	01/08/23	C
J0434913/0	Reseal Hydraulic Leak	07/09/23	C
J0434914/0	Check-In & Minor Repairs	07/09/23	C
J0434963/0	Swing Motor Warranty	08/09/23	C
J0440433/0	Replace Starter Isolator & Wiring	03/11/23	C
P0069594/0	3000hr service	13/11/23	C
J0438716/0	Replace LHS Joy Stick	17/11/23	C
J0438717/0	Reseal Swivel On Hitch	17/11/23	C
J0438718/0	Adjust Aux Hyd Pressures	17/11/23	C
P0068138/0	750hr service	28/11/23	C
J0440373/0	Replace Hydraulic Hose	18/12/23	C
J0440893/0	Repair Minor Defects	05/01/24	C
J0440874/0	Repair Lighting Harness	05/01/24	C
J0440925/0	ITS Mangoola Mt Owen Ulan & MDG15	08/01/24	C
J0442703/0	Replace Flat Battery	08/02/24	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0442822/0	Pre-Delivery Inspection	12/02/24	C
J0444246/0	Hi-Rail Alarm Batteries	05/03/24	C
J0446614/0	Hi-Rail Alarm Sensors	17/04/24	C
J0448837/0	ITS Inspection ROC	28/05/24	C
J0448892/0	Replace Alternator	29/05/24	C
J0449466/0	Repair List of Defects	07/06/24	C
J0449877/0	Sleeper Grab Cylinder	17/06/24	C
P0072176/0	250hr service	12/07/24	C
J0451508/0	Replace Hydraulic Hose	16/07/24	C
J0451931/0	UGL Rail Recertification	24/07/24	C
J0454280/0	ITS Inspection ROC CHPP 3 Monthly	04/09/24	C
J0459889/0	ITS MGO Ulan Mangoola & MDG15	17/12/24	C
J0460756/0	Non-Compliance Repair	09/01/25	C
J0467623/0	UGL Rail Recertification	14/05/25	C
J0467870/0	Non-Compliance Repair	19/05/25	C
J0468727/0	Check In & Minor Defects	03/06/25	C
J0468728/0	Repair Coolant Hose Leak	03/06/25	C
J0469018/0	Repair quick hitch guard	06/06/25	C
J0473102/0	Repair Minor Defects	01/08/25	C
P0075837/0	500hr service	23/09/25	A
J0475821/0	Machine Wont Start	02/10/25	C
P0077293/0	Fire Risk Reassessment	10/11/25	C
J0478198/0	ITS Mangoola MGO USO & MDG15	26/11/25	C
J0479457/0	Hitch Hydraulic Oil Leak	18/12/25	N
J0480255/0	Repair Start Fault	14/01/26	N
J0480279/0	Purchase Lifting Tongs	14/01/26	N
J0484014/0	Sleeper Grab Cylinder	24/03/26	N
J0484927/0	Fuel Cap - Replace	14/04/26	N
J0485211/0	Check In Inspection	16/04/26	N
P0078987/0	250hr Service	04/05/26	N

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed